

22/03/2002

ASS. REC. BY:

REF:

CS/FCI18016622/Ddbm

Special Instruction:

Survivor:

Bryan

ASSIGNMENT (Office)

From (Person):

Koen Tan

of

FCI

Date/Time:

12/09/2018 12:05PM

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 1374D

Insured:

SH 7686H

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

Blk 101mk Ind Park 2A #03-19

Policy No:

Claim No:

D18006741MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-09-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

20/9/18 12:08pm

Person Contacted:

Tune

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 1374D - CCA / 17013110 / Gpb3

DCA: 15062017

SH 7686H - C3/ALH16014973 / H1hg3g2

DCA: 06082016

14/9/18

Email preli revised to FCI

REF:

ASSIGNMENT

COR Dec 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 Vehicle No: _____
 at Workshop No: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 1374D Yr Regn: 2016 / Dec

Type: M, Car / M, Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 CC: 1685

Colour: Blue A/C: Insured / Std / TR / HA

Sp. Branding: 250711 Luggage: Insured / Std / TR / HA

Eng No: 24FDGU695227

Ch No: KMHLB41UMHW097327

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD / R/Rim or

Tyre Size: F: 205/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A. 11/09/2018 D.O.I. 12/09/2018

Survey held at Churri AMK

Loc. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/10/18 First capital SH7686H
 Jniper 4/3 86501- with 5 days of rep

Red: \$ 3831.92, 31%

RECEIVED 17 OCT 2018

Date/Time, File Name for?

☐ : Preli. Report

1) typist

☒ : Final Report

Date/Time, File Return for?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: TP

Lump Sum / Hrs (\$): 8650.00

Survey Fee:

Transportation:

S + RR, 24

Phone:

Others:

17/10/18

2x15=30

170+30

50

50+50

106

456



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006741MFSH
Our ref: CS/FCI18016622/Drb

Date: 14/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 1374D


We thank you for your instruction on 12/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/9/2018 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$12,481.92
Revised Estimate Amount	: S\$10,872.00
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	11-09-2018	Our Ref No. D18006741MFSH
Accident Date	11-09-2018	Claim Type. Third Party
Insured Vehicle	SH7686H	Third Party Vehicle. SHC1374D
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 14 September 2018 10:04 AM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006741MFSH/1, SHC 1374D
Attachments: SHC 1374D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 1374D
Date of survey: 12/9/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 12 September 2018 12:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006741MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 12 September, 2018 12:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006741MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

10 Surveys by LKR.

DATE : 11.09.2018

LKK Auto Consultants **TEL no 6542 5119**

the Repairer of the following: **FAX: • 6542 6039**

FCI

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

115 8650 | -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016622/Drbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7686H	Veh. Inspected	SHC 1374D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006741MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	12/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU097327	Colour	BLUE	
Odometer	250711	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/09/2018	Inspection Date	12/09/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1374D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT	2,265.90	2,265.90
1	BONNET LOCK	SERVICEABLE	36.90	-
1	RADIATOR GRILLE	BROKEN	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	NECESSARY	39.50	39.50
1	FRONT BUMPER COVER	CUT	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	DENTED	402.10	402.10
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NOT NECESSARY	49.20	-
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BENT	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	MOUNTING CRACKED	2,776.00	2,776.00
1	RADIATOR	BENT	698.30	698.30
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	BROKEN	792.95	792.95
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
2	RADIATOR GUARD @\$20.00	O/S BROKEN / N/S NOT NECESSARY	40.00	20.00
2	HORN UNIT (LH/RH) @\$73.80	BROKEN	147.60	147.60
1	AIRCON CONDENSER	BENT	927.50	927.50
1	INTER COOLER	PUNCTURE	1,032.50	1,032.50
1	INTER COOLER MOUNTING (2 PCS)	NOT NECESSARY	25.90	-
	LESS 20% DISCOUNT		-2,536.73	-2,454.25
			10,146.92	9,817.00
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	DISLODGE	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	SERVICEABLE	30.00	-
			55.00	25.00
LABOUR				
	PANEL BEATING.		1,000.00	500.00
	SPRAY PAINTING CHARGE.		500.00	400.00

Report Ref No. CS/FC118016622/Drbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	20.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			2,280.00	1,030.00
	GRAND TOTAL		12,481.92	10,872.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,650.00

Report Ref No. CS/FCI18016622/Drbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.