

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR H&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	2		TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, RH FENDER, RH F DOOR, RH R DOOR, RH FENDER, REAR BUMPER, RH SIDE SKIRT, LH F FENDER)	1800	0	0	Reviewing		
	3		TO CHECK WIRING & FOCUS HEADLAMP.	20	0	0	Reviewing		
	4		TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD. TO TOP UP A/C GAS. (*CHECK \$150.00)	0	0	0	Reviewing		
	5		TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD. (*CHECK \$250.00)	0	0	0	Reviewing		
	6		TO DO WHEEL ALIGNMENT	60	0	0	Reviewing		
	7		TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD. (RH F DOOR, RH R DOOR)	120	0	0	Reviewing		
	8		TO REFIT AIRBAG SYSTEM.	200	0	0	Reviewing		
	9		TO RESET AIRBAG CONTROL UNIT.	180	0	0	Reviewing		
	10		TO TUFF COAT.	150	0	0	Reviewing		
	11		TO REMOVE & REFIT DASHBOARD TO ASSIST WORK LOAD.	250	0	0	Reviewing		
	12		TO REMOVE & REFIT RH FRONT QUARTER GLASS TO ASSIST WORK LOAD.	50	0	0	Reviewing		
	13		TO RE-ALIGN FRONT CHASSIS. (*CHECK \$600.00)	0	0	0	Reviewing		
	14		TOWING.	50	0	0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTR%	DISC COUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	66	1			RHF POWER WINDOW REGULATOR (NPA)			Serviceable	0		20		0	Reviewing	
	67	1			RH FRONT FENDER QUARTER GLASS			Cut	290.7		20		232.56	Reviewing	
	68	1			RH FRONT FENDER QUARTER GLASS MOULDING			Necessary	55		20		44	Reviewing	
	69	1			RH REAR DOOR			Denied	1050		20		840	Reviewing	
	70	1			RH REAR DOOR HINGE TOP			Repair	0		20		0	Reviewing	
	71	1			RH REAR DOOR HINGE BOTTOM			Repair	0		20		0	Reviewing	
	72	1			RH REAR DOOR CHECKER			Serviceable	0		20		0	Reviewing	
	73	1			RH REAR DOOR WEATHERSTRIP			Serviceable	0		20		0	Reviewing	
	74	1			RHR DOOR GLASS Moulding ("CHECK \$53.50)				0		20		0	Reviewing	
	75	1			RH SIDE SKIRT ("CHECK \$363.60)				0		20		0	Reviewing	
	76	10			RH SIDE SKIRT CLIP ("CHECK \$35.00)				0		20		0	Reviewing	
	77	1			LH FRONT FENDER			Repair	0		20		0	Reviewing	
	78	1			LH FRONT FENDER UNDERSHIELD			Serviceable	0		20		0	Reviewing	
	79	10			LH FRONT FENDER UNDERSHIELD CLIP			Serviceable	0		20		0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	40	1			RH WING MIRROR COVER			Dented	47.3		20		37.84	Reviewing	
	41	1			RH FRONT FENDER			Bent	435		20		348	Reviewing	
	42	1			RH FRONT FENDER UNDERSHIELD			Damaged	110		20		88	Reviewing	
	43	10			RH FRONT FENDER UNDERSHIELD CLIP			Necessary	3.5		20		28	Reviewing	
	44	1			RHF FENDER WORDING "HYBRID"			Necessary	58		20		46.4	Reviewing	
	45	1			RH FRONT LOWER ARM ("CHECK \$230.80)				0		20		0	Reviewing	
	46	1			RH FRONT SHOCK ABSORBER TOP MOUNTING ("CHECK \$36.80)				0		20		0	Reviewing	
	47	1			RH FRONT SHOCK ABSORBER STOPPER ("CHECK \$21.30)				0		20		0	Reviewing	
	48	1			RH FRONT KNUCKLE ARM			Bent	330.6		20		264.48	Reviewing	
	49	1			RH FRONT KNUCKLE BEARING			Necessary	168		20		134.4	Reviewing	
	50	1			RH FRONT WHEEL HUB ("CHECK \$138.30)				0		20		0	Reviewing	
	51	1			RH FRONT WHEEL HUB LOCK NUT ("CHECK \$8.00)				0		20		0	Reviewing	
	52	1			RH FRONT TIE ROD ("CHECK \$95.60)				0		20		0	Reviewing	

EDIT	SIR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPIL/ BITING	DISC CUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	12	1			FRONT GRILLE UPPER CHROME			Cracked	302.5		20		242	Reviewing	
	13	1			FRONT GRILLE LOWER CHROME			Damaged	220.7		20		176.56	Reviewing	
	14	4			FRONT GRILLE CLIP			Necessary	3.9		20		12.48	Reviewing	
	15	1			FRONT SUPPORT PANEL (COMPLETE) (*CHECK \$780.00)				0		20		0	Reviewing	
	16	1			FRONT SUPPORT PANEL TOP GARNISH (*CHECK \$48.20)				0		20		0	Reviewing	
	17	10			FRONT SUPPORT PANEL TOP GARNISH CLIP (*CHECK \$39.00)				0		20		0	Reviewing	
	18	1			BRACE PANEL (NPA)			Serviceable	0		20		0	Reviewing	
	19	1			CONDENSER (*CHECK \$985.00)				0		20		0	Reviewing	
	20	1			CONDENSER FAN MOTOR (*CHECK \$330.00)				0		20		0	Reviewing	
	21	1			CONDENSER FAN BLADE (*CHECK \$78.00)				0		20		0	Reviewing	
	22	1			CONDENSER FAN COWLING (*CHECK \$121.90)				0		20		0	Reviewing	
	23	1			RADIATOR (*CHECK \$1540.40)				0		20		0	Reviewing	
	24	1			RADIATOR FAN MOTOR (*CHECK \$328.80)				0		20		0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	BLK 125 GEYLANG EAST AVENUE #07-27, 381125, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	S1167764I	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
TAN Jas	9/11/18 3:44 PM	17697.24	17697.24	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
ACCIDENT PHOTO 3.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 13.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 1.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 11.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
SLU9096L TP GIA REPORT.pdf	Reports & Statement	GIA Report	TAN Jas	September 11, 2018
SMD5158X GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	September 11, 2018
TP ESTEEM-SMA3650U TP GIA REPORT W /CAMERA.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	September 11, 2018
XD8737A INSD GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	September 11, 2018
TP ESTEEM-EMAIL RECEIVED WITH TP GIA REPORT & EST.msg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	September 11, 2018

NAME	TYPE	SUB- TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Mermen	
SMA 3650U20180908_140715_EK (online-video-culter.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
SMA 3650U20180908_140715_EF (online-video-culter.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
20171231_224811_Forward-camera.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
20171231_224811_Forward-camera.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 28.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 26.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 19.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 24.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 21.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 18.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 29.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 20.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 22.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018
ACCIDENT PHOTO 27.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	September 13, 2018