

ISS/00

INS. CASE OWNER:

val

CCU / AXA1801

6641

T1 sub 52
LKK:
IDAC:

Surveyor:

MTH

DOI:

ASSIGNMENT

17/1/18

Date / Time:

17/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XB 9870B

Claim No.:

8800000069227

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

2/1/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

XB 9870B


SJA 22470

SDT 15227

SUP 9191X

INSRS:
WSP:
Tel:
Liability:
RMKS:

01

INSRS:
WSP:
Tel:
Liability:
RMKS:Shs
RMC
TPINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

17/1/18
MTH

SJA 22470 - X XB 9870B - V

* Small claim - virtual
- Oliver

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: DS FORM

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by: MTH

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

RIS SS 10,000

(12)

days) Reduction:

44 %

Email

Call

FINAL SETTLEMENT

Date/Time: 27-05-19

Confirm with SHARON

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28. Ass. Lia: 100%

Repair Cost:

W/L/S:

SS 10,700.00

4 YEN CC OLD LPST

Loss of Rental (LOR):

SS -

()

days)

Loss of Use (LOU):

SS 900.00

(\$60

x 15 days)

Loss of Income (LOI):

SS -

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS 94.94

(e.g. Tow/ Independent) + ANDREX FEE

Legal Cost

SS -

Total:

SS 11,696.94

Global Sum SS:

FINAL PAYMENT

Date/Time: 27-05-19

Confirm with: SHARON

Email

Call

Payee 1:

SS 11,696.94

Name 1:

SHS AN TEE MOORE + PANEL SERVICE PRE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
26/1/18

**SNG AH TEE MOTOR &
 PANEL SERVICE PTE LTD
 3 PIONEER ROAD NORTH
 #01-18
 SINGAPORE 628457**

* Owner want to claim
 general item like baby
 seat, jump start tools etc.

Claim Reference:
Assessment Number: DS000558
Version: SNGAHTEE/3
Date Calculated: 12/09/2018 02:59

Full Report - V1
Registration: SJA2243D
Printed: 12/09/2018 09:59

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	SNG AH TEE	Date of Incident:	07/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	HONDA	FROM MODEL 2014	AIR CONDITIONING
Model:	Mobilio	ELECT DOOR MIRRORS	REARVIEW CAMERA
Sub Model:	BASE MODEL	SIDE FLASHER	REAR WIPER
Model Sheet Number:	HM2 01	PAINTED DOOR HANDLES	MOULDINGS PAINTED
Registration:	SJA2243D	1.5 LTR 87 KW	LWR GRILLE PAINTED
Registration Month:		ROOF SPOILER	SILL TRIMS
Registration Year:		TWO COAT METALLIC	PREPARE OFF VEHICLE
VIN Number:			
Odometer:	Not Known		
Colour:			
Engine Number:			
Fuel Level:	%		

Vehicle Condition

Vehicle Status		
Pre-Accident Condition:	Severity of Impact:	sur @ 11km/h to wall
Steering:	Vehicle Status on Inspection:	12 days
Brakes Pedal Travel:	Date of Inspection:	11/09/2018
Place of Inspection:		13/9/18 @ 3pm
Pre-Accident Damage:		

Tyres Condition:
 Tread Depth LHF:
 Tread Depth LHR:
 Damage Areas:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tread Depth RHF:
 Tread Depth RHR:
 Direction of Impact:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558



Version: SNGAHTTE/3

Date Calculated: 12/09/2018 02:59

Full Report - V1

Registration: SJA2243D

Printed: 12/09/2018 09:59



Addresses

Cost Summary

Total Labour	\$3,627.00
Total Paint/Material	\$583.56
Total Parts	\$12,328.00
Total of Additional Costs	\$1,242.00
Excess:	TBA
Grand Total Exc GST:	\$17,780.56
7 % GST:	\$1,244.64
Grand Total Inc GST:	\$19,025.20

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
812100	RENEW BONNET INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE	5.0	22.50
8101A2	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER CPL AND R + R RADIATOR GRILLE.	5.0	22.50
813110)	RENEW RADIATOR GRILLE	3.0	13.50
712103)	R + R L/HEADLAMP (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMP	5.0	22.50
713103)	R + R R/HEADLAMP (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMP	5.0	22.50
831120	R + R WINDSCREEN INCLUDES: FRT AIR GRILLE, WIPER ARM AND REQUIRED TRIMS REMOVE AND REFIT	30.0	135.00
8101B1	R + R FRONT BUMPER SUPPORT	5.0	22.50
NO NUMBER	RENEW FRONT PANEL CPL	28.0	126.00
710100	R + R BATTERY	2.0	9.00
NO NUMBER	RENEW ROOF	110.0	495.00
8471A2)	R + R FLOOR CARPET CPL	12.0	54.00
823100	RENEW TAILGATE INCLUDES: TAILGATE, REAR SCREEN AND REQUIRED ATTACHED PARTS R + R. ADJUST TAILGATE.	33.0	148.50
918411	RENEW REAR PANEL	21.0	94.50
NO NUMBER	RENEW L/R SIDE PANEL	100.0	450.00
8341A0	R + R R/SIDE WINDOW	21.0	94.50

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTTE/3

Date Calculated: 12/09/2018 02:59

Full Report - V1

Registration: SJA2243D

Printed: 12/09/2018 09:59

NO NUMBER	R + R FUEL TANK ASS-WORK	6.0	27.00
8111A5	RENEW REAR BUMPER	4.0	18.00
	INCLUDES: BUMPER AND ALL		
	REQUIRED ATTACHED PARTS R + R		
714135	R + R RIGHT TAILLAMP	2.0	9.00
NO NUMBER	RENEW BOOT FLOOR CROSSMEMBER	45.0	202.50
NO NUMBER	R + R L/F SEAT	3.0	13.50
NO NUMBER	R + R LEFT SEAT 3. SEAT ROW	3.0	13.50
NO NUMBER	R + R R/F SEAT	3.0	13.50
NO NUMBER	R + R RIGHT SEAT 3. SEAT ROW	3.0	13.50
114100)	R + R RADIATOR	6.0	27.00
NO NUMBER	DRAIN-REFILL COOLENT LIQUID	3.0	13.50
0741	REPAIR L/F WING	5.0*	22.50
0742	REPAIR R/F WING	5.0*	22.50
3482	REPAIR R/R SIDE PANEL	10.0*	45.00
4101	REPAIR L/R IN S-PANEL REINF	10.0*	45.00
4102	REPAIR R/R IN S-PANEL REINF	5.0*	22.50

LABOUR COST

Total Work Units	498.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	49.8HRS	\$2,241.00 1,710
Paint Labour	30.8HRS	\$1,386.00 1,309.5
Total Labour	80.6HRS	\$3,627.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	FRT BUMPER SUPPORT NEW PART PAINTING	9.0	
471	BONNET NEW PART PAINTING	17.0	
1009	FRONT PANEL CPL SURFACE PAINT	5.0	
2351	ROOF NEW PART PAINTING	72.0	
2711	REAR PANEL NEW PART PAINTING	15.0	
2931	BOOTLID/TAILGATE NEW PART PAINTING	20.0	
3481	L/R SIDE PANEL NEW PART PAINTING	27.0	
3903	CTR LUGG COMP C-MEMBSURFACE PAINT	6.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
294	FRT TOWING EYE COVERNEW PART PAINT K1R	3.0	
2583	REAR BUMPER NEW PART PAINT K1R	10.0	
2707	NUMBER PLATE TRIM NEW PART PAINT K1R	6.0	
3047	ROOF SPOILER NEW PART PAINT K1R	6.0	
741	L/F WING REPAIR PAINTING >50%	16.0	
742	R/F WING REPAIR PAINTING >50%	16.0	
3482	R/R SIDE PANEL REPAIR PAINTING >50%	21.0	
347	L/BUMPER TRIM GRILLESURFACE PAINT PLAST.	3.0	
348	R/BUMPER TRIM GRILLESURFACE PAINT PLAST.	3.0	
4101	L/R IN S-PANEL REINFSURFACE PAINT	5.0	
4102	R/R IN S-PANEL REINFSURFACE PAINT	5.0	

LABOUR COST - PAINT

TIME(PAINT)	278.0
-------------	-------

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTEE/3

Date Calculated: 12/09/2018 02:59

Full Report - V1

Registration: SJA2243D

Printed: 12/09/2018 09:59

Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	308.0	
Total Paintwork Labour	30.8HRS	\$1,386.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$299.02
New Part Painting - Plastic K1R		\$151.04
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$35.36
Surface Paint Plastic		\$3.66
Repair Painting		\$56.88
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$583.56
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$583.56

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0% <i>See X</i> 0.00F
283	1	FRONT BUMPER	71101TE7K00ZZ		0% <i>de</i> 300.00*
294	1	FRT TOWING EYE COVER	71104TE7K00ZC		0% <i>de</i> 10.00*
321	1	L/LWR BUMPER BRACKET	71198TG1T01		0% <i>re</i> 10.00*
322	1	R/LWR BUMPER BRACKET	71193TG1T01		0% <i>re</i> 10.00*
340	1	FRT BUMPER SUPPORT	71130SYY000ZZ		0% <i>see g</i> 75.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% <i>see</i> 25.00*
410	1	GRILLE	71121TE7K01		0% <i>see</i> 120.00*
414	1	GRILLE MOULDING	71122TE7K01		0% <i>see</i> 145.00*
431	1	GRILLE BADGE	75700TE7K00		0% <i>see</i> 15.00*
471	1	BONNET	60100TG1T01ZZ		0% <i>bt</i> 360.00*
493	1	BONNET LOCK	74120TG1T01		0% <i>bt</i> 28.00*
561	1	L/F HEADLAMP	33150TG4T01		0% <i>see g</i> 330.00*
562	1	R/F HEADLAMP	33100TG4T01		0% <i>see X</i> 330.00*
1009	1	FRONT PANEL CPL	60400TE7K00ZZ		0% <i>bt</i> 290.00*
1411	1	WINDSCREEN BOND KIT	0871899960EH		0% <i>see X</i> 0.00F
1413	2	FRT SCREEN MNTG KIT	91568TF0003		0% <i>see</i> 0.00F
2351	1	ROOF	62100TE7K00ZZ		0% <i>Rx</i> 600.00*
2583	1	REAR BUMPER	71501TE7K00ZZ		0% <i>de</i> 300.00*
2619	1	L/R BUMPER BRACKET	71598TE7K01		0% <i>re</i> 15.00*
2620	1	R/R BUMPER BRACKET	71593TE7K01		0% <i>re</i> 15.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% <i>re</i> 25.00*
2702	1	REAR NUMBER PLATE	KNPL6		0% <i>bt X</i> 0.00F
2707	1	NUMBER PLATE TRIM	74890TE7K01ZC		0% <i>de</i> 270.00*
2711	1	REAR PANEL	66100TE7K01ZZ		0% <i>bt</i> 270.00*
2931	1	BOOTLID/TAILGATE	68100TE7K00ZZ		0% <i>bt X</i> 500.00*
2933	1	BOOT/TAILGATE LOCK	74801TF0902		0% <i>? bt</i> 75.00*
2944	1	BOOT/TAILGATE SEAL	74440TE7K01		0% <i>cut</i> 80.00*
2997	1	L/TAILGATE DAMPER	74870TE7K01		0% <i>? bt</i> 95.00*
2998	1	R/TAILGATE DAMPER	74820TE7K01		0% <i>? X</i> 95.00*
3016	1	REAR BADGE	75722TE7K00		0% <i>re</i> 23.00*
3017	1	BADGE I-VTEC	75725TE8K10		0% <i>see g</i> 0.00F
3020	1	BADGE HONDA	75711TE7K00		0% <i>see</i> 0.00F

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTEE/3

Date Calculated: 12/09/2018 02:59

Full Report - V1

Registration: SJA2243D

Printed: 12/09/2018 09:59

3047	1	ROOF SPOILER	74900TE7K91ZC	0%	ms	300.00*	✓
3151	1	REAR SCREEN	73201TE7K01	0%	bro	650.00*	✓
3159	1	REAR SCREEN BOND KIT	0871899960EH	0%	an	0.00F	
3160	1	REAR SCREEN FIX SET	USE SINGLE PARTS	0%	an	0.00	
3162	1	LWR REAR SCREEN SEAL	73225TE7K00	0%	an	50.00*	✓
3163	4	REAR SCREEN SPACER	91501S70003	0%	an	0.00F	
3164	2	REAR SCREEN SPACER	91502S70003	0%	an	0.00F	
3165	2	REAR SCREEN SPACER	91536SS0J01	0%	an	0.00F	
3191	1	THIRD BRAKE LIGHT	34270SYYJ01	0%	an	170.00*	✓
3221	1	REAR WIPER MOTOR	76710TE7K01	0%	bf	190.00*	✓
3225	1	REAR WIPER ARM	76720TE7K01	0%	an	26.00*	✓
3227	1	REAR WIPER BLADE	76730TE7K01	0%	an	35.00*	✓
3283	1	L/R LAMP	33551TE7T01	0%	bniz	135.00*	✓
3284	1	R/R LAMP	33501TE7T01	0%	Xun	135.00*	
3285	1	L/R INNER LAMP	34155TE7T01	0%	an	95.00*	✓
3286	1	R/R INNER LAMP	34150TE7T01	0%	an	95.00*	✓
3363	1	L/NUMBER PLATE LAMP	34901S6DG01	0%	dis	22.00*	✓
3364	1	R/NUMBER PLATE LAMP	34901S6DG01	0%	dis	22.00*	✓
3481	1	L/R SIDE PANEL	04646TE7K00ZZ	0%	bn	500.00*	✓
3803	1	L/R SIDE WINDOW	73551TE7K01	0%	bro	350.00*	✓
3805	2	L/INN SIDE WDW SEAL	73525SYY000	0%	an	0.00F	
3806	2	R/INN SIDE WDW SEAL	73525SYY000	0%	an	0.00F	
3807	1	L/R SIDE WINDOW SEAL	73525TE7K00	0%	an	0.00F	
3808	1	R/R SIDE WINDOW SEAL	73525TE7K00	0%	an	0.00F	
3809	1	L/LWR S/WINDOW SEAL	73579TE7K00	0%	an	30.00*	✓
3810	1	R/LWR S/WINDOW SEAL	73529TE7K00	0%	an	30.00*	✓
3812	1	R/R SIDE WINDOW SEAL	73528TE7K00	0%	Xun	0.00F	
3861	1	L/R WDW BONDING KIT	0871899960EH	0%	an	0.00F	
3862	1	R/R WDW BONDING KIT	0871899960EH	0%	Xun	0.00F	
3863	1	L/SIDE WDW MNTG KIT	USE SINGLE PARTS	0%	an	0.00	
3864	1	R/SIDE WDW MNTG KIT	USE SINGLE PARTS	0%	Xun	0.00	
3867	1	L/FASTENING CLIP	91553TE7K00	0%	an	0.00F	
3868	1	R/FASTENING CLIP	91503TE7K00	0%	Xun	0.00F	
3869	2	L/FASTENING CLIP	91501TE7K00	0%	an	0.00F	
3870	2	R/FASTENING CLIP	91502TE7K00	0%	Xun	0.00F	
3903	1	CTR LUGG COMP C-MEMB	65750TE7K00ZZ	0%	Xun	500.00*	
4465	1	CONDENSER	80110TE7K01	0%	?bt	300.00*	✓
4904	1	REAR PANEL TRIM	83780TE7K01ZA	0%	de	55.00*	✓
4907	1	LOWER TAILGATE TRIM	84440TE7K00ZA	0%	de	150.00*	✓
4957	1	ROOF COVER PANEL	83200TE7K00ZA	0%	de	380.00*	✓
5015	1	L/R SIDE PANEL TRIM	83780TE7K01ZA	0%	de	180.00*	✓
5016	1	R/R SIDE PANEL TRIM	83735TE7K01ZA	0%	?de	180.00*	✓
7761	1	RADIATOR	190105EAK51	0%	?bt	780.00*	✓
1000	1	REAR WIPER ARM COVER	Renew	0%	an	6.00*	✓
1000	1	RR BUMP TOP BEAM	Renew	0%	bt	30.00*	✓
1000	1	RR TAILGATE CHROME	Renew	0%	an	140.00*	✓
1000	1	L/R WING INN SHIELD	Renew	0%	Xun	28.00*	
1000	1	L/R INNERSHIELD CLIP	Renew	0%	Xun	20.00*	
1000	1	L/R WING AIRWAVE	LOGO	0%	an	75.00*	✓
1000	1	R/R WING AIRWAVE	LOGO	0%	an	75.00*	✓
1000	1	SPARE TYRE TRIMBOARD	Renew	0%	Xun	140.00*	
1000	1	SPARE TYRE SPONGE	Renew	0%	Xun	150.00*	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTEE/3

Date Calculated: 12/09/2018 02:59

Full Report - V1

Registration: SJA2243D

Printed: 12/09/2018 09:59

1000	1	INSULATOR CLIPS	Renew	0%	ne	25.00*
1000	1	F/BUMP UNDER COVER	Renew	0%	ne	65.00*
1000	1	L/F HEADLAMP BRKT	Renew	0%	ay &	25.00*
1000	1	R/F HEADLAMP BRKT	Renew	0%	ne	25.00*
1000	1	BONNET CHROME	Renew	0%	out	145.00*
f: OEM Parts			Saving			\$263.60
g: Original			Sub Total			\$10,720.00
h: Secondhand			Mark Up From Cost	(15 %)		\$1,608.00
p: Parallel			Total Parts			\$12,328.00
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE SPECIALIST	0%	\$42.00*
REAR NUMBER PLATE SPECIALIST		\$35.00*
AIRCON GAS SPECIALIST	0%	\$100.00*
REAR SCREEN GUM SPECIALIST		\$40.00*
RR REVERSE CAMERA SPECIALIST	0%	\$300.00*
REVERSE SENSOR SPECIALIST		\$180.00*
L/R WING GLASS SPECIALIST	0%	\$40.00*
GUM		\$40.00*
R/R WING GLASS SPECIALIST		\$40.00*
GUM		\$40.00*
FRONT NUMBER PLATE SPECIALIST	0%	\$35.00*
CHECK WIRING SPECIALIST		\$50.00*
RESET FAULT CODE SPECIALIST	0%	\$180.00*
ANTI RUST COATING SPECIALIST		\$150.00*
TOWING CHARGE SPECIALIST	0%	\$50.00*
Total Extras		\$1,242.00

Final Calculation

Total Parts		\$12,328.00
Labour		
Total Panel/Mechanical	\$2,241.00	1710
Total Paintwork	\$1,386.00	1309.50
Total Labour		\$3,627.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,242.00	
Total of Additional Costs		\$1,242.00
Total Paint/Material Costs		\$583.56
Grand Total Excludes GST		\$17,780.56
GST @ 7 %		\$1,244.64
Grand Total Includes GST		\$19,025.20

14230.91

Assessment Notes

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: DS000558

Registration: SJA2243D

Version: SNGAHTEE/3

Printed: 12/09/2018 09:59

Date Calculated: 12/09/2018 02:59

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000558
Version: SNGAHTEE/5
Date Calculated: 02/01/2019 04:11

Full Report - V1
Registration: SJA2243D
Printed: 02/01/2019 12:12

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SNG AH TEE	Date of Incident:	07/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Mobilio
Sub Model:	BASE MODEL
Model Sheet Number:	HM2 01
Registration:	SJA2243D
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM MODEL 2014	AIR CONDITIONING
ELECT DOOR MIRRORS	REARVIEW CAMERA
SIDE FLASHER	REAR WIPER
PAINTED DOOR HANDLES	MOULDINGS PAINTED
1.5 LTR 87 KW	LWR GRILLE PAINTED
ROOF SPOILER	SILL TRIMS
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status



Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	11/09/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: **DS000558**Version: **SNGAHTTE/5**Date Calculated: **02/01/2019 04:11**

Full Report - V1

Registration: **SJA2243D**Printed: **02/01/2019 12:12****Addresses****Cost Summary**

Total Labour	\$3,019.50
Total Paint/Material	\$577.16
Total Parts	\$10,885.90
Total of Additional Costs	\$1,060.00
Repair Cost Exc GST:	\$15,542.56
Overall Discount (20%):	-\$3,108.51
Excess:	TBA
After Deduction -	
Grand Total Exc GST:	\$12,434.05
7 % GST:	\$870.38
Grand Total Inc GST:	\$13,304.43

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
812100	RENEW BONNET	5.0	22.50
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		
8101A2	RENEW COMPLETE FRONT BUMPER	5.0	22.50
	INCLUDES: FRONT BUMPER CPL AND R + R RADIATOR GRILLE.		
813110)	RENEW RADIATOR GRILLE	3.0	13.50
712103)	R + R L/HEADLAMP	5.0	22.50
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMP		
713103)	R + R R/HEADLAMP	5.0	22.50
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMP		
8131A6	R + R L/F WHEELHOUSE COVER	4.0	18.00
8131A7	R + R R/F WHEELHOUSE COVER	4.0	18.00
8101B1	R + R FRONT BUMPER SUPPORT	5.0	22.50
NO NUMBER	RENEW FRONT PANEL CPL	28.0	126.00
710100	R + R BATTERY	2.0	9.00
8141A7	R + R REAR ROOF MOULDING	2.0	9.00
842100	REMOVE AND REFIT ALL ROOF TRIMS	29.0	130.50
823100	RENEW TAILGATE	33.0	148.50
	INCLUDES: TAILGATE, REAR SCREEN AND REQUIRED ATTACHED PARTS R + R.		
	ADJUST TAILGATE.		

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTEE/5

Date Calculated: 02/01/2019 04:11

Full Report - V1

Registration: SJA2243D

Printed: 02/01/2019 12:12

918411	RENEW REAR PANEL	21.0	94.50
NO NUMBER	RENEW L/R SIDE PANEL	100.0	450.00
8341A0	R + R R/SIDE WINDOW	21.0	94.50
NO NUMBER	R + R FUEL TANK ASS-WORK	6.0	27.00
8111A5	RENEW REAR BUMPER	4.0	18.00
	INCLUDES: BUMPER AND ALL REQUIRED ATTACHED PARTS R + R		
714135	R + R RIGHT TAILLAMP	2.0	9.00
NO NUMBER	RENEW R/UPP INN SIDE PANEL REINFORCEMENT	10.0	45.00
114100)	R + R RADIATOR	6.0	27.00
NO NUMBER	DRAIN-REFILL COOLENT LIQUID	3.0	13.50
NO NUMBER	R + R L/F WHEEL	1.0	4.50
NO NUMBER	R + R R/F WHEEL	1.0	4.50
0741	REPAIR L/F WING	5.0*	22.50
0742	REPAIR R/F WING	5.0*	22.50
2351	REPAIR ROOF	25.0*	112.50
3482	REPAIR R/R SIDE PANEL	10.0*	45.00
3900	REPAIR BOOTFLOOR CPL	15.0*	67.50
4101	REPAIR L/R IN S-PANEL REINF	10.0*	45.00
4102	REPAIR R/R IN S-PANEL REINF	5.0*	22.50

LABOUR COST

Total Work Units	380.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	38.0HRS	\$1,710.00
Paint Labour	29.1HRS	\$1,309.50
Total Labour	67.1HRS	\$3,019.50

PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR. Price = \$45.00/HR	WU	Cost Price (\$)
	- TWO COAT METALLIC			
	- PREPARE OFF VEHICLE			
340	FRT BUMPER SUPPORT NEW PART PAINTING		9.0	
471	BONNET NEW PART PAINTING		17.0	
1009	FRONT PANEL CPL SURFACE PAINT		5.0	
2711	REAR PANEL NEW PART PAINTING		15.0	
2931	BOOTLID/TAILGATE NEW PART PAINTING		20.0	
3481	L/R SIDE PANEL NEW PART PAINTING		27.0	
283	FRONT BUMPER NEW PART PAINT K1R		13.0	
294	FRT TOWING EYE COVERNEW PART PAINT K1R		3.0	
2583	REAR BUMPER NEW PART PAINT K1R		10.0	
2707	NUMBER PLATE TRIM NEW PART PAINT K1R		6.0	
3047	ROOF SPOILER NEW PART PAINT K1R		6.0	
741	L/F WING REPAIR PAINTING >50%		16.0	
742	R/F WING REPAIR PAINTING >50%		16.0	
2351	ROOF REPAIR PAINTING >50%		49.0	
3482	R/R SIDE PANEL REPAIR PAINTING >50%		21.0	
347	L/BUMPER TRIM GRILLESURFACE PAINT PLAST.		3.0	
348	R/BUMPER TRIM GRILLESURFACE PAINT PLAST.		3.0	
3900	BOOTFLOOR CPL SURFACE PAINT		12.0	
4101	L/R IN S-PANEL REINFSURFACE PAINT		5.0	
4102	R/R IN S-PANEL REINFSURFACE PAINT		5.0	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTTE/5

Date Calculated: 02/01/2019 04:11

Full Report - V1

Registration: SJA2243D

Printed: 02/01/2019 12:12

LABOUR COST - PAINT

TIME(PAINT)

Preparation Main Work Plastic
Preparation Main Work Metal
Preparation Work Multi Layer Paint
Total Work Units (10WU/HR)
Total Paintwork Labour

261.0
5.0
25.0
0.0
291.0
29.1HRS

\$1,309.50
Cost Price

MATERIAL COST - PAINT

New Part Painting
New Part Painting - Plastic K1R
Material-Constant Main Work Metal
Surface-/Blend Paint
Surface Paint Plastic
Repair Painting
Material-Const Main Work Plastic
Total Excluding Pearlescent Uplift
Pearlescent Uplift @ 0.0%
Total Paint Material Cost

\$179.12
\$151.04
\$28.60
\$62.75
\$3.66
\$142.99
\$9.00
\$577.16
\$0.00
\$577.16

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0% 0.00F
283	1	FRONT BUMPER	71101TE7K00ZZ		0% 300.00*
294	1	FRT TOWING EYE COVER	71104TE7K00ZC		0% 10.00*
321	1	L/LWR BUMPER BRACKET	71198TG1T01		0% 10.00*
322	1	R/LWR BUMPER BRACKET	71193TG1T01		0% 10.00*
340	1	FRT BUMPER SUPPORT	71130SYY000ZZ		0% 75.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% 25.00*
410	1	GRILLE	71121TE7K01		0% 120.00*
414	1	GRILLE MOULDING	71122TE7K01		0% 145.00*
431	1	GRILLE BADGE	75700TE7K00		0% 15.00*
471	1	BONNET	60100TG1T01ZZ		0% 360.00*
493	1	BONNET LOCK	74120TG1T01		0% 28.00*
561	1	L/F HEADLAMP	33150TG4T01		0% 330.00*
1009	1	FRONT PANEL CPL	60400TE7K00ZZ		0% 290.00*
1411	1	WINDSCREEN BOND KIT	0871899960EH		0% 0.00F
1413	2	FRT SCREEN MNTG KIT	91568TF0003		0% 0.00F
2422	1 *	R/ROOF MOULDING	75250TE7K91		0% 145.00*
2583	1	REAR BUMPER	71501TE7K00ZZ		0% 300.00*
2619	1	L/R BUMPER BRACKET	71598TE7K01		0% 15.00*
2620	1	R/R BUMPER BRACKET	71593TE7K01		0% 15.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% 25.00*
2702	1	REAR NUMBER PLATE	KNPL6		0% 0.00F
2707	1	NUMBER PLATE TRIM	74890TE7K01ZC		0% 270.00*
2711	1	REAR PANEL	66100TE7K01ZZ		0% 270.00*
2931	1	BOOTLID/TAILGATE	68100TE7K00ZZ		0% 0.00*
2933	1	BOOT/TAILGATE LOCK	74801TF0902		0% 75.00*
2944	1	BOOT/TAILGATE SEAL	74440TE7K01		0% 80.00*
2953	1 *	L/TAILGATE HINGE	68260TE7K00ZZ		0% 35.00*
2954	1 *	R/TAILGATE HINGE	68210TE7K00ZZ		0% 35.00*
2997	1	L/TAILGATE DAMPER	74870TE7K01		0% 95.00*
3016	1	REAR BADGE	75722TE7K00		0% 23.00*
3017	1	BADGE I-VTEC	75725TE8K10		0% 0.00F

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTTE/5

Date Calculated: 02/01/2019 04:11

Full Report - V1

Registration: SJA2243D

Printed: 02/01/2019 12:12

3020	1	BADGE HONDA	75711TE7K00	0%	0.00F
3047	1	ROOF SPOILER	74900TE7K91ZC	0%	300.00*
3151	1	REAR SCREEN	73201TE7K01	0%	650.00*
3159	1	REAR SCREEN BOND KIT	0871899960EH	0%	0.00F
3160	1	REAR SCREEN FIX SET	USE SINGLE PARTS	0%	0.00
3162	1	LWR REAR SCREEN SEAL	73225TE7K00	0%	50.00*
3163	4	REAR SCREEN SPACER	91501S70003	0%	0.00F
3164	2	REAR SCREEN SPACER	91502S70003	0%	0.00F
3165	2	REAR SCREEN SPACER	91536SS0J01	0%	0.00F
3191	1	THIRD BRAKE LIGHT	34270SYYJ01	0%	170.00*
3221	1	REAR WIPER MOTOR	76710TE7K01	0%	190.00*
3225	1	REAR WIPER ARM	76720TE7K01	0%	26.00*
3227	1	REAR WIPER BLADE	76730TE7K01	0%	35.00*
3283	1	L/R LAMP	33551TE7T01	0%	135.00*
3285	1	L/R INNER LAMP	34155TE7T01	0%	95.00*
3286	1	R/R INNER LAMP	34150TE7T01	0%	95.00*
3363	1	L/NUMBER PLATE LAMP	34901S6DG01	0%	22.00*
3364	1	R/NUMBER PLATE LAMP	34901S6DG01	0%	22.00*
3481	1	L/R SIDE PANEL	04646TE7K00ZZ	0%	500.00*
3783	1 *	L/R AIR VENT GRILLE	75450SDET00	0%	65.00*
3803	1	L/R SIDE WINDOW	73551TE7K01	0%	350.00*
3805	2	L/INN SIDE WDW SEAL	73525SYY000	0%	0.00F
3806	2	R/INN SIDE WDW SEAL	73525SYY000	0%	0.00F
3807	1	L/R SIDE WINDOW SEAL	73525TE7K00	0%	0.00F
3808	1	R/R SIDE WINDOW SEAL	73525TE7K00	0%	0.00F
3809	1	L/LWR S/WINDOW SEAL	73579TE7K00	0%	30.00*
3810	1	R/LWR S/WINDOW SEAL	73529TE7K00	0%	30.00*
3812	1	R/R SIDE WINDOW SEAL	73528TE7K00	0%	0.00F
3861	1	L/R WDW BONDING KIT	0871899960EH	0%	0.00F
3862	1	R/R WDW BONDING KIT	0871899960EH	0%	0.00F
3863	1	L/SIDE WDW MNTG KIT	USE SINGLE PARTS	0%	0.00
3864	1	R/SIDE WDW MNTG KIT	USE SINGLE PARTS	0%	0.00
3867	1	L/FASTENING CLIP	91553TE7K00	0%	0.00F
3868	1	R/FASTENING CLIP	91503TE7K00	0%	0.00F
3869	2	L/FASTENING CLIP	91501TE7K00	0%	0.00F
3870	2	R/FASTENING CLIP	91502TE7K00	0%	0.00F
4103	1 *	L/R UPP S-PNL REINF	64742TE7K00ZZ	0%	105.00*
4465	1	CONDENSER	80110TE7K01	0%	300.00*
4904	1	REAR PANEL TRIM	83780TE7K01ZA	0%	55.00*
4907	1	LOWER TAILGATE TRIM	84440TE7K00ZA	0%	150.00*
4957	1	ROOF COVER PANEL	83200TE7K00ZA	0%	380.00*
4971	1 *	L/R UPP S/PANEL TRIM	84191TE7K01ZA	0%	100.00*
5010	1 *	REAR ROOF LAMP	34254T2A023ZB	0%	55.00*
5015	1	L/R SIDE PANEL TRIM	83780TE7K01ZA	0%	180.00*
5016	1	R/R SIDE PANEL TRIM	83735TE7K01ZA	0%	180.00*
7761	1	RADIATOR	190105EAK51	0%	780.00*
9649	1 *	HIGH TONE HORN	38100TG1T01	0%	40.00*
1000	1	REAR WIPER ARM COVER	Renew	0%	6.00*
1000	1	RR BUMP TOP BEAM	Renew	0%	30.00*
1000	1	RR TAILGATE CHROME	Renew	0%	140.00*
1000	1	L/R WING AIRWAVE	LOGO	0%	75.00*
1000	1	R/R WING AIRWAVE	LOGO	0%	75.00*
1000	1	INSULATOR CLIPS	Renew	0%	25.00*
1000	1	F/BUMP UNDER COVER	Renew	0%	65.00*

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTEE/5

Date Calculated: 02/01/2019 04:11

Full Report - V1

Registration: SJA2243D

Printed: 02/01/2019 12:12

1000	1	R/F HEADLAMP BRKT	Renew	0%	25.00*
1000	1	BONNET CHROME	Renew	0%	145.00*
1000	1	AIRCON TEMP SENSOR	Renew	0%	120.00*
1000	1	FRT LWR GRILLE	Renew	0%	120.00*
1000	1	TAILGATE HINGE CVR	Renew	0%	35.00*
1000	1	TAILLAMP CLIP	X4PC	0%	14.00*
1000	1	TAILGATE INNTRIM UPP	Renew	0%	120.00*
1000	1	ROOF TOP PANEL INNER	@REAR	0%	280.00*
f: OEM Parts				Saving	\$263.60
g: Original				Sub Total	\$9,466.00
h: Secondhand				Mark Up From Cost (15 %)	\$1,419.90
p: Parallel				Total Parts	\$10,885.90
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REAR NUMBER PLATE SPECIALIST	0%	\$35.00
AIRCON GAS SPECIALIST		\$100.00
REAR SCREEN GUM SPECIALIST	0%	\$40.00
RR REVERSE CAMERA SPECIALIST		\$300.00
REVERSE SENSOR SPECIALIST	0%	\$180.00
L/R WING GLASS SPECIALIST		\$40.00
GUM		
R/R WING GLASS SPECIALIST	0%	\$40.00
GUM		
FRONT NUMBER PLATE SPECIALIST		\$35.00
CHECK WIRING SPECIALIST	0%	\$40.00
RESET FAULT CODE SPECIALIST		\$150.00
ANTI RUST COATING SPECIALIST	0%	\$100.00
Total Extras		\$1,060.00

Final Calculation

Total Parts	\$10,885.90
Labour	
Total Panel/Mechanical	\$1,710.00
Total Paintwork	\$1,309.50
Total Labour	\$3,019.50
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$1,060.00
Total of Additional Costs	\$1,060.00
Total Paint/Material Costs	\$577.16
Repair Costs Excludes GST	\$15,542.56
Deductions	
Deduction (20.00 %) Before GST	-\$3,108.51
Deduction for Excess	TBA
Total Deductions	-\$3,108.51
Grand Total Excludes GST (After Deduction)	\$12,434.05
GST @ 7 %	\$870.38

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000558

Version: SNGAHTEE/5

Date Calculated: 02/01/2019 04:11

Full Report - V1

Registration: SJA2243D

Printed: 02/01/2019 12:12

Grand Total Includes GST (After Deduction)

\$13,304.43

Assessment Notes



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18016641/ub3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 12-09-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 9870B	Veh. Inspected	SJA 2243D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/09/2018	Inspection Date	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Service Request Details

Claim

S8M00V02

Reference

None

Loss Date

September 7, 2018

Request Date

September 12, 2018

Due Date

September 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

12.09.2018 @ 11am
Joyce veh in
'Virtual'
Sng Ah Tee
Blk 3 Pioneer Rd North #01-18
13.09.2018 @ morning

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJA2243D

Make

TPVD HONDA

Model

AIRWAVE-1.5 (A)

Service Address

...

Primary Contact/Insured

DHEVESH INTERNATIONAL PRIVATE LIMITED

190 WOODLANDS INDUSTRIAL PK E5, #07-17 WOODLANDS BIZHUB, 757516, Singapore
63380083

dheveshinternational@gmail.com

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

VIRTUAL CASE NON REPORTING

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



RE: Re:RE: Re:RE: Re:Request for Direct settlement for S8M00V02

Type

🔗 Question

Message

Hi Vale, The revised IA and resurvey photo uploaded. Please advise if we can process with D/S. Thanks

Asher Sng - 01/02/2019

Reply



Re:Request for Direct settlement for S8M00V02

Type

🔗 Question

Message

Hi Pls proceed, thanks VO

Reply

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457

TEL: 62686183 (4LINES) FAX: 62681429

CO. REG. NO. & GST REG. NO.: 200810440N

02/01/2019

YOUR REF: TBA
OUR REF: 2243AXA

ATTN: MOTOR CLAIMS DEPT
AXA INSURANCE PTE LTD

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING YOUR INSURED'S XB9870B & OUR CLIENT'S VEHICLE SJA2243D ON
07/09/2018 ALONG ADAM ROAD TOWARDS PIE**

We are assisting our client, KOK CHEE HUO, in his/her claim against your insured XB9870B as it is due to the negligence of your insured, causing the damage of our client's vehicle SJA2243D. The vehicle SJA2243D has been completed repairs to the satisfaction by M/S SNG AH TEE MOTOR & PANEL SERVICE PTE LTD.

Our letter of demand is as per proposed quantum stated below:-

COST OF REPAIR	\$10700.00
LOSS OF USE(20 DAYS x \$80)	\$1600.00
SEARCH FEE/GIA REPORT	\$2.00
TOWING CHARGE	\$50.00
GENERAL DAMAGE (BABY CHAIR/BABY SEAT)	\$583.00
TOTAL	\$12935.00

Hope to hear from you soon. Thank you.

Yours Faithfully,
SHARON SNG
Sng Ah Tee Motor & Panel Service Pte Ltd

Please note there is only for property claims for damages relating to my client's claim, shall not prejudice or effect or prelude my client from making a further claim for general and special damages for my client's and/or passenger's personal injuries sustained in the same accident.*



Victory Recovery

(Business Reg No.: 53096358B)

65 Teban Gardens Rd #23-617, Singapore 600065.

Mobile: 9618 0311 Fax: 6267 8996

TP AXA

CASH /
W.O. No. 95721

TOW JOB WORKS ORDER

M Sing Ah Tee Svc Date 7-9-18
Car Make/Model Honda Airave Vehicle No. SJA2243D
M'ship/NRIC No./Card No. 92722778 Contact No. 92722778
Time - Rec'd 22:00 Arrived 22:00 Completed 22:40
Amount Charge S\$ 450 Tow Truck No GP3375X
Destination (from) Arccadia Road (to) Pioneer Rd North BIK3 NO1-18
Remark (if any) _____

Tow Driver's Signature _____ Member's Signature _____

☐ Change Tyres & Towing	☐ Using King Drolley	☐ Use Car Carrier
☐ Basement / Multi Carpark	☐ Low Spoiler / Low Oil Sump	☐ Release Brake / Shaft
☐ Causeway / 2nd Link	☐ Accident / Over-turn	☐ Loaded

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	XB 9870B (Insd veh)	Model:	HONDA AIRWAVE
	SJA 2243D (TP veh)		
Date of Accident:	07/09/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	20,586.70
Final Repair Cost	:	\$	10,700.00
Loss of Use	:	\$	900.00
Rental (if any)	:	\$	15 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Audatex Fee	:	\$	94.94
-------------	---	----	-------

	:	\$	
Final Settlement Sum	:	\$	11,696.94

Is Third Party Workshop GIA Registered?		☒ YES	☐ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
		28		
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____100_____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	:	\$ 11,696.94

NUR SHAQILAH BTE ABDOL
WAHAB

31/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18016641/T1eb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 31-05-2019



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 9870B	Veh. Inspected	SJA 2243D
Policy No.	VCC/P1917214	Coverage (\$)	0.00
Claim No.	S8M00V02	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	12/09/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA AIRWAVE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	GJ11203693	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70R14	DUNLOP	6 mm
L/H Front Tyre	185/70R14	DUNLOP	6 mm
R/H Rear Tyre	185/70R14	DUNLOP	6 mm
L/H Rear Tyre	185/70R14	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/09/2018	Inspection Date	13/09/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 2243D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT NUMBER PLATE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	300.00	300.00
1	FRT TOWING EYE COVER (CONSISTENT)	DEFORMED	10.00	10.00
1	L/LWR BUMPER BRACKET (CONSISTENT)	NECESSARY	10.00	10.00
1	R/LWR BUMPER BRACKET (CONSISTENT)	NECESSARY	10.00	10.00
1	FRT BUMPER SUPPORT (CONSISTENT)	NECESSARY	75.00	75.00
1	FRT BUMPER CLAMP KIT (CONSISTENT)	NECESSARY	25.00	25.00
1	GRILLE (CONSISTENT)	CRACKED	120.00	120.00
1	GRILLE MOULDING (CONSISTENT)	CRACKED	145.00	145.00
1	GRILLE BADGE (CONSISTENT)	NECESSARY	15.00	15.00
1	BONNET (CONSISTENT)	BENT	360.00	360.00
1	BONNET LOCK (CONSISTENT)	BENT	28.00	28.00
1	L/F HEADLAMP (CONSISTENT)	CRACKED	330.00	330.00
1	R/F HEADLAMP (CONSISTENT)	NOT NECESSARY	330.00	-
1	FRONT PANEL CPL (CONSISTENT)	BENT	290.00	290.00
1	WINDSCREEN BOND KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	FRT SCREEN MNTG KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	ROOF (CONSISTENT)	TO REPAIR SEE LABOUR	600.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	300.00	300.00
1	L/R BUMPER BRACKET (CONSISTENT)	NECESSARY	15.00	15.00
1	R/R BUMPER BRACKET (CONSISTENT)	NECESSARY	15.00	15.00
1	RR BUMPER CLAMP KIT (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR NUMBER PLATE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	NUMBER PLATE TRIM (CONSISTENT)	DEFORMED	270.00	270.00
1	REAR PANEL (CONSISTENT)	BENT	270.00	270.00
1	BOOTLID / TAILGATE (CONSISTENT)	NOT NECESSARY	500.00	-
1	BOOTLID / TAILGATE LOCK (CONSISTENT)	BENT	75.00	75.00
1	BOOTLID / TAILGATE SEAL (CONSISTENT)	CUT	80.00	80.00
1	L/TAILGATE DAMPER (CONSISTENT)	BENT	95.00	95.00
1	R/TAILGATE DAMPER (CONSISTENT)	NOT NECESSARY	95.00	-

Report Ref No. CC4/ASM18016641/T1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BADGE (CONSISTENT)	NECESSARY	23.00	23.00
1	BADGE I-VTEC (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BADGE HONDA (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	ROOF SPOILER (CONSISTENT)	MISSING	300.00	300.00
1	REAR SCREEN (CONSISTENT)	BROKEN	650.00	650.00
1	REAR SCREEN BOND KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	SET REAR SCREEN FIX (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	LWR REAR SCREEN SEAL (CONSISTENT)	NECESSARY	50.00	50.00
4	REAR SCREEN SPACER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	REAR SCREEN SPACER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	REAR SCREEN SPACER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	THRID BRAKE LIGHT (CONSISTENT)	CRACKED	170.00	170.00
1	REAR WIPER MOTOR (CONSISTENT)	BENT	190.00	190.00
1	REAR WIPER ARM (CONSISTENT)	DISTORTED	26.00	26.00
1	REAR WIPER BLADE (CONSISTENT)	CUT	35.00	35.00
1	L/R LAMP (CONSISTENT)	MISSING	135.00	135.00
1	R/R LAMP (CONSISTENT)	NOT NECESSARY	135.00	-
1	L/R INNER LAMP (CONSISTENT)	CRACKED	95.00	95.00
1	R/R INNER LAMP (CONSISTENT)	CRACKED	95.00	95.00
1	L/NUMBER PLATE LAMP (CONSISTENT)	DISTORTED	22.00	22.00
1	R/NUMBER PLATE LAMP (CONSISTENT)	DISTORTED	22.00	22.00
1	L/R SIDE PANEL (CONSISTENT)	BUCKLED	500.00	500.00
1	L/R SIDE WINDOW (CONSISTENT)	BROKEN	350.00	350.00
2	L/INN SIDE WDW SEAL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	R/INN SIDE WDW SEAL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R SIDE WINDOW SEAL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R SIDE WINDOW SEAL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/LWR S/WINDOW SEAL (CONSISTENT)	NECESSARY	30.00	30.00
1	R/LWR S/WINDOW SEAL (CONSISTENT)	NECESSARY	30.00	30.00
1	R/R SIDE WINDOW SEAL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R WDW BONDING KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R WDW BONDING KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/SIDE WDW MNTG KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-

Report Ref No. CC4/ASM18016641/T1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R/SIDE WDW MNTG KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/FASTENING CLIP (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	R/FASTENING CLIP (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	L/FASTENING CLIP (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	R/FASTENING CLIP (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	CTR LUGG COMP C-MEMB (CONSISTENT)	NOT NECESSARY	500.00	-
1	CONDENSER (CONSISTENT)	BENT	300.00	300.00
1	REAR PANEL TRIM (CONSISTENT)	DEFORMED	55.00	55.00
1	LOWER TAILGATE TRIM (CONSISTENT)	DEFORMED	150.00	150.00
1	ROOF COVER PANEL (CONSISTENT)	DEFORMED	380.00	380.00
1	L/R SIDE PANEL TRIM (CONSISTENT)	DEFORMED	180.00	180.00
1	R/R SIDE PANEL TRIM (CONSISTENT)	DEFORMED	180.00	180.00
1	RADIATOR (CONSISTENT)	BENT	780.00	780.00
1	REAR WIPER ARM COVER (CONSISTENT)	MISSING	6.00	6.00
1	RR BUMP TOP BEAM (CONSISTENT)	BENT	30.00	30.00
1	RR TAILGATE CHROME (CONSISTENT)	CRACKED	140.00	140.00
1	L/R WING INN SHIELD (CONSISTENT)	NOT NECESSARY	28.00	-
1	L/R INNERSHIELD CLIP (CONSISTENT)	NOT NECESSARY	20.00	-
1	L/R WING AIRWAVE (CONSISTENT)	NECESSARY	75.00	75.00
1	R/R WING AIRWAVE (CONSISTENT)	NECESSARY	75.00	75.00
1	SPARE TYRE TRIMBOARD (CONSISTENT)	NOT NECESSARY	140.00	-
1	SPARE TYRE SPONGE (CONSISTENT)	NOT NECESSARY	150.00	-
1	INSULATOR CLIPS	NECESSARY	25.00	25.00
1	F/BUMP UNDER COVER (CONSISTENT)	NECESSARY	65.00	65.00
1	L/F HEADLAMP BRKT (CONSISTENT)	NOT NECESSARY	25.00	-
1	R/F HEADLAMP BRKT (CONSISTENT)	NECESSARY	25.00	25.00
1	BONNET CHROME (CONSISTENT)	CUT	145.00	145.00
1	R/ROOF MOULDING (CONSISTENT) (ADDITIONAL)	NECESSARY	145.00	145.00
1	L/TAILGATE HINGE (CONSISTENT) (ADDITIONAL)	BENT	35.00	35.00
1	R/TAILGATE HINGE (CONSISTENT) (ADDITIONAL)	BENT	35.00	35.00
1	L/R AIR VENT GRILLE (CONSISTENT) (ADDITIONAL)	CRACKED	65.00	65.00
1	L/R UPP S-PNL REINF (CONSISTENT) (ADDITIONAL)	BENT	105.00	105.00
1	L/R UPP S/PANEL TRIM (CONSISTENT) (ADDITIONAL)	DEFORMED	100.00	100.00

Report Ref No. CC4/ASM18016641/T1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR ROOF LAMP (CONSISTENT) (ADDITIONAL)	DISTORTED	55.00	55.00
1	HIGH TONE HORN (CONSISTENT) (ADDITIONAL)	CRACKED	40.00	40.00
1	AIRCON TEMP SENSOR (CONSISTENT) (ADDITIONAL)	DISTORTED	120.00	120.00
1	FRT LWR GRILLE (CONSISTENT) (ADDITIONAL)	CRACKED	120.00	120.00
1	TAILGATE HINGE CVR (CONSISTENT) (ADDITIONAL)	BENT	35.00	35.00
1	TAILLAMP CLIP (CONSISTENT) (ADDITIONAL)	NECESSARY	14.00	14.00
1	TAILGATE INNETRIM UPP (CONSISTENT) (ADDITIONAL)	DEFORMED	120.00	120.00
1	ROOF TOP PANEL INNER (CONSISTENT) (ADDITIONAL)	BENT	280.00	280.00
	COST PLUS 15%		1,798.35	1,419.90
			13,787.35	10,885.90
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	35.00	35.00
1	AIRCON GAS (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	REAR SCREEN GUM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	RR REVERSE CAMERA (SN) (CONSISTENT)	DISTORTED	300.00	300.00
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	180.00	180.00
1	L/R WING GLASS GUM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	R/R WING GLASS GUM (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	CRACKED	35.00	35.00
1	AUDATEX FEE (SN) (CONSISTENT)		42.00	-
			812.00	770.00
	<u>LABOUR</u>			
	CHECK WIRING.		50.00	40.00
	RESET FAULT CODE.		180.00	150.00
	ANTI RUST COATING.		150.00	100.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	TOTAL PANEL / MECHANICAL. INCLUSIVE OF THE REPAIR OF ROOF.		2,241.00	1,710.00
	TOTAL PAINTWORK.		1,386.00	1,309.50
	TOTAL PAINT / MATERIAL COSTS.	NOT NECESSARY	583.56	-
			4,640.56	3,309.50
	GRAND TOTAL		19,239.91	14,965.40

Report Ref No. CC4/ASM18016641/T1eb3s2



RECOMMENDED COST OF REPAIR SUM			10,000.00
--------------------------------	--	--	-----------

Report Ref No. CC4/ASM18016641/T1eb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.