



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18016641/T1eb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 31-05-2019



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 9870B	Veh. Inspected	SJA 2243D
Policy No.	VCC/P1917214	Coverage (\$)	0.00
Claim No.	S8M00V02	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	12/09/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA AIRWAVE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	GJ11203693	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70R14	DUNLOP	6 mm
L/H Front Tyre	185/70R14	DUNLOP	6 mm
R/H Rear Tyre	185/70R14	DUNLOP	6 mm
L/H Rear Tyre	185/70R14	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION AND ROOFTOP. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/09/2018	Inspection Date	13/09/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------