

LKK  
Catherine

**ETHOZ AUTOMOTIVE  
SOLUTIONS LTD  
22 TAMPINES STREET 92  
SINGAPORE  
528876**

**Claim Reference:**  
**Assessment Number: SHA00440**  
**Version: ETHOZASL/1**  
**Date Calculated: 11/09/2018 09:08**

**Full Report - V1**  
**Registration: SGU291H**  
**Printed: 11/09/2018 16:09**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ethoz Bukit Batok 01	Date of Incident:	04/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	TP - SBB69T	Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS
Model Sheet Number:	YCM 13
Registration:	SGU291H
Registration Month:	April
Registration Year:	2007
VIN Number:	MR053ZEC107143792
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**

FROM 01/2008	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Tanpin 974215749  
 WP' 19/9/18 @ 1040  
 R 02days  
 Resurvey after repair  
 suv@lkkauto.com

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
Brakes Pedal Travel:	Inspection:
Place of Inspection:	Date of Inspection:
Pre-Accident Damage:	11/09/2018
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

**LKK Auto Consultants hence notify the Repairer of the following:**



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**ETHOZ AUTOMOTIVE SOLUTIONS LTD**

**Claim Reference:**  
**Assessment Number: SHA00440**  
**Version: ETHOZASL/1**  
**Date Calculated: 11/09/2018 09:08**

**Full Report - V1**  
**Registration: SGU291H**  
**Printed: 11/09/2018 16:09**



**Addresses**

**Cost Summary**

Total Labour	\$216.00
Total Paint/Material	\$130.80
Total Parts	\$212.75
Excess:	TBA
Grand Total Exc GST:	\$559.55
7 % GST:	\$39.17
Grand Total Inc GST:	\$598.72

**Repair Information**

**LABOUR**

**Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR**  
**Price/Dent = \$45.00/HR**

**Repair /**

<b>Guide Number</b>	<b>Repair Details</b>	<b>WU</b>	<b>Cost Price (\$)</b>
B410	R + R REAR BUMPER	4.0	18.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.50
NO NUMBER	R + R REAR BUMPER SUPPORT	1.0	4.50

**LABOUR COST**

<b>Total Work Units</b>	<b>6.0</b>	
<b>Corrosion Protection External Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Corrosion Protection Internal Labour</b>	<b>0.0HRS</b>	<b>0.00</b>
<b>Sub Total</b>	<b>0.6HRS</b>	<b>\$27.00</b>
<b>Paint Labour</b>	<b>4.2HRS</b>	<b>\$189.00</b>
<b>Total Labour</b>	<b>4.8HRS</b>	<b>\$216.00</b>

**PAINT WORK**

**Time Basis 10 WU = 1 HR. Price = \$45.00/HR**

<b>Guide Number</b>	<b>Description</b>	<b>WU</b>	<b>Cost Price (\$)</b>
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2581	REAR BUMPER NEW PART PAINT K1R	15.0	
3482	R/R SIDE PANEL SURFACE PAINT	7.0	

**LABOUR COST - PAINT**

<b>TIME(PAINT)</b>	<b>22.0</b>	
<b>Preparation Main Work Plastic</b>	<b>15.0</b>	
<b>Preparation Comp. Work Metal</b>	<b>5.0</b>	
<b>Preparation Work Multi Layer Paint</b>	<b>0.0</b>	
<b>Total Work Units (10WU/HR)</b>	<b>42.0</b>	
<b>Total Paintwork Labour</b>	<b>4.2HRS</b>	<b>\$189.00</b>

**MATERIAL COST - PAINT**

<b>New Part Painting - Plastic K1R</b>		<b>\$75.77</b>
--	--	----------------

**ETHOZ AUTOMOTIVE SOLUTIONS LTD**

**Claim Reference:**  
**Assessment Number: SHA00440**  
**Version: ETHOZASL/1**  
**Date Calculated: 11/09/2018 09:08**

**Full Report - V1**  
**Registration: SGU291H**  
**Printed: 11/09/2018 16:09**

Surface-/Blend Paint	\$17.43
Material-Const Main Work Plastic	\$28.60
Material-Const Comp. Work Metal	\$9.00
<b>Total Excluding Pearlescent Uplift</b>	<b>\$130.80</b>
Pearlescent Uplift @ 0.0%	\$0.00
<b>Total Paint Material Cost</b>	<b>\$130.80</b>

**PARTS**

						Price Valid: 01/06/2015
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2581	1	REAR BUMPER	52159 02540		0% <i>de</i>	160.00*
2622	1	R/F BUMPER RR BRKT	52155 02120		0% <i>na</i>	10.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS		0% <i>sh</i>	15.00*
f: OEM Parts			Sub Total			\$185.00
g: Original			Mark Up From Cost	(15 %)		\$27.75
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			<b>Total Parts</b>			<b>\$212.75</b>
x: Exchange						

**NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**

Total Extras **\$0.00**

**Final Calculation**

<b>Total Parts</b>	<b>\$212.75</b>
<b>Labour</b>	
Total Panel/Mechanical	\$27.00
Total Paintwork	\$189.00
<b>Total Labour</b>	<b>\$216.00</b>
<b>Total Paint/Material Costs</b>	<b>\$130.80</b>
<b>Grand Total Excludes GST</b>	<b>\$559.55</b>
GST @ 7 %	\$39.17
<b>Grand Total Includes GST</b>	<b>\$598.72</b>

**Assessment Notes**