

ASS. REC. BY:

REF:

CS/IC618016678/11vbn2

Special Instruction:

SUPERVISOR

ASSIGNMENT (Office)

From (Person): McGowan Crystabelle Ton of ICS Date/Time: 12092018 3:13pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 7049U Insured: SJD 4016Xat Workshop m/s: Focus Auto Tel: 6886 9097.of Bik 1 Kaki Bukit Ave 6 #02-50Policy No: _____ Claim No: DMPC1800358H / CT

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11-09-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 13092018 H.O.D. Endorsement: _____Date/Time: 12092018 3:26pm Person Contacted: Ms Sin Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>PA 7049U - X</u>
	<u>SJD 4016X - X</u>

REF: TCS

ASSIGNMENT

9/10/2007

From: Date: 13052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 7049U

at Workshop m/s Focus Auto

of Bk 1 Kaki Bukit Aveb # 02-50

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 50

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 31/7/2007

Date: Person Contacted: Vehicle: IN / OUT

Veh No: PA 7049U Yr Regn: 10 / 01

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota hiace C.C. 2494

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 387792 T/Radio: Insured / Std / NI / NA

Eng/No: KDH2220035818

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15- R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 11/9/18	D.O.I. 13/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/10/18	HTA 30278 Syrs. 10ml. net 19722
	cost 16,000 with MR way (Red 17,348.87, 50%)
	RECEIVED 10 OCT 2018

Date/Time: File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time: File Return to?

2) 10/10 - typist.

Days Of Repair: 15

Resurvey No. of Trip: 4

Survey Fee:

Transportation:

S + RS: \$

Photos:

Others:

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: merimen

Lump Sum / I.B.I: (\$ 16,000)

450

10

460

Catherine Chong (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Wednesday, 12 September, 2018 3:13 PM
To: Admin-D (LKKAuto); Admin A (admin-a@lkkauto.com)
Cc: Focus Auto; ECICS Claims
Subject: RE: RE: ACCIDENT INVOLVING PA 7049 U & SJQ 4016 X ON 11/09/18 ALONG BRADDELL ROAD JUNCTION OF UPPER SERANGOON RD AT ABOUT 0630 HOUR

Dear LKK

Please refer to below email and arrange PRI.

Best regards,
Crystabelle Tan
Claims Division
DID: +65 6303 0190
FAX: +65 6338 9267
Email: crystabelle_tan@ecics.com.sg

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

From: Focus Auto [mailto:focus.autopteltd@yahoo.com.sg]
Sent: Wednesday, 12 September, 2018 12:23 PM
To: ECICS Claims
Cc: Crystabelle Tan Gek Peng (ECICS, Claims)
Subject: Re: RE: ACCIDENT INVOLVING PA 7049 U & SJQ 4016 X ON 11/09/18 ALONG BRADDELL ROAD JUNCTION OF UPPER SERANGOON RD AT ABOUT 0630 HOUR

Without Prejudice

Your Ref: DMPC1800358H/CT

Dear OIC,

Thanks for your reply

We have choose

1) LKK

Thank You

Best Regards
Laura - On Behalf Of Ms Sin

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

On Wednesday, 12 September 2018, 10:52:27 AM GMT+8, ECICS Claims <claims@ecics.com.sg> wrote:

Our ref DMPC1800358H/CT

Without Prejudice

Dear Ms Sin

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg

directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Focus Auto [mailto:focus.autopteltd@yahoo.com.sg]

Sent: Tuesday, 11 September, 2018 4:32 PM

To: ECICS Claims

Subject: ACCIDENT INVOLVING PA 7049 U & SJQ 4016 X ON 11/09/18 ALONG BRADDELL ROAD JUNCTION OF UPPER SERANGOON RD AT ABOUT 0630 HOUR

Dear Officer-In-Charge,

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 11/09/18 at about 0630 hours along BRADDELL ROAD JUNCTION OF UPPER SERANGOON RD involving our client's PA 7049 U and SJQ 4016 X driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the

vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : FOCUS AUTO PTE LTD

Address: No.1 Kaki Bukit Ave 6

AutoBay #02-50

Singapore 417883

Telephone no. : 6886 9097

Best Regards,

Ms Sin

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

☐	☐	☐
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Toyota HiacePrice RangeDepreciation> 10 year(s) ofVehicle TypeSearchAdvanced Search

Home > Used Cars > Direct Owners > Toyota Hiace Commuter (COE till 07/2027)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle

BRAND NEW FLEET AVAILABLE FOR RENT / LEASE

NISSAN NV500 \$7,200

NISSAN CARGO \$1,200

CALL: 8482 3003

EMAIL: sales@panpacleasing.com.sg

Lenovo

ThinkPad X280

September Offer

5.3% ThinkPad T Series

USE CODE SEP1

Intel Core i3

Toyota Hiace Commuter (COE till 07/2027)

OverviewFinancialAccessoriesSimilarResearchPhotosMap

DIRECT OWNER

Add to ShortlistAdd to CompareAdd a NoteReport ErrorMore ActionsShare

Car Details

Price	\$55,800
Depreciation	\$6,280 /yr
Reg Date	17-Jun-2008 (8yrs 10mths 20days COE left)
Lifespan	16-Jun-2028
Manufactured	2008
Mileage	-
Transmission	Auto
Engine Cap	2,982 cc
Curb Weight	2,160 kg
Fuel type	Diesel
Features	Toyota Hiace 13 Plus 1 Seaters High Roof, Auto Sliding Door, Aircon Vents Above Passenger's Seats, Reverse Camera And Sensors.

Accessories

DescriptionRunning Well. No Repairs Needed. Must Sell Because Upgrading.

COE	\$34,070
OMV	\$43,932
ARF	\$2,197
Deleg Value	\$30,290 as of today (change)
No. of Owners	5
Type of Veh	Bus/Mini Bus
Category	COE Car, Direct Owner Sale
Availability	Available

Add to ShortlistAdd to CompareAdd a Note

Posted on: 27-Jul-2018 | Last Updated on: 11-Sep-2018
Tags: Toyota Hiace, 2008 Toyota Hiace, Toyota, Hiace, Used Toyota

Upfront Payment

more Financial info

Transfer Fee	\$25	
Down Payment	\$5,580 (charge)	Maximum 90% Loan
1st Instalment	\$1,235	
Total Upfront Payment	\$6,840 (excluding insurance)	

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.

Items for Toyota Hiace

View All



Rearview Mirror
\$180



Modelista Front Grill
\$150



100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER



Seller Information

Contact Person(s) Darren Tan
Contact No. 83831088
Enquiry Contact Seller

USEFUL FORMS

- Indemnity form
- Receipt
- M01
- Sales agreement
- Hand-over form

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

7752D

Vehicle Details

Vehicle No.:

PA7049U

Vehicle to be Exported:

No

Intended Deregistration Date:

11 Sep 2018

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE 2.5 A

Primary Colour:

Silver

Manufacturing Year:

2007

Engine No.:

2KD1663496

Chassis No.:

KDH2220035818

Maximum Power Output:

-

Open Market Value:

\$28,996.00

Original Registration Date:

09 Oct 2007

First Registration Date:

09 Oct 2007

Transfer Count:

5

Actual ARF Paid:

\$0.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

31 Jul 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$34,070.00

COE Rebate Amount:

\$30,278.00

Total Rebate Amount:

\$30,278.00

The information contained herein is correct as at 11 Sep 2018

OK

Prima 2001
Carter

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

not Authorised
note

Reprint:1

2/5416.000
13/9/18

the photo After repair
15dy.

M/S : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

TEL: 6337-4779

FAX: 6338-9267

ATTN: Motor Claim Department

Your Ref No: PA7049U

Claim Type: Third Party

Accident Date: 11-09-2018

TP Veh Reg No: SJQ4016X

Estimate No: EST0000703

Date: 12 Sep 2018

Policy No: SD18V00762/VBS/R00

Veh Reg No: PA7049U

Make/Model: TOYOTA HIACE 2.5A

Chassis No: KDH2220035818

Engine No: 2KD1663496

Reg. Date: 09-10-2007

Estimate Repair Cost for Vehicle No :PA7049U

PAGE:1/3

Description	U/Price	Quantity	List Price SS	Amount SS
TOYOTA HIACE 2.5 A				
List Price				
1 Front Grille	651.9000	1 PC	651.90	α
2 Front Head Lamp LH	655.8000	1 PC	655.80	—
3 Front Bumper	751.6000	1 PC	751.60	—
4 Front Bumper Side Bracket	155.6000	1 PC	155.60	—
5 Front Bumper Lower Reinforcement	412.6000	1 PC	412.60	α
6 Front Bumper Clipse	5.5000	6 PC	33.00	—
7 Front Step Panel Garnish LH & RH	155.8000	2 PC	311.60	α
8 Front Wheel Ace Panel LH	681.6000	1 PC	681.60	—
9 Front Wheel Housing LH	684.2000	1 PC	684.20	α
10 Front Wheel Ace Panel Rubber LH	90.4000	1 PC	90.40	—
11 Front Door LH	1,795.0000	1 PC	1,795.00	—
12 Front Door Lock LH	550.0000	1 PC	550.00	—
13 Front Door Inner Cover Board LH	756.6000	1 PC	756.60	—
14 Front Door Weather Strip LH	191.6000	1 PC	191.60	—
15 Front Wheel Ace Panel Inner Garnish LH	298.2000	1 PC	298.20	—
16 Front Door Frame Seal LH	356.4000	1 PC	356.40	α
17 RH Centre Panel Outer LH	691.5000	1 PC	691.50	—
18 RH Centre Panel Inner LH	619.6000	1 PC	619.60	—
19 Front Seat Belt LH	586.2000	1 PC	586.20	α
20 Front Centre Panel Inner Garnish LH	367.4000	1 PC	367.40	—
21 Front Door Hinges (Top & Lower) LH	155.6000	2 PC	311.20	—
22 Front Step Panel Inner Garnish	196.9000	2 PC	393.80	α
23 Front Step Panel Garnish Clipse	5.5000	4 PCS	22.00	α
24 Front Door Lower Rubber LH	101.9000	1 PC	101.90	α
25 LH Side Door	2,365.2000	1 PC	2,365.20	—
26 LH Side Door Lock	855.9000	1 PC	855.90	—
27 LH Side Door Lock Centre Roller	296.9000	1 PC	296.90	α
28 LH Side Door Lock Lower Roller	198.5000	1 PC	198.50	—
29 LH Side Door Weather Strip	296.9000	1 PC	296.90	—
30 LH Side Door Frame Rubber	392.2000	1 PC	392.20	α
31 LH Side Step Panel	346.2000	1 PC	346.20	α
32 LH Side Step Panel Inner Garnish	489.2000	1 PC	489.20	—
33 LH Side Door Inner Lock Motor	896.9000	1 PC	896.90	α

1695.00
350.10

653.10

17607-6

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

TEL: 6337-4779 FAX: 6338-9267

ATTN: Motor Claim Department

Your Ref No: PA7049U

Claim Type: Third Party

Accident Date: 11-09-2018

TP Veh Reg No: SJQ4016X

Estimate No: EST0000703

Date: 12 Sep 2018

Policy No: SD18V00762/VBS/R00

Veh Reg No: **PA7049U**

Make/Model: TOYOTA HIACE 2.5A

Chassis No: KDH2220035818

Engine No: 2KD1663496

Reg. Date: 09-10-2007

Estimate Repair Cost for Vehicle No :PA7049U

PAGE:2/3

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
34 Front Aircon Condenser <i>1920.30</i>	1,530.900	1 PC <i>Per</i>	1,530.90 ✓	
35 Front Air Cleaner Box	886.6000	1 PC <i>CM</i>	886.60 ✓	
36 Front Radiator	1,985.600	1 PC <i>11</i>	1,985.60 X	
37 Front Radiator Lower Member	695.9000	1 PC <i>3rd</i>	695.90 ✓	
38 Front Rim	356.4000	2 PC <i>100/15</i>	712.80 <i>120 505 ✓</i>	
39 Front Rim Cap	191.6000	2 PC <i>m-3</i>	383.20 ✓	
40 Front Aircon Condenser Side Garnish LH	161.8000	1 PC <i>11</i>	161.80 X	
41 Front Upper Arm LH <i>645.10</i>	896.9000	1 PC <i>3rd</i>	896.90 ✓	
42 Front Shock Absorber LH	261.9000	1 PC <i>11</i>	261.90 ✓	
43 Front Rod Link LH	169.6000	1 PC <i>11</i>	169.60 ✓	
44 Front Stabilizer Bar LH	519.8000	1 PC <i>11</i>	519.80 X	
45 Front Step Bar LH	286.9000	1 PC <i>3rd</i>	286.90 ✓	
46 Front Knuckle Arm LH	481.6000	1 PC <i>3rd</i>	481.60 ✓	
47 Front Lower Arm LH	366.7000	1 PC <i>11</i>	366.70 ✓	
48 Front Hub Bearing LH	558.6000	1 PC <i>11</i>	558.60 ✓	
49 Front Brake Hose LH	226.2000	1 PC <i>11</i>	226.20 X	
50 Front A.B.S Sensor LH	346.4000	1 PC <i>11</i>	346.40 X	
51 Front Engine Crossmember	3,198.500	1 PC <i>3rd</i>	3,198.50 X	
52 Front Steering Rack & Pinion <i>2845.10</i>	3,598.500	1 PC <i>3rd</i>	3,598.50 ✓	
53 Front Steering Ball Joint LH	101.6000	1 PC <i>11</i>	101.60 X	
54 Front Steering Tie Rod End LH	156.9000	1 PC <i>3rd</i>	156.90 ✓	
55 Front Lower Arm Ball Joint LH	178.6000	1 PC <i>11</i>	178.60 ✓	
56 Front Fuel Tank Pipe	246.5000	1 PC <i>3rd</i>	246.50 ✓	
57 Front Fuel Tank Cover	101.9000	1 PC <i>11</i>	101.90 X	
58 Front Fuel Tank Cover Inner Panel	150.2000	1 PC <i>11</i>	150.20 X	
			35,811.70	
		Less 25%	8,952.93	26,858.87

Special Net

59 Front Number Plate	40.0000	1 PC <i>3rd</i>	40.00 <i>15</i>	
60 LH Side Door Sticker	30.0000	1 PC <i>11</i>	30.00 ✓	
61 LH Side Door Glass Gum	60.0000	1 PC <i>11</i>	60.00 <i>40</i>	
62 LH Side Step Panel Top Aluminium Plate	450.0000	1 PC <i>11</i>	450.00 X	
63 Front Tyre LH <i>12200</i>	280.0000	1 PC <i>CU 2</i>	280.00 <i>602 120</i>	
			860.00	860.00

2855 S. Net

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

TEL: 6337-4779 FAX: 6338-9267

ATTN: Motor Claim Department

Your Ref No: PA7049U

Claim Type: Third Party

Accident Date: 11-09-2018

TP Veh Reg No: SJQ4016X

Estimate No: EST0000703

Date: 12 Sep 2018

Policy No: SD18V00762/VBS/R00

Veh Reg No: **PA7049U**

Make/Model: TOYOTA HIACE 2.5A

Chassis No: KDH2220035818

Engine No: 2KD1663496

Reg. Date: 09-10-2007

Estimate Repair Cost for Vehicle No :PA7049U

PAGE:3/3

Description	U/Price	Quantity	List Price SS	Amount SS
Labour				
64 Towing	80.0000	1 PC	80.00 ⁶⁰	
65 Panel Beating	2,800.000	1 PC	2,800.00 ¹⁸⁰⁰	
66 Check Wiring	100.0000	1 PC	100.00 ³⁰	
67 To Remove & Replace Radiator	120.0000	1 PC	120.00 ³¹⁰⁰	
68 To Remove & Replace Aircon Condensor And Charge Gas	160.0000	1 PC	160.00 ³⁸⁰	
69 To Remove & Replace Under Carriage	520.0000	1 PC	520.00 ⁶⁰	
70 To Adjust Alignment	50.0000	1 PC	50.00 ⁶⁰	
71 To Remove & Replace front Side Door Assy	160.0000	1 PC	160.00 ⁶⁰	
72 To Remove & Refit Front Seat & Upholstery	160.0000	1 PC	160.00 ⁶⁰	
73 To Remove & Refit LH Side Door Glass	80.0000	1 PC	80.00 ¹²⁰⁰	
74 To Spray Painting	1,400.000	1 PC	1,400.00 ¹²⁰⁰	
			5,630.00	5,630.00
			Total	SS 33,348.87 ¹⁷

TOTAL: SINGAPORE DOLLAR THIRTY THREE THOUSAND THREE HUNDRED FORTY EIGHT AND CENTS EIGHTY SEVEN ONLY

For FOCUS AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No further modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18016678/UVBN2

Date: 16/10/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	PA7049U	Insured Vehicle No :	SJQ4016X
Date of Loss:	11/09/2018	Nature of Claim:	TP
		Claim No:	DMPC1800358H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA7049U	Engine No:	2KD1663496
Make & Model:	TOYOTA HIACE, 2.5 (A)	Chassis No:	KDH2220035818
Reg. Date:	09/10/2007 (Man. Year: 2007)	Odometer:	387792 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,718.77	16,183.20	11,535.57	41.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,630.00	3,820.00	1,810.00	32.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,348.77	20,003.20	13,345.57	40.02
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	33,348.77	16,000.00	17,348.77	52.02
+ GST 7.00/7.00% (S\$)	2,334.41	1,120.00	1,214.41	52.02
Nett Amount (S\$)	35,683.18	17,120.00	18,563.18	52.02

INSPECTION

Date of Assignment:	12/09/2018	
Date Inspected:	13/09/2018 Inspected At:	Focus Auto Pte Ltd (Kaki Bukit) NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-50 Singapore 417883
Estimated Period of Repair:	15.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Oct 2018)	
Parts:	N/A	TOYOTA HIACE 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA7049U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Repair	651.90 FL	*- FL
2	1		*FRONT HEAD LAMP LH	Cracked	655.80 FL	*655.80 FL
3	1		*FRONT BUMPER	Distorted	751.60 FL	*751.60 FL
4	1		*FRONT BUMPER SIDE BRACKET	Cracked	155.60 FL	*155.60 FL
5	1		*FRONT BUMPER LOWER REINFORCEMENT	Repair	412.60 FL	*- FL
6	6		*FRONT BUMPER CLIPSE	Necessary	33.00 FL	*33.00 FL
7	2		*FRONT STEP PANEL GARNISH LH & RH	Not Necessary	311.60 FL	*- FL
8	1		*FRONT WHEEL ACE PANEL LH	Badly Dented	681.60 FL	*681.60 FL
9	1		*FRONT WHEEL HOUSING LH	Repair	684.20 FL	*- FL
10	1		*FRONT WHEEL ACE PANEL RUBBER LH	Torn	90.40 FL	*90.40 FL
11	1		*FRONT DOOR LH	Distorted	1,795.00 FL	*1,695.00 FL
12	1		*FRONT DOOR LOCK LH	Twisted/Jammed	550.00 FL	*350.10 FL
13	1		*FRONT DOOR INNER COVER BOARD LH	Deformed/Cracked	756.60 FL	*756.60 FL
14	1		*FRONT DOOR WEATHER STRIP LH	Torn	191.60 FL	*191.60 FL
15	1		*FRONT WHEEL ACE PANEL INNER GARNISH LH	Torn	298.20 FL	*298.20 FL
16	1		*FRONT DOOR FRAME SEAL LH	Not Necessary	356.40 FL	*- FL
17	1		*RH CENTRE PANEL OUTER LH	Badly Dented	691.50 FL	*691.50 FL
18	1		*RH CENTRE PANEL INNER LH	Badly Dented	619.60 FL	*619.60 FL
19	1		*FRONT SEAT BELT LH	Not Necessary	586.20 FL	*- FL
20	1		*FRONT CENTRE PANEL INNER GARNISH LH	Broken	367.40 FL	*367.40 FL
21	2		*FRONT DOOR HINGES (TOP & LOWER) LH	Bent	311.20 FL	*311.20 FL
22	2		*FRONT STEP PANEL INNER GARNISH	Not Necessary	393.80 FL	*- FL
23	4		*FRONT STEP PANEL GARNISH CLIPSE	Not Necessary	22.00 FL	*- FL
24	1		*FRONT DOOR LOWER RUBBER LH	No such part	101.90 FL	*- FL
25	1		*LH SIDE DOOR	Badly Dented	2,365.20 FL	*2,365.20 FL
26	1		*LH SIDE DOOR LOCK	Twisted/Shorted	855.90 FL	*655.10 FL
27	1		*LH SIDE DOOR LOCK CENTRE ROLLER	Not Necessary	296.90 FL	*- FL
28	1		*LH SIDE DOOR LOCK LOWER ROLLER	Twisted	198.50 FL	*198.50 FL
29	1		*LH SIDE DOOR WEATHER STRIP	Torn	296.90 FL	*296.90 FL
30	1		*LH SIDE DOOR FRAME RUBBER	Not Necessary	392.20 FL	*- FL
31	1		*LH SIDE STEP PANEL	Repair	346.20 FL	*- FL
32	1		*LH SIDE STEP PANEL INNER GARNISH	Twisted	489.20 FL	*489.20 FL
33	1		*LH SIDE DOOR INNER LOCK MOTOR	Not Necessary	896.90 FL	*- FL
34	1		*FRONT AIRCON CONDENSER	Punctured	1,530.90 FL	*1,420.30 FL
35	1		*FRONT AIR CLEANER BOX	Cracked	886.60 FL	*886.60 FL
36	1		*FRONT RADIATOR	Not Necessary	1,985.60 FL	*- FL
37	1		*FRONT RADIATOR LOWER MEMBER	Bent	695.90 FL	*695.90 FL
38	2		*FRONT RIM CAP	Missing	383.20 FL	*383.20 FL
39	1		*FRONT AIRCON CONDENSER SIDE GARNISH LH	Not Necessary	161.80 FL	*- FL
40	1		*FRONT UPPER ARM LH	Bent	896.90 FL	*645.10 FL
41	1		*FRONT SHOCK ABSORBER LH	Twisted	261.90 FL	*261.90 FL
42	1		*FRONT ROD LINK LH	Twisted	169.60 FL	*169.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT STABILIZER BAR LH	Not Necessary	519.80 FL	*- FL
44	1		*FRONT STEP BAR LH	Bent	286.90 FL	*286.90 FL
45	1		*FRONT KNUCKLE ARM LH	Bent	481.60 FL	*481.60 FL
46	1		*FRONT LOWER ARM LH	Twisted	366.70 FL	*366.70 FL
47	1		*FRONT HUB BEARING LH	Damaged	558.60 FL	*558.60 FL
48	1		*FRONT BRAKE HOSE LH	Not Necessary	226.20 FL	*- FL
49	1		*FRONT ABS SENSOR LH	Not Necessary	346.40 FL	*- FL
50	1		*FRONT ENGINE CROSSMEMBER	Serviceable	3,198.50 FL	*- FL
51	1		*FRONT STEERING RACK & PINION	Bent/Jammed	3,598.50 FL	*2,845.10 FL
52	1		*FRONT STEERING BALL JOINT LH	No such part	101.60 FL	*- FL
53	1		*FRONT STEERING TIE ROD END LH	Bent	156.90 FL	*156.90 FL
54	1		*FRONT LOWER ARM BALL JOINT LH	Twisted	178.60 FL	*178.60 FL
55	1		*FRONT FUEL TANK PIPE	Bent	246.50 FL	*246.50 FL
56	1		*FRONT FUEL TANK COVER	Repair	101.90 FL	*- FL
57	1		*FRONT FUEL TANK COVER INNER PANEL	Repair	150.20 FL	*- FL
58	2		*FRONT RIM	N/s Dented	534.60 FS	*50.00 FS
59	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*15.00 FS
60	1		*LH SIDE DOOR STICKER	Necessary	30.00 FS	*30.00 FS
61	1		*LH SIDE DOOR GLASS GUM	Necessary	60.00 FS	*40.00 FS
62	1		*LH SIDE STEP PANEL TOP ALUMINIUM PLATE	Not Necessary	450.00 FS	*- FS
63	1		*FRONT TYRE LH (LOCAL PURCHASE)(\$200.00) (60%)	Cut	280.00 FS	*120.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	36,493.50	21,492.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	8,774.73	5,309.40
Total Parts (\$\$)	27,718.77	16,183.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	80.00	60.00
2	PANEL BEATING	New	2,800.00	1,800.00
3	CHECK WIRING	New	100.00	30.00
4	TO REMOVE & REPLACE RADIATOR }	New	120.00	100.00
5	TO REMOVE & REPLACE AIRCON CONDENSOR AND CHARGE GAS }	New	160.00	-
6	TO REMOVE & REPLACE UNDER CARRIAGE	New	520.00	380.00
7	TO ADJUST ALIGNMENT	New	50.00	50.00
8	TO REMOVE & REPLACE FRONT SIDE DOOR ASSY	New	160.00	60.00
9	TO REMOVE & REFIT FRONT SEAT & UPHOLSTERY	New	160.00	60.00
10	TO REMOVE & REFIT LH SIDE DOOR GLASS	New	80.00	80.00
11	TO SPRAY PAINTING	New	1,400.00	1,200.00
Gross Labour Cost (S\$)			5,630.00	3,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >