

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*Front Headlamp Bulb RH X	X 0.00	0.00	27	- BURST
47	1		*Front Headlamp Top Bracket LH	0.00	0.00	255	- /CR
48	1		*Front Headlamp Top Bracket RH X✓	✓ 0.00	0.00	255	- /CR
49	1		*Front Grille	500 0.00	0.00	1180	- /CR
50	1		*Front Grille Badge	0.00	0.00	245	- /MC
51	1		*Front Grille Chrome Moulding LH	0.00	0.00	75	- /CR
52	1		*Front Grille Chrome Moulding RH	0.00	0.00	75	- /CR
53	1		*Front Wheelhouse LH	0.00	0.00	1452	- /R
54	1		*Front Bonnet Lock Bracket Center	200 0.00	0.00	475	- /BT
55	1		*Front Windscreen Moulding LH	0.00	0.00	64.52	- /BT
56	1		*Front Windscreen Moulding RH	0.00	0.00	64.50	- /BT
57	1		*Front Horn LH	0.00	0.00	212	- /DD
58	1		*Front Horn RH X	X 0.00	0.00	212	- /DD
59	1		*Front Grille Housing - ?	X 0.00	0.00	375.10	- /CR
60	1		*Front Engine Mounting RH = photo? ✓	✓ 0.00	0.00	86.50	- /SUL
61	1		*Air Cond Pipe To Cooling Coil Bracket	0.00	0.00	95.52	- /BT
62	1		*Engine Oil Cap	0.00	0.00	75	- /MC
63	1		*Air Cleaner Box	0.00	0.00	326	- /CR
64	1		*Exhaust Manifold - photo? X 1000	0.00	0.00	2535	- /CRK
65	1		*Air Cond Condenser Pipe To Cooling Coil	0.00	0.00	215.30	- /BT
66	1		*Air Cond Condenser Pipe To Condenser	0.00	0.00	210.70	- /BT
67	1		*Air Cleaner House 1405	0.00	0.00	120	- /SUL
68	1		*Air Cleaner Front	600 0.00	0.00	386	- /CR
69	1		*Radiator	600 0.00	0.00	1280	- /BT
70	1		*Radiator Panel	700 0.00	0.00	1850.30	- /CR
71	1		*Radiator Fan	650 0.00	0.00	1595	- /CR
72	1		*Radiator Fan Guard	0.00	0.00	480	- /CR
73	1		*Radiator Fan Motor	0.00	0.00	128	- /NEC
74	1		*Air Cond Condenser	800 0.00	0.00	1909	- /BT
75	1		*Gear Box Oil Cooler	500 0.00	0.00	1280	- /BT
76	1		*Exhaust Manifold Front Cover	400 0.00	0.00	1183	- /BT
77	1		*Headlamp Rear Cap LH	0.00	0.00	75	- /NEC
78	1		*Headlamp Rear Cap RH	0.00	0.00	75	- /NEC
79	1		*Front Member	0.00	0.00	315.40	- /BT
80	1		*Steering Column Button X	0.00	0.00	224	- /MC
81	1		*Front Alternator	1784 1500 0.00	0.00	3220	- /CR
82	1		*Front Thermostat	0.00	0.00	123	- /SUL
83	1		*Front Gear Box Wiring Outer Cover	0.00	0.00	275.40	- /MC
84	1		*Front Bonnet Lock Cable	0.00	0.00	172	- /SUL
85	1		*Total Body Throttle X✓	1100 700 0.00	0.00	1750.30	- /CR
Total Parts (S\$)						52,960.65	0.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

86	1		* Air Sensor			218.50	? /not with
87	1		* Air Sensor Bracket			315.10	? /def.
88	1		* Wiper Grille			375.00	? /CRK

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Air Cond Compressor Oil	50.00 20
2	1	Air-cond gas (Normal)	150.00 20
3	1	Check alignment	50.00 /
4	1	Check Balancing	50.00 / 30
5	1	Electrical (check & diagnose)	150.00 50
6	1	Number plate, front	80.00 40
7	1	Painting Materials	400.00 100
8	1	Radiator coolant	40 70.00 / ne
9	1	Underseal materials	100.00 60
10	1	Number plate stay	80 430 NE.
Sub Total (\$\$)			1,080.00

1160

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Remove & Refix Air Bag, Cable, Module & Sensor	New	180.00 50
2	Spray Painting on Front Bonnet, Fender LH & RH, Bumper, Wheelhouse LH, Front Panel	New	800.00 /
3	To Knock, Welding, Cut and Hydraulically Jack & Align Chasis Frame Front Wheel House	New	1,000.00 800
4	To Remove & Refix All Accident Parts	New	600 1,200.00 800
5	To remove & replace engine		700 3x NN
Gross Labour Cost (\$\$)			3,880 3,180.00

high.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA 2 LKK
18/9/18 1530
L/S
10-12 days
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chai Motor Workshop Sdn Bhd (Co.Reg.No:599246-K)No 3, Jalan Bertam 8, Taman Daya,
81100 Johor Bahru, Johor Darul Takzim

Tel: +607 3556862 Fax: +607 3547335 Email: chaimotorwks@yahoo.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	55560918-OD
Policy No:	DMPCSN3078531701	Date of Loss:	30/08/2018
Vehicle Reg. No.:	SLE1493K	Driveable?	YES
Driver Age/Info:	26 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SE KIAH LEE		
Driver:	TAY XIANG WEN EUGENE		

Make/Model:	VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A)	Vehicle Reg. Date:	25/04/2014
Vehicle Colour:	WHITE	Gen Condition:	GOOD
Engine No:	CXS083273	Chassis No:	WVWZZZAUZEW318060
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss	COLLISION- HEAD TO REAR (INSURED HIT TP)
Present Location:	CHAI MOTOR WORKSHOP SDN BHD (HQ)

COST OF CLAIMS	Amount
Parts	52,960.65
Miscellaneous Items	1,160.00
Labour	3,880.00
Paintwork Labour	0.00
Towing	300.00
Nett Amount (S\$)	58,300.65

This claim is handled by: SOO WUN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Chai Motor Workshop Sdn Bhd (Co.Reg.No:599246-K)

No 3, Jalan Bertam 8, Taman Daya,
81100 Johor Bahru, Johor Darul Takzim
Tel: +607 3556862 Fax: +607 3547335 Email: chaimotorwks@yahoo.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	55560918-OD
Policy No:	DMPCSN3078531701	Date of Loss:	30/08/2018
Vehicle Reg. No.:	SLE1493K	Driveable?	YES
Driver Age/Info:	26 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SE KIAH LEE		
Driver:	TAY XIANG WEN EUGENE		
Make/Model:	VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A)	Vehicle Reg. Date:	25/04/2014
Vehicle Colour:	WHITE	Gen Condition:	GOOD
Engine No:	CXS083273	Chassis No:	WVWZZZAUZEW318060
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	COLLISION- HEAD TO REAR (INSURED HIT TP)		
Present Location:	CHAI MOTOR WORKSHOP SDN BHD (HQ)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	52,960.65 0.00
Labour	1,160.00 1,080.00
Paintwork Labour	3,880.00 3,180.00
Towing	0.00
	300.00
Nett Amount (S\$)	4,560.00

This claim is handled by: SOO WUN HUA

58,300.65

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 19 Sep 2018)**Parts:** 144 **VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Chai Motor Workshop Sdn Bhd/SLE1493K/19/09/2018 16:31**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*Front Airbag Steering RH	1511.66	0.00	0.00	ACT *6,142.00 F	✓
2	1		*Front Airbag Dashboard LH	1300	0.00	0.00	ACT *2,430.00 F	✓
3	1		*Front Airbag ECU	896.15	0.00	0.00	NEC *2,650.00 F	✓
4	1		*Front Airbag Sensor LH		0.00	0.00	NEC *525.00 F	✓
5	1		*Front Airbag Sensor RH		0.00	0.00	NEC *525.00 F	✓
6	1		*Front Seatbelt LH		0.00	0.00	Jm *475.00 F	✓
7	1		*Front Seatbelt RH		0.00	0.00	Jm *475.00 F	✓
8	1		*Front Steering Spare Cable RH		0.00	0.00	NN *260.00 F	X
9	1		*Front Wiper Tank		0.00	0.00	NN *295.00 F	X
10	1		*Front Wiper Tank Motor Front		0.00	0.00	NN *76.50 F	X
11	1		*Front Wiper Tank Motor Rear		0.00	0.00	NN *90.50 F	X
12	1		*Front Wiper Tank Top Hose		0.00	0.00	MIS *89.70 F	✓
13	1		*Front Harness Wiring	450	0.00	0.00	MIS *785.10 F	✓
14	1		*Front Fuel Box Lower Housing LH		0.00	0.00	BT *314.50 F	✓
15	1		*Front Bonnet	1000	0.00	0.00	DD *2,200.00 F	✓
16	1		*Front Bonnet Hinge LH		0.00	0.00	BT *157.00 F	✓
17	1		*Front Bonnet Hinge RH		0.00	0.00	BT *157.00 F	✓
18	1		*Front Bonnet Lock	200	0.00	0.00	BT *475.00 F	✓
19	1		*Front Bonnet Inner Trim	250	0.00	0.00	TN *550.00 F	✓
20	1		*Front Fender LH	700	0.00	0.00	DD *1,110.00 F	✓
21	1		*Front Fender RH	700	0.00	0.00	DD *1,260.00 F	✓
22	1		*Front Fender Inner Trim LH		0.00	0.00	CRA *255.00 F	✓
23	1		*Front Fender Inner Trim RH		0.00	0.00	CRA *255.00 F	✓
24	1		*Front Fender Inner Trim Rear LH		0.00	0.00	NN *214.00 F	X
25	1		*Front Fender Inner Trim Rear RH		0.00	0.00	NN *214.00 F	X
26	1		*Front Bumper		0.00	0.00	CRA *580.00 F	✓
27	1		*Front Bumper Side Bracket LH		0.00	0.00	CRA *44.00 F	✓
28	1		*Front Bumper Side Bracket RH		0.00	0.00	CRA *44.00 F	✓
29	1		*Front Bumper Fog Lamp LH		0.00	0.00	MIS *62.50 F	✓
30	1		*Front Bumper Fog Lamp RH		0.00	0.00	CRA *62.50 F	✓
31	1		*Front Bumper Fog Lamp Bracket LH		0.00	0.00	MIS *190.00 F	✓
32	1		*Front Bumper Fog Lamp Bracket RH		0.00	0.00	CRA *190.00 F	✓
33	1		*Front Bumper Towing Cover		0.00	0.00	MIS *92.00 F	✓
34	1		*Front Bumper Lower Grille		0.00	0.00	CRA *280.00 F	✓
35	1		*Front Bumper Fog Lamp Lower Moulding LH		0.00	0.00	MIS *242.00 F	✓
36	1		*Front Bumper Fog Lamp Lower Moulding RH		0.00	0.00	CRA *242.00 F	✓
37	1		*Front Bumper Lower Garnish		0.00	0.00	CRA *295.00 F	✓
38	1		*Front Bumper Bracket Bin	400	0.00	0.00	CRA *785.15 F	✓
39	1		*Front Bumper Air Guard LH		0.00	0.00	CRA *77.50 F	✓
40	1		*Front Bumper Air Guard RH		0.00	0.00	CRA *77.50 F	✓
41	1		*Front Bumper Bracket Top Garnish		0.00	0.00	CRA *295.00 F	✓
42	1		*Front Bumper Sponge		0.00	0.00	MIS *285.10 F	✓
43	1		*Front Headlamp LH		0.00	0.00	CRA *255.00 F	✓
44	1		*Front Headlamp RH		0.00	0.00	CRA *255.00 F	✓

Chai Motor Workshop Sdn Bhd/SLE1493K/19/09/2018 16:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*Front Headlamp Bulb LH	0.00	0.00	SVC *27.00 F X
46	1		*Front Headlamp Bulb RH	0.00	0.00	SVC *27.00 F X
47	1		*Front Headlamp Top Bracket LH	0.00	0.00	CRA *255.00 F ✓
48	1		*Front Headlamp Top Bracket RH	0.00	0.00	CRA *255.00 F ✓
49	1		*Front Grille	500	0.00	CRA *1,180.00 F ✓
50	1		*Front Grille Badge	0.00	0.00	NEL *245.00 F ✓
51	1		*Front Grille Chrome Moulding LH	0.00	0.00	CRA *75.00 F ✓
52	1		*Front Grille Chrome Moulding RH	0.00	0.00	CRA *75.00 F ✓
53	1		*Front Wheelhouse LH	0.00	0.00	R *1,458.00 F X
54	1		*Front Bonnet Lock Bracket Center	200	0.00	BT *475.00 F ✓
55	1		*Front Windscreen Moulding LH	0.00	0.00	BT *64.50 F ✓
56	1		*Front Windscreen Moulding RH	0.00	0.00	BT *64.50 F ✓
57	1		*Front Horn LH	0.00	0.00	DD *218.00 F ✓
58	1		*Front Horn RH	0.00	0.00	SVC *218.00 F X
59	1		*Front Grille Housing	0.00	0.00	SVC *375.10 F X
60	1		*Front Engine Mounting RH	0.00	0.00	NEL *86.50 F ✓
61	1		*Air Cond Pipe To Cooling Coil Bracket	0.00	0.00	BT *95.50 F ✓
62	1		*Engine Oil Cap	0.00	0.00	MIS *75.00 F ✓
63	1		*Air Cleaner Box	0.00	0.00	CRA *386.00 F ✓
64	1		*Exhaust Manifold	0.00	0.00	SVC *2,535.00 F X
65	1		*Air Cond Condenser Pipe To Cooling Coil	0.00	0.00	BT *215.30 F ✓
66	1		*Air Cond Condenser Pipe To Condenser	0.00	0.00	BT *210.70 F ✓
67	1		*Air Cleaner House	0.00	0.00	SVC *120.00 F X
68	1		*Air Cleaner Front	0.00	0.00	CRA *386.00 F ✓
69	1		*Radiator	600	0.00	BT *1,280.00 F ✓
70	1		*Radiator Panel	700	0.00	CRA *1,850.30 F ✓
71	1		*Radiator Fan	650	0.00	CRA *1,595.00 F ✓
72	1		*Radiator Fan Guard	0.00	0.00	CRA *480.00 F ✓
73	1		*Radiator Fan Motor	0.00	0.00	Deform *128.00 F ✓
74	1		*Air Cond Condenser	800	0.00	BT *1,909.00 F ✓
75	1		*Gear Box Oil Cooler	500	0.00	BT *1,280.00 F ✓
76	1		*Exhaust Manifold Front Cover	400	0.00	BT *1,183.00 F ✓
77	1		*Headlamp Rear Cap LH	0.00	0.00	NEL *75.00 F ✓
78	1		*Headlamp Rear Cap RH	0.00	0.00	NEL *75.00 F ✓
79	1		*Front Member	0.00	0.00	BT *315.40 F ✓
80	1		*Steering Column Button	0.00	0.00	MIS *224.00 F ✓
81	1		*Front Alternator	1784	0.00	CRA *3,880.00 F ✓
82	1		*Front Thermostat	0.00	0.00	SVC *123.00 F X
83	1		*Front Gear Box Wiring Outer Cover	0.00	0.00	MIS *275.40 F ✓
84	1		*Front Bonnet Lock Cable	0.00	0.00	SVC *172.00 F X
85	1		*Total Body	1100	0.00	CRA *1,750.30 F ✓
86	1		*Air sensor	0.00	0.00	NW *218.50 F ✓
87	1		*Air sensor bracket	0.00	0.00	Deform *315.10 F ✓
88	1		*Wiper Grille	0.00	0.00	CRA *375.00 F ✓

F=Franchise part.

Total Parts (\$\$)

52,960.65

Chai Motor Workshop Sdn Bhd/SLE1493K/19/09/2018 16:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Air Cond Compressor Oil	NEC 50.00 20
2	1	Air-cond gas (Normal)	150.00 20
3	1	Check alignment	50.00 ✓
4	1	Check Balancing	50.00 30
5	1	Electrical (check & diagnose)	150.00 50
6	1	Number Plate Stay	NEC 80.00 30
7	1	Number plate, front	DD 60.00 40
8	1	Painting Materials	NEC 400.00 100
9	1	Radiator coolant	NEC 70.00 40
10	1	Underseal materials	100.00 60
Sub Total (S\$)			1,160.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Remove & Refix Air Bag, Cable, Module & Sensor	New	180.00 50
2	Spray Painting on Front Bonnet, Fender LH & RH , Bumper, Wheelhouse LH, Front Panel	New	800.00 ✓
3	To Knock, Welding, Cut and Hydraulically Jack & Align Chasis Frame Front Wheel House	New	1,000.00 800
4	To Remove & Refix All Accident Parts	New	1,200.00 600
5	To Remove & Replace Engine	New	NN 700.00 X
Gross Labour Cost (S\$)			3,880.00

Chai Motor Workshop Sdn Bhd/SLE1493K/19/09/2018 16:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Sep 2018 Sendback Est	19 Sep 2018 16:31 S\$58,300.65	13 Sep 2018 10:35 Edit Adj Rpt	S\$20,000.00 Edit Estimates	S\$20,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SE KIAH LEE, ID: S9209740D, Email: chaimotorwks@yahoo.com		
Vehicle Reg. No.:	SLE1493K	Date of Loss:	30/08/2018 15:00 - :59 [52 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D04274C01	Policy/Cover Note No.:	DMPCSN3078531701 (Comprehensive) Coverage: 25/10/2017 - 24/10/2018
		Excess:	S\$1,000.00
Repairer:	Chai Motor Workshop Sdn Bhd (HQ) No 3, Jalan Bertam 8, Taman Daya,, 81100 Johor Bahru - Tel: +607 3556862		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 24/09/2018]		
Driver/Custodian:	TAY XIANG WEN EUGENE (26 / Male), NRIC: S9209740D		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT. EXCESS OF \$1,000.00 APPLIES. HOWEVER IF CTL, EXCESS WILL BE \$2,000.00. PART PRICING IS STILL NOT READY.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPIING (25/09/2018): Alert - Adj Mandate Approved (S\$35000.00) - SLE1493K - Claim Handler: Jowyn Tay

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLE1493K (SNM18D04274C01)

OD

Aug 30 2018 3:00PM

[SE KIAH LEE]

Chai Motor Workshop Sdn Bhd

Upload Documents Upload Photos Compose New Letter

View View In Browser ▼

Assessment Reports

No	Finalized On	Chai Motor Workshop Sdn Bhd (HQ)	1 per page ▼	Thumbnail	Print
1	19/09/18 16:31	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/09/18 16:12	Adjuster Immediate Advice	1	Load HTM	
2	25/09/18 09:18	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

No	Finalized On	Chai Motor Workshop Sdn Bhd (HQ)	3 per page ▼	Thumbnail	Print
1	12/09/18 10:52	Photos - Before	1	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/09/18 16:09	General View	1	Load JPG	✓
2	20/09/18 16:09	General View	1	Load JPG	✓
3	20/09/18 16:09	General View	1	Load JPG	✓
4	20/09/18 16:09	General View	1	Load JPG	✓
5	20/09/18 16:09	General View	1	Load JPG	✓
6	20/09/18 16:09	General View	1	Load JPG	✓
7	20/09/18 16:09	General View	1	Load JPG	✓
8	20/09/18 16:09	General View	1	Load JPG	✓
9	20/09/18 16:09	General View	1	Load JPG	✓
10	20/09/18 16:09	General View	1	Load JPG	✓
11	20/09/18 16:09	General View	1	Load JPG	✓
12	20/09/18 16:09	General View	1	Load JPG	✓
13	20/09/18 16:09	General View	1	Load JPG	✓
14	20/09/18 16:09	General View	1	Load JPG	✓
15	20/09/18 16:09	Odometer Reading	1	Load JPG	✓
16	20/09/18 16:09	Chassis Number	1	Load JPG	✓
17	20/09/18 16:09	General View	1	Load JPG	✓
18	20/09/18 16:09	General View	1	Load JPG	✓
19	20/09/18 16:09	General View	1	Load JPG	✓
20	20/09/18 16:09	General View	1	Load JPG	✓
21	20/09/18 16:09	General View	1	Load JPG	✓
22	20/09/18 16:09	General View	1	Load JPG	✓
23	20/09/18 16:09	General View	1	Load JPG	✓
24	20/09/18 16:09	General View	1	Load JPG	✓
25	20/09/18 16:09	General View	1	Load JPG	✓
26	20/09/18 16:09	General View	1	Load JPG	✓
27	20/09/18 16:09	General View	1	Load JPG	✓
28	20/09/18 16:11	Dismantled Parts	1	Load JPG	✓
29	20/09/18 16:11	Dismantled Parts	1	Load JPG	✓

Assessment Reports			1 per page ▾	☒
No	Finalized On	Chai Motor Workshop Sdn Bhd (HQ)	Thumbnail	Print
30	20/09/18 16:11	Dismantled Parts		☒
31	20/09/18 16:11	Dismantled Parts		☒
32	20/09/18 16:11	Dismantled Parts		☒
33	20/09/18 16:11	Dismantled Parts		☒
34	20/09/18 16:11	Dismantled Parts		☒
35	20/09/18 16:11	Dismantled Parts		☒
36	20/09/18 16:11	Dismantled Parts		☒
37	20/09/18 16:11	Dismantled Parts		☒
38	20/09/18 16:11	Dismantled Parts		☒
39	20/09/18 16:11	Dismantled Parts		☒
40	20/09/18 16:11	Dismantled Parts		☒
41	20/09/18 16:11	Dismantled Parts		☒
42	20/09/18 16:11	Dismantled Parts		☒
43	20/09/18 16:11	Dismantled Parts		☒
44	20/09/18 16:11	Dismantled Parts		☒
45	20/09/18 16:11	Dismantled Parts		☒
46	20/09/18 16:11	Dismantled Parts		☒
47	20/09/18 16:11	Dismantled Parts		☒
48	20/09/18 16:11	Dismantled Parts		☒
49	20/09/18 16:11	Dismantled Parts		☒
50	20/09/18 16:11	Dismantled Parts		☒
51	20/09/18 16:11	Dismantled Parts		☒
52	20/09/18 16:11	Dismantled Parts		☒
53	20/09/18 16:11	Dismantled Parts		☒
54	20/09/18 16:11	Dismantled Parts		☒
55	20/09/18 16:11	Dismantled Parts		☒
56	20/09/18 16:11	Dismantled Parts		☒
57	20/09/18 16:11	Dismantled Parts		☒
58	20/09/18 16:11	Dismantled Parts		☒
59	20/09/18 16:11	Dismantled Parts		☒
60	20/09/18 16:11	Dismantled Parts		☒
61	20/09/18 16:11	Dismantled Parts		☒
62	20/09/18 16:11	Dismantled Parts		☒
63	20/09/18 16:11	Dismantled Parts		☒
64	20/09/18 16:11	Dismantled Parts		☒
65	20/09/18 16:11	Dismantled Parts		☒
66	20/09/18 16:11	Dismantled Parts		☒
67	20/09/18 16:11	Dismantled Parts		☒
68	20/09/18 16:11	Dismantled Parts		☒
69	20/09/18 16:11	Dismantled Parts		☒
70	20/09/18 16:11	Dismantled Parts		☒
71	20/09/18 16:11	Dismantled Parts		☒
72	20/09/18 16:11	Dismantled Parts		☒
73	20/09/18 16:11	Dismantled Parts		☒
74	20/09/18 16:11	Dismantled Parts		☒
75	20/09/18 16:11	Dismantled Parts		☒
76	20/09/18 16:11	Dismantled Parts		☒
77	20/09/18 16:11	Dismantled Parts		☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Chai Motor Workshop Sdn Bhd (HQ)	Thumbnail	Print
78	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
79	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
80	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
81	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
82	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
83	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
84	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
85	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
86	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
87	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
88	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
89	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
90	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
91	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
92	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
93	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
94	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
95	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
96	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
97	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
98	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
99	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
100	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
101	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
102	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
103	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
104	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
105	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
106	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
107	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
108	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
109	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
110	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
111	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
112	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
113	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
114	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
115	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
116	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
117	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
118	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
119	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
120	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
121	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
122	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
123	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
124	20/09/18 16:11	Dismantled Parts	 Load JPG	☒
125	20/09/18 16:11	Dismantled Parts	 Load JPG	☒

Assessment Reports			1 per page ▾	✓
No	Finalized On	Chai Motor Workshop Sdn Bhd (HQ)	Thumbnail	Print
126	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
127	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
128	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
129	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
130	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
131	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
132	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
133	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
134	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
135	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
136	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
137	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
138	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
139	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
140	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
141	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
142	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
143	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
144	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
145	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
146	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
147	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
148	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
149	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
150	20/09/18 16:11	Dismantled Parts	 Load JPG	✓
151	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
152	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
153	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
154	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
155	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
156	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
157	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
158	30/01/19 11:46	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	Chai Motor Workshop Sdn Bhd (HQ)	Thumbnail	Print
1	12/09/18 10:50	Insured's Driving License	 Load JPG	✓
2	12/09/18 10:51	Insured's NRIC	 Load JPG	✓
3	12/09/18 10:58	Log card (if available)	 Load JPG	✓
4	12/09/18 10:58	Log card (if available)	 Load JPG	✓
5	12/09/18 10:59	Log card (if available)	 Load JPG	✓
6	12/09/18 11:39	Driver's Driving License (BACK)	 Load JPG	✓
7	12/09/18 11:42	Certificate of Insurance	 Load JPG	✓
8	12/09/18 12:36	Driver's NRIC	 Load JPG	✓
9	12/09/18 14:28	Workshop Photo 1	 Load PDF	
10	12/09/18 14:29	Workshop Photo 2	 Load PDF	
11	13/09/18 10:27	Police Report	 Load JPG	✓
12	13/09/18 17:41	Claim Form	 Load JPG	✓
13	13/09/18 17:53	Driver's Driving License	 Load JPG	✓

Assessment Reports			1 per page ▼	☒
No	Finalized On		Thumbnail	Print
14	18/09/18 11:37	Chai Motor Workshop Sdn Bhd (HQ)		
		Claim Form 2	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/09/18 14:31	ESTIMATE.pdf	 Load PDF	
2	27/09/18 14:15	UNDERTAKING LETTER.pdf	 Load PDF	
3	30/01/19 11:44	ESTIMATE MARKED.pdf	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118016720/NSBS2

Date: 31/01/2019

REFERENCE

Insured/Claimant: SE KIAH LEE Policy No: DMPCSN3078531701
Date of Loss: 30/08/2018 Nature of Claim: OD Claim No: SNM18D04274C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE1493K**
Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A) Engine No: CXS083273
Reg. Date: 25/04/2014 (Man. Year: 2014) Chassis No: WVVZZZAUZEW318060
Colour: White Odometer: 92236 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$52,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,960.65	23,964.76	28,995.89	54.75
Miscellaneous Items	1,160.00	440.00	720.00	62.07
Labour	3,880.00	2,250.00	1,630.00	42.01
Paintwork Labour	0.00	0.00	0.00	
Towing	300.00	0.00	300.00	100.00
Calculated Gross Total (S\$)	58,300.65	26,654.76	31,645.89	54.28
Approved Total (Overridden) (S\$)		20,000.00		
- Excess (S\$)	0.00	1,000.00	-1,000.00	
Nett Amount (S\$)	58,300.65	19,000.00	39,300.65	67.41

INSPECTION

Date of Assignment: 13/09/2018 Present Location: Chai Motor Workshop Sdn Bhd (HQ)
Date Inspected: 18/09/2018 Inspected At: Chai Motor Workshop Sdn Bhd (HQ)
Estimated Period of Repair: 10.0 days No 3, Jalan Bertam 8, Taman Daya,
81100 Johor Bahru, Johor Darul Takzim

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 31 Jan 2019)

Parts: 144 VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE1493K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Airbag Steering RH	Activated	6,142.00 F	*1,511.66 FL
2	1		*Front Airbag Dashboard LH	Activated	2,430.00 F	*1,300.00 FL
3	1		*Front Airbag ECU	Necessary	2,650.00 F	*896.15 FL
4	1		*Front Airbag Sensor LH	Necessary	525.00 F	*525.00 FL
5	1		*Front Airbag Sensor RH	Necessary	525.00 F	*525.00 FL
6	1		*Front Seatbelt LH	Jammed	475.00 F	*475.00 FL
7	1		*Front Seatbelt RH	Jammed	475.00 F	*475.00 FL
8	1		*Front Steering Spare Cable RH	Not Necessary	260.00 F	*- FL
9	1		*Front Wiper Tank	Not Necessary	295.00 F	*- FL
10	1		*Front Wiper Tank Motor Front	Not Necessary	76.50 F	*- FL
11	1		*Front Wiper Tank Motor Rear	Not Necessary	90.50 F	*- FL
12	1		*Front Wiper Tank Top Hose	Missing	89.70 F	*89.70 FL
13	1		*Front Harness Wiring	Missing	785.10 F	*450.00 FL
14	1		*Front Fuel Box Lower Housing LH	Bent	314.50 F	*314.50 FL
15	1		*Front Bonnet	Dented	2,200.00 F	*1,000.00 FL
16	1		*Front Bonnet Hinge LH	Bent	157.00 F	*157.00 FL
17	1		*Front Bonnet Hinge RH	Bent	157.00 F	*157.00 FL
18	1		*Front Bonnet Lock	Bent	475.00 F	*200.00 FL
19	1		*Front Bonnet Inner Trim	Torn	550.00 F	*250.00 FL
20	1		*Front Fender LH	Dented	1,110.00 F	*700.00 FL
21	1		*Front Fender RH	Dented	1,260.00 F	*700.00 FL
22	1		*Front Fender Inner Trim LH	Cracked	255.00 F	*255.00 FL
23	1		*Front Fender Inner Trim RH	Cracked	255.00 F	*255.00 FL
24	1		*Front Fender Inner Trim Rear LH	Not Necessary	214.00 F	*- FL
25	1		*Front Fender Inner Trim Rear RH	Not Necessary	214.00 F	*- FL
26	1		*Front Bumper	Cracked	580.00 F	*580.00 FL
27	1		*Front Bumper Side Bracket LH	Cracked	44.00 F	*44.00 FL
28	1		*Front Bumper Side Bracket RH	Cracked	44.00 F	*44.00 FL
29	1		*Front Bumper Fog Lamp LH	Missing	62.50 F	*62.50 FL
30	1		*Front Bumper Fog Lamp RH	Cracked	62.50 F	*62.50 FL
31	1		*Front Bumper Fog Lamp Bracket LH	Missing	190.00 F	*190.00 FL
32	1		*Front Bumper Fog Lamp Bracket RH	Cracked	190.00 F	*190.00 FL
33	1		*Front Bumper Towing Cover	Missing	92.00 F	*92.00 FL
34	1		*Front Bumper Lower Grille	Cracked	280.00 F	*280.00 FL
35	1		*Front Bumper Fog Lamp Lower Moulding LH	Missing	242.00 F	*242.00 FL
36	1		*Front Bumper Fog Lamp Lower Moulding RH	Cracked	242.00 F	*242.00 FL
37	1		*Front Bumper Lower Garnish	Cracked	295.00 F	*295.00 FL
38	1		*Front Bumper Bracket Bin	Cracked	785.15 F	*400.00 FL
39	1		*Front Bumper Air Guard LH	Cracked	77.50 F	*77.50 FL
40	1		*Front Bumper Air Guard RH	Cracked	77.50 F	*77.50 FL
41	1		*Front Bumper Bracket Top Garnish	Cracked	295.00 F	*295.00 FL
42	1		*Front Bumper Sponge	Missing	285.10 F	*285.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*Front Headlamp LH	Cracked	255.00 F	*255.00 FL
44	1		*Front Headlamp RH	Cracked	255.00 F	*255.00 FL
45	1		*Front Headlamp Bulb LH	Serviceable	27.00 F	*- FL
46	1		*Front Headlamp Bulb RH	Serviceable	27.00 F	*- FL
47	1		*Front Headlamp Top Bracket LH	Cracked	255.00 F	*255.00 FL
48	1		*Front Headlamp Top Bracket RH	Cracked	255.00 F	*255.00 FL
49	1		*Front Grille	Cracked	1,180.00 F	*500.00 FL
50	1		*Front Grille Badge	Necessary	245.00 F	*245.00 FL
51	1		*Front Grille Chrome Moulding LH	Cracked	75.00 F	*75.00 FL
52	1		*Front Grille Chrome Moulding RH	Cracked	75.00 F	*75.00 FL
53	1		*Front Wheelhouse LH	Repair	1,458.00 F	*- FL
54	1		*Front Bonnet Lock Bracket Center	Bent	475.00 F	*200.00 FL
55	1		*Front Windscreen Moulding LH	Bent	64.50 F	*64.50 FL
56	1		*Front Windscreen Moulding RH	Bent	64.50 F	*64.50 FL
57	1		*Front Horn LH	Dented	218.00 F	*218.00 FL
58	1		*Front Horn RH	Serviceable	218.00 F	*- FL
59	1		*Front Grille Housing	Serviceable	375.10 F	*- FL
60	1		*Front Engine Mounting RH	Necessary	86.50 F	*86.50 FL
61	1		*Air Cond Pipe To Cooling Coil Bracket	Bent	95.50 F	*95.50 FL
62	1		*Engine Oil Cap	Missing	75.00 F	*75.00 FL
63	1		*Air Cleaner Box	Cracked	386.00 F	*386.00 FL
64	1		*Exhaust Manifold	Serviceable	2,535.00 F	*- FL
65	1		*Air Cond Condenser Pipe To Cooling Coil	Bent	215.30 F	*215.30 FL
66	1		*Air Cond Condenser Pipe To Condenser	Bent	210.70 F	*210.70 FL
67	1		*Air Cleaner House	Serviceable	120.00 F	*- FL
68	1		*Air Cleaner Front	Cracked	386.00 F	*386.00 FL
69	1		*Radiator	Bent	1,280.00 F	*600.00 FL
70	1		*Radiator Panel	Cracked	1,850.30 F	*700.00 FL
71	1		*Radiator Fan	Cracked	1,595.00 F	*650.00 FL
72	1		*Radiator Fan Guard	Cracked	480.00 F	*480.00 FL
73	1		*Radiator Fan Motor	Deformed	128.00 F	*128.00 FL
74	1		*Air Cond Condenser	Bent	1,909.00 F	*800.00 FL
75	1		*Gear Box Oil Cooler	Bent	1,280.00 F	*500.00 FL
76	1		*Exhaust Manifold Front Cover	Bent	1,183.00 F	*400.00 FL
77	1		*Headlamp Rear Cap LH	Necessary	75.00 F	*75.00 FL
78	1		*Headlamp Rear Cap RH	Necessary	75.00 F	*75.00 FL
79	1		*Front Member	Bent	315.40 F	*315.40 FL
80	1		*Steering Column Button	Missing	224.00 F	*224.00 FL
81	1		*Front Alternator	Cracked	3,880.00 F	*1,784.00 FL
82	1		*Front Thermostat	Serviceable	123.00 F	*- FL
83	1		*Front Gear Box Wiring Outer Cover	Missing	275.40 F	*275.40 FL
84	1		*Front Bonnet Lock Cable	Serviceable	172.00 F	*- FL
85	1		*Total Body	Cracked	1,750.30 F	*1,100.00 FL
86	1		*Air sensor	Not Working	218.50 F	*218.50 FL
87	1		*Air sensor bracket	Deformed	315.10 F	*315.10 FL
88	1		*Wiper Grille	Cracked	375.00 F	*375.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	52,960.65	26,627.51
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	2,662.75
Total Parts (\$\$)	52,960.65	23,964.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Air Cond Compressor Oil (NECESSARY)	50.00	20.00
2	1	Air-cond gas (Normal)	150.00	20.00
3	1	Check alignment	50.00	50.00
4	1	Check Balancing	50.00	30.00
5	1	Electrical (check & diagnose)	150.00	50.00
6	1	Number Plate Stay (NECESSARY)	80.00	30.00
7	1	Number plate, front (DENTED)	60.00	40.00
8	1	Painting Materials (NECESSARY)	400.00	100.00
9	1	Radiator coolant (NECESSARY)	70.00	40.00
10	1	Underseal materials	100.00	60.00
Sub Total (S\$)			1,160.00	440.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Remove & Refix Air Bag, Cable, Module & Sensor	New	180.00	50.00
2	Spray Painting on Front Bonnet, Fender LH & RH , Bumper, Wheelhouse LH, Front Panel	New	800.00	800.00
3	To Knock, Welding, Cut and Hydraulically Jack & Align Chasis Frame Front Wheel House	New	1,000.00	800.00
4	To Remove & Refix All Accident Parts	New	1,200.00	600.00
5	To Remove & Replace Engine	New	700.00	0.00
Gross Labour Cost (S\$)			3,880.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >