23/03/2002 ASS. REC. BY:		REF:	(s/msh	18016	27/	Klsb	22 s	pecial Instruction	m:	
Survajor :	Kalvin		ASSIGN	MENT	(Off	ice)			E.	
From (Person):	Irone Tun		of	, N	1341			Date/Time:	13052118	1039 am
Estimated Cost	•		-	Bil	l to: _					
	TP RES / OD R									
To Inspect Vel	nicle No;	2110	6912C				Insure	d:	GBD 13	3C
at Workshop m	√s	Poten	ill				Te	1: 65	44 6689	
				th Ave		#13	-02			
Policy No:	7897354	MKC	4	(	Claim	No:		570039		
Sum Insured:_		-11								
Make of Veh: (Client's Record)								D.O.A	12092019	<b>S</b>
CA / REV / Date/Time:	REP. / REV 24 1509 2018 11140	HRS W	son Contact	ed:	Vr	nunt	****	H.O.D. En	dorsement:	
Date/Time	Action/Instruction	ı ( <b>v</b>	) Estim	nte.						
	SIK 62650 -	0(3/	ALG 1500	1204/	HISE	$Q_{ij}$		- DVA	: 16.01-15	
	GBO 2320 -					00-				
14/09/18	@14:58 p	m. 0	evised	ZA T	Lo	Ine	e 7	an ack	Zy via	e merine
7										

(08/11/13)	REF:	n n
ameyn: Kalvin		
	ASS	SIGNMENT
From:	Date:	Veh No: SH C 6265 C Yr Regn: "NOV , 2014
EstimatedCost		Type: M.Car / M.Cycle / Bus / Van / Lorry / Tel i / Prime Mover /
OD ITP IWS ITP RES	/OD RES / EVA / INV / MV	Truck / Trailer or
To Insped Vehicle No:	ă ă	Make: KIA optima c.c 1665.  Colour Silve A/C: Insuffed / Std / NI / NA
		Colour Silve A/C: Insuffed / Std / NI / NA
		Sp.Reading 363240 T/Radio: Insufed / Std / NI / NA
to accorde		Eng/No:
-		C/No: KNAGM414 MF555 4293
		Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	OATMA DESIGNATION OF THE PARTY	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:		Modi: Nil / S/Rim / STB A/Rim or
-		Tyre Size; F: 205/65R16
(Policy Condition)		R:
Remark: The veh had	commenced its N/S O/S	
	e time of inspection.	TOYO/YOKO or Achilles
Bal. or Market Value:		Front Rear
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 7 mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. 7 mm
Est. Repairs:	days Res.: Yes or No	D.O.A. 12/9/18 D.O.I. 13/9/18
Lum Sum:	% 3 Val.: Yes or No	Survey held at Premier
Luii ouii.		Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP	P. / 24 HRS Vehicle: IN / O	NS For a
Date:	Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Ac	tion / Instruction	4.50
2./9/.8 6	Am 1 4/5\$1150/3 Pgs.	MZK
24/09/18 Co		@ 3 days with Kalvin 45
C 9	\$517.55 Rd. 31%.	)
	RECEIVED 2	+ SEP 2018
		parameter statements
Date/Time, File Pass to?	: Preli. Report	Days Of Repair: 5
1) Typist	: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to	₁º Add I	
2)	— Add I	Interview (\$ ) Photos /0
		: Tech. Invs (\$ ) Others
Report Format:		
Lump Sum / I.B.	1: (\$ 1,150/- 2/5)	:Weekend (\$)
		TOTAL 160

(Ent (180)

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	12 Sep 2018		13 Sep 2018 10:39 Assign				New Assignm Cancel Case	nent	
	Main	R	eference		Claim Details	Doc	uments	Show All	
	UBFOLDER DET						Created by ins	urer]	
nsured:		12712777		The state of the s	Co. Reg. No.: 20080	7428M			
Main Clair	mant:	PREM	IER TAXIS PTE L	TD, Co. Reg	. No.: 200304975H				
/ehicle Re	eg. No.:	SHC	5265C		Date of Loss:	1	12/09/2018 08:00 - :59 [ <b>46</b> Months and <b>1</b> Days Fro Reg Date (Man Yr)]		
Claim Typ	e:	TP/	570039		Policy/Cover Note No.	:	28973541MKC Coverage: 27/07/2017 - 04/11/2018		
Vehicle Re	eg. No. (Insured)	GBD2	32C		Policy No. (Claimant):				
					Excess:		S\$600.00		
Repairer:		Premi	er Taxis Pte Ltd	- Changi (HC	) 23 Changi South Av	e 2 #03-02, 486	443 Changi - Tel:		
landling 1	Insurer:	<b>MSIG</b> 6594 2		apore) Pte. I	Ltd. (HQ) - Tel: +65 6	5827 7888 [Ha	andled by Irene	Tan Gek Ing -	
Adjuster:		LKK A	uto Consultants	Pte Ltd (HQ)	- Tel: 6256-3561	[Imm.Advice	due 14/09/20	18]	
Adj Asg. F	Remarks:	SURVE	Y AGREE ON SJE	REQ TO ASS	IGN LKK (KALVIN ANG	) OI NOT REPOR	TED CONTACT: V	INCENT 6544 668	
ASSOCIA	ATED MAIL REC	EIVED				Vi	ew All   Con	npose Case Mail	
There are	no mail for this o	case.							
E									
ALL ASS	OCIATED TASK	(S			View All S	earch Tasks	Create New Tas	k   Complete	
Due Da		Type Task	Group Subje	ct Handle	er Assigned By	Completed	On Create	ed On Done?	

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date: 14 Sep 2018

# **Preliminary Advice**

Insured Vehicle No : GBD232C

TP Vehicle No

: SHC6265C

Accident Date

: 12/09/2018

Make

: KIA OPTIMA

Assignment Date

: 13/09/2018

Date of Inspection : 13/09/2018

Est. Duration of Repair

: 3 days

Inspection At

: Premier Taxis Pte Ltd - Changi (HQ)

23 Changi South Ave 2 #03-02

Singapore 486443

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,667.55
Revised Amount	:S\$	1,486.15
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,486.15

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

atoresaid.	
	ACCIDENT STATEMENT
Date Of Report	12/09/2018 14:28
Date Of Accident	12/09/2018 08:35
Exact Location Of Accident	PIE - TUAS
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC6265C
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	500304975H
Cover Note Number	
Driver	
Name of Driver	SAAID BIN MOKLAS
NRIC No	S0123530C
Date Of Birth	19/05/1953
Occupation	OUTDOOR
Date Of Driving Pass	04/07/1977
Driving Experience	41 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93624997

NOEMAIL

Address

BLK 276 #02-303

CHOA CHU KANG AVE 2

Postcode

680276

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) Passenger 1

2

NAME:

: DAUGHTER ONBOARD

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

BOTH VEHICLES - 1 PAX

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD232C

Vehicle Make/Model/Colour

TOYOTA LORRY

**Details Of Properties** 

VEH. B

Vehicle Category

**GOODS VEHICLE** 

Name of Driver

WONG KEE MENG

NRIC/Passport Number

S1563871J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (II) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time: 0123530/C

\*SHC 6265-C


12 SEP 2018

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

GrafiMU SkatztiPlaniform VI

### Sketch Plan Pg. 2



#### Sketch Plan Pg. 3

# Describe Circumstance of the Accident.

ON 12/09/2018 AT ABOUT 0835HRS, I WAS DRIVING MY TAXI ( SHC 6265 C ) TRVELLING ALONG PIE – TUAS (AFTER STEVENS ROAD EXIT) IN LANE 1 WITH MY DAUGHTER ONBOARD.

TRAFFIC WAS SLOW MOVING & CONGESTED AHEAD AS THERE WAS AN ACCIDENT OCCURRED.


WHILE I WAS MOVING STRAIGHT AHEAD – WITHIN MY LANE & ACCORDING TO THE FLOW OF TRAFFIC, SUDDENLY VEHICLE B ( GBD 232 C – TOYOTA LORRY ) WHICH WAS INITIALLY IN LANE 2 – FAILED TO KEEP FOR PROPER LOOK OUT, HAD ENCROACHED ONTO MY PATH ON MY LEFT FRONT ABRUPTLY WITHOUT ANY ADVANCE SIGNAL.

AS SUCH, THE RIGHT REAR OF VEHICLE B HAD COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI – WHILE HE WAS FILTERING INTO LANE 1.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE LEFT FRONT PORTION AND I WAS NOT AWARE OF DAMAGES TO VEHICLE B.

NO INJURY INVOLVED.
VEHICLE B HAD A PASSENGER ONBOARD.

\*VIDEO FOOTAGE CAPTURED.



Text size + -

### Enquire Transaction History

Transaction History Details

Log Date/Time:

11 Nov 2014 / 10:22:08

Receipt No .:

AACCK001-AX239-141111-000018

Asset Type:

Vehicle

Transaction Amount:

\$63,968.00

Asset ID:

SHC6265C

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction

Reference No.:

01.02 Register New Vehicle (AA)

20141111102208876212

Vehicle No.:

SHC6265C

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 11 Nov 2014

Original Registration

11 Nov 2014

Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No .:

KNAGM414MF5554293

Engine No.:

D4FDEH311791

Motor No.:

Trailer Chassis No .:

Propellant:

Diesel Passenger Capacity: 4

Engine Capacity:

1685

Power Rating:

Unladen Weight:

1584

Maximum Laden

2050

Weight: Primary Color:

Silver

Secondary Color:

Manufacturing Year:

2014

Open Market Value:

\$19,991.00

Minimum PARF

Benefit:

\$7,494.00

PARF Eligibility:

No. of Transfer:

0

Effective Ownership

11 Nov 2014 10:22:08

Date/Time: COE No .:

2014111101001265D

COE Expiry Date:

10 Nov 2022

COE Bid Category:

Actual QP/PQP Paid

Amount:

\$51,337.00

Lifespan Expiry Date:

10 Nov 2022

Owner ID Type:

Company

# PREMIER AUTOMOTIVE SERVICES PTE LTD 23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0042

Assessor Report Version: PREMIERA/1 Printed: 13/09/2018

Summary Information

Claim

Claim Reference:

SHC6265C

Insured:

Policy Number:

Date of Decision:

13/09/2018

Third Party:

Able to Authorise Repairs: TBA Repairs Authorised? TBA

Estimated Repair Time

(Working Days):

0.0

Insured's Liability

Excess:

Repairer:

TBA

Customer Contribution:

\$0.00 (excl GST)

Vehicle Details

Vehicle

Registration:

SHC6265C

VIN/Chassis Number:

Manufacturer:

Registration Month:

KIA

Model:

Optima 2014

Odometer:

November Not Known Registration Year: Colour:

Build Date:

Model Specs

FROM 09/2014

WHEEL COVER 16 INCH PREPARE OFF VEHICLE BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Date of Incident:

Pre-Accident Condition:

12/09/2018

Market Value:

Salvage Value:

Unknown Unknown

Pre-Accident Damage: Steering Rim Ply:

Brake Pedal Travel: Vehicle Status:

Damage Severity:

Date of Inspection:

13/09/2018

Place of Inspection:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Tread Depth RHF: Tread Depth RHR:

Repair Information

LABOUR Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR Price/Dent = \$50.00/HR

Repair / Cost Price (\$) **Guide Number Repair Details** wu 66300R00) RENEW L/FRT WING 6.0 30.00 (BUMPER REMOVED) INCLUDE: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS IN REPAIR AREA R + R 3.0 15.00 86512R00 ZAX R + R FRONT BUMPER 87602R00 R + R LEFT MIRROR 2.0 10.00 87755R00 R + R L/SILL TRIM 3.0 15.00 20.0\* 0283 REPAIR FRONT BUMPER 100.00

# PREMIER AUTOMOTIVE SERVICES PTE LTD 23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0042

**Assessor Report** Version: PREMIERA/1 Printed: 13/09/2018

1481	REPAIR LEFT FRONT DOOR			10.0*	50.00			
LAB	OUR COST							
	Total Work Units			44.0				
	<b>Corrosion Protection Exte</b>	ernal Labour		0.0HRS	0.00			
	<b>Corrosion Protection Inte</b>	rnal Labour		0.0HRS				
	Sub Total			4.4HRS	\$220.00			
	Paint Labour			7.8HRS	\$390.00			
	Total Labour		_	12.2HRS _	\$610.00			
PAINT WORK Guide Number	Description	Time Bas	is 10 WU =	1 HR. Price : WU	= \$50.00/HR Cost Price (\$)			
Guide Number	- PREPARE OFF VE	HICLE		WO	cost Price (\$)			
	<ul> <li>BASECOAT CLEA</li> </ul>	R						
741	L/F WING NEW PART PAINT	ING		9.0				
1737	L/DOOR MIRROR NEW PART	PAINT K1R		3.0				
283	FRONT BUMPER REPAIR PAI	NT PLASTIC		16.0				
1481	LEFT FRONT DOOR REPAIR	PAINTING <50%		17.0				
LAB	OUR COST - PAINT							
	TIME(PAINT)			45.0				
	Preparation Main Work P			8.0				
	Preparation Main Work M			25.0				
	Preparation Work Multi L	•		0.0				
	Total Work Units (10WU/	HR)		78.0				
	Total Paintwork Labour			7.8HRS	\$390.00			
				7.onks				
MAT	ERIAL COST - PAINT			7.onks	<b>Cost Price</b>			
МАТ	ERIAL COST - PAINT New Part Painting			7.6HR3	Cost Price \$16.51			
МАТ	ERIAL COST - PAINT New Part Painting New Part Painting - Plast			7.0113	<b>Cost Price</b>			
МАТ	ERIAL COST - PAINT New Part Painting			7.onk3	Cost Price \$16.51			
МАТ	ERIAL COST - PAINT New Part Painting New Part Painting - Plast			7.onk3	Cost Price \$16.51 \$2.46			
МАТ	ERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W			7.onks	Cost Price \$16.51 \$2.46 \$28.60			
МАТ	REIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting	Vork Metal		7.onk3	Cost Price \$16.51 \$2.46 \$28.60 \$28.10			
МАТ	RERIAL COST - PAINT  New Part Painting  New Part Painting - Plast  Material-Constant Main W  Repair Painting  Repair Painting Plastic	Vork Metal k Plastic		7.onks	\$16.51 \$2.46 \$28.60 \$28.10 \$54.68			
МАТ	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main World	Vork Metal k Plastic ent Uplift		7.0113	\$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70			
	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce	Vork Metal k Plastic ent Uplift		7.0113	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05			
PARTS	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.0% Total Paint Material Cost	Vork Metal k Plastic ent Uplift %		Price V	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05			
PARTS Guide No.Qty	RERIAL COST - PAINT  New Part Painting  New Part Painting - Plast  Material-Constant Main W  Repair Painting  Repair Painting Plastic  Material-Const Main Worl  Total Excluding Pearlesce  Pearlescent Uplift @ 0.0%  Total Paint Material Cost  Description	Vork Metal  k Plastic ent Uplift 6  Part Number	Supplier	Price V	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05			
PARTS Guide No.Qty 1737 1	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.0% Total Paint Material Cost  Description L/DOOR MIRROR	Vork Metal  k Plastic ent Uplift 6  Part Number 876102T940	Supplier	Price V Bet	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 *Valid: 01/06/2015 c. Price (\$) 590.00*			
PARTS  Guide No. Qty 1737 1 7211 1	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Work Total Excluding Pearlesce Pearlescent Uplift @ 0.0% Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER	Vork Metal  k Plastic ent Uplift 6  Part Number 876102T940 529602T100	Supplier	Price V Bet 0% 2md 5m 0%	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 c. Price (\$) 590.00* 116.00*			
PARTS  Guide No. Qty 1737 1 7211 1 841 1	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.09 Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER	Vork Metal  k Plastic ent Uplift  6  Part Number 876102T940 529602T100 868112T500	Supplier	Price V <b>Bet</b> 0% 5w 0% 0%	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 Valid: 01/06/2015 c. Price (\$) 590.00* 116.00* 120.00*			
PARTS  Guide No. Qty 1737 1 7211 1 841 1 741 1	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Work Total Excluding Pearlesce Pearlescent Uplift @ 0.0% Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER	Vork Metal  k Plastic ent Uplift  6  Part Number 876102T940 529602T100 868112T500 663112T000	X	Price V Bet 0% 2md 5m 0%	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 Valid: 01/06/2015 C. Price (\$) 590.00* 116.00* 120.00* 384.00*			
PARTS  Guide No.Qty 1737 1 7211 1 841 1 741 1 f: OEM Parts	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.09 Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER	Vork Metal  k Plastic ent Uplift  6  Part Number 876102T940 529602T100 868112T500 663112T000 Sub Total	X to	Price V <b>Bet</b> 0% 0% 0% 0%	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 C. Price (\$) 590.00* 116.00* 120.00* 384.00* \$1,210.00			
PARTS  Guide No.Qty 1737 1 7211 1 841 1 741 1 f: OEM Parts g: Original	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.09 Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER	Part Number 876102T940 529602T100 868112T500 663112T000 Sub Total Deduction	from RRP	Price V <b>Bet</b> 0% 5w 0% 0%	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 c. Price (\$) 590.00* 116.00* 120.00* 384.00* \$1,210.00 -\$423.50			
PARTS  Guide No.Qty 1737 1 7211 1 841 1 741 1 f: OEM Parts g: Original h: Secondhand	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.09 Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER	Vork Metal  k Plastic ent Uplift  6  Part Number 876102T940 529602T100 868112T500 663112T000 Sub Total	from RRP	Price V <b>Bet</b> 0% 0% 0% 0%	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 C. Price (\$) 590.00* 116.00* 120.00* 384.00* \$1,210.00			
PARTS  Guide No.Qty 1737 1 7211 1 841 1 741 1 f: OEM Parts g: Original h: Secondhand p: Parallel	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.09 Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER	Part Number 876102T940 529602T100 868112T500 663112T000 Sub Total Deduction	from RRP	Price V <b>Bet</b> 0% 0% 0% 0%	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 c. Price (\$) 590.00* 116.00* 120.00* 384.00* \$1,210.00 -\$423.50			
PARTS  Guide No.Qty 1737 1 7211 1 841 1 741 1 f: OEM Parts g: Original h: Secondhand	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.0% Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER L/F WING	Part Number 876102T940 529602T100 868112T500 663112T000 Sub Total Deduction Total Pai	n from RRP	Price V Bet 0% 5w 0% 0% 0% (35 %)	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 c. Price (\$) 590.00* 116.00* 120.00* 384.00* \$1,210.00 -\$423.50			
PARTS  Guide No. Qty 1737 1 7211 1 841 1 741 1 f: OEM Parts g: Original h: Secondhand p: Parallel x: Exchange	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.09 Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER	Part Number 876102T940 529602T100 868112T500 663112T000 Sub Total Deduction Total Pai	n from RRP	Price V Bet 0% 5w 0% 0% 0% (35 %)	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 c. Price (\$) 590.00* 116.00* 120.00* 384.00* \$1,210.00 -\$423.50			
PARTS  Guide No.Qty 1737 1 7211 1 841 1 741 1 f: OEM Parts g: Original h: Secondhand p: Parallel	RERIAL COST - PAINT New Part Painting New Part Painting - Plast Material-Constant Main W Repair Painting Repair Painting Plastic Material-Const Main Worl Total Excluding Pearlesce Pearlescent Uplift @ 0.0% Total Paint Material Cost  Description L/DOOR MIRROR L/F WHEEL COVER L/F WHEELHOUSE COVER L/F WING	Vork Metal  k Plastic ent Uplift  6  Part Number 876102T940 529602T100 868112T500 663112T000 Sub Total Deduction Total Part  ITEMS/TRIM - PART	n from RRP	Price V Bet 0% 5w 0% 0% 0% (35 %)	Cost Price \$16.51 \$2.46 \$28.60 \$28.10 \$54.68 \$12.70 \$143.05 \$0.00 \$143.05 (alid: 01/06/2015 c. Price (\$) 590.00* 116.00* 120.00* 384.00* \$1,210.00 -\$423.50			

# PREMIER AUTOMOTIVE SERVICES PTE LTD 23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0042

**Assessor Report** Printed: 13/09/2018 Version: PREMIERA/1

FENDER SHEILD CLIP SPECIALIST	× 0%	\$28.00
N/S DOOR STICKER SPECIALIST	ALL	\$100.00
	Total Extras	\$128.00
Final Calculation		
Total Parts		\$786.50
Labour		
Total Panel/Mechanical	\$220.00	
Total Paintwork	\$390.00	
Total Labour		\$610.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$128.00	
Total of Additional Costs		\$128.00
Total Paint/Material Costs		\$143.05
Grand Total Excludes GST		\$1,667.55
GST @ 7 %		\$116.73
Grand Total Includes GST		\$1,784.28

**Assessment Notes** 

Kehrilley

M 13/9/8 137. C.

3 ly.

LKK Auto C
the Repaire

To resurvey

To display the
Parts of res

Third of the

After Repaire LKK Auto Consultants hence notify the Repairer of the following: Signature:

# 51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

408933

Claim Reference: SHC6265C Assessment Number: MSIG0042

Version: LKKAUTOC/2

Date Calculated: 14/09/2018 07:46

Full Report - V1 Registration: SHC6265C

Printed: 14/09/2018 14:50

SGD

TBA

12/09/2018

**Summary Information** 

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference: Policy Number: Other Reference: Third Party:

Insured Amount: Under Warranty: Warranty Expired:

Singapore (SG) LKK AUTO

Interim

MSIG Insurance (Singapore) Pte

SHC6265C

Quote Due Date: Actual Repair Days: Parts Ordered Date:

Hire Car Start: Hire Car End: Vehicle Collected:

Currency:

Date of Incident:

Repairs Authorised:

Estimated Repair Time:

Able to Authorise Repairs: TBA

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration: Registration Month:

Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

%

KIA

Optima BASE MODEL

2836 01

2014

SHC6265C

November

Not Known

**Model Specs** 

FROM 09/2014 PREPARE OFF VEHICLE WHEEL COVER 16 INCH BASECOAT CLEAR

Vehicle Condition

**Vehicle Status** 

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

13/09/2018

Tread Depth RHF:

Tread Depth RHR: Direction of Impact:

# 51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHC6265C


Full Report - V1 Registration: SHC6265C


Assessment Number: MSIG0042

Printed: 14/09/2018 14:50

Version: LKKAUTOC/2

Date Calculated: 14/09/2018 07:46





### **Addresses**

Cost	Sum	mary
------	-----	------

Total Labour	\$610.00
Total Paint/Material	\$143.05
Total Parts	\$633.10
Total of Additional Costs	\$100.00
Excess:	TBA
Grand Total Exc GST:	\$1,486.15
7 % GST:	\$104.03
Grand Total Inc GST:	\$1,590.18

**Repair Information** 

LABOUR

Time	Basis	10	wu	=	1	HR.	Price,	/CL	1	=	\$50.0	00/	HR	

Price/Dent = \$50.00/HR

		riice, bene	- 450.00/1110
Repair /			Ver 1000 /201 /2010
<b>Guide Numbe</b>	r Repair Details	WU	Cost Price (\$)
66300R00)	RENEW L/FRT WING	6.0	30.00
	(BUMPER REMOVED)		
	INCLUDE: WHEELHOUSE LINER AND REQUIRED		
	ATTACHED PARTS IN REPAIR AREA R + R		
86512R00 ZAX	R + R FRONT BUMPER	3.0	15.00
87602R00	R + R LEFT MIRROR	2.0	10.00
87755R00	R + R L/SILL TRIM	3.0	15.00
0283	REPAIR FRONT BUMPER	20.0*	100.00
1481	REPAIR LEFT FRONT DOOR	10.0*	50.00
LAB	OUR COST		
	Total Work Units	44.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	4.4HRS	\$220.00
	Paint Labour	7.8HRS	\$390.00
	Total Labour	12.2HRS	\$610.00

PAINT WORK		me Basis 10 WU = 1 HR. Pric	e = \$50.00/HR
	umber Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- BASECOAT CLEAR		
741	L/F WING NEW PART PAINTING	9.0	
1737	L/DOOR MIRROR NEW PART PAINT K1R	3.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
1481	LEFT FRONT DOOR REPAIR PAINTING <	50% 17.0	
	LABOUR COST - PAINT TIME(PAINT)	45.0	

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHC6265C Full Report - V1
Assessment Number: MSIG0042 Registration: SHC6265C

Version: LKKAUTOC/2 Printed: 14/09/2018 14:50

Date Calculated: 14/09/2018 07:46

Preparation Main Work Plastic	8.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	78.0	
Total Paintwork Labour	7.8HRS	\$390.00
MATERIAL COST - PAINT		<b>Cost Price</b>
New Part Painting		\$16.51
New Part Painting - Plastic K1R		\$2.46
Material-Constant Main Work Metal		\$28.60
Repair Painting		\$28.10
Repair Painting Plastic		\$54.68
Material-Const Main Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$143.05
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$143.05

PARTS						
					Price Vali	d: 01/06/2015
Guide 1737	No.Qty	Description L/DOOR MIRROR	Part Number 876102T940	Supplier	Bet. 0%	Price (\$) 590.00*
741	1	L/F WING	663112T000		0%	384.00*
f: OEM g: Origi h: Seco p: Para	inal ondhand		Sub Total Deduction <b>Total Par</b>		(35 %)	\$974.00 -\$340.90 \$633.10

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

_				
_	•	-	-	S
			•	
_	•			

x: Exchange

Betterment	Price
0%	\$100.00
Total Extras	\$100.00
	\$633.10
\$220.00	
\$390.00	
	\$610.00
\$0.00	
\$0.00	
\$100.00	
	\$100.00
	\$143.05
	\$1,486.15
·	\$104.03
	\$1,590.18
	0% Total Extras \$220.00 \$390.00 \$0.00 \$0.00

# **Assessment Notes**

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHC6265C Full Report - V1

Assessment Number: MSIG0042 Registration: SHC6265C Version: LKKAUTOC/2 Printed: 14/09/2018 14:50

Version: LKKAUTOC/2 Printed: 14/09
Date Calculated: 14/09/2018 07:46

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING		Transaction in the same of the			Terror construction	(I see to the see		
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj 5	Submitted	Ins Auth'ed	Status		
Main	12 Sep 2018		13 Sep 2018 10:39 Edit Adj Rpt	S\$1,150.00 Edit Estimates	100000000000000000000000000000000000000	,150.00 ew Rpt		Report	Pending for Survey Report Cancel Case	
	Main	R	eference	Claim D	etails		Document	s	Show All	
CLAIM SU	BFOLDER DE	TAILS				[Created l	by insurer]			
Insured:	HARVEST	PRODUCTIONS	PTE LTD, Co. Reg	. No.: 200807428N	1					
Main Claimant:	PREMIER	TAXIS PTE LTD,	Co. Reg. No.: 20	0304975H						
Vehicle Reg No.:	SHC626	5C		Date o	f Loss:		3 08:00 - :59 and <b>1</b> Days Fron	n LTA Reg D	ate (Man Yr)]	
Claim Type	TP / 570	039		Policy, Note N	Cover	28973541M Coverage: 2	IKC 27/07/2017 - 04/	11/2018		
Vehicle Reg No. (Insured):	GBD232C			Policy (Claim						
				Exces	5:	S\$600.00				
Repairer:	Premier 1	axis Pte Ltd - Cl	nangi (HQ) 23 Cha	ngi South Ave 2 #0	3-02, 4	86443 Chang	gi - Tel:			
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65 6827 7	888 [	Handled by	Irene Tan Gek	Ing - 6594 2	2541]	
Adjuster:	13/10/20		Ltd (HQ) - Tel: 62	56-3561 [Hand	ed by <b>K</b>	ALVIN ANG	WEI KUN ] [	Final Rpt	due	
Adj Asg. Remarks:	SURVEY A	GREE ON SJE - RE	Q TO ASSIGN LKK (	KALVIN ANG) OI N	OT REPO	ORTED CONT	ACT: VINCENT 6	544 6689		
ASSOCIAT	TED MAIL RE	CEIVED					Vie	w All Co	ompose Case Mai	
There are n	o mail for this	case.								
ALL ASSO	CIATED TAS	ks⊟			V	/iew All S	earch Tasks C	Create New T	ask   Complete	
Due Dat	e Priority	Type Task	Group Subject	t Handler	Assign	ed By	Completed On	Creat	ed On Done	

### Claim Documents

\*SHC6265C (570039)

[GBD232C]

TP

PREMIER TAXIS PTE LTD

Sep 12 2018 8:00AM

[HARVEST PRODUCTIONS PTE LTD]

Premier Taxis Pte Ltd - Changi

Ass	essment Reports		1 per page	~ ~
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thun	nbnail Pri
1	17/09/18 08:56	Accident Statement From:SC - Reg. No: GBD232C, Claimant: HARVEST PRODUCTIONS PTE LTD	1 Load	і нтм
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		nbnail Pri
1	14/09/18 14:58	Adjuster Immediate Advice	1 Load	HTM
Pho	tos/Images		3 per page	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thun	nbnail Pri
1	13/09/18 17:29	General View	1 Load	d JPG
2	13/09/18 17:29	General View	1 Load	JPG 🔽
3	13/09/18 17:29	General View	1 Load	JPG 🔽
4	13/09/18 17:29	General View	1 Load	d JPG
5	13/09/18 17:29	General View	1 Load	JPG 🔽
6	13/09/18 17:29	General View	1 Load	JPG 🔽
7	13/09/18 17:29	General View	1 Load	JPG 🔽
8	13/09/18 17:29	General View	1 Load	JPG 🔽
9	13/09/18 17:29	General View	€ Load	JPG 🗸
10	13/09/18 17:29	General View	1 Load	JPG 🔽
11	13/09/18 17:29	General View		JPG 🗸
12	13/09/18 17:29	General View		JPG 🔽
13	13/09/18 17:29	General View		JPG 🔽
14	13/09/18 17:29	General View	-	JPG 🗸
15	13/09/18 17:29	General View		d JPG ☑
16	13/09/18 17:29	General View		JPG 🔽
17	13/09/18 17:29	General View		JPG 🔽
18	13/09/18 17:29	General View		JPG 🔽
19	13/09/18 17:29	General View		i JPG
20	13/09/18 17:29	General View		JPG ▼
21	13/09/18 17:29	General View		JPG 🗸
22	21/09/18 17:45	Reinspection Photo		1 JPG
23	21/09/18 17:45	Reinspection Photo		i JPG ✓
24	21/09/18 17:45	Reinspection Photo		JPG 🔽
25	21/09/18 17:45	Reinspection Photo		JPG 🗸
2.3	21/05/10 17.43	Remspection Filoto	0 1500	23,0
Doc	umentation	1	1 per page	V V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		nbnail Pri
1	12/09/18 17:33	FAX FROM TP TO ARRANGE SURVEY		1 PDF
2	12/09/18 17:33	SHC6265C TP E-FILE REPORT		PDF
3	12/09/18 17:33	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KALVIN ANG)	1 Load	PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thun	nbnail Pri

Merimen e-Claims Page 2 of 2

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18016727/K1SBE2

Date:

27/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28973541MKC

Claimant Vehicle SHC6265C No:

Insured Vehicle No:

GBD232C

Date of Loss:

12/09/2018

Nature of Claim:

TP

Claim No: 570039

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SHC6265C

Make & Model:

KIA OPTIMA, 1.7 D (A)

Engine No:

D4FDEH311791

Reg. Date: Colour:

11/11/2014 (Man. Year: 2014) Silver

Chassis No: Odometer:

KNAGM414MF5554293 363240 km

**Engine Capacity:** 

1685 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/65 R16

Rear Tyre Size:

205/65 R16

Front Left Side:

Achilles 7 mm

Rear Left Side:

Achilles 7 mm

Front Right Side:

Achilles 7 mm

Rear Right Side:

Achilles 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	914.50	733.10	181.40	19.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	753.05	753.05	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,667.55	1,486.15	181.40	10.88
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	1,667.55	1,150.00	517.55	31.04
+ GST 7.00/7.00% (S\$)	116.73	80.50	36.23	31.04
Nett Amount (S\$)	1,784.28	1,230.50	553.78	31.04

INSPECTION

Date of Assignment:

13/09/2018

Date Inspected:

13/09/2018 Inspected At:

Premier Taxis Pte Ltd - Changi (HQ)

23 Changi South Ave 2 #03-02

Singapore 486443

Estimated Period of Repair:

3.0 days

Adjuster Report Page 2 of 4

Adjuster: KALVIN ANG WEI KUN Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 27 Sep 2018)

Parts:

143

KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC6265C)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*L/DOOR MIRROR	Cracked	590.00 FL	*590.00 FL
1		*L/F WHEEL COVER	Serviceable	116.00 FL	*-FL
1		*L/F WHEELHOUSE COVER	Serviceable	120.00 FL	*-FL
1		*L/F WING	Dented	384.00 FL	*384.00 FL
1		*FENDER SHIELD CLIP	Not Necessary	28.00 FS	*- FS
1		*N/S DOOR STICKER	Necessary	100.00 FS	*100.00 FS
anchise	part. S=SpcNe	tt. L=ListItemDisc.	_		
			Sub Total (S\$)	1,338.00	1,074.00
		- List Item Discount on	L Items 35.00/35.00% (S\$)	423.50	340.90
			Total Parts (S\$)	914.50	733.10
	1 1 1 1 1	1 1 1 1 1	1 *L/DOOR MIRROR 1 *L/F WHEEL COVER 1 *L/F WHEELHOUSE COVER 1 *L/F WING 1 *FENDER SHIELD CLIP 1 *N/S DOOR STICKER anchise part. S=SpcNett. L=ListItemDisc.	1 *L/DOOR MIRROR Cracked 1 *L/F WHEEL COVER Serviceable 1 *L/F WHEELHOUSE COVER Serviceable 1 *L/F WING Dented 1 *FENDER SHIELD CLIP Not Necessary 1 *N/S DOOR STICKER Necessary anchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 35.00/35.00% (S\$)	1         *L/DOOR MIRROR         Cracked         590.00 FL           1         *L/F WHEEL COVER         Serviceable         116.00 FL           1         *L/F WHEELHOUSE COVER         Serviceable         120.00 FL           1         *L/F WING         Dented         384.00 FL           1         *FENDER SHIELD CLIP         Not Necessary         28.00 FS           1         *N/S DOOR STICKER         Necessary         100.00 FS           anchise part. S=SpcNett. L=ListItemDisc.         Sub Total (S\$)         1,338.00           - List Item Discount on L Items 35.00/35.00% (S\$)         423.50

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOTAL PANEL / MECHANICAL	New	220.00	220.00
2	TOTAL PAINTWORK	New	390.00	390.00
3	TOTAL PAINT / MATERIAL COSTS	New	143.05	143.05
		Gross Labour Cost (S\$)	753.05	753.05
	Report wa	as unsubmitted during this print-out.		

< END OF ESTIMATES >