



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110  Contact No	Cust No/Name	LCV01675/Ms Ho Yuet Chun
	Reg No/Reg Date	SKC1225R / 31/10/2017
	Date In/Mileage	11/09/2018/ 0
	Chassis No	KNAFZ411MJ5749231
	Engine No	G4FGHH683954
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	K3R / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	13/09/2018/ 12:44	DS	218 / MarsLer	64868

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00
S MIPNT88088 TO REPLACE FRONT BUMPER,BODY KIT,RH HEADLAMP,RHF FENDER,ETC STRIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS				2400.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				300.00
S MIPNT88088 TO PERFORM COMPUTERIZE WHEEL ALIGNMENT				180.00
S MIPNT88088 WHEEL BALANCING				50.00
S MIPNT98088 SPRAY PAINTING ON RH & FRONT ACCIDENT AFFECTED AREAS				2100.00
M KS 86511 A7 810 COVER - FRONT BUMPER	1.00	633.00	0.00	633.00
M KS 86568 A7 800 RH DUCT ASSY-AIR CUR	1.00	6.00	0.00	6.00
M KS 86513 A7 000 LH SIDE BRACKET-FR B	1.00	12.00	0.00	12.00
M KS 86514 A7 000 RH SIDE BRACKET -FR	1.00	12.00	0.00	12.00
M KS 95720 A7 0009 P ULTRASONIC SENSOR AS	1.00	177.00	0.00	177.00
M SUK11010113-K3 K3 BODY KIT	1.00	1680.00	0.00	1680.00
P KS 92102 A7 610 RH HEADLAMP ASSY	1.00	2209.00	0.00	2209.00
P KS 84142 A7 000 INSULATOR - FENDER	1.00	28.00	0.00	28.00
M KS 66321 A7 000 RH FENDER PANEL	1.00	396.00	0.00	396.00
M KS 52910 A7 CA0 WHEEL ASSY - ALUMINI	1.00	1560.00	0.00	1560.00
P KS 0G032 50 037A CLIP - BUMPER	10.00	2.00	0.00	20.00

**Z NOTES**

ACCIDENT ON 11/09/2018 AT 5022 ANG MO KIO INDUSTRIAL PARK 2 CAR PARK  
 OWNER CLAIMING THIRD PARTY  
 REQUIRED REPLACEMENT CAR  
 TP # GT7458D TP INS : EQ

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting

**Confirm & accepted by**

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Parts	6,733.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,360.00
Others(Lub,etc)	0.00
Sundry	0.00
<b>Total(w/o GST)</b>	<b>12,093.00</b>

**Authorized signatory and company stamp**

Signature:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.