

Supplementary

VEHICLE NO.: YN4790C
 MAKE: ISUZU/NJR85AUE6W-3.0 D
 MODEL:
 YEAR OF MAKE: 2013
 CHASSIS NO.: NJR857030594

0

PAGE 1

COST / LIST

S/N	Parts Description	PART NUMBE	Qty	Remarks	
				COST	LIST
1	FRONT LH DOOR LOCK CYLINDER OUTER <i>not dgd</i>		1	✓	\$80.00
2	FRONT LH DOOR POWER WINDOW MOTOR <i>Rgd.</i>		1	✓	\$230.00
3	FRT PANEL & LHF DOOR STICKER <i>Not New</i>		1	✓	\$104.00
4	FRONT LH DOOR <i>Buckled</i>		1	✓	\$779.00
5	FOG LAMP LH <i>Buckled</i>		1	✓	\$292.00
6	FRT LH DOOR GLASS REAR CHANNEL <i>not dgd</i>		1	✓	\$65.00
7	FRT LH DOOR GLASS CHANNEL RUBBER <i>not dgd</i>		1	✓	\$84.00
8	FRONT GRILLE <i>Missing</i>		1	✓	\$373.00
9	FRT LH HOUSING UNDERSHIELD <i>Not Cracked</i>		1	✓	\$114.00
10	FRT LH A- PILLAR PLASTIC <i>not dgd</i>		1	✓	\$75.00
11	LH CONER SQUARE CLIPS		2	✓	\$20.80
12	LH CONER COVER ROUND BASE CLIPS <i>Not</i>		3	✓	\$23.40
13	FRONT PANEL TOP CLIPS		4	✓	\$24.00
14	FRONT PANEL BOTTOM CLIPS		2	✓	\$8.00
15	LH MIRROR STAY CAP <i>Missing</i>		1	✓	\$15.00
16	LH HEADLAMP LOWER RUBBER <i>Missing</i>		1	✓	\$19.00
17	LH ROUND SIDE MIRROR <i>Not New</i>		1	X	\$50.00
18	BIG AIR CON BLOWER MOTOR <i>Cracked</i>		1	✓	\$1,261.00
19	FRT DOOR SIDE LAMP BASE <i>Buckled</i>		1	✓	\$21.00
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					

→ not before
vno 649.

(A)

→ not before

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 29 Nov 2018)**Parts:** N/A ISUZU NJR85AUE6W 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/YN4790G/29/11/2018 11:45**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIRCON CONDENSER <i>Repeat</i>	0.00	0.00	*450.00 F
2	1		*AIRCON CONDENSER FAN MOTOR HOUSING <i>repeat.</i>	0.00	0.00	*280.00 F
Sub Total (S\$)						730.00
+ Margin on L,N Items 10.00% (S\$)						73.00
Total Parts (S\$)						803.00

F=Franchise part.

ComfortDelGro Engineering Pte Ltd/YN4790G/29/11/2018 11:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

320 UBI ROAD 3
Singapore 408649
Email: denisteo@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	M493107	Date of Loss:	23/06/2018
Vehicle Reg. No.:	YN4790G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SBS TRANSIT DTL PTE LTD		
Make/Model:	ISUZU NJR85AUE6W, 3.0 D (M)	Vehicle Reg. Date:	30/12/2013
Vehicle Colour:	WHITE		
Engine No:	4JJ1381184	Chassis No:	NJR857030594
Odometer:	63861 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (UBI)		

COST OF CLAIMS

	Amount
Parts	15,029.30
Miscellaneous Items	10.00
Labour	4,600.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,639.30
+ GST 7.00% (S\$)	1,374.75
Nett Amount (S\$)	21,014.05

This claim is handled by: **CHNG KING LYE JASMINE**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Sep 2018)

Parts: N/A ISUZU NJR85AUE6W 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/YN4790G/12/09/2018 20:14

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN <i>Cracked</i>	0.00	0.00	*1,645.00 F ✓
2	1		*FRONT WINDSCREEN RUBER <i>new</i>	142.80 0.00	0.00	*142.00 F ✓
3	1		*FRONT WINDSCREEN LOWER RUBBER <i>new</i>	142.80 0.00	0.00	*142.00 F ✓
4	1		*FRONT WINDSCREEN SIDE GARNISH RH <i>3 new new</i>	0.00	0.00	*26.00 F +
5	1		*FRONT WINDSCREEN SIDE GARNISH LH	0.00	0.00	*26.00 F +
6	1		*FRONT PANEL <i>Distorted</i>	0.00	0.00	*720.00 F ✓
7	1		*FRONT PANEL ISUZU WORDING <i>new</i>	0.00	0.00	*120.00 F ✓
8	1		*FRONT PANEL LH SIDE <i>Distorted</i>	0.00	0.00	*279.00 F ✓
9	1		*FRONT PANEL LH SIDE TOP COVER <i>missing</i>	47.60 0.00	0.00	*47.00 F ✓
10	1		*HEAD LAMP LH <i>Cracked</i>	0.00	0.00	*441.00 F ✓
11	1		*HEAD LAMP RH <i>Cracked</i>	0.00	0.00	*441.00 F ✓
12	1		*SIDE LAMP LH <i>Cracked</i>	0.00	0.00	*153.00 F ✓
13	1		*SIDE LAMP RH <i>Wt</i>	0.00	0.00	*153.00 F ✓
14	1		*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*546.00 F ✓
15	1		*FRONT BUMPER BRACKET LH <i>Bent</i>	0.00	0.00	*153.00 F ✓
16	1		*FOG LAMP LH <i>new</i>	0.00	0.00	*285.00 F ✓
17	1		*FOG LAMP BRACKET LH <i>new</i>	0.00	0.00	*98.00 F ✓
18	1		*LHF DOOR CYLINDER OUTER <i>new</i>	0.00	0.00	*80.00 F ✓
19	1		*LHF DOOR LOCK <i>Jammed</i>	0.00	0.00	*198.00 F ✓
20	1		*LHF DOOR RUBBER <i>Wt</i>	0.00	0.00	*98.00 F ✓
21	1		*LHF DOOR TRIM BOARD <i>Cracked</i>	0.00	0.00	*342.00 F ✓
22	1		*LHF DOOR GLASS <i>Shattered</i>	0.00	0.00	*402.00 F ✓
23	1		*LHF DOOR POWER WINDOW MOTOR <i>new</i>	0.00	0.00	*288.00 F +
24	1		*LHF DOOR POWER WINDOW REGULATOR <i>new</i>	0.00	0.00	*142.00 F +
25	1		*LHF POWER WINDOW SWITCH <i>new</i>	0.00	0.00	*204.00 F +
26	1		*LHF DOOR INNER LOCK LEVER <i>new</i>	0.00	0.00	*32.00 F +
27	1		*LHF DOOR GLASS INNER MOULDING <i>3 Delam</i>	0.00	0.00	*99.00 F ✓
28	1		*LHF DOOR GLASS OUTER MOULDING	0.00	0.00	*99.00 F ✓
29	1		*LHF DOOR GLASS FRONT CHANNEL <i>Bent</i>	0.00	0.00	*102.00 F ✓
30	1		*LHF DOOR GLASS REAR CHANNEL <i>Bent</i>	0.00	0.00	*51.00 F ✓
31	1		*LHF DOOR GLASS CHANNEL RUBBER <i>Bent</i>	0.00	0.00	*112.00 F ✓
32	1		*LHF DOOR OUTER GARNISH <i>new</i>	0.00	0.00	*185.00 F +
33	1		*LHF DOOR SIDE SIGNAL <i>new Cracked</i>	0.00	0.00	*91.00 F +
34	1		*LHF DOOR LOWER GARNISH <i>Delam</i>	0.00	0.00	*100.00 F ✓
35	1		*LHF DOOR HINGE TOP <i>Bent</i>	0.00	0.00	*119.00 F ✓
36	1		*LHF DOOR HINGE BOTTOM <i>Bent</i>	0.00	0.00	*119.00 F ✓
37	1		*LHF DOOR CHECKER <i>new</i>	0.00	0.00	*68.00 F +
38	1		*LHF DOOR CATCH <i>new</i>	0.00	0.00	*45.00 F +
39	1		*LHF A-PILLER RUBBER <i>Bent</i>	0.00	0.00	*150.00 F ✓
40	1		*LHF A-PILLER PANEL <i>Bent</i>	0.00	0.00	*1,425.00 F ✓
41	1		*LHF DOOR SPECKER <i>new</i>	0.00	0.00	*75.00 F ✓
42	1		*FRONT DASHBOARD <i>Cracked</i>	0.00	0.00	*1,170.00 F ✓
43	1		*LHF STEP PANEL <i>Bent</i>	0.00	0.00	*210.00 F +
44	1		*LHF DOOR STEP GARNISH <i>Wt</i>	0.00	0.00	*172.00 F ✓

ComfortDelGro Engineering Pte Ltd/YN4790G/12/09/2018 20:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKET AND REMOVE REINSTALL DAMAGE PARTS,TEST AND RETIFY FOR FUNCTION	New	120.00 ³⁰
2	TO REMOVE AND REPLACE A/C CONDENSER AND A/C SYSTEM AS WELL AS REFILL A/C GAS .	New	180.00 ¹²⁰
3	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	180.00 ¹²⁰
4	TO REMOVE AND REPLACE FRONT DASHBOARD	New	300.00 ²²⁰
5	TO DISMANTLE AND TRANFER DOOR,FITTINGS AND MECHANIS TO NEW DOOR	New	200.00 ⁸⁰
6	TO REMOVE AND REINSTALL WIPER COMPARTMENT SUCH WIPER MOTOR AND BLADE	New	120.00 ⁵⁰
7	TO REMOVE AND REINSTALL FRONT SEAT,CARPET ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIR	New	200.00 ¹⁰⁰
8	CUT & WELD,KNOCK AND REPAIR FRONT OUTER PANEL,LHF A-PILLER,LHF WHEEL HOUSE,STEP PANEL,FRONT INNER PANEL AND AFFECTED AREA	New	1,800.00 ¹⁴⁰⁰
9	PUTTY AND SPRAY PAINT,FRONT INNER PANEL,OUTER PANEL,A-PILLER,WHEEL HOUSE,STEP PANEL,FRONT DOOR AND AFFECTED AREA	New	1,500.00 ¹²⁰⁰
Gross Labour Cost (S\$)			4,600.00

ComfortDelGro Engineering Pte Ltd/YN4790G/12/09/2018 20:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lim 96893735

w/ 13/09/18

Not Authorised.

Exen TBA

120 days.

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*AIR CON CONDENSER <i>Bent</i>	0.00	0.00	*450.00 F ✓
46	1		*AIR CON CONDENSER BRACKET <i>Bent</i>	0.00	0.00	*270.00 F ✓
47	1		*AIR CON CONDENSER FAN MOTOR ?	0.00	0.00	*320.00 F "
48	1		*AIR CON CONDENSER FAN MOTOR BLADE ?	0.00	0.00	*95.00 F ?
49	1		*AIR CON CONDENSER FAN MOTOR HOUSING ?	0.00	0.00	*280.00 F ?
50	1		*AIR CON COIL ?	0.00	0.00	*340.00 F ?
51	1		*AIR CON VALVE ?	0.00	0.00	*115.00 F ?
52	1		*AIR CON DRIER ?	0.00	0.00	*98.00 F ?
53	1		*NUMBER PLATE <i>Bent</i>	0	0.00	*45.00 FS ✓
54	1		*IU BRACKET <i>3/4"</i>	0	0.00	*25.00 FS ✓
55	1		*SEALANT	0	0.00	*40.00 FS ✓

F=Franchise part, S=SpcNett.

Sub Total (S\$)	13,673.00
+ Margin on L,N Items 10.00% (S\$)	1,356.30
Total Parts (S\$)	15,029.30

ComfortDelGro Engineering Pte Ltd/YN4790G/12/09/2018 20:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Spark Car Care

ComfortDelgro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Finalization Form

Bill To : INDIA

Vehicle Number : YN4790C

Attn to : MR ADRIAN LING

Type Of Claim : OD

A. Spare parts \$9,147.60

F. Total Parts \$11,017.93

B. Supplementary \$3,638.20

G. Total Labour \$3,870.00

C. Nett Price

H. Total Repair \$14,887.93

D. Supp Nett Price \$-

I. Excess

E. S/Nett \$150.00

P/P Total 14,887.93

Total Spare Parts Price		\$12,785.80
Cost plus / List Down	15%	1,917.87
Total		10,867.93

Total Nett Price		\$-
Nett Price Less		\$-
Total		-

Lump Sum Less \$-

Lump Sum Rounding

Total Finalized

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In :

Total Repair Day

Date Survey :

LOU/ Day

Date Out :

Total LOU

Sat/Sun/Ph. :

Rental/Day

Authorized Repair Day

Total Rental

Submitted By / Date :

Confirmed By / Date :

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : YN4790C Case Owner : JOHARI
Make & Model : ISUZU/NJR85AUE6W-3.0 D Year Manufacture : 2013
Chassis No : NJR857030594 Engine No : 4JJ1381184
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	FRONT WINDSCREEN	1		\$1,645.00		
2	FRONT WINDSCREEN RUBBER	1		\$142.80		
3	FRONT WINDSCREEN RUBBER LOWER	1		\$142.80		
4	FRONT PANEL	1		\$720.00		
5	FRONT PANEL ISUZU WORDING	1		\$120.00		
6	FRONT PANEL LH SIDE	1		\$279.00		
7	FRONT PANEL LH SIDE TOP COVER	1		\$47.60		
8	FRONT HEAD LAMP LH	1		\$441.00		
9	FRONT HEAD LAMP RH	1		\$447.00		
10	FRONT SIDE LAMP LH	1		\$153.00		
11	FRONT SIDE LAMP RH	1		\$153.00		
12	FRONT BUMPER	1		\$546.00		
13	FRONT BUMPER BRACKET LH	1		\$153.00		
14	LHFDOOR LOCK	1		\$198.00		
15	LHF DOOR RUBBER	1		\$98.00		
16	LHF DOOR TRIM BOARD	1		\$342.00		
17	LHF DOOR GLASS	1		\$402.00		
18	LHF DOOR POWER WINDOW REGULATOR	1		\$142.80		
19	LHF DOOR GLASS INNER MOULDING	1		\$99.00		
20	LHF DOOR GLASS OUTER MOULDING	1		\$99.00		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : YN4790CCase Owner : JOHARIMake & Model : ISUZU/NJR85AUE6W-3.0 DYear Manufacture : 2013Chassis No : NJR857030594Engine No : 4JJ1381184Sales Order : 0Supplier : 0Order By : 0Type of Claim : 05

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
21	LHF DOOR GLASS FRONT CHANNEL	1		\$102.00		
22	LHF DOOR SIDE SIGNAL	1		\$91.80		
23	LHF DOOR GARNISH (AT DOOR LOWER)	1		\$100.30		
24	LHF DOOR HINGE TOP	1		\$119.00		
25	LHF DOOR HINGE BOTTOM	1		\$119.00		
26	LHF CANTER PILLER LOWER GARNISH	1		\$172.00		
27	FRONT DASHBOARD	1		\$1,170.00		
28	LHF DOOR STEP GARNISH	1		\$172.50		
29	AIR CON CONDENSER	1		\$450.00	✓	
30	AIR CON CONDENSER FAN MOTOR HOUSING	1		\$280.00	✓	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Type of Claim : 09

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 320 UBI ROAD 3 SINGAPORE 408649
 Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : YN4790C Case Owner : JOHARI
 Make & Model : ISUZU / NJR857030594 Year of Manufacture : 2013

S/No	Labour Description	Estimated Price	Adjusted Price
	To disconnect and check electrical wiring,wire socket,etc,remove and reinstall damage parts, test and retify for function.	\$120.00	\$30.00
	To remove and replace A/C condenser and A/C system as well as refill A/C gas and replace A/C fan motor complet.	\$280.00	\$120.00
	To remove and replace front windscreen.	\$180.00	\$120.00
	To remove and replace font dashboard	\$320.00	\$220.00
	To dismantle and transfer door, fittings and mechanis to new door facilitate repair (LHF)	\$280.00	\$80.00
	To remove and reinstall wiper compartment such wiper motor and wiper blades.	\$200.00	\$50.00
	Cut & weld , front outer panel , LHF A- pillar , LHF wheel housing and step panel. Knock & repair front inner penal.	\$1,500.00	\$1,400.00
	To remove and reinstall front passanger seat , carpet ,roof linning or upholstery to facilitate repairs	\$280.00	\$100.00
	Putty and spray paint , front inner panel , outer panel , A- pillar LHF , wheel house LHF , step panel LHF and front door LHF.	\$1,450.00	\$1,200.00
*	To knock , repair & straighten left hand front A pillar , wheelhouse , floor panel & affected areas.	\$550.00	300

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018 18:56	12 Sep 2018 20:14	13 Sep 2018 08:49	S\$14,605.43 Edit Estimates	S\$14,605.43 View Rpt		Pending for Survey Report Cancel Case
	Sendback Est	S\$19,639.30	Edit Adj Rpt				
Supp #1	16 Oct 2018 10:43	29 Nov 2018 11:22 S\$3,947.02	29 Nov 2018 11:22			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	29 Nov 2018 11:23	29 Nov 2018 11:24 S\$189.20	29 Nov 2018 11:24			(Combined)	Combined with Main Uncombine Suppl.
Supp #3	29 Nov 2018 11:44	29 Nov 2018 11:45 S\$803.00	29 Nov 2018 11:45			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SBS TRANSIT DTL PTE LTD, Co. Reg. No.: 201202781W		
Vehicle Reg. No.:	YN4790G	Date of Loss:	23/06/2018 02:00 - :59 [53 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / MC2018/2555	Policy/Cover Note No.:	M493107 (Comprehensive) Coverage: 30/08/2017 - 29/08/2018
		Excess:	S\$750.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3, 408649 Ubi - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (17/09/2018): Alert - Adj Mandate Approved (S\$17427.30) - YN4790G - Claim Handler: Lalitha Kri...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YN4790G (MC2018/2555)
 OD
 Jun 23 2018 2:00AM
 [SBS TRANSIT DTL PTE LTD]
 ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports					1 per page ▼	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)		Thumbnail	Print	
1	12/09/18 20:14	Repairer Estimates		Load HTM		
2	29/11/18 11:22	Repairer Estimates Suppl. #1		Load HTM		
3	29/11/18 11:24	Repairer Estimates Suppl. #2		Load HTM		
4	29/11/18 11:45	Repairer Estimates Suppl. #3		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	14/09/18 13:16	Adjuster Immediate Advice		Load HTM		

Photos/Images					3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	14/09/18 13:18	General View		Load JPG	☒	
2	14/09/18 13:18	General View		Load JPG	☒	
3	14/09/18 13:18	General View		Load JPG	☒	
4	14/09/18 13:18	General View		Load JPG	☒	
5	14/09/18 13:18	General View		Load JPG	☒	
6	14/09/18 13:18	General View		Load JPG	☒	
7	14/09/18 13:18	General View		Load JPG	☒	
8	14/09/18 13:18	General View		Load JPG	☒	
9	14/09/18 13:18	General View		Load JPG	☒	
10	14/09/18 13:18	General View		Load JPG	☒	
11	14/09/18 13:18	General View		Load JPG	☒	
12	14/09/18 13:18	General View		Load JPG	☒	
13	14/09/18 13:18	General View		Load JPG	☒	
14	14/09/18 13:18	General View		Load JPG	☒	
15	14/09/18 13:18	General View		Load JPG	☒	
16	14/09/18 13:18	General View		Load JPG	☒	
17	14/09/18 13:18	General View		Load JPG	☒	
18	14/09/18 13:18	General View		Load JPG	☒	
19	14/09/18 13:18	General View		Load JPG	☒	
20	14/09/18 13:18	General View		Load JPG	☒	
21	14/09/18 13:18	General View		Load JPG	☒	
22	14/09/18 13:18	General View		Load JPG	☒	
23	14/09/18 13:18	General View		Load JPG	☒	
24	14/09/18 13:18	General View		Load JPG	☒	
25	14/09/18 13:18	General View		Load JPG	☒	
26	14/09/18 13:18	General View		Load JPG	☒	
27	14/09/18 13:18	General View		Load JPG	☒	
28	14/09/18 13:18	General View		Load JPG	☒	
29	14/09/18 13:18	General View		Load JPG	☒	

Assessment Reports			1 per page ▼	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
30	14/09/18 13:18	General View	 Load JPG	☒
31	14/09/18 13:18	General View	 Load JPG	☒
32	14/09/18 13:18	General View	 Load JPG	☒
33	14/09/18 13:18	General View	 Load JPG	☒
34	14/09/18 13:18	General View	 Load JPG	☒
35	14/09/18 13:18	General View	 Load JPG	☒
36	14/09/18 13:18	General View	 Load JPG	☒
37	14/09/18 13:18	General View	 Load JPG	☒
38	14/09/18 13:18	General View	 Load JPG	☒
39	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
40	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
41	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
42	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
43	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
44	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
45	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
46	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
47	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
48	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
49	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
50	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
51	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
52	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
53	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
54	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
55	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
56	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
57	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
58	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
59	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
60	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
61	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
62	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
63	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
64	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
65	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
66	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
67	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
68	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
69	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
70	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
71	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
72	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
73	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
74	30/11/18 15:28	Reinspection Photo	 Load JPG	☒
75	30/11/18 15:28	Reinspection Photo	Load JPG	☒
76	30/11/18 15:28	Reinspection Photo	Load JPG	☒
77	30/11/18 15:28	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
78	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
79	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
80	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
81	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
82	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
83	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
84	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
85	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
86	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
87	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
88	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
89	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
90	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
91	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
92	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
93	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
94	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
95	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
96	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
97	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
98	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
99	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
100	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
101	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
102	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
103	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
104	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
105	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
106	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
107	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
108	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
109	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
110	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
111	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
112	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
113	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
114	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
115	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
116	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
117	30/11/18 15:28	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/09/18 08:46	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/18 13:17	ESTIMATE	 Load PDF	
2	29/11/18 10:20	supplementary	 Load PDF	
3	05/12/18 15:25	SUPPLEMENTARY	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III18016786/ATBS2

Date: 05/12/2018

REFERENCE

Insured/Claimant:	SBS TRANSIT DTL PTE LTD	Policy No:	M493107	
Date of Loss:	23/06/2018	Nature of Claim:	OD	Claim No: MC2018/2555

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN4790G		
Make & Model:	ISUZU NJR85AUE6W, 3.0 D (M)	Engine No:	4JJ1381184
Reg. Date:	30/12/2013 (Man. Year: 2013)	Chassis No:	NJR857030594
Colour:	Orange	Odometer:	0 km
Engine Capacity:	2999 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/75R15	Rear Tyre Size:	195/75R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,968.52	10,975.43	8,993.09	45.04
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	4,600.00	3,620.00	980.00	21.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,578.52	14,605.43	9,973.09	40.58
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	24,578.52	13,855.43	10,723.09	43.63
+ GST 7.00/7.00% (S\$)	1,720.49	969.88	750.61	43.63
Nett Amount (S\$)	26,299.01	14,825.31	11,473.70	43.63

INSPECTION

Date of Assignment:	13/09/2018	
Date Inspected:	13/09/2018	Inspected At: ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3 Singapore 408649
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

09

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Dec 2018)	
Parts:	N/A	ISUZU NJR85AUE6W 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN4790G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN (WCP)	Cracked	1,645.00 F	*1,645.00 FL
2	1		*FRONT WINDSCREEN RUBER (WCP)	Necessary	142.00 F	*142.80 FL
3	1		*FRONT WINDSCREEN LOWER RUBBER (WCP)	Necessary	142.00 F	*142.80 FL
4	1		*FRONT WINDSCREEN SIDE GARNISH RH (WCP)	Not Necessary	26.00 F	*- FL
5	1		*FRONT WINDSCREEN SIDE GARNISH LH (WCP)	Not Necessary	26.00 F	*- FL
6	1		*FRONT PANEL (WCP)	Distorted	720.00 F	*720.00 FL
7	1		*FRONT PANEL ISUZU WORDING (WCP)	Necessary	120.00 F	*120.00 FL
8	1		*FRONT PANEL LH SIDE (WCP)	Dented	279.00 F	*279.00 FL
9	1		*FRONT PANEL LH SIDE TOP COVER (WCP)	Missing	47.00 F	*47.60 FL
10	1		*HEAD LAMP LH (WCP)	Cracked	441.00 F	*441.00 FL
11	1		*HEAD LAMP RH (WCP)	Cracked	441.00 F	*447.00 FL
12	1		*SIDE LAMP LH (WCP)	Cracked	153.00 F	*153.00 FL
13	1		*SIDE LAMP RH (WCP)	Cut	153.00 F	*153.00 FL
14	1		*FRONT BUMPER (WCP)	Distorted	546.00 F	*546.00 FL
15	1		*FRONT BUMPER BRACKET LH (WCP)	Bent	153.00 F	*153.00 FL
16	1		*FOG LAMP LH (WCP)	Not Necessary	285.00 F	*- FL
17	1		*FOG LAMP BRACKET LH (WCP)	Not Necessary	98.00 F	*- FL
18	1		*LHF DOOR CYLINDER OUTER (WCP)	Not Necessary	80.00 F	*- FL
19	1		*LHF DOOR LOCK (WCP)	Jammed	198.00 F	*198.00 FL
20	1		*LHF DOOR RUBBER (WCP)	Cut	98.00 F	*98.00 FL
21	1		*LHF DOOR TRIM BOARD (WCP)	Cracked	342.00 F	*342.00 FL
22	1		*LHF DOOR GLASS (WCP)	Shattered	402.00 F	*402.00 FL
23	1		*LHF DOOR POWER WINDOW MOTOR (WCP)	Not Necessary	288.00 F	*- FL
24	1		*LHF DOOR POWER WINDOW REGULATOR (WCP)	Damaged	142.00 F	*142.80 FL
25	1		*LHF POWER WINDOW SWITCH (WCP)	Not Necessary	204.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*LHF DOOR INNER LOCK LEVER (WCP)	Not Necessary	32.00 F	*- FL
27	1		*LHF DOOR GLASS INNER MOULDING (WCP)	Deformed	99.00 F	*99.00 FL
28	1		*LHF DOOR GLASS OUTER MOULDING (WCP)	Deformed	99.00 F	*99.00 FL
29	1		*LHF DOOR GLASS FRONT CHANNEL (WCP)	Bent	102.00 F	*102.00 FL
30	1		*LHF DOOR GLASS REAR CHANNEL (WCP)	Not Necessary	51.00 F	*- FL
31	1		*LHF DOOR GLASS CHANNEL RUBBER (WCP)	Not Necessary	112.00 F	*- FL
32	1		*LHF DOOR OUTER GARNISH (WCP)	Not Necessary	185.00 F	*- FL
33	1		*LHF DOOR SIDE SIGNAL (WCP)	Cracked	91.00 F	*91.80 FL
34	1		*LHF DOOR LOWER GARNISH (WCP)	Deformed	100.00 F	*100.30 FL
35	1		*LHF DOOR HINGE TOP (WCP)	Bent	119.00 F	*119.00 FL
36	1		*LHF DOOR HINGE BOTTOM (WCP)	Bent	119.00 F	*119.00 FL
37	1		*LHF DOOR CHECKER (WCP)	Not Necessary	68.00 F	*- FL
38	1		*LHF DOOR CATCH (WCP)	Not Necessary	45.00 F	*- FL
39	1		*LHF A-PILLER RUBBER (WCP)	Not Necessary	150.00 F	*- FL
40	1		*LHF A-PILLER PANEL (WCP)	Not Necessary	1,425.00 F	*- FL
41	1		*LHF DOOR SPECKER (WCP)	Not Necessary	75.00 F	*- FL
42	1		*FRONT DASHBOARD (WCP)	Cracked	1,170.00 F	*1,170.00 FL
43	1		*LHF STEP PANEL (WCP)	Not Necessary	210.00 F	*- FL
44	1		*LHF DOOR STEP GARNISH (WCP)	Cut	172.00 F	*172.50 FL
45	1		*AIR CON CONDENSER (WCP)	Bent	450.00 F	*450.00 FL
46	1		*AIR CON CONDENSER BRACKET (WCP)	Not Necessary	270.00 F	*- FL
47	1		*AIR CON CONDENSER FAN MOTOR (WCP)	Not Necessary	320.00 F	*- FL
48	1		*AIR CON CONDENSER FAN MOTOR BLADE (WCP)	Not Necessary	95.00 F	*- FL
49	1		*AIR CON CONDENSER FAN MOTOR HOUSING (WCP)	Cracked	280.00 F	*280.00 FL
50	1		*AIR CON COIL (WCP)	Not Necessary	340.00 F	*- FL
51	1		*AIR CON VALVE (WCP)	Not Necessary	115.00 F	*- FL
52	1		*AIR CON DRIER (WCP)	Not Necessary	98.00 F	*- FL
53	1		*NUMBER PLATE	Bent	45.00 FS	*45.00 FS
54	1		*IU BRACKET	Necessary	25.00 FS	*25.00 FS
55	1		*SEALANT	Necessary	40.00 FS	*80.00 FS
Supplementary #1						
56	1		*FRONT LH DOOR LOCK CYLINDER OUTER (WCP)	Damaged	80.00 F	*80.00 FL
57	1		*FRONT LH DOOR POWER WINDOW MOTOR (WCP)	Damaged	230.00 F	*230.00 FL
58	1		*FRT PANEL & LHF DOOR STICKER (WCP)	Necessary	104.00 F	*104.00 FL
59	1		*FRONT LH DOOR (WCP)	Buckled	779.00 F	*779.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
60	1		*FOG LAMP LH (WCP)	Cracked	292.00 F	*292.00 FL
61	1		*FRT LH DOOR GLASS REAR CHANNEL (WCP)	Damaged	65.00 F	*65.00 FL
62	1		*FRT LH DOOR GLASS CHANNEL RUBBER (WCP)	Damaged	84.00 F	*84.00 FL
63	1		*FRONT GRILLE (WCP)	Missing	373.00 F	*373.00 FL
64	1		*FRT LH HOUSING UNDERSHIELD (WCP)	Crumpled	114.00 F	*114.00 FL
65	1		*FRT LH A- PILLAR PLASTIC (WCP)	Deformed	75.00 F	*75.00 FL
66	2		*LH CONER SQUARE CLIPS (WCP)	Necessary	20.80 F	*20.80 FL
67	3		*LH CONER COVER ROUND BASE CLIPS (WCP)	Necessary	23.40 F	*23.40 FL
68	4		*FRONT PANEL TOP CLIPS (WCP)	Necessary	24.00 F	*24.00 FL
69	2		*FRONT PANEL BOTTOM CLIPS (WCP)	Necessary	8.00 F	*8.00 FL
70	1		*LH MIRROR STAY CAP (WCP)	Missing	15.00 F	*15.00 FL
71	1		*LH HEADLAMP LOWER RUBBER (WCP)	Missing	19.00 F	*19.00 FL
72	1		*BIG AIR CON BLOWER MOTOR (WCP)	Cracked	1,261.00 F	*1,261.00 FL
73	1		*FRT DOOR SIDE LAMP BASE (WCP)	Cracked	21.00 F	*21.00 FL
Supplementary #2						
74	1		*lhf center panel garnish (WCP)	Deformed	172.00 F	*172.00 FL
Supplementary #3						
75	1		*AIRCON CONDENSER (WCP)	Repeated	450.00 F	*- FL
76	1		*AIRCON CONDENSER FAN MOTOR HOUSING (WCP)	Repeated	280.00 F	*- FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	18,163.20	12,885.80
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	1,910.37
+ Margin on L,N Items 10.00/0.00% (\$\$)	1,805.32	0.00
Total Parts (\$\$)	19,968.52	10,975.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKET AND REMOVE REINSTALL DAMAGE PARTS,TEST AND RETIFY FOR FUNCTION	New	120.00	30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND A/C SYSTEM AS WELL AS REFILL A/C GAS .	New	180.00	120.00
3	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	180.00	120.00
4	TO REMOVE AND REPLACE FRONT DASHBOARD	New	300.00	220.00
5	TO DISMANTLE AND TRANFER DOOR,FITTINGS AND MECHANIS TO NEW DOOR	New	200.00	80.00
6	TO REMOVE AND REINSTALL WIPER COMPARTMENT SUCH WIPER MOTOR AND BLADE	New	120.00	50.00
7	TO REMOVE AND REINSTALL FRONT SEAT,CARPET ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIR	New	200.00	100.00
8	CUT & WELD,KNOCK AND REPAIR FRONT OUTER PANEL,LHF A-PILLER,LHF WHEEL HOUSE,STEP PANEL,FRONT INNER PANEL AND AFFECTED AREA	New	1,800.00	1,400.00
9	PUTTY AND SPRAY PAINT,FRONT INNER PANEL,OUTER PANEL,A-PILLER,WHEEL HOUSE,STEP PANEL,FRONT DOOR AND AFFECTED AREA	New	1,500.00	1,200.00
10	TO KNOCK, REPAIR & STRAIGHTEN LEFT HAND FRONT A PILLAR, WHEELHOUSE, FLOOR PANEL & AFFECTED AREAS.	New	-	300.00
Gross Labour Cost (S\$)			4,600.00	3,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >