



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SJL7562S
Date of Accident : 12 September 2018

Miss Nur Azera Binte Johana

Date : 14 September 2018

Not Authorised
L/L/L
13/9/18
Take photo. After repair
4 day 4/5 @ 3000/-

Estimate To Repair SLV7234M - Honda Stream 1.8A
Chassis No : RN61053586

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>body</i>	\$ 903.20
02	1 pc	tailgate lid lock <i>2/1/1</i>	\$ 109.40
03	1 pc	tailgate lid lock stricker <i>1/1</i>	\$ 27.50
04	1 pc	tailgate lid weatherstrip <i>2/1/1</i>	\$ 121.60
05	1 pc	tailgate lid inner trimboard <i>one</i>	\$ 141.00
06	1 pc	tailgate lid inner closing garnish <i>1/1</i>	\$ 25.00
07	2 pc	tailgate lid rubber stopper @ \$12.50 <i>1/1</i>	\$ 25.00
08	2 pc	tailgate lid absorber stay @ \$118.60 <i>1/1</i>	\$ 237.20
09	1 pc	tailgate lid stream badge <i>ML</i>	\$ 31.60
10	1 pc	tailgate lid outer garnish <i>1/1</i>	\$ 162.80
11	1 pc	tailgate lid outer garnish emblem badge <i>1/1</i>	\$ 21.90
12	1 pc	rear windshield glass weatherstrip <i>ML</i>	\$ 65.00
13	2 pc	rear license plate lamp @ \$32.80 <i>1/1</i>	\$ 65.60
14	1 pc	rear end panel <i>R</i>	\$ 306.70
15	1 pc	rear end panel inner trim <i>1/1</i>	\$ 116.70
16	1 pc	rear bumper <i>Dis</i>	\$ 588.90
17	2 pc	rear bumper side retainer @ \$19.40 <i>3/1</i>	\$ 38.80
18	2 pc	rear bumper side holder @ \$10.00 <i>1/1</i>	\$ 20.00
19	8 pc	rear bumper clips @ \$3.90 <i>ML</i>	\$ 31.20
20	1 pc	rear bumper tow cover <i>1/1</i>	\$ 13.90
21	1 pc	rear bumper screw <i>1/1</i>	\$ 16.00
22	1 pc	n/s rear lamp <i>one</i>	\$ 385.50
23	3 pc	rear lamp clip holder @ \$7.00 <i>1/1</i>	\$ 21.00
Less 20 %			\$ 3,475.50
			\$ 695.10
			\$ 2,780.40
<u>SPECIAL NETT ITEMS</u>			
24	1 pc	rear windshield glass sealant <i>ML</i>	\$ 180.00
25	1 pc	rear windshield glass sponge <i>ML</i>	\$ 100.00
26	1 pc	rear license plate <i>1/1</i>	\$ 60.00
27	1 pc	back off camera lens <i>1/1</i>	\$ 380.00
28	1 pc	rear bumper parking sensor <i>short</i>	\$ 450.00
			\$ 1,170.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit rear windscreen glass.	\$ 180.00
02		To rust-proofing of the affected areas.	\$ 150.00

Handwritten notes and calculations:
 2430.1
 1944.08
 40 S.N
 30 S.N
 2005.2
 270
 120
 50



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SJL7562S
Date of Accident : 12 September 2018

Miss Nur Azera Binte Johana

Date : 14 September 2018

Estimate To Repair SLV7234M - Honda Stream 1.8A
Chassis No : RN61053586

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 160.00
04		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
05		To reinstall of rear bumper parking sensor.	\$ 120.00
06		To check electrical lighting concerned.	\$ 60.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
08		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,820.00
		Total	\$ 6,770.40

80
60
40
30
150
600
1540

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1944.08
S.N-270
1650-1540
3754.08
202
3003.24