

15/5/2010

INS. CASE OWNER:

Lynthia

CC 4/AXA1801

6878, Uurb352

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

14/6/18

Date / Time:

14/6/18

Registered in Merimen:

14/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 966XP

Name of Insured:

TRANS-IPB SERVICES PW

Insured Tel No.:

HP:

Excess Sec II :SS

5500

D.O.A.:

5/6/18

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

HOW MOLE SOON

Driver Tel No.:

(V/L) YES / NO

Claim No.:

WU74241

Policy No.:

WY1P1080570

Make / Model:

CHEVROLET

Place of Accident:

ELP

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUB 8265X

INSRS:
WSP:
Tel:
Liability:
RMKS:RICO
60INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

14/6/18
TH

SHD 966XP

SUB 8265X

FILE REASON: 3 VEN CC OIO LOST.

09.1.19

FILE PASS TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 09.01.19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45 \$513,500

(14 days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

W/L

\$514,445.00

3 VEN CC OIO LOST

Loss of Rental (LOR):

\$5 1,700.00

(17 days) x 100

Loss of Use (LOU):

\$5 -

(5 x days)

Loss of Income (LOI):

\$5 -

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

\$5 36.45

Medical:

\$5 -

Disbursement:

\$5 120.00

(e.g. Tow/Independent)

Legal Cost

\$5 -

Total:

\$5 16,301.45

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 16,301.45

Name 1:

RICO 60 AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

350

COPY SENT

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG8265Xat Workshop m/s Rico

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 93

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LYA61859

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLG8265X Yr Regn: 10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Subaru Legacy GT c.c. 1600Colour: Carm A/C: Insured / Std / NI / NASp. Reading: 35198 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1VM4K5566002314

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 7/9/18 D.O.I. 14/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sys. Ins. Rep 10/11. Not 3/1414s \$13,500 (REQ: 9)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1)

☐ : Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS, SI☐ : Interview (\$ _____) ☐ : Photos☐ : Tech. Invs (\$ _____) ☐ : Others☐ : Weekend (\$ _____) ☐ : TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Survey Fee:

Transportation:

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/AXA18016818/Uub3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 14-09-2018



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 9662P	Veh. Inspected	SLG 8265X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/09/2018	Inspection Date	14/09/2018
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2018		14 Sep 2018 09:39 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		[Created by insurer]
Main Claimant:	GOH CHUAN YONG (WU JUNRONG), ID: S8126780D		
Vehicle Reg. No.:	SLG8265X	Date of Loss:	07/09/2018 19:00 - :59
Claim Type:	TP / C0474341	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHD9662P	Policy No. (Claimant):	
		Excess:	\$5,000.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]		
Driver/Custodian (Insured):	CHOW HOCK SOON (54 / Male), NRIC: S1608952D, Tel: +6590294935		

ASSOCIATED MAIL RECEIVED

- AXA_SG (14/09/2018): New TP Assignment - C0474341/P1680520

View All


Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

14/09/2018 @ 9:03am
John veh in
marus.



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLG 8265 X
SUBARU LEVORG
JF1VM4K55GG002314

Not Authorized
4/5/13:500
14/9/18
15 day.

AFA

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT BONNET 2x		2792.00 X
2	FRONT BONNET SEAL 11x		12.60 X
4	FRONT BONNET INSULATOR 11x		102.00 X
6	FRONT BONNET LOCK 7w/ ✓	65.80	65.80 ✓
7	FRONT BUMPER 70cm ✓	540.00	540.00 ✓
8	FRONT BUMPER SIDE RETAINER L+R 64 ✓	35.60	70.20 x2 ✓
9	FRONT BUMPER BRACKET L+R 64 ✓	64.80	32.40 x2 ✓
10	FRONT BUMPER GRILLE BASE 2.2 ✓		42.60 ✓
11	FRONT BUMPER GRILLE CHROME MOULDING CRA ✓		22.50 ✓
12	FRONT BUMPER GRILLE LOGO 2.2 ✓		18.70 ✓
13	FRONT BUMPER LOWER GRILLE 70cm ✓		50.40 ✓
14	FRONT BUMPER TOW COVER m X		14.40 X
15	ENGINE UNDERCOVER 70cm ✓	180.00	180.00 ✓
17	HEADLAMP ASSY L+R 2.2 ✓ 20.50 x 2 = 41.00	44320	2160 x2 ✓
18	HEADLAMP LOWER BRACKET L+R 2.2 ✓	864.80	32.40 x2 ✓
19	HEADLAMP WASHER MOTOR L+R 21x		68x2 ✓
20	HEADLAMP WASHER CAP L+R 21x X		47.60 x2 X
21	FOG LAMP ASSY L+R 11x		425 x2 X
22	FOG LAMP COVER L+R 11x		72 x2 X
23	FOG LAMP CHROME MOULDING L+R 11x		80 x2 X
24	SIGNAL LAMP L+R 11x		140.30 x2 X
25	SIGNAL LAMP BRACKET L+R 11x		80.00 x2 X
26	FRONT BUMPER REINFORCEMENT Bel ✓		152.00 ✓
27	FRONT SUPPORT PANEL 2.2 ✓		522.00 ✓
28	FRONT BRACE PANEL Bel ✓		480.00 ✓
29	AIR DUCT INTAKE 2.2 ✓	180	65.40 ✓
30	A/C CONDENSOR ASSY Bel/pur ✓		510.00 ✓
31	A/C LOW PRESSURE PIPE 11x		144.80 X
32	A/C HIGH PRESSURE PIPE 11x		180.00 X
33	A/C DISCHARGE PIPE 11x		180.00 X
34	OIL COOLER ASSY 11x		920.00 X
35	OIL COOLER PIPE 11x		232.00 X
36	REAR WINDSCREEN COMPLETE SET WITH MOULDING , 2.2 110		910.80 ✓
37	BOOTLID 3.0 ✓ 600 ✓		1072.80 ✓
38	BOOTLID LOCK 7w/ ✓		36.00 ✓
39	BOOTLID WEATHERSTRIP 70cm ✓		106.80 ✓
40	BOOTLID LOGO 2.2 ✓		68.40 ✓
41	BOOTLID CENTER CHROME MOULDING 2.2 ✓		158.40 ✓
42	BOOTLID EMBLEM - SUBARU 70 ✓		82.80 ✓
43	BOOTLID EMBLEM - SYMMETRICAL 2.2 ✓		48.50 ✓

44	BOOTLID EMBLEM - AWD	new ✓		\$42.00	✓
45	BOOTLID EMBLEM - LEVORG	new ✓		\$39.60	✓
46	BOOTLID LAMP L+R	1P/S one 1P C	1476	\$228.00 X2	1P C
47	BOOTLID INNER TRIM	17 X		\$198.00	X
49	REAR BUMPER	7.5 ✓	840	\$840.00	✓
51	REAR BUMPER SIDE RETAINER L+R	24 1/5 1P C		\$35 X2	1P C
52	REAR BUMPER BRACKET L+R	25 X		\$25.20 X2	X
53	REAR BUMPER REINFORCEMENT	3m ✓		\$278.80	✓
54	REAR BUMPER REFLECTOR L+R	570 1/5 1P C		\$24.20 X2 1P C	
55	REAR BUMPER SENSOR	5 hrs		\$280.70	✓
56	REAR END PANEL	2.13.00 ✓		\$252.00	✓
57	REAR END PANEL TOP GARNISH	2w1 ✓		\$45.8	✓
59	SPARE WHEEL PANEL	R X		\$396.00	X
60	SPARE WHEEL PANEL TOP BOARD	17 X		\$288.00	X
61	SPARE WHEEL PANEL SIDE BOARD	201m ✓		\$90.00	✓
62	SPARE WHEEL PANEL QUARTER PANEL LH	13.1300 ✓	650	\$216.00	✓
63	SPARE WHEEL CONTAINER BOX/ SPONGE	70m ✓		\$180.00	✓
64	LH REAR FENDER	3.13.00 ✓		\$864.00	✓
65	LH REAR FENDER COWLING	70. ✓		\$54.00	✓
67	LH REAR FENDER INNER TRIM	215 ✓		\$417.60	✓
69	LH REAR FENDER AIR DUCT	7w1 ✓		\$60.00	✓
70	LH REAR FENDER QUARTER GLASS COMPLETE SET WITH MOULDING	12. ✓		\$583.20	✓
71	LH REAR CHASSIS MEMBER	12 X		\$716.00	X
72	LH REAR CHASSIS EXTENSION	12 X		\$240.00	X
73	LH REAR WHEEL HOUSING	12 X		\$1480.70	X
74	LH TAILLAMP	320 ✓		\$425.00	✓
75	LH TAILLAMP PANEL	3.1300 ✓		\$25.60	✓
77	LH TAILLAMP LOWER BRACKET	cm ✓		\$22.80	✓
78	LH REAR DOOR	12 X		\$648.00	X
79	LH REAR DOOR LOCK	17 X		\$180.00	X
80	LH REAR DOOR WEATHERSTRIP	17 X		\$126.00	X
81	EXHAUST PIPE LH	31 + 7w1 ✓		\$540.00	✓
82	EXHAUST PIPE CHROME TIPS	20 ✓		\$100.00	✓
83	EXHAUST PIPE GASKET	2m ✓		\$18.00	✓
84	EXHAUST PIPE MOUNTING	2m ✓		\$16.50	✓
85	EXHAUST PIPE CENTER PIPE	7w1 ✓		\$612.00	✓
86	EXHAUST PIPE HEAT SHEILD	24 ✓		\$432.00	✓
87	LH REAR DAMPER	~ 1 X		\$228.60	X
88	LH REAR LOWER ARM	17 X		\$166.60	X
89	LH REAR THRUST ARM	~ 1 X		\$100.80	X
90	LH REAR TOE LINK	11 X		\$144.00	X
91	LH REAR WHEEL BEARING	17 X		\$212.40	X
92	LH REAR BEARING HUB	17 X		\$224.80	X
93	CROSSMEMBER ASSY	20/20 ✓		\$644.40	✓
94	CROSSMEMBER GUIDE BAR	31 ✓		\$43.20	✓
95	STABILAZER BAR	34 ✓		\$120.00	✓
96	STABILAZER BAR LINK	17 X		\$92.00	X
97	DRIVESHAFT ASSY LH	17 X		\$800.00	X

98	AXLE ASSY	17 X			\$ 358.00	X
99	CRUISE CONTROL SENSOR	311 X			\$ 385.00	X
				PARTS TOTAL = \$18,750.80		
				LESS 20% = \$15,005.44	SUBTOTAL	\$ -
				LESS 10%		\$ -
				PARTS TOTAL		\$ -
SPECIAL NETT			QTY	PRICE		
FRONT NUMBER PLATE	set 40	40		\$	80.00	
REAR NUMBER PLATE	set 40	40		\$	80.00	
REVERSE SENSOR	Replaced	X		\$	250.00	
REVERSE CAM	Shocks	350		\$	400.00	
REAR END PANEL SEALANT	14 50	50		\$	100.00	
SPARE WHEEL PANEL SEALANT	11	X		\$	100.00	
WHEEL HOUSING SEALANT	11	X		\$	100.00	
RADIATOR COOLANT	11	X		\$	150.00	
SPARE WHEEL INSULATOR	11	X		\$	400.00	
REAR FENDER SEALANT	11	X		\$	100.00	
FRONT BONNET SEAL CLIPS	11	X		\$	80.00	
FRONT BONNET INSULATOR CLIPS	11	X		\$	80.00	
FRONT BUMPER CLIPS	all	50		\$	100.00	
ENGINE UNDERCOVER CLIPS	11	X		\$	100.00	
BOOTLID INNER TRIM CLIPS	11	X		\$	100.00	
REAR BUMPER CLIPS	all	50		\$	100.00	
REAR END PANEL TOP GARNISH CLIPS	11	X		\$	80.00	
LH REAR FENDER COWLING CLIPS	11	X		\$	100.00	
LH REAR FENDER INNER TRIM CLIPS	11	X		\$	100.00	
LH TAILLAMP CLIPS	11	X		\$	40.00	
		580				
				SPECIAL NETT TOTAL	\$	2,640.00
LABOUR			QTY	PRICE		
TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	2000			\$	2,400.00	
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800			\$	2,200.00	
TO RUST PROOF ACCIDENT AFFECTED AREA	120			\$	180.00	
TO RNR REAR WINDSCREEN	120			\$	150.00	
TO RNR REAR BOOT MECHANISM	60			\$	200.00	
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	40			\$	400.00	
TO RNR REVERSE SENSOR & CHECK FUNCTION.	50			\$	80.00	
TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	100			\$	250.00	
TO RNR UNDERCARRIAGE SYSTEM	300			\$	800.00	
TO CHECK WHEEL ALIGNMENT	60			\$	150.00	
TO RNR A/C CONDENSOR ASSY AND REFILL GAS	100			\$	150.00	
TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	30			\$	80.00	
TO RNR TYRE AND WHEEL BALANCING	11 X			\$	100.00	
TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11 X			\$	250.00	
TO DO WATER LEAK TEST .	11 X			\$	100.00	
TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11 X			\$	150.00	
TO REPROGRAM AND CODING FOR HEADLAMP ASSY	11 X			\$	400.00	
		14820				

	LABOUR TOTAL	\$ 8,040.00
	GRAND TOTAL COST	\$ 10,680.00

PAGE 2 OF 2

39268.90

2-16278.90
 less 502
139.45
 S.N + 580.00
 labor + 4820.00
13539.45

8427
 147



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060
VEHICLE NUM: SLG 8265 X
MAKE & MODEL: SUBARU LEVORG
MILEAGE:
TYRE:
CHASSIS NUM: JF1VM4K55GG002314

Not Allowed
w/br
1/59
14/9/18
the phone number

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	
1	FRONT BONNET 2X		
2	FRONT BONNET SEAL 11X		
4	FRONT BONNET INSULATOR 11X		
6	FRONT BONNET LOCK 2wi ✓		
7	FRONT BUMPER Torn ✓		
8	FRONT BUMPER SIDE RETAINER L+R 64 ✓		
9	FRONT BUMPER BRACKET L+R 64 ✓		
10	FRONT BUMPER GRILLE BASE CRA ✓		
11	FRONT BUMPER GRILLE CHROME MOULDING CRA ✓		
12	FRONT BUMPER GRILLE LOGO CRA ✓		
13	FRONT BUMPER LOWER GRILLE Torn ✓		
14	FRONT BUMPER TOW COVER 11X ✓		
15	ENGINE UNDERCOVER Torn ✓		
17	HEADLAMP ASSY L+R CRA ✓		
18	HEADLAMP LOWER BRACKET L+R CRA ✓		
19	HEADLAMP WASHER MOTOR L+R 11X		
20	HEADLAMP WASHER CAP L+R 11X		
21	FOG LAMP ASSY L+R 11X		
22	FOG LAMP COVER L+R 11X		
23	FOG LAMP CHROME MOULDING L+R 11X		
24	SIGNAL LAMP L+R 11X		
25	SIGNAL LAMP BRACKET L+R 11X		
26	FRONT BUMPER REINFORCEMENT Bel ✓		
27	FRONT SUPPORT PANEL Bel ✓		
28	FRONT BRACE PANEL Bel ✓		
29	AIR DUCT INTAKE 2wi ✓		
30	A/C CONDENSOR ASSY 3		
31	A/C LOW PRESSURE PIPE 11X		
32	A/C HIGH PRESSURE PIPE 11X		
33	A/C DISCHARGE PIPE 11X		
34	OIL COOLER ASSY 11X		
35	OIL COOLER PIPE 11X		
36	REAR WINDSCREEN COMPLETE SET WITH MOULDING 11X		
37	BOOTLID 30 ✓		
38	BOOTLID LOCK 2wi ✓		
39	BOOTLID WEATHERSTRIP 2wi ✓		
40	BOOTLID LOGO rec ✓		
41	BOOTLID CENTER CHROME MOULDING One ✓		
42	BOOTLID EMBLEM - SUBARU rec ✓		
43	BOOTLID EMBLEM - SYMMETRICAL rec ✓		

44	BOOTLID EMBLEM - AWD	nee ✓	
45	BOOTLID EMBLEM - LEVORG	nee ✓	
46	BOOTLID LAMP L+R	RP/S one 1pc	
47	BOOTLID INNER TRIM	11x	
49	REAR BUMPER	DP5 ✓	
51	REAR BUMPER SIDE RETAINER L+R	24 1/5 1pc	
52	REAR BUMPER BRACKET L+R	25x	
53	REAR BUMPER REINFORCEMENT	3at ✓	
54	REAR BUMPER REFLECTOR L+R	B70 1/5 1pc	
55	REAR BUMPER SENSOR	5 hrs	
56	REAR END PANEL	2at 1/5 ✓	
57	REAR END PANEL TOP GARNISH	2w1 ✓	
59	SPARE WHEEL PANEL	Rx	
60	SPARE WHEEL PANEL TOP BOARD	11x	
61	SPARE WHEEL PANEL SIDE BOARD	7011 ✓	
62	SPARE WHEEL PANEL QUARTER PANEL LH	3at 500 ✓	
63	SPARE WHEEL CONTAINER BOX/ SPONGE	7011 ✓	
64	LH REAR FENDER	3.65 00 ✓	
65	LH REAR FENDER COWLING	701A ✓	
67	LH REAR FENDER INNER TRIM	DIS ✓	
69	LH REAR FENDER AIR DUCT	7w1 ✓	
70	LH REAR FENDER QUARTER GLASS COMPLETE SET WITH MOULDING	nee ✓	
71	LH REAR CHASSIS MEMBER	12x	
72	LH REAR CHASSIS EXTENSION	12x	
73	LH REAR WHEEL HOUSING	12x	
74	LH TAILLAMP	320 ✓	
75	LH TAILLAMP PANEL	3at 500 ✓	
77	LH TAILLAMP LOWER BRACKET	2w1 ✓	
78	LH REAR DOOR	12x	
79	LH REAR DOOR LOCK	11x	
80	LH REAR DOOR WEATHERSTRIP	11x	
81	EXHAUST PIPE LH	3at 1w1 ✓	
82	EXHAUST PIPE CHROME TIPS	DP ✓	
83	EXHAUST PIPE GASKET	nee ✓	
84	EXHAUST PIPE MOUNTING	nee ✓	
85	EXHAUST PIPE CENTER PIPE	7w1 - ?	
86	EXHAUST PIPE HEAT SHEID	3at ✓	
87	LH REAR DAMPER	11x	
88	LH REAR LOWER ARM	11x	
89	LH REAR THRUST ARM	11x	
90	LH REAR TOE LINK	11x	
91	LH REAR WHEEL BEARING	11x	
92	LH REAR BEARING HUB	11x	
93	CROSSMEMBER ASSY	7	
94	CROSSMEMBER GUIDE BAR	31 ✓	
95	STABILAZER BAR	11x ✓	
96	STABILAZER BAR LINK	11x	
97	DRIVESHAFT ASSY LH	11x	

98	AXLE ASSY	11X		
99	CRUISE CONTROL SENSOR	?		
			SUBTOTAL	\$ -
			LESS 10%	\$ -
			PARTS TOTAL	\$ -
		SPECIAL NETT	QTY	PRICE
	FRONT NUMBER PLATE	set 40		\$ 80.00
	REAR NUMBER PLATE	set 40		\$ 80.00
	REVERSE SENSOR	shld 200		\$ 250.00
	REVERSE CAM	11X		\$ 400.00
	REAR END PANEL SEALANT	1m 100		\$ 100.00
	SPARE WHEEL PANEL SEALANT	11X		\$ 100.00
	WHEEL HOUSING SEALANT	11X		\$ 100.00
	RADIATOR COOLANT	1cc 40		\$ 150.00
	SPARE WHEEL INSULATOR	11X		\$ 400.00
	REAR FENDER SEALANT	11X		\$ 100.00
	FRONT BONNET SEAL CLIPS	11X		\$ 80.00
	FRONT BONNET INSULATOR CLIPS	11X		\$ 80.00
	FRONT BUMPER CLIPS	1m 50		\$ 100.00
	ENGINE UNDERCOVER CLIPS	11X		\$ 100.00
	BOOTLID INNER TRIM CLIPS	1m 50		\$ 100.00
	REAR BUMPER CLIPS	1m 50		\$ 100.00
	REAR END PANEL TOP GARNISH CLIPS	11X		\$ 80.00
	LH REAR FENDER COWLING CLIPS	11X		\$ 100.00
	LH REAR FENDER INNER TRIM CLIPS	11X		\$ 100.00
	LH TAILLAMP CLIPS	11X		\$ 40.00
			SPECIAL NETT TOTAL	\$ 2,640.00
		LABOUR	QTY	PRICE
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1800		\$ 2,400.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800		\$ 2,200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA	120		\$ 180.00
	TO RNR REAR WINDSCREEN	120		\$ 150.00
	TO RNR REAR BOOT MECHANISM	60		\$ 200.00
	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	80		\$ 400.00
	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50		\$ 80.00
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	100		\$ 250.00
	TO RNR UNDERCARRAIGE SYSTEM	180		\$ 800.00
	TO CHECK WHEEL ALIGNMENT	60		\$ 150.00
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	100		\$ 150.00
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	30		\$ 80.00
	TO RNR TYRE AND WHEEL BALANCING	11X		\$ 100.00
	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X		\$ 250.00
	TO DO WATER LEAK TEST .	11X		\$ 100.00
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11X		\$ 150.00
	TO REPROGRAM AND CODING FOR HEADLAMP ASSY	11X		\$ 400.00

		LABOUR TOTAL	\$ 8,040.00
		GRAND TOTAL COST	\$ 10,680.00

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Print Sent Message

This mail is associated with :

***SLG8265X (C0474341)**

[SHD9662P]

TP

GOH CHUAN YONG (WU JUNRONG)

Sep 7 2018 7:00PM

[TRANS-CAB SERVICES PTE LTD]

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 10/01/2019 17:04 PM.
To cynthia.loh@axa.com.sg
CC AXA_SG; ashersng@lkkauto.com
Subject [MANDATE REQUEST] C0474341

Hi Sir,

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer at \$16,301.45 (all-in).

For your approval in merimen please.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

*SLG8265X (C0474341)

[SHD9662P]

TP

GOH CHUAN YONG (WU JUNRONG)

Sep 7 2018 7:00PM

[TRANS-CAB SERVICES PTE LTD]

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 11/01/2019 12:00 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16301.45) - SLG8265X - Claim Handler: Cynthia Loh

Approved:16301.45.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2018		14 Sep 2018 09:39 Edit Adj Rpt	S\$13,500.00 Edit Estimates	S\$13,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	GOH CHUAN YONG (WU JUNRONG), ID: S8126780D		
Vehicle Reg. No.:	SLG8265X	Date of Loss:	07/09/2018 19:00 - :59 [22 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0474341	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHD9662P	Policy No. (Claimant):	2100486429-01
		Excess:	S\$5,000.00
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 25/09/2018]		
Driver/Custodian (Insured):	CHOW HOCK SOON (54 / Male), NRIC: S1608952D, Tel: +6590294935		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (11/01/2019): Alert - Adj Mandate Approved (S\$16301.45) - SLG8265X - Claim Handler: Cynthia Lo...
- AXA_SG (01/12/2018): C0474341 STATUS OF CLAIM
- AXA_SG (14/09/2018): New TP Assignment - C0474341/P1680520

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG8265X (C0474341)
[SHD9662P]
TP
GOH CHUAN YONG (WU JUNRONG)
Sep 7 2018 7:00PM
[TRANS-CAB SERVICES PTE LTD]
RICO 60 AUTO SERVICES PTE LTD

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/19 17:03	LKK Survey Photo		Load PDF	
2	10/01/19 17:03	LKK Resurvey Photo		Load PDF	
3	10/01/19 17:03	LKK Resurvey Photo		Load PDF	
4	10/01/19 17:03	LKK Resurvey Photo		Load PDF	
5	10/01/19 17:03	LKK Resurvey Photo		Load PDF	

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	13/09/18 09:42	EMAIL		Load PDF	
2	13/09/18 09:42	GIA REPORT OF SLG8265X (TP)		Load PDF	
3	13/09/18 09:42	GIA REPORT OF SHD6394H		Load PDF	
4	13/09/18 09:42	GIA REPORT OF SHD9662P (INSD)		Load PDF	
5	13/09/18 12:24	CO LEGAL		Load PDF	
6	13/09/18 12:24	PRI Arrangement		Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/09/18 19:28	TP ESTIMATE- MARKED (INCOMPLETE)		Load PDF	
2	09/01/19 17:49	GIA LTA SEARCH		Load PDF	
3	09/01/19 17:49	LETTER TO OI		Load PDF	
4	09/01/19 17:49	TOWING FEE		Load PDF	
5	10/01/19 17:02	TP ESTIMATE - MARKED		Load PDF	
6	10/01/19 17:02	LTA REBATE DETAILS		Load PDF	
7	10/01/19 17:02	Immediate Advice with Mandate		Load PDF	
8	29/01/19 17:54	LOD		Load PDF	
9	29/01/19 17:54	AUTHORISATION TO ACT		Load PDF	
10	29/01/19 17:54	DISCHARGE VOUCHER		Load PDF	
11	29/01/19 17:54	WORKSHOP INVOICE		Load PDF	
12	29/01/19 17:54	RENTAL RECEIPT		Load PDF	
13	29/01/19 17:54	RENTAL MILEAGE		Load PDF	
14	29/01/19 17:54	GIA LTA SEARCH		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHD9662P (Insd veh)	Model:	SUBARU LEVORG 1.6 (A)
	SLG8265X (TP veh)		
Date of Accident:	07/09/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	42,552.72
Final Repair Cost	:	\$	14,445.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,700.00 17 days
LTA / GIA Search Fee	:	\$	36.45
Towing Fee	:	\$	120.00
	:	\$	
Final Settlement Sum	:	\$	16,301.45
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown

1)	RICO 60 AUTO SERVICES PTE. LTD.	:	\$	16,301.45
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

29 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18016818/UEB3S2

Date: 29/01/2019

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SLG8265X	Insured Vehicle No :	SHD9662P
Date of Loss:	07/09/2018	Nature of Claim:	TP
		Claim No:	C0474341

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG8265X	Engine No:	FB16A827803
Make & Model:	SUBARU LEVORG, 1.6 (A)	Chassis No:	JF1VM4K55GG002314
Reg. Date:	15/10/2016 (Man. Year: 2015)	Odometer:	35198 km
Colour:	Grey		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	31,800.90	8,719.45	23,081.45	72.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,968.00	4,820.00	3,148.00	39.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,768.90	13,539.45	26,229.45	65.95
Approved Total (Overridden) (S\$)		13,500.00		
(S\$)	39,768.90	13,500.00	26,268.90	66.05
+ GST 7.00/7.00% (S\$)	2,783.82	945.00	1,838.82	66.05
Nett Amount (S\$)	42,552.72	14,445.00	28,107.72	66.05
+ Car Rental (17.0 x S\$100.00/day) (S\$)		1,700.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		16,301.45		

INSPECTION

Date of Assignment: 14/09/2018

Date Inspected: 14/09/2018

Inspected At:

RICO 60 AUTO SERVICES PTE LTD
8 KAKI BUKIT AVENUE 4
#02-24 PREMIER @ KAKI BUKIT
SINGAPORE 415875

Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jan 2019)	
Parts:	N/A	SUBARU LEVORG 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG8265X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (CONSISTENT)	Repair	792.00 FL	*- FL
2	1		*FRONT BONNET SEAL (CONSISTENT)	Not Necessary	12.60 FL	*- FL
3	1		*FRONT BONNET INSULATOR (CONSISTENT)	Not Necessary	102.00 FL	*- FL
4	1		*FRONT BONNET LOCK (CONSISTENT)	Twisted	65.80 FL	*65.80 FL
5	1		*FRONT BUMPER (CONSISTENT)	Torn	540.00 FL	*540.00 FL
6	2		*FRONT BUMPER SIDE RETAINER L+R (CONSISTENT)	Bent	35.60 FL	*35.60 FL
7	2		*FRONT BUMPER BRACKET L+R (CONSISTENT)	Bent	64.80 FL	*64.80 FL
8	1		*FRONT BUMPER GRILLE BASE (CONSISTENT)	Cracked	47.60 FL	*47.60 FL
9	1		*FRONT BUMPER GRILLE CHROME MOULDING (CONSISTENT)	Cracked	32.50 FL	*32.50 FL
10	1		*FRONT BUMPER GRILLE LOGO (CONSISTENT)	Cracked	18.70 FL	*18.70 FL
11	1		*FRONT BUMPER LOWER GRILLE (CONSISTENT)	Torn	50.40 FL	*50.40 FL
12	1		*FRONT BUMPER TOW COVER (CONSISTENT)	Not Necessary	14.40 FL	*- FL
13	1		*ENGINE UNDERCOVER (CONSISTENT)	Torn	180.00 FL	*180.00 FL
14	2		*HEADLAMP ASSY L+R (CONSISTENT)	Cracked	4,320.00 FL	*4,100.00 FL
15	2		*HEADLAMP LOWER BRACKET L+R (CONSISTENT)	Cracked	64.80 FL	*64.80 FL
16	2		*HEADLAMP WASHER MOTOR L+R (CONSISTENT)	Not Necessary	136.00 FL	*- FL
17	2		*HEADLAMP WASHER CAP L+R (CONSISTENT)	Not Necessary	95.20 FL	*- FL
18	2		*FOG LAMP ASSY L+R (CONSISTENT)	Not Necessary	850.00 FL	*- FL
19	2		*FOG LAMP COVER L+R (CONSISTENT)	Not Necessary	144.00 FL	*- FL
20	2		*FOG LAMP CHROME MOULDING L+R (CONSISTENT)	Not Necessary	160.00 FL	*- FL
21	2		*SIGNAL LAMP L+R (CONSISTENT)	Not Necessary	280.60 FL	*- FL
22	2		*SIGNAL LAMP BRACKET L+R (CONSISTENT)	Not Necessary	160.00 FL	*- FL
23	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Bent	252.00 FL	*252.00 FL
24	1		*FRONT SUPPORT PANEL (CONSISTENT)	Bent	522.00 FL	*522.00 FL
25	1		*FRONT BRACE PANEL (CONSISTENT)	Bent	480.00 FL	*180.00 FL
26	1		*AIR DUCT INTAKE (CONSISTENT)	Cracked	65.40 FL	*65.40 FL
27	1		*A/C CONDENSER ASSY (CONSISTENT)	Bent / Punctured	510.00 FL	*510.00 FL
28	1		*A/C LOWER PRESSURE PIPE (CONSISTENT)	Not Necessary	144.00 FL	*- FL
29	1		*A/C HIGH PRESSURE PIPE (CONSISTENT)	Not Necessary	180.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*A/C DISCHARGE PIPE (CONSISTENT)	Not Necessary	180.00 FL	*- FL
31	1		*OIL COOLER ASSY (CONSISTENT)	Not Necessary	920.00 FL	*- FL
32	1		*OIL COOLER PIPE (CONSISTENT)	Not Necessary	232.00 FL	*- FL
33	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Cracked	910.80 FL	*110.00 FL
34	1		*BOOTLID (CONSISTENT)	Badly Dented	1,072.80 FL	*1,072.80 FL
35	1		*BOOTLID LOCK (CONSISTENT)	Twisted	316.00 FL	*316.00 FL
36	1		*BOOTLID WEATHERSTRIP (CONSISTENT)	Torn	106.80 FL	*106.80 FL
37	1		*BOOTLID LOGO (CONSISTENT)	Necessary	68.40 FL	*68.40 FL
38	1		*BOOTLID CENTRE CHROME MOULDING (CONSISTENT)	Cracked	158.40 FL	*158.40 FL
39	1		*BOOTLID EMBLEM - SUBARU (CONSISTENT)	Necessary	82.80 FL	*82.80 FL
40	1		*BOOTLID EMBLEM - SYMMETRICAL (CONSISTENT)	Necessary	48.50 FL	*48.50 FL
41	1		*BOOTLID EMBLEM - AWD (CONSISTENT)	Necessary	42.00 FL	*42.00 FL
42	1		*BOOTLID EMBLEM - LEVORG (CONSISTENT)	Necessary	39.60 FL	*39.60 FL
43	1		*BOOTLID LAMP L+R (CONSISTENT)	N/s Cracked	476.00 FL	*238.00 FL
44	1		*BOOTLID INNER TRIM (CONSISTENT)	Not Necessary	198.00 FL	*- FL
45	1		*REAR BUMPER (CONSISTENT)	Distorted	840.00 FL	*840.00 FL
46	1		*REAR BUMPER SIDE RETAINER L+R (CONSISTENT)	N/s Bent	70.00 FL	*35.00 FL
47	2		*REAR BUMPER BRACKET L+R (CONSISTENT)	No such part	50.40 FL	*- FL
48	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	278.80 FL	*278.80 FL
49	1		*REAR BUMPER REFLECTOR L+R (CONSISTENT)	N/s Broken	48.40 FL	*24.20 FL
50	1		*REAR BUMPER SENSOR (CONSISTENT)	Shorted	280.70 FL	*280.70 FL
51	1		*REAR END PANEL (CONSISTENT)	Badly Dented	252.00 FL	*252.00 FL
52	1		*REAR END PANEL TOP GARNISH (CONSISTENT)	Twisted	45.80 FL	*45.80 FL
53	1		*SPARE WHEEL PANEL (CONSISTENT)	Repair	396.00 FL	*- FL
54	1		*SPARE WHEEL PANEL TOP BOARD (CONSISTENT)	Not Necessary	288.00 FL	*- FL
55	1		*SPARE WHEEL PANEL SIDE BOARD (CONSISTENT)	Torn	90.00 FL	*90.00 FL
56	1		*SPARE WHEEL PANEL QUARTER PANEL LH (CONSISTENT)	Badly Dented	1,216.00 FL	*650.00 FL
57	1		*SPARE WHEEL CONTAINER BOX / SPONGE (CONSISTENT)	Torn	180.00 FL	*180.00 FL
58	1		*LH REAR FENDER (CONSISTENT)	Badly Dented	864.00 FL	*864.00 FL
59	1		*LH REAR FENDER COWLING (CONSISTENT)	Torn	54.00 FL	*54.00 FL
60	1		*LH REAR FENDER INNER TRIM (CONSISTENT)	Distorted	417.60 FL	*417.60 FL
61	1		*LH REAR FENDER AIR DUCT (CONSISTENT)	Twisted	60.00 FL	*60.00 FL
62	1		*LH REAR FENDER QUARTER GLASS COMPLETE SET WITH MOULDING (CONSISTENT)	Necessary	583.20 FL	*583.20 FL
63	1		*LH REAR CHASSIS MEMBER (CONSISTENT)	Repair	716.00 FL	*- FL
64	1		*LH REAR CHASSIS EXTENSION (CONSISTENT)	Repair	240.00 FL	*- FL
65	1		*LH REAR WHEEL HOUSING (CONSISTENT)	Repair	1,480.70 FL	*- FL
66	1		*LH TAILLAMP (CONSISTENT)	Broken	425.00 FL	*425.00 FL
67	1		*LH TAILLAMP PANEL (CONSISTENT)	Badly Dented	25.60 FL	*25.60 FL
68	1		*LH TAILLAMP LOWER BRACKET (CONSISTENT)	Cracked	22.80 FL	*22.80 FL
69	1		*LH REAR DOOR (CONSISTENT)	Repair	648.00 FL	*- FL
70	1		*LH REAR DOOR LOCK (CONSISTENT)	Not Necessary	180.00 FL	*- FL
71	1		*LH REAR DOOR WEATHERSTRIP (CONSISTENT)	Not Necessary	126.00 FL	*- FL
72	1		*EXHAUST PIPE LH (CONSISTENT)	Bent / Twisted	540.00 FL	*540.00 FL
73	1		*EXHAUST PIPE CHROME TIPS (CONSISTENT)	Dented	100.00 FL	*100.00 FL
74	1		*EXHAUST PIPE GASKET (CONSISTENT)	Necessary	18.00 FL	*18.00 FL
75	1		*EXHAUST PIPE MOUNTING (CONSISTENT)	Necessary	16.50 FL	*16.50 FL
76	1		*EXHAUST PIPE CENTRE PIPE (CONSISTENT)	Twisted	612.00 FL	*612.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
77	1		*EXHAUST PIPE HEAT SHIELD (CONSISTENT)	Bent	43.20 FL	*43.20 FL
78	1		*LH REAR DAMPER (CONSISTENT)	Not Necessary	218.60 FL	*- FL
79	1		*LH REAR LOWER ARM (CONSISTENT)	Not Necessary	166.60 FL	*- FL
80	1		*LH REAR THRUST ARM (CONSISTENT)	Not Necessary	100.80 FL	*- FL
81	1		*LH REAR TOE LINK (CONSISTENT)	Not Necessary	144.00 FL	*- FL
82	1		*LH REAR WHEEL BEARING (CONSISTENT)	Not Necessary	212.40 FL	*- FL
83	1		*LH REAR BEARING HUB (CONSISTENT)	Not Necessary	234.80 FL	*- FL
84	1		*CROSSMEMBER ASSY (CONSISTENT)	Dented / Bent	644.40 FL	*644.40 FL
85	1		*CROSSMEMBER GUIDE BAR (CONSISTENT)	Bent	43.20 FL	*43.20 FL
86	1		*STABILIZER BAR (CONSISTENT)	Bent	120.00 FL	*120.00 FL
87	1		*STABILIZER BAR LINK (CONSISTENT)	Not Necessary	92.00 FL	*- FL
88	1		*DRIVESHAFT ASSY LH (CONSISTENT)	Not Necessary	800.00 FL	*- FL
89	1		*AXLE ASSY (CONSISTENT)	Not Necessary	2,858.00 FL	*- FL
90	1		*CRUISE CONTROL UNIT SENSOR (CONSISTENT)	Not Necessary	385.00 FL	*- FL
91	1		*FRONT NUMBER PLATE (CONSISTENT)	Bent	80.00 FS	*40.00 FS
92	1		*REAR NUMBER PLATE (CONSISTENT)	Bent	80.00 FS	*40.00 FS
93	1		*REVERSE SENSOR (CONSISTENT)	Repeated	250.00 FS	*- FS
94	1		*SET REVERSE CAM (CONSISTENT)	Shorted	400.00 FS	*350.00 FS
95	1		*REAR END PANEL SEALANT (CONSISTENT)	Necessary	100.00 FS	*50.00 FS
96	1		*SPARE WHEEL PANEL SEALANT (CONSISTENT)	Not Necessary	100.00 FS	*- FS
97	1		*WHEEL HOUSING SEALANT (CONSISTENT)	Not Necessary	100.00 FS	*- FS
98	1		*RADIATOR COOLANT (CONSISTENT)	Not Necessary	150.00 FS	*- FS
99	1		*SPARE WHEEL INSULATOR (CONSISTENT)	Not Necessary	400.00 FS	*- FS
100	1		*REAR FENDER SEALANT (CONSISTENT)	Not Necessary	100.00 FS	*- FS
101	1		*FRONT BONNET SEAL CLIPS (CONSISTENT)	Not Necessary	80.00 FS	*- FS
102	1		*FRONT BONNET INSULATOR CLIPS (CONSISTENT)	Not Necessary	80.00 FS	*- FS
103	1		*FRONT BUMPER CLIPS (CONSISTENT)	Necessary	100.00 FS	*50.00 FS
104	1		*ENGINE UNDERCOVER CLIPS (CONSISTENT)	Not Necessary	100.00 FS	*- FS
105	1		*BOOTLID INNER TRIM CLIPS (CONSISTENT)	Not Necessary	100.00 FS	*- FS
106	1		*REAR BUMPER CLIPS (CONSISTENT)	Necessary	100.00 FS	*50.00 FS
107	1		*REAR END PANEL TOP GARNISH CLIPS (CONSISTENT)	Not Necessary	80.00 FS	*- FS
108	1		*LH REAR FENDER COWLING CLIPS (CONSISTENT)	Not Necessary	100.00 FS	*- FS
109	1		*LH REAR FENDER INNER TRIM CLIPS (CONSISTENT)	Not Necessary	100.00 FS	*- FS
110	1		*LH TAILLAMP CLIPS (CONSISTENT)	Not Necessary	40.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) 35,041.00 16,858.90

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/50.00% (S\$)						3,240.10 8,139.45
Total Parts (S\$)						31,800.90 8,719.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN.	New	2,400.00	2,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	2,200.00	1,800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	180.00	120.00
4	TO RNR REAR WINDSCREEN.	New	150.00	120.00
5	TO RNR REAR BOOT MECHANISM.	New	200.00	60.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	New	400.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	New	8.00	50.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	New	250.00	100.00
9	TO RNR UNDERCARRIAGE SYSTEM.	New	800.00	300.00
10	TO CHECK WHEEL ALIGNMENT.	New	150.00	60.00
11	TO RNR A/C CONDENSER ASSY AND REFILL GAS.	New	150.00	100.00
12	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.	New	80.00	30.00
13	TO RNR TYRE AND WHEEL BALANCING.	New	100.00	0.00
14	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	New	250.00	0.00
15	TO DO WATER LEAK TEST.	New	100.00	0.00
16	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.	New	150.00	0.00
17	TO REPROGRAM AND CODING FOR HEADLAMP ASSY.	New	400.00	0.00
Gross Labour Cost (\$\$)			7,968.00	4,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >