



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 7873G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER (CONSISTENT)	TO REPAIR SEE LABOUR	850.00	-
1	CTR REAR BUMPER MLDG (CONSISTENT)	NECESSARY	90.00	90.00
1	L/R BUMPER MOULDING (CONSISTENT)	NECESSARY	80.00	80.00
1	L/R INN PARKING SENS (CONSISTENT)	SERVICEABLE	180.00	-
1	L/R OUT PARKING SENS (CONSISTENT)	SERVICEABLE	180.00	-
	COST PLUS 15%		207.00	25.50
			1,587.00	195.50
	<u>SPECIAL NETT ITEMS</u>			
1	AUDATEX FEEDS (SN) (CONSISTENT)		42.00	-
			42.00	-
	<u>LABOUR</u>			
	ECU DIAGNOSTIC.	NOT NECESSARY	180.00	-
	TOTAL PANEL / MECHANICAL EXTERNAL.	NOT NECESSARY	202.50	-
	TOTAL PAINTWORK.	NOT NECESSARY	387.00	-
	TOTAL PAINT / MATERIAL COST.	NOT NECESSARY	178.10	-
			947.60	-
GRAND TOTAL			2,576.60	195.50
RECOMMENDED COST OF REPAIRS				195.50

Report Ref No. CC4/ASM18016819/Kba3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.