



Your Ref: S8M00AUQ

Date: 27th September 2018

Our Ref: CS3/ASM18005022/Apa3s2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

Attn: Shirley Tan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBG 1721K
INSURED VEHICLE: XE 3314P
ACCIDENT DATE: 14/03/2018**

We thank you for your instruction on 16/03/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBG 1721K from M/s FormTeam Consultancy Pte Ltd.
- b) Final Repair Bill of GBG 1721K from M/s Hua Meng Spray Painting Workshop.
- c) Singapore Accident Statement of Vehicles GBG 1721K and XE 3314P.
- d) Colour damaged vehicle photographs of GBG 1721K.

Pre-Repair Inspection Date : 16/03/2018 at M/s Hua Meng Spray Painting Workshop, 1 Kaki Bukit Ave 6 #01-61 Autobay Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBG 1721K
Make & Model	: Toyota Hiace
Year of Registration	: 2017
Chassis Number	: JTFHT02P300224553
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.