

1952000

INS. CASE OWNEP:

CC6 /LPC1801

6824, AUBURN

LKK:
IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

12/1/18

Date / Time:

12/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

EK 300E

Name of Insured:

MAM PIK HOONH.

Insured Tel No.:

HP: 9187418

Excess Sec II :SS

D.O.A: 20/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: CHOW CHEE KONG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

18/12/18/005/020868

Policy No.:

218UP0501808

Make / Model:

SUBARU

Place of Accident:

PARK ARE 3 SUP RO TO CTG

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SW NEBRT

EK 300E

SJE 574H

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

01

INSRS: MB
WSP: SOUTHERN
Tel:
Liability:
RMKS: TPINSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

18/12/18
TH

3 vehicle chain collision and oi 2nd vehicle.

18-2-19

FILE PASS TO TYPST TO PREPARE REPORT.

STAGE

DATE/ PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

45

SS 3,300

(5 days)

Reduction:

33 %

Confirm by: LWP

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 12-01-19

Confirm with: SU WONG

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28. Ass. Lia : 0%.

Repair Cost:

2187

SS 3,531.00

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 480.00

(S 80

x 6 days)

Loss of Income (LOI):

SS -

(S

x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 4,018.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 12-01-19

Confirm with: SU WONG

Email ☒ Call ☐

Payee 1:

SS 4,018.45

Name 1:

MG SOUTHERN PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 450

COPY SENT
12/1/18

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

24/10/08

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 30 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJK 572514 Yr Regn: 2008 / octType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Stream c.c. 1799Colour: Black A/C: Insured / Std / NI / NASp. Reading: 157802 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN61070436Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/65R15R: 205/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 13/09/18Survey held at M6 SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
TP Lon Pae.COE Expiry: 30/09/28

45: 73,300 (RBD: 73,112.96 57/-)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp. (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC18016824/Aub3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 14-09-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EK 3020E	Veh. Inspected	SJK 5725H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/08/2018	Inspection Date	13/09/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: LONPAC	DATE	: 13/09/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJK5725H		
MODEL	: HONDA STREAM 1.8A	Thin Thin	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 30-Aug-18
		TIME	: 10:10HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented.</i>	1	\$ 980.00	\$ 980.00
2	TAILGATE LOGO <i>new</i>	1	\$ 62.00	\$ 62.00
3	TAILGATE EMBLEM 'STREAM' <i>new</i>	1	\$ 55.00	\$ 55.00
4	TAILGATE INNER LOCK <i>Damaged</i>	1	\$ 194.60	\$ 194.60
5	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 157.80	\$ 157.80
6	TAILGATE INNER HANDLE <i>new</i>	1	\$ 55.00	\$ 55.00
7	TAILGATE INNER BOARD <i>Not new</i>	1	\$ 211.00	\$ 211.00
8	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 133.00	\$ 133.00
9	REAR BUMPER <i>Replaced</i>	1	\$ 633.20	\$ 633.20
10	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 48.00	\$ 48.00
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 42.30	\$ 84.60
12	REAR END PANEL <i>Dented</i>	1	\$ 412.00	\$ 412.00
13	REAR END PANEL TOP GARNISH <i>Not new</i>	1	\$ 130.00	\$ 130.00

2621.2 TOTAL PRICE \$ 3,156.20

2086.96 LESS 20% \$ 631.24

SUB TOTAL PRICE \$ 2,524.96

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	REAR NUMBER PLATE <i>not new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	TAILGATE SEALANT <i>not new</i>	1	\$ 100.00	\$ 100.00	<i>+</i>
3	TAILGATE INNER BOARD CLIP(SET) <i>not new</i>	1	\$ 25.00	\$ 25.00	<i>+</i>
4	TAILGATE WINDSCREEN SEALANT <i>3 per</i>	1	\$ 100.00	\$ 100.00	<i>30</i>
5	TAILGATE WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00	<i>30</i>
6	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 33.00	\$ 33.00	<i>✓</i>
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 80.00	\$ 80.00	<i>60</i>
8	REAR END PANEL TOP GARNISH CLIPS(SET) <i>not new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
9	REVERSE SENSOR <i>damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

353 TOTAL \$ 708.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,400.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00	<i>600</i>	
3	TUFF COAT	\$250.00	<i>40</i>	
4	WIRING AND BULB CHECK	\$180.00	<i>30</i>	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$150.00	<i>60</i>	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$150.00	<i>50</i>	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$180.00	<i>120</i>	
8	TRANSFER TAILGATE MECHANISM	\$150.00	<i>80</i>	
9	CONDUCT WATER LEAKAGE TEST	\$120.00	<i>x</i>	

TOTAL \$3,780.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,232.96

TOTAL LABOUR COST : \$ 3,780.00

TOTAL REPAIR COST : \$ 7,012.96

APPROVED DETAILS

SURVEYOR

CONTACT NO

PART BY PART / LUMP SUM

NO OF DAYS

LKK Auto Consultants hence notify the Repairer of the following
 • To survey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and approved from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

FAX :

Adrian Lij total: 4225.96
13/09/18 L/S: 331C
05 pages

Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 14 September 2018 3:49 PM
To: Shu Pei (LKKAUTO); GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Thin Thin (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving EK3020E (OI : LPC - 18/18/18/VP05/020868) AND SJK5725H (TP : LKK REF -CC6/LPC18016824/Aub3) on 30.08.2018
Attachments: EK3020E 300818.PDF

Hi Shu Pei

Please see attached.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Friday, 14 September, 2018 3:42 PM
To: GERALD POH WEE BIN; ericwoo; ONG LI LI
Cc: MT_Claim_SG; Admin A; Thin Thin (LKKAUTO)
Subject: Direct Settlement - Accident Involving EK3020E (OI : LPC - TBA) AND SJK5725H (TP : LKK REF - CC6/LPC18016824/Aub3) on 30.08.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJK 5725H at M/s MG Solution Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC18016824/Aeb3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 16-05-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EK 3020E	Veh. Inspected	SJK 5725H
Policy No.	Z18VP05019808	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020868	Excess (\$)	0.00
Assign From		Assign Date	13/09/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61070436	Colour	BLACK
Odometer	157802	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R15	MAXXIS	6 mm
L/H Front Tyre	205/65 R15	MAXXIS	6 mm
R/H Rear Tyre	205/65 R15	MAXXIS	6 mm
L/H Rear Tyre	205/65 R15	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/08/2018	Inspection Date	13/09/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 5725H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	DENTED	980.00	903.00
1	TAILGATE LOGO	NOT NECESSARY	62.00	-
1	TAILGATE EMBLEM 'STREAM'	NECESSARY	55.00	55.00
1	TAILGATE INNER LOCK	DAMAGED	194.60	194.60
1	TAILGATE WEATHERSTRIP	CUT	157.80	157.80
1	TAILGATE INNER HANDLE	NOT NECESSARY	55.00	-
1	TAILGATE INNER BOARD	NOT NECESSARY	211.00	-
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	133.00	133.00
1	REAR BUMPER	DEFORMED	633.20	633.20
1	REAR BUMPER TOWING COVER	DEFORMED	48.00	48.00
2	REAR BUMPER SIDE RETAINER @\$42.30	NECESSARY	84.60	84.60
1	REAR END PANEL	DENTED	412.00	412.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	130.00	-
	LESS 20% DISCOUNT		-631.24	-524.24
			2,524.96	2,096.96
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	TAILGATE SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET TAILGATE INNER BOARD CLIP (SN)	NOT NECESSARY	25.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	30.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NECESSARY	80.00	30.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	33.00	33.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	80.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			708.00	353.00
LABOUR				
	TO PANEL BEAT, RMEOVE AND REPLACE PARTS.		1,400.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	600.00
	TUFF COAT.		250.00	40.00

Report Ref No. CC6/LPC18016824/Aeb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING AND BULB CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		150.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		150.00	50.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		180.00	120.00
	TRANSFER TAILGATE MECHANISM.		150.00	80.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
			3,780.00	1,780.00
	GRAND TOTAL		7,012.96	4,229.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00

Report Ref No. CC6/LPC18016824/Aeb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.