

ASS. REC. BY:

REF: 093/CT18016847 / A CBS²

Special Instruction:

Survivor
Maramin

ASSIGNMENT (Office)

From (Person): Chung Boon Sen of CTL Date/Time: 14/09/2018 2:50pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JRF 8239 Insured: SJC 3381 X

at Workshop m/s Autowork Automotive Tel: 9091 0000

of 8 Kaki Bukit Ave 4 #05-01

Policy No: DMPCON 300953100 Claim No: SNM18DD442502

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11.09.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi' 17/09/2018 @ morning H.O.D. Endorsement: _____

Date/Time: 14/09/2018 3:27pm Person Contacted: Alx Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	JRF 8239 - X
	SJC 3381 X - X
	Dismantle: 18/9/2018
	After repair: 26/9/2018.

Surveyor

REF:

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: JRF 8239
 at Workshop n/s Autowerke Automotive
 of 8 Kaki Bukit Ave 4 # 05-01 Premier
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
Morning
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: JRF 8239 Yr Regn: 2000 April
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota uses. c.c. 1781
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 367899 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PN111KF8104007980
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/70R14 Toyo
 R: 195/70R14 Silvestone
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A.		D.O.I. <u>17/09/18</u>	

 Survey held at Autowerke Automotive
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP claim PRS.</u>
	<u>Estimated repair range \$8,000 - \$10,000</u>
	<u>[Signature]</u>
	<u>9/10/2018</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to? _____
 Report Format : PRS
 Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 12
 Resurvey No. of Trip: 2

Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + PRS, SI _____
 Photos: _____
 Others: _____
 TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2018		14 Sep 2018 14:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	TAN KANG HAI , ID: F0275491Q		[Created by insurer]
Main Claimant:	TEH SHAE CHIAM , ID: G2549128P		
Vehicle Reg. No.:	JRF8239	Date of Loss:	11/09/2018 09:00 - :59
Claim Type:	TP / SNM18D04425C02	Policy/Cover Note No.:	DMPCSN300953100 (Comprehensive)
Vehicle Reg. No. (Insured):	SJC3381X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Autowerke Automotive Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-01/02, Premier Building, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN XING QUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED	
There are no mail for this case.	View All Compose Case Mail

ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180911/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/09/2018 12:18	Vide Report No.: J/20180911/0084	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars			
Name of Informant: TEH SHAE CHIAM		Address: 7 GAMBAS CRESCENT ARK@GAMBAS SINGAPORE 757087	
ID Type / ID No.: NRIC NO / G2549128P		Contact No.: Home/Office:	Mobile: 90592372
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 31	Date of Birth: 25/08/1987	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: CONSTRUCTION WORKER		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/09/2018 09:15	Type of Location:
Location: Along Road 1 ADMIRALTY ROAD WEST ADMIRALTY ROAD EAST Lamp Post Number: 21				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JFR8239	Car				Seriously Damaged	0
SJC3381X		TOYOTA	PREVIA 8 SEATER			0
SLD3113A	Car	BMW	116D 5DR HATCHBACK DSC LED			0



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEH SHAE CHIAM	ID No.	G2549128P
Related Vehicle	JFR8239 (Car)	Contact No.	90592372
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/09/2018 AT ABOUT 0915 HRS, I WAS TRAVELING ALONG ADMIRALTY RD WEST > ADMIRALTY RD EAST WHERE I MET AN ACCIDENT BETWEEN 2 OTHER VEHICLES. AS THE FRONT VEHICLE JAM BRAKE, I FOLLOW SUIT WHEN I WAS ABOUT TO COME TO A COMPLETE STOP, THE CAR BEHIND ME COLLIDED ONTO MY CAR REAR PORTION AND MY CAR SURGE FORWARD AND HIT ONTO THE CAR IN FRONT OF ME.



**SINGAPORE
POLICE FORCE**



T/20180911/2053

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180911/2053

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
SEBASTIAN NG JING PEI

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:
TP / GIT /
Staff Sgt LEE GUANG HUI
Contact No.: 65476138

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
11/09/2018 12:18

Classification Of Case:



Signature:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Sep 2018		14 Sep 2018 14:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN KANG HAI , ID: F0275491Q		
Main Claimant:	TEH SHAE CHIAM , ID: G2549128P		
Vehicle Reg. No.:	JRF8239	Date of Loss:	11/09/2018 09:00 - :59 [220 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04425C02	Policy/Cover Note No.:	DMPCSN300953100 (Comprehensive)
Vehicle Reg. No. (Insured):	SJC3381X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Autowerke Automotive Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-01/02, Premier Building, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/09/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN XING QUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***JRF8239 (SNM18D04425C02)**
[SJC3381X]
TP
TEH SHAE CHIAM
Sep 11 2018 9:00AM
[TAN KANG HAI]
Autowerke Automotive Pte Ltd

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/09/18 17:46	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	12/09/18 17:46	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/10/18 16:12	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
21	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/10/18 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
69	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	09/10/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
113	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
114	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
115	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
116	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
117	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
118	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
119	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
120	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
121	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
122	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
123	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
124	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
125	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
126	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
127	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
128	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
129	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
130	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
131	09/10/18 16:13	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
132	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
133	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
134	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
135	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
136	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
137	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
138	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
139	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
140	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
141	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
142	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
143	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
144	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
145	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
146	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
147	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
148	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
149	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
150	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
151	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
152	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
153	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
154	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
155	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
156	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
157	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
158	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
159	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
160	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
161	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
162	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
163	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
164	09/10/18 16:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/09/18 17:44	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	12/09/18 17:44	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	12/09/18 17:45	Driver's NRIC + Driving License [Linked Accident Report Documents]	Load TIF	
4	12/09/18 17:45	Certificate of Insurance [Linked Accident Report Documents]	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/09/18 14:50	PRS	Load PDF	
2	14/09/18 14:50	OI GIA	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/09/18 17:46	Accident Statement	Load HTM	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
2	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
3	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
4	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
5	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
6	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
7	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
8	12/09/18 17:46	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	12/09/18 17:44	Sketch Plan Sketch Plan	Load TIF	
2	12/09/18 17:44	Sketch Plan #2 Police Report	Load TIF	
3	12/09/18 17:45	Driver's NRIC + Driving License	Load TIF	
4	12/09/18 17:45	Certificate of Insurance	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118016847/ACBS2
Date: 19/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN300953100
Claimant Vehicle No :	JRF8239	Insured Vehicle No :	SJC3381X
Date of Loss:	11/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04425C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JRF8239	Engine No:	7K0308267
Make & Model:	TOYOTA UNSER, 1.8 GLI (A)	Chassis No:	PN111KF8104007930
Reg. Date:	13/04/2000 (Man. Year: 2000)	Odometer:	367899 km
Colour:	Silver		
Engine Capacity:	1781 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/70R14	Rear Tyre Size:	195/70R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Silverstone 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Silverstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/09/2018		
Date Inspected:	17/09/2018	Inspected At:	Autowerke Automotive Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-01/02, Premier Building Singapore 415875
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Oct 2018)

Parts: M1-MPV TOYOTA UNSER 1.8 GLI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JRF8239)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >