. Further		REF: CSI/LA	W18016903/	Gtbsz	Special Instruction:	
	See You	Consultation of the Consul	ENMENT (OI	Tire)	P/P: # 303 Third Parties: Claimant:	5000-00011
OD/TP Re-inspe	ection / (Evalua	tion			Surveyor: A	Pricision Apprilisal & All
To Inspect Vehic	3.00	0.00	Insured:	SL(7 9342A	Workshop: 3	ikid ri mi
		heng li lai	The second secon	47 0302		1000
of	9 K	(4KI BUKH AM)	# 01-36	42 0007		
Policy No:				GS/17/241	1 (SLL/84	
Sum Insured:			Excess:		7	
Make of Veh: (Client's Record)			D.O.A.			SJE
Date/Time:		Person Contacted: _	V		H.O.D. Endorsement/I	Date:
Date/Time:	Confi	rmed withit Final Fig £[1,8]5	Final Fig	,days (Red \$_10,5\\\).	ds /_%; Origina	; Original 18 days) 1_18 days)
	Action/Instruction	- 0		,		
		NA/ INC170U3910/	F3	Bu	A: DRUTAL	
	SL(1 9347A -	X			- Anorthi	1, / \
	de el al-l					moth
	chouse hindle	iph in View				1 1
19/9	of Lau said.	submit part by p	art \$11,815.	2,6 days.		19/9/2018.
Para(1): Pa	erts found no	t replaced (To	highlight 1	or UB, L	R, Etc)	
Para(2) · C	ammonts on	consist 6 1				
1 414(2): C(omments on	consistency of da	mages (Parts	Not Consist	ent: NC)	
	•					
T) (2) 71						
Para(3): No	ett Value					
	Market Value		Inspected/		Fee Charged: Basic & Ade	Date:
			Evaluated		Transport	d
	Salvage Value	:			Photos	
	Nett Value	:			Others Total	
1) Date/Time	1-2-50	File Pass to	2) Date/Tin	ie.	File Return to	-
3) Date/Time_		File Pass to	4) Date/Tin		File Return to	
5) Date/Time		File Pass to	6) Date/Tir	100.	_ File Return to_	

GUDDZEP SINGH SEKHON CHIÁ KOK SENG REY FOO JONG HAN GOH LAM CHUAN NAVINDER SINGH P. PADMAN KWEH SOON HAN PRADEEP KUMAR GOBIND HUE JIAPEI MUNIRAH BINTE MYDIN JASPREET KAUR PURBA LIM YUN HENG



MAIN OFFICE:

10 Hoe Chiang Road, #13-03A Keppel Towers, Singapore 089315

Tel: 6538 3611 Fax: 6538 3708

Website: www.kscgp.com

(Fax/Email not for service of court documents) Registered in Singapore with limited liability

as a Limited Liability Partnership Registration Number T10LL1855L

3152 0987

Email:

motor@kscgp.com

DID:

By Email & Post

Your Ref:

Our Ref : GS/17/2417/SLL/sy

: 2 August 2018

LKK Auto Consultants Pte Ltd 51 Ubi Avenue #01-25 Paya Ubi Ind East Singapore 408933

Attn: Mr. Lau Kwok Kwong

Dear Sirs,

MC/MC 10954/2017

ACCIDENT INVOLVING SLB 8071P & SLG 9342A ALONG KAKI BUKIT AVENUE 2 AND KAKI BUKIT ROAD 2 ON 24.02.17

We act for Ms. Sng Bee Khim, the owner of vehicle no. SLB 8071R in her property damage claim against the third party, arising out of the above-mentioned accident. M/s KhattarWong LLP act for the insurer of SLG 9342A, NTUC Income Insurance Co-operative Limited.

(a) Liability

A consent Interlocutory Judgment has been entered for liability at 90% in our client's favour on 11 May 2018.

(b) Single Joint Expert

We are pleased to inform you that you have been appointed as Single Joint Expert in the above matter.

Please render your report (concerning the reasonable repairs and the estimated period to complete such repairs) as well as to give evidence in Court subsequently (if need be).

In the meanwhile, we enclose below the following documents for your reference: -

- (a) A copy each of the Accident Reports made by both drivers;
- (b) Photographs taken at the accident site;
- (c) A copy of Survey Report of our client's vehicle no. SLB 8071P dated 3 April 2017 and photographs from our clients' surveyor, Precision Appraisal Services; and
- (d) Pre-repair survey report of our client's vehicle no. SLB 8071P from AJAX Inspection Services Pte Ltd, the surveyor appointed by the insurer of SLG 9342A.

For billing purposes, it should made to the name of our clients, Sng Bee Khim, though you may mail it to us.

Yours faithfully,

(Main Office)

Enc.

c.c. client

c.c. Withers KhattarWong LLP - Your ref: PYK/KTMY/KW00007.1901

(By Fax 6535 1030 Only)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report oxyrectly the dotate of the accident to speed up the cialms process.
- This Form must be completed by the Policyholder und/or the Authorised Driver.
- 3. information provided must be as intifful and accurate as possible. Any world misrepresentation or witholding of muterial facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any tales reporting may be referred to the Police for Investigation.
- This report will be forwarded by the incurers of the insurers of the OIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIE	ENT	STA	ILMEN
			1000

Date Of Report

25/02/2017 15:36

Date Of Accident

24/02/2017 19:30

Exact Location Of Accident

ALONG KAKI BUKIT AVE 2 & KAKI BUKIT RD 3

Singapore Country/State of Loss

DETAILS OF CWN VEHICLE

Vehicle Registration Number

SLB8071P

Inaured@olicyholder

Name Of Registered Owner

SNG BEE KHIM S7033483F

NRIC No

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-90047711

Alternative Phone No

Others-93898773

Vehicle Particulara

Manufacturer

TOYOTA

Model

HARRIER

Exact Purpose for which vehicle was being used

PRIVATE USE

at time of accident

No

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

Third Party

Vehicle Category

Private Car

Insurance Company

Name of Insurance Company

NTUC income Insurance Co-operative Ltd

Type Of Coverage

Comprehensive

Fleet Policy

No 5079674628

Policy Number

Cover Note Number

SENG CHIOW HARK

Driver Name of Driver

S1686266E

NRIC No

18/06/1965

Date Of Birth Occupation

Outdoor

Date Of Driving Pass

14/07/1988

Driving Experience

28 Years And 7 Months

Gender

Male

Mobile Number

(Local) +65-93898773

Fax Number

Contact Number

EMail Address

NOEMAIL

Page 1 of 14

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Formby insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8, Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (silinsurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) Investigating the accident and/or my claims;
- (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall
- (v) complying with applicable law in administering, processing, handling end/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (Including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes,

Policyholder's Signature / Date & Time	Driver's S & Time	ignature (f	driver is no	t the policy	holder) /		Vitne ed ersonnel	by Repo	rting Ca	antre	
Sketch Plan		177	-1-6-1-1	7777			ПП		П	רד	Т
		1	1						+		1
	2	4		1111			11		#	#	
The state of the s	1 1 1 .1 1					Caki	BWI	11			
						ROX	d				
5.11 2 4			1131	4					H		
								+++	H	#	H
	10		111	HH	##			H	111	31	H

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	25/02/2017 11:45
Date Of Accident	24/02/2017 19:20
Exact Location Of Accident	KAKI BUKIT AVE 2
Country/State of Loss	SINGAPORE
State of the state	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLG9342A
Insured/Policyholder	
Name Of Registered Owner	YTK TRANSPORT
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC HYBRID
Vehicle Category	PRIVATE CAR

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

Type Of Coverage COMPREHENSIVE

NO Fleet Policy

5086936919 Policy Number DRIVO CLASSIC Cover Note Number

Driver

Name of Driver YEO TECK KWANG

S0754959H NRIC No

BLK 166 #13-453 Address BEDOK SOUTH AVENUE 3

General Information of the Accident

COLLISION- CHANGE/CROSS LANE Type Of Accident

Weather Conditions CLEAR

Other Information

Was any foreign vehicle involved in this accident? Was any body injured in the Accident? NO Was any other material or property damaged? YES Number of Passengers (Including Driver) 1

Circumstances of Accident

I was travelling along lane 1 of Kaki Bukit Ave 2 intending to make a lane change to lane 2. After checking for safety, I did the lane change and vehicle B came from lane 2, from my left, and side swpied me to my front left area.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Sketch Plan Pg. 1

Income Motor Service Centre			Vehicle No:	SLG9342A	Report Date & Start Tim	e: 25-02-17 / 11:43
Report No: MT/		24-02-2017 1920 hrs	Make / Mode	el: <u>HONDA CIVIC</u>	HYBR Reporting Type:	End Time:/
			SKETO	CH PLAN		
MPORTANT NOTICE						
 Please report correctly the detail. This Form must be completed. 						
 Information provided must be a 	s truthful	and accurate	as possible.	Any wilful misrep	resentation or withholding of	material facts may
allow insurance companies to rep 4. The issue and acceptance of the	is Form by	insurance co	ompanies is no	ot an admission of	f policy liability on the part of	the insurance
companies 5. Any false reporting may be re	ferred to	the Police fo	r investigatio	n.		
6. The report will be forwarded by	the insure	rs of the GIA	Records Mana	agement Centre e	stablished by the General Ins	surance Association of
Singapore (GIA) for archiving and 7. By the lodgement of this report	that copie to the insu	is of this repo irers, you hen	nt will for a fee aby consent to	the archiving of	this report at the centre and t	o copies of the
report being made available afore	said.					
 Consent under the Personal I I understand, acknowledge, agree 	and cons	ent that:				
(a) My insurer, my workshop and and/or process my personal data	the Gener	ral Insurance	Association of	Singapore ("GIA"	") may/are permitted to collect	t, use, disclose and/or ed by me or
possessed by my insurer (collective	ely the "P	ersonal Infor	mation") and	disclose and tran	sfer such Personal Information	on to all insurer(s) who
have insured vehicle(s) involved in collectively referred to as the "Ins						
government agency/authority (suc	h as the p	olice), for the	purpose(s) of	9		
 (i) processing, handling and/or de the claims; 	aling with	my claims inc	auding the set	thement of the cla	ims and any necessary inves	ugations relating to
(ii) investigating the accident and/(iii) carrying out and/or dealing wit		0.000	ponding to an	v enquiries by me	D-1	
(iv) administering my claims (inclu	ding the n	nailing of corre	espandence, s	statements, invoic	es, reports or notices to me,	w hich could involve
disclosure of certain personal data packages); and/or	a about me	e to bring abo	ut delivery of t	the same as well a	as on the external cover of er	iveiopes/mail
(v) complying with applicable law (b) all insurer(s) who have insured	n adminis	tering, proces	sing, handling	and/or dealing w	ith my claims. (collectively the	e "Purposes")
use, disclose and/or process my F	Personal Ir	nformation for	one or more	of the above Purp	oses; and	
(c) my Personal Information may/ (including their lawyers/law firms).	can be dis	closed by any	of the Insure	rs and/or GIA to the	heir third party service providence of the above Purposes.	ars or agents
(including their lawyershaw littles),	WHICH HIS	ly be alted ou	iside or origin	pore, for olde of the	and of the above rangement.	
TUISEES						
(*) E			11		Alan Tang	(\$098825)
9 () ()		kefik	H	25.02	Customer C	are Executive
Policyholder Signature / Date & Tir	<u> </u>	Signature	A driver is not	the policyholder) / 0	17 / 11:43 Motor Serv	Reporting Centre Peronnel
Policyholder's Signature / Date & Tir	ne Din	7 Signature	(ii dirivoi io rioc	the policyholecry / a	value a rance by	reporting denied definer
Sketch Plan						
			Kaki Bukit R	oad 2		
			1	- 1		
			i	- 1		
			1	- 1		
			1			
		(B)-		(A)		
			11 1/2	Ä		

Kaki Bukit Ave 2


Vehicle B: SLB8071P

Vehicle A: SLG9342A































PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/Adjusters, Cargo Surveyors & Licensed Appraisers.

Blk 227 Simei St 4 #06-42 Singapore 520227 Fax: 6441 6884 Reg. No.: 53139926E



AUTOMOBILE INSPECTION REPORT INSURANCE DETAILS To: Insured Sng Bee Khim Claim No 449 Hougang Ave 10 Policy No. #06-505 (S) 530449 Sum Insured Excess Clause Windscreen Coverage Type of Claims Third Party Claims Third Part Insurer Third Party Policy No REFERENCE 03.4.17 As above Inspection Report Date : PAS/SLL/ SLB 8071 P /TP Assigned By Accident Date Our Reference 28 Feb 17 Assignment Date 28 Feb 17 Inspection Date Reinspection Date Sheng Li Lai Workshop Name 2 Kaki Bukit Ave 2 Inspection Address ; Kaki Bukit AutoHub (S) 417921 9948 XX PARTICULARS OF VEHICLE 071 P Km/mph Toyota Harrier 2.0 Premium Style Mauveleage : Fitted Registration No : Fitted Radio/Casette Make/Model 2015 CD Disc Player : Fitted Yr of Manu/Regn 4seater Air Conditioner : Fitted Carrying Capacity ZSU600073657 Clock Chassis No Fitted Hidden from view Seat Belt Engine No Metallic Black Wing Mirror Colour Passenger(Pte) Other Accessories Class PRE-ACCIDENT CONDITION (Static Check Only) VEHICLE VALUE Good Market Value Bodywork Wreck Value (Parf) Serviceable Paint work Handbrake Serviceable Footbrake Serviceable Steering None Any Apparent Eng Modifications 80 235/55R18 TYRE SIZE & CONDITION /55R18 80 B/stone B/stone 96 Front O/S Size Front N/S Size 80 235/55R18 80 235/55R18 Make Make B/stone % Rear O/S Size Rear N/S Size B/stone Make Make 235/55R18 20 Spare Size Spare Size B/stone Make XXXXX Type of Wheel Rims : Standard/Alloy

Jack & Tools

; Intact/Missing

NOTE: The above percentage % represent the estimated remaining tyre threads.

VEHICLE REGN NO :

PAS/SLL/ SLB 8071 P /TP

OUR REFERENCE :

No	Qty .	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
		DADES CLEDEL V. LIGHTERAS		\$ cts	\$ cts
.		PARTS SUPPLY - LIST ITEMS	Canalizad	3336.90	3336.90
1	lpc	O/s Headlamp	Cracked	35.00	35.00 >
2	1pc	O/s Headlamp clips	Necessary Bent	47.00	47.00
3	1pc	O/s headlamp lower bracket	Badly dented	798.80	798.80 ×
4	1pc	Front support panel Front bumper top beam	Bent	238.50	238.50
5	lpc lpc	Front bumper reinforcement	Bent	413.70	413.70 /
7	1pc	Front bumper lower grille	Bent /	237.30	237.30 >
8	20,000,000	Front bumper sponge, black	Torn	88.90	88.90
9	1pc	Front bumper sponge, white@\$27.2	Torn	54.40	54:40 /
200	2pcs	Front bumper fog lamp garnish o/s	Bent	82.90	82.90
10	1pc	Front bumper fog lamp garnish o/s Front bumper fog lamp o/s	Cracked	264.50	264.50
12	lpc lpc-	Front bumper	Badly dented	1450.40	1450.40
13	1pc	Front bumper lower spoiler	Tom	283.80	283.80
14	1pc	Front bumper side retainer o/s	Bent	91.20	91.20 /
15	1set	Front bumper clips	Necessary	45.00	45.00 >
16	1pc	Front o/s fender	Badly dented	1022.40	1022.40
17	1pc	Front o/s fender inner shield	Torn	413.70	413.70
18	1set	Front o/s fender inner shield clips	Necessary	38.00	38.00/
19	1pc	Front o/s shock absorber	Bent	430.00	430.00
20	1pc	Front o/s shock absorber	Bent	.679.60	679.60
21	1pc	Front o/s knuckle arm	Bent	550.50	550.50
22	1pc	Front o/s wheel rim	Dented/Warped	2062.40	2062.40
23	1pc	Front o/s wheel rim emblem	Necessary	83.40	83.40
24	1 set	Front suspension crossmember	Bent	2521.40	2521.40
25	1pc	Steering rack assy	Bent	1621.30	1621.30
26	1pc	O/s tie rod	Bent	161.60	161.60
27	1pc	Front o/s wheel bearing hub assy	Warped	555.00	555.00
28	1pc	Wiper spare tank	Torn	151.30	151.30 -
29		Wiper spare tank motor	Bent	242.70	242.70 >
25.7	1pc	Front bumper sensor o/s	Jammed	381.60	381.60
30	1pc	Front bumper side beam	Bent	93.60	93.60
32	1pc	Front bumper under cover	Torn	136.00	136.00
33	1pc	Stabilizer side link	Bent	137.20	137.20
34	1pc	Stabilizer side link Stabilizer bar	Bent	337.40	337.40
35	lpc	Torque Converter assy	Jammed	3391.30	3391.30
36	lpc.	Gearbox assy	Jammed	17881.30	Repair
37	0 lpc	Lower Valve Body	Jammed	1050.40	1050.40
27/4	lpc	5	Jammed	958.20	958.20
38	1pc	Upper Valve Body		42368.60	24487.30
		Loss 259/ discount	12981.1	42308.00	6121.82
		Less: 25% discount	25.4. 9735.8	/2	0121.02

PRECISION APPRAISAL SERVICES

Inspection Services Pte Ltd

PRE-REPAIR	SURVEY REPORT
------------	---------------

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Rajeswary D/o Doraisamy

Assign Date:

28/02/2017

Survey Date:

28/02/2017

TP Report Date:

25/02/2017

Accident Date:

24/02/2017

TP Policy No:

5079674628 Our Ref:

AVS2017-09617/PN

Place of Survey:

Sheng Li Lai

Your Ref:

MT/0935412-002

2 Kaki Bukit Avenue 2 #01-36 Kaki Bukit Autohub Singapore

417921

Claim Type: Claimant:

Third Party Sng Bee Khim

Description of Vehicle:

Veh. No: Colour:

SLB8071P

Make/Model:

Toyota Harrier 2.0 Premium Style Mauve

agine Capacity:

Blue 1.986cc Engine No: Chassis No:

3ZRB739606 ZSU600073657

Sum Insured (5\$): NA Mkt Value (S\$):

udometer:

9890

Reg. Date:

22/04/2016

Excess (S\$):

\$137,000.00

Condition of Vehicle:

General: Handbrake:

Good NA

Modification: Footbrake:

No NA

Steering: Paint work: NA Good

Tyre Make:

Front Tyre Size:

Michelin

235/55R18

Front Left Side: Rear Left Side:

6mm 6mm Front Right Side: Rear Right Side:

6mm 6mm

Rear Tyre Size: 235/55R18 Description of Damage:

The vehicle sustained damage on the front right portion.

The right front wheel, right front wheel tyre, right front fender, right front fender cowling, front bumper and right front headlamp were among the items affected.

emarks:

Our recommended amount for the cost of contract lumpsum repair is \$\$8,600.00 with approximately six (6) working days to complete. However, the amount was not finalised with the repairer.

All the stated damage are subject to consistency of the mentioned accident.

COMPLETED 3.7 APR 2017

Adjuster:

Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis. AJAX Inspection Services Pte Ltd

AJAX Inspection Services Pte Ltd

Adjus	tment	of Repair Cost for Vehicle:	SLB8071P	Our Ref:	AV\$2017-09617/PN
No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation S\$
List It					
1	1	O/s headlamp	Cracked	3,336.90	3,336.90
2	1	O/s headlamp clips	Necessary	35.00	35.00
3	1	O/s headlamp lower bracket	Bent	47.00	47.00
4	1	Front support panel	Not necessary	798.80	-
5	1	Front bumper top beam	Buckled	238.50	238.50
6	1	Front bumper reinforcement	Bent	413.70	413.70
1	1	Front bumper lower grille	Not necessary	237.30	**
8	1	Front bumper sponge, black	Cracked	88.90	88.90
9	2	Front bumper sponge, white	Cracked	54.40	54.40
10	1	Front bumper fog lamp garnish o/s	Not necessary	82.90	**
11	1	Front bumper fog lamp o/s	Not necessary	264.50	**
12	1	Front bumper	Damaged	1,450.40	1,450.40
13	1	Front bumper lower spoiler	Cracked	283.80	283.80
14	1	Front bumper side retainer o/s	Necessary	91.20	91.20
15	1	Front bumper clips	Necessary	45.00	45.00
16	1	Front o/s fender	Damaged	1,022.40	1,022.40
17	1	Front o/s fender inner shield	Cracked	413.70	413.70
18	1	Front o/s fender inner shield clips	Necessary	38.00	38.00
19	1	Front o/s shock absorber	Bent	430.00	430.00
00	1	Front o/s lower arm	Not necessary	679.60	
21	1	Front o/s knuckle arm	Not necessary	550.50	**
22	1	Front o/s wheel rim	Damaged	2,062.40	2,062.40
23	1	Front o/s wheel rim emblem	Re-use	83.40	**
24	1	Front suspension crossmember	Not necessary	2,521.40	
25	1	Steering rack assy	Not necessary	1,621.30	
26	1	O/s tie rod	Bent	161.60	161.60
27	1	Front o/s wheel bearing hub assy	Jammed	555.00	555.00
28	1	Wiper spare tank	Damaged	151.30	151.30
29	1	Wiper spare tank motor	Not necessary	242.70	-
30	1	Front bumper sensor o/s	Malfunction	381.60	381.60
31	1	Front bumper side beam	Bent	93.60	93.60
32	1	Front bumper under cover	Cracked	136.00	136.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:			SLB8071P	Our Ref: AVS2017-09617/P		
No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation S\$	
33	1	Stabilizer side link	Bent	137.20	137.20	
34	1	Stabilizer bar	Not necessary	337.40		
35	1	Torque converter assy	Repair	3,391.30	**	
36	1	Gearbox assy	Repair		44	
37	1	Lower valve body	Repair	1,050.40		
38	1	Upper valve body	Repair	958.20		
			Sub Total:	24,487.30	11,667.60	
			Discount (less 25%):	6,121.83	2,916.90	
				18,365.48	8,750.70	

	1	Brake oil	Not necessary	40.00	
2	1	Auto gearbox oil	Not necessary	40.00	**
			Sub Total:	80.00	0.00
			Total Parts Price:	18,445.48	8,750.70

ab	our Cost		
1	Towing.	150.00	100.00
2	Remove the necessary affected parts cut/weld front support panel, straighten front o/s wheel house and chassis and door and replace parts	780.00	600.00
3	Putty and spraypaint (include front bumper)	880.00	600.00
4	Check and reset cmplete electrical using diagnostic tools.	150.00	30.00
5	Tuff kote.	60.00	50.00
6	Remove and refit front o/s suspension and steering rack (twice).	800.00	600.00
7	Remove and relit torque converter and overhaul gearbox etc.	800.00	
8	Reset wheel alignment.	150.00	100.00
9	Remove and refit aircon parts and refill freon gas.	150.00	**
_	Sub Total:	3,920.00	2,080.00
	Grand Total:	22,365.48	10,830.70

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: GS/17/2417/SLL/sy

Date: 20th September 2018

Our Ref: CS1/LAW18016903/Gtbs2

M/s KSCGP Juris LLP 10 Hoe Chiang Road #13-03A Keppel Towers Singapore 089315

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLB 8071P INSURED VEHICLE: SLG 9342A ACCIDENT DATE: 24/02/2017

We thank you for your instruction on 13/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLB 8071P from M/s Precision Appraisal Services.
- b) Survey report by AJAX Inspection Services Pte Ltd.
- Singapore Accident Statement of Vehicles SLB 8071P and SLG 9342A.
- d) Colour damaged vehicle photographs of SLB 8071P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SLB 8071P

Make & Model

: Toyota Harrier 2.0 Premium Style Mauve

Year of Registration

: 2015

Chassis Number

: ZSU600073657

- We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 8071P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS		10-5800	
1	O/S HEADLAMP	CRACKED	3,336.90	3,336.90
1	O/S HEADLAMP CLIPS	NECESSARY	35.00	35.00
1	O/S HEADLAMP LOWER BRACKET	BENT	47.00	47.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	798.80	11
1	FRONT BUMPER TOP BEAM	BENT	238.50	238.50
1	FRONT BUMPER REINFORCEMENT	BENT	413.70	413.70
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	237.30	14-15-16-16-16-16-16-16-16-16-16-16-16-16-16-
1	FRONT BUMPER SPONGE, BLACK	TORN	88.90	88.90
2	FRONT BUMPER SPONGE, WHITE @ \$27.20	TORN	54.40	54.40
1	FRONT BUMPER FOG LAMP GARNISH O/S	NOT NECESSARY	82.90	-
1	FRONT BUMPER FOG LAMP O/S	NOT NECESSARY	264.50	13-
1	FRONT BUMPER	BADLY DENTED	1,450,40	1,450.40
1	FRONT BUMPER LOWER SPOILER	TORN	283.80	283.80
1	FRONT BUMPER SIDE RETAINER O/S	BENT	91.20	91.20
1	SET FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
1	FRONT O/S FENDER	BADLY DENTED	1,022.40	1.022.40
1	FRONT O/S FENDER INNER SHIELD	TORN	413.70	413.70
1	SET FRONT O/S FENDER INNER SHIELD CLIPS	NECESSARY	38.00	38.00
1	FRONT O/S SHOCK ABSORBER	BENT	430.00	430.00
1	FRONT O/S LOWER ARM	BENT	679.60	679.60
1	FRONT O/S KNUCKLE ARM	BENT	550.50	550,50
1	FRONT O/S WHEEL RIM	DENTED / WARPED	2,062.40	2,062.40
1	FRONT O/S WHEEL RIM EMBLEM	NECESSARY	83.40	83.40
1	SET FRONT SUSPENSION CROSSMEMBER	NOT NECESSARY	2,521.40	150000
1	STEERING RACK ASSY	NOT NECESSARY	1,621.30	- 12
1	O/S TIE ROD	BENT	161,60	161.60
1	FRONT O/S WHEEL BEARING HUB ASSY	WARPED	555.00	555.00
1	WIPER SPARE TANK	TORN	151.30	151.30
1	WIPER SPARE TANK MOTOR	NOT NECESSARY	242.70	-
1	FRONT BUMPER SENSOR O/S	JAMMED	381.60	381.60
1	FRONT BUMPER SIDE BEAM	BENT	93.60	93.60

Report Ref No. CS1/LAW18016903/Gtbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted
1	FRONT BUMPER UNDER COVER	TORN	136.00	136.00
1	STABILIZER SIDE LINK	BENT	137.20	137.20
1	STABILIZER BAR	NOT NECESSARY	337.40	in we come
1	TORQUE CONVERTER ASSY	NOT NECESSARY	3,391.30	
1	GEARBOX ASSY	TO REPAIR SEE LABOUR	17,881.30	-
1	LOWER VALVE BODY	NOT NECESSARY	1,050.40	22
1	UPPER VALVE BODY	NOT NECESSARY	958.20	-
	LESS 25% DISCOUNT		-	-3,245.28
			42,368.60	9,735.82
	SPECIAL NETT ITEMS			
1	TIN BRAKE OIL (SN)	NOT NECESSARY	40.00	
	TIN AUTO GEARBOX OIL (SN)	NOT NECESSARY	40.00	-
			80.00	-
	LABOUR			
	TOWING.		200.00	100.00
	REMOVE THE NECESSARY AFFECTED PARTS CUT / WELD FRONT SUPPORT PANEL, STRAIGHTEN FRONT O/S WHEEL HOUSE AD CHASSIS AND DOOR AND REPLACE PARTS.		880.00	600.00
	PUTTY AND SPRAY PAINT (INCLUDE FRONT BUMPER)		980.00	600.00
	CHECK AND RESET COMPLETE ELECTRICAL USING DIAGNOSTIC TOOLS.		200.00	30.00
	TUFF KOTE.		100.00	50.00
	REMOVE AND REFIT FRONT O/S SUSPENSION AND STEERING RACK (TWICE). INCLUSIVE OF THE REPAIR OF GEARBOX ASSY.		1,000.00	600.00
	REMOVE AND REFIT TORQUE CONVERTER AND OVERHAUL GEARBOX ETC.	NOT NECESSARY	1,000.00	8
	RESET WHEEL ALIGNMENT.		200.00	100.00
	REMOVE AND REFIT AIRCON PARTS AND REFILL FREON GAS.	NOT NECESSARY	200.00	-
			4,760.00	2,080.00
	GRAND TOTAL		47,208.60	11,815.82

Report Ref No. CS1/LAW18016903/Gtbs2



Page No.:3 of 3

RECOMMENDED COST REPAIRS

11,815.82

Report Ref No. CS1/LAW18016903/Gtbs2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No Bability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.