Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18016912/KEA3Q2

HIDDEN

Date: 19/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 2100462469 Policy No: Claimant SJZ7712C Insured Vehicle No: SLB7872B Vehicle No:

Date of Loss: 11/09/2018 ΤP Nature of Claim: Claim No: 9250549822SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJZ7712C Reg No:

NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR Make & Model: Engine No:

(A)

01/12/2010 (Man. Year: 2010) JN1BAAC11Z0111701 Reg. Date: Chassis No:

Colour: Metallic Maroon Odometer: 138700 km

1498 cc **Engine Capacity:** Market Value/New Car

N/A Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Achilles 9 mm Rear Left Side: Neuton 5 mm Front Right Side: Rear Right Side: Neuton 5 mm Achilles 9 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
4,727.59	3,301.47	1,426.12	30.17
0.00	0.00	0.00	
2,240.00	1,320.00	920.00	41.07
0.00	0.00	0.00	
0.00	0.00	0.00	
6,967.59	4,621.47	2,346.12	33.67
	3,700.00		
6,967.59	3,700.00	3,267.59	46.90
487.73	259.00	228.73	46.90
7,455.32	3,959.00	3,496.32	46.90
7.00% GST) (S\$)	749.00		
c/Search Fee (S\$)	29.00		
Nett Liability (S\$)	4,737.00		
n Settlement (S\$)	4,730.00		
	4,727.59 0.00 2,240.00 0.00 0.00 6,967.59 6,967.59 487.73	4,727.59 3,301.47 0.00 0.00 2,240.00 1,320.00 0.00 0.00 0.00 0.00 6,967.59 4,621.47 3,700.00 3,700.00 487.73 259.00 7,455.32 3,959.00 F 7.00% GST) (S\$) 749.00 c/Search Fee (S\$) 29.00 Nett Liability (S\$) 4,737.00	4,727.59 3,301.47 1,426.12 0.00 0.00 0.00 2,240.00 1,320.00 920.00 0.00 0.00 0.00 0.00 0.00 0.00 6,967.59 4,621.47 2,346.12 3,700.00 3,267.59 487.73 259.00 228.73 7,455.32 3,959.00 3,496.32 + 7.00% GST) (S\$) 749.00 c/Search Fee (S\$) 29.00 Nett Liability (S\$) 4,737.00

INSPECTION

17/09/2018 Date of Assignment:

17/09/2018 Inspected At: Date Inspected: Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint

Singapore 568047

Adjuster Report Page 2 of 4

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Cracked	622.00 FN	*541.00 FN	
2	12		*FRONT BUMPER CLIPS	Necessary	31.20 FN	*31.20 FN	
3	1		*FRONT BUMPER TOP RETAINER RH	Distorted	37.00 FN	*37.00 FN	
4	1		*FRONT BUMPER BRACKET	Repair	172.00 FN	*- FN	
5	1		*FRONT BUMPER REINFORCEMENT	Bent	620.00 FN	*561.90 FN	
6	1		*FRONT BUMPER SPONGE	Serviceable	231.00 FN	*- FN	
7	1		*FRONT BUMPER FOG LAMP COVER	Dented	143.00 FN	*143.00 FN	
8	1		*FRONT BUMPER CORNER RETAINER RH	Cracked	82.00 FN	*82.00 FN	
9	2		*FRONT BUMPER MOULDINGS	Necessary	112.00 FN	*112.00 FN	
10	1		*FRONT BUMPER BEAM	Repair	245.00 FN	*- FN	
11	1		*HEADLAMP ASSY RH	Mtg Cracked	550.00 FN	*550.00 FN	
12	1		*GRILLE	Mtg Cracked	362.00 FN	*331.70 FN	
13	1		*GRILLE EMBLEM	Necessary	73.00 FN	*73.00 FN	
14	1		*SUPPORT PANEL	Repair	557.00 FN	*- FN	
15	1		*SUPPORT PANEL TOP GARNISH	Cracked	417.00 FN	*371.90 FN	
16	12		*SUPPORT PANEL TOP GARNISH CLIPS	Necessary	31.20 FN	*31.20 FN	
17	1		*WIPER TANK	Dented	246.00 FN	*168.00 FN	
18	1		*WIPER TANK MOTOR	Shorted	225.70 FN	*181.40 FN	
19	1		*AIR CON CONDENSER SIDE AIR GUIDE	Cracked	112.00 FN	*112.00 FN	
20	1		*BONNET STOPPER RH	Serviceable	13.00 FN	*- FN	
21	1		*FRONT BUMPER FOG LAMP	Mtg Cracked	333.70 FS	*306.90 FS	
F=Fra	nchise	part. S=Spcl	Nett. N=NettItemDisc.				
				Sub Total (S\$)	5,215.80	3,634.20	
- Nett Item Discount on N Items 10.00/10.00% (S\$) 488.21 332.73						332.73	
				Total Parts (S\$)	4,727.59	3,301.47	
	Report was unsubmitted during this print-out.						
	Report was unsubmitted during this print-out.						

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=... 19/11/2020

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CONDUCT FRONT ELECTRICAL CHECK ,LOCKING SYSTEM ADJUST FOCUS HEADLAMP ETC	New	30.00	20.00
2	TO REMOVE/REFIT ,RADIATOR SYSTEM ,BLEED ,REFILL COOLANT	New	90.00	0.00
3	TO REMOVE /REFIT AIR CON CONDENSER & REFILL GAS	New	120.00	0.00
4	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FRONT CHASSIS MEMBER INNER PANEL ,BONNET ,FRONT FENDER ETC ,CNT ,WELD SUPPORT AND PARTS REPLACEMENT	New	900.00	500.00
5	TO RESPRAY AFFECTED AREAS	New	1,100.00	800.00
	Gross Labour	Cost (S\$)	2,240.00	1,320.00
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >