



陳林摩喀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLQ5434S
Date of Accident : 12 September 2018

Mr Ang Day Liong @ Ang Lay Leong Henry

Date : 15 September 2018

Marcus
17/09/18 @ 0920hrs

Estimate To Repair SKH9935X - Toyota LEXUS CT200H
Chassis No : JTHKD5BH502105763

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	rear bumper <i>deep cut</i>	\$ 837.20
02	1 pc	rear bumper side retainer RH <i>11</i>	\$ 145.00
03	10 ps	rear bumper clip @ \$4.30 <i>nu</i>	\$ 43.00
			\$ 1,025.20
		Less 25 %	\$ 256.30
			\$ 768.90
		LABOUR & MISC. CHARGES	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 1,420.00
		Total	\$ 2,188.90

Not Authorized
LKL
2/5 \$1100/2
2 day

the photo after repair

Have \$1100 x 2 days
confirm & return
17/09/18
sup

LKL Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
nature

P- 880.2
LSZ
660.15
1410.15
1128.12