

11/07/2018

ASS. REC. BY:

REF:

CS/CTU18016970/R1dp

Special Instruction:

Survivor

Rosal

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTU

Date/Time:

18/07/2018 1:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 8536Y

Insured:

GBD 388L

at Workshop m/s

Kah Motor.

Tel:

6471 5419

of

255 Alexandra Rd

Policy No:

DMCVSN1513851813

Claim No:

SNM18104503102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17092018

CA / REV / REP. / REV 24 HRS 'wip'

H.O.D. Endorsement:

Date/Time:

18/07/2018 2:13pm

Person Contacted:

Sin Hui

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKV 8536Y - x

GBD 388L - x

19/07/18@

2:13pm confirmed with Sin Hui for final fig to 14510.86, 10 days
(Red to 9364.68, 39.1%)


Rohan

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV 85364 Yr Regn: 2015 / OCT
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda car 2.4 5 AT C.C. 235K
 Colour: GREEN A/C Insured / Std / NI / NA
 Sp Reading: 029716 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRHRM 3850 G1000113
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50R18
 R: 1 -
 BS: OUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 17/07/18 D.O.I: 18/09/18
 Survey held at: KATH mupra
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 19/10/2018

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee: 220

Transportation

1) \$ + RS. \$k

2) Photos

3) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

over-tp

Lump Sum / I.B.I. (\$

14520.86

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2018		18 Sep 2018 13:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																																																		
CLAIM SUBFOLDER DETAILS			[Created by insurer]																																																			
<table border="1"> <tr> <td>Insured:</td> <td colspan="4"></td> </tr> <tr> <td>Main Claimant:</td> <td colspan="4">JO-ANNE LAM MAY CHENG</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td>SKV8536Y</td> <td>Date of Loss:</td> <td colspan="2">17/09/2018 00:00 - :59</td> </tr> <tr> <td>Claims Type:</td> <td>TP / SNM18D04503C02</td> <td>Policy/Cover Note No.:</td> <td colspan="2">DMCVSN1513851803</td> </tr> <tr> <td>Vehicle Reg. No. (Insured):</td> <td>G8D388L</td> <td>Policy No. (Claimant):</td> <td colspan="2"></td> </tr> <tr> <td></td> <td></td> <td>Excess:</td> <td colspan="2">S\$0.00</td> </tr> <tr> <td>Repairer:</td> <td colspan="4">Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="4">China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]</td> </tr> <tr> <td>Adjuster:</td> <td colspan="4">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2018]</td> </tr> <tr> <td>Adj Asg. Remarks:</td> <td colspan="4">NO EST, CASE WITH SJE.</td> </tr> </table>					Insured:					Main Claimant:	JO-ANNE LAM MAY CHENG				Vehicle Reg. No.:	SKV8536Y	Date of Loss:	17/09/2018 00:00 - :59		Claims Type:	TP / SNM18D04503C02	Policy/Cover Note No.:	DMCVSN1513851803		Vehicle Reg. No. (Insured):	G8D388L	Policy No. (Claimant):					Excess:	S\$0.00		Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:				Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]				Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2018]				Adj Asg. Remarks:	NO EST, CASE WITH SJE.			
Insured:																																																						
Main Claimant:	JO-ANNE LAM MAY CHENG																																																					
Vehicle Reg. No.:	SKV8536Y	Date of Loss:	17/09/2018 00:00 - :59																																																			
Claims Type:	TP / SNM18D04503C02	Policy/Cover Note No.:	DMCVSN1513851803																																																			
Vehicle Reg. No. (Insured):	G8D388L	Policy No. (Claimant):																																																				
		Excess:	S\$0.00																																																			
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:																																																					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]																																																					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2018]																																																					
Adj Asg. Remarks:	NO EST, CASE WITH SJE.																																																					
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail																																																			
There are no mail for this case.																																																						
ALL ASSOCIATED TASKS																																																						
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																																							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																																													
No results.																																																						

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 19 October 2018 2:13 PM
To: Ng Sin Hai; Admin-D (LKKAuto)
Subject: RE: PRI of SKV8536Y (CTI REF: SNM18D04503C02)

Dear Sin Hai,

WITHOUT PREJUDICE

Confirm final fig \$14,510.86 before GST and 10 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Tuesday, 18 September 2018 11:59 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: PRI of SKV8536Y (CTI REF: SNM18D04503C02)

FYI ONLY

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2018 10:15
Date Of Accident	17/09/2018 19:15
Exact Location Of Accident	CTE TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV8536Y
Insured/Policyholder	
Name Of Registered Owner	JO-ANNE LAM MAY CHENG
NRIC No	S1659199H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92701437
Alternative Phone No	OFFICE-92701437

Vehicle Particulars

Manufacturer	HONDA
Model	CR-V-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	JO-ANNE LAM MAY CHENG
NRIC No	S1659199H
Date Of Birth	05/09/1964
Occupation	INDOOR
Date Of Driving Pass	26/10/1982
Driving Experience	35 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92701437
Fax Number	
Contact Number	OFFICE-92701437
Email Address	NOEMAIL

Vehicle No SKV8536 Y

ABR1 F

Describe Circumstances of the Accident

I, owner of SKV8536 Y, was driving along CTE on 17.9.18 around 7.15pm (in the direction north just before the 10km sign & turn off to Ang Mo Kio Ave 1). Traffic was moderate & I was on the lane 2nd from the left slowing down when I was hit on the rear by a Toyota Dyna GBD 388 L driven by a Mr Yan Tiong San S1479380A (hp 90271097).

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

I/we declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18003932	Page	1
	3 ANSON ROAD #16-00	Date	: 18. Sep 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: NG SIN HAI		
Registration No	: SKV8536Y	Engine No	: K24Z98502568		
Chassis No	: MRHRM3850GP000113	Date Time	: 18. Sep 2018 10:48:25 AM		
Model	: CRV 2.4L 2016 MODEL (EURO 4)	Surveyor Name	:		
Owner's Name	: JO-ANNE LAM MAY CHENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:JO-ANNE LAM MAY CHENG						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:17/09/2018						
	SURVEYED BY:						
	DATE:18/09/2018						
	REF NO:						
	TP INSURER:CHINA TAIPING						
	TP VEH:GBD388L						
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 <i>X</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	560.00 <i>Xan</i>		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN (N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL.	1	6000.00 <i>2800</i>		6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00 <i>2700</i>		4000.00	280.00	4280.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	450.00 <i>Xan</i>		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00		380.00	26.60	406.60
BOMISC1	REMOVE AND RENEW FRONT AND REAR DVR	1	560.00		560.00	39.20	599.20
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	560.00		560.00	39.20	599.20
BOMISC1	RESET AND CALIBRATE ALL SMART ENTRY FOR ALL DOORS	1	380.00		380.00	26.60	406.60



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SKV8536Y
Chassis No : MRHRM3850GP000113
Model : CRV 2.4L 2016 MODEL (EURO 4)
Owner's Name : JO-ANNE LAM MAY CHENG
Ins Policy No. :
Date of Accident :

Document No. : SQT18003932
Date : 18. Sep 2018
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : K24Z98502568
Date | Time : 18. Sep 2018 10:48:25 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Labor					15370.00	1,075.90	16,445.90
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
33500-T0N-Q01	TAILLIGHT ASSYR.LOWER	1	247.60	25	185.70	13.00	198.70
33550-T0N-Q01	TAILLIGHT ASSYL.LOWER	1	247.60	25	185.70	13.00	198.70
34170-T1W-Y01	TAILLIGHT ASSYR.UPPER	1	155.50	25	116.62	8.16	124.78
34175-T1W-Y01	TAILLIGHT ASSYL.UPPER	1	155.50	25	116.62	8.16	124.78
34270-T1W-A01	LIGHT ASSYHIGH MOUNT STOP	1	132.80	25	99.60	6.97	106.57
68100-T0Y-E50ZZ	TAILGATECOMP	1	781.90	25	586.42	41.05	627.47
74440-T0A-J01	WEATHERSTRIPTAILGATE	1	100.70	25	75.52	5.29	80.81
74800-TF0-J01	LOCKTAILGATE	1	181.70	25	136.27	9.54	145.81
74810-T1W-A01	SWITCH ASSYTAILGATE OPENER	1	59.10	25	44.32	3.10	47.42
74820-T0G-A11	STAY ASSYR.TAILGATE OPENER	1	37.30	25	27.97	1.96	29.93
74823-T0A-A00	BRACKETR.TAILGATE OPEN STAY	1	11.90	25	8.92	0.62	9.54
74870-T0G-A11	STAY ASSYL.TAILGATE OPENER	1	37.30	25	27.97	1.96	29.93
74873-T0A-A00	BRACKETL.TAILGATE OPEN STAY	1	11.90	25	8.92	0.62	9.54
74890-TFA-U10	GARNISH ASSYRR.LICENSE	1	236.40	25	177.30	12.41	189.71
74895-T0N-T01ZJ	GARNISH ASSYTAILGATE NSE	1	274.90	25	206.17	14.43	220.60
75722-T0N-T00	EMBLEMRR.	1	20.30	25	15.22	1.07	16.29
84431-T0A-A01ZC	LINING ASSYTAILGATE LOWER	1	170.10	25	127.57	8.93	136.50
84433-T0A-A01ZA	GARNISH ASSYTAILGATE UPPER	1	38.00	25	28.50	2.00	30.50
84435-T0A-A01ZA	GARNISH ASSYR.TAILGATE SIDE	1	30.70	25	23.02	1.61	24.63
84485-T0A-A01ZA	GARNISH ASSYL.TAILGATE SIDE	1	30.70	25	23.02	1.61	24.63
73211-T0A-A01	SETRR.WINDSHIELD GLASS	1	720.60	25	540.45	37.83	578.28
73226-SZW-000	DAMPERSTD 5X5	3	8.30	25	18.67	0.44	6.66
73226-T0A-000	RUBBER B WINDSCREEN DAMPER 1	4	8.20	25	24.60	0.86	13.16
73227-T0A-000	RUBBER CWINDSHIELD DAMPER 2	2	9.60	25	17.28	0.50	7.70
73228-T0A-A01	MOLDINGR.RR.WINDSHIELD CORNER	2	16.80	25	25.20	0.88	13.48
73229-T0A-A01	MOLDINGL.RR.WINDSHIELD CORNER	1	16.80	25	12.60	0.88	13.48
75717-SNB-E01	STICKER I-VTEC	1	12.40	25	9.30	0.65	9.95

Printed on 18/9/2018 11:13:01 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 Registration No : SKV8536Y
 Chassis No : MRHRM3850GP000113
 Model : CRV 2.4L 2016 MODEL (EURO 4)
 Owner's Name : JO-ANNE LAM MAY CHENG
 Ins Policy No. :
 Date of Accident :

Document No. : SQT18003932 Page 3
 Date : 18. Sep 2018
 Customer No. : WZC008
 Svc Advisor : NG SIN HAI
 Engine No : K24Z98502568
 Date | Time : 18. Sep 2018 10:48:25 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
04715-T1W-A00ZZ	FACERR.BUMPER	* 1 482	609.40	25	457.05	31.99	489.04
33505-T1W-A01	REFLECTOR ASSYR.RR.	1	54.00	25	40.50	2.84	43.34
33555-T1W-A01	REFLECTOR ASSYL.RR.	1	54.00	25	40.50	2.84	43.34
71502-TFA-T00	FACERR.R.BUMPER LOWER	1	64.50	25	48.37	3.39	51.76
71503-S9A-000ZB	CAPREAR BUMPER	2	9.80	25	14.70	1.03	15.73
71507-TFA-T00	FACERR.L.BUMPER LOWER	1	64.50	25	48.37	3.39	51.76
71510-TFA-T20	GARNISHRR.BUMPER LOWER	1	144.80	25	108.60	7.60	116.20
71593-T1W-A01	SPACERR.RR.BUMPER SIDE	1	13.40	25	10.05	0.70	10.75
71598-T1W-A01	SPACERL.RR.BUMPER SIDE	1	13.40	25	10.05	0.70	10.75
91505-TM8-003	CLIPBUMPER	15	2.00	25	22.50	1.58	24.08
04646-T0N-T01ZZ	PANEL SETL.RR.OUTSIDE	1	619.90	25	464.92	32.54	497.46
63720-T0T-H00ZZ	GUTTER COMP.L.RR.	1	111.60	25	83.70	5.86	89.56
66100-T0A-J00ZZ	PANEL COMPRR.	1	470.00	25	352.50	24.68	377.18
04655-T0S-P00ZZ	PANEL SETRR.FLOOR	1	566.00	25	424.50	29.72	454.22
65741-T0A-A00ZZ	CROSS MEMBERRR.FLOOR UPPER	1	108.80	25	81.60	5.71	87.31
84520-T0A-D01ZB	LID ASSYCARGO FLOOR	1	260.80	25	195.60	13.69	209.29
84611-T0A-U11ZB	LINING COMPR.RR.SIDE	1	219.30	25	164.47	11.51	175.98
84620-T0G-A01ZC	LIDR.DMP MAINTENANCE	1	10.30	25	7.72	0.54	8.26
84640-T0A-A01ZC	LINING ASSYRR.PANEL	1	82.60	25	61.95	4.34	66.29
84661-T0A-U11ZB	LINING COMPLRR.SIDE	1	219.30	25	164.47	11.51	175.98
65660-T0N-Z00ZZ	FRAME COMPLRR.	1	683.50	25	512.62	35.88	548.50
64700-T0A-306ZZ	PANEL COMPLRR.INSIDE	1	809.40	25	607.05	42.49	649.54
NMDVR-DR750S-2CH	DVR BLACKVUE 2 CHANNEL	1	568.00		568.00	39.76	607.76
Sum Item					7796.81	545.77	8,342.58
BO-V-KOOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00

Survey By

Printed on 18/9/2018 11:13:01 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance. Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18003932	Page	4
	: 3 ANSON ROAD #16-00	Date	: 18. Sep 2018		
	: SPRINGLEAF TOWER	Customer No.	: WZC008		
	: SINGAPORE 079909	Svc Advisor	: NG SIN HAI		
Registration No	: SKV8536Y	Engine No	: K24Z98502568		
Chassis No	: MRHRM3850GP000113	Date Time	: 18. Sep 2018 10:48:25 AM		
Model	: CRV 2.4L 2016 MODEL (EURO 4)	Surveyor Name	:		
Owner's Name	: JO-ANNE LAM MAY CHENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	18/09/18 @ 1345						
					Total Amount	23,466.81	1,642.67
Excess							
					Total (Inclusive of GST)		25,109.48
Status							
Signature							

Hp 90010068

Rasul

Resy b8 paint

19/9/18

LKK Auto Consultants hence colly
the Repairer of the following:

- In resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) when deemed necessary
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 18/9/2018 11:13:01 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

73875.54



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHRM3850GP000113
License No: SKV8536Y
Mileage: 28902
Engine No: K24Z98502568

Document No: SVO18054945
Printed By: SHNG
Order Date: 18. September 2018
Order Time: 2:38:28 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:JO-ANNE LAM MAY CHENG OWNER INSURER:TOKIO MARINE ACC DATE:17/09/2018 SURVEYED BY:RASUL DATE:18/09/2018 REF NO: TP INSURER:CHINA TAIPING TP VEH:GBD388L ADDITIONAL PART						
RS-4P	BUMPER SENSOR 4PCS	1	180.00		180.00	12.60	192.60
33500-T0N-Q01	TAILLIGHT ASSYR.LOWER	1	247.60	25	185.70	13.00	198.70
33550-T0N-Q01	TAILLIGHT ASSYLL.LOWER	1	247.60	25	185.70	13.00	198.70
68100-T0Y-E50ZZ	TAILGATECOMP	1	781.90	25	586.42	41.05	627.47
74440-T0A-J01	WEATHERSTRIPTAILGATE	1	100.70	25	75.52	5.29	80.81
74800-TF0-J02	LOCKTAILGATE	1	181.70	25	136.27	9.54	145.81
74890-TFA-U10	GARNISH ASSYRR.LICENSE	1	236.40	25	177.30	12.41	189.71
74895-T0N-T01ZJ	GARNISH ASSYTAILGATE NSE	1	274.90	25	206.17	14.43	220.60
75722-T0N-T00	EMBLEMRR.	1	20.30	25	15.22	1.07	16.29
84431-T0A-A01ZC	LINING ASSYTAILGATE LOWER	1	170.10	25	127.57	8.93	136.50
73211-T0N-T12	GLASS SET,RR.WINDSHIELD	1	654.70	25	491.02	34.37	525.39
73226-SZW-000	DAMPERSTD 5X5	3	8.30	25	18.67	1.31	19.98
91501-S70-003	1 FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	2 FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	3 FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
76707-T0A-000	Y SEAL A	1	15.40	25	11.55	0.81	12.36
75717-SNB-E01	STICKER I-VTEC	1	12.40	25	9.30	0.65	9.95
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
71501-T1W-A00ZE	FACERR.BUMPER UPPER	1	482.00	25	361.50	25.31	386.81
71502-TFA-T00	FACERR.R.BUMPER LOWER	1	64.50	25	48.37	3.39	51.76
71510-TFA-T20	GARNISHRR.BUMPER LOWER	1	144.80	25	108.60	7.60	116.20
71593-T1W-A01	SPACERR.RR.BUMPER SIDE	1	13.40	25	10.05	0.70	10.75
71598-T1W-A01	SPACERL.RR.BUMPER SIDE	1	13.40	25	10.05	0.70	10.75
91505-TM8-003	CLIPBUMPER	15	2.00	25	22.50	1.58	24.08
66100-T0A-J00ZZ	PANEL COMPRR.	1	470.00	25	352.50	24.68	377.18
84640-T0A-A01ZC	LINING ASSYRR.PANEL	1	82.60	25	61.95	4.34	66.29
NMDVR-DR750S-2CH	DVR BLACKVUE 2 CHANNEL	1	568.00		568.00	39.76	607.76
74940-T0A-J01	BUZZER ASSYSMART	1	59.10	25	44.32	3.10	47.42
74410-T0A-J01	PROTECTORR.RR.WHEEL ARCH	1	111.90	25	83.92	5.87	89.79
74450-T0A-J01	PROTECTORL.RR.WHEEL ARCH	1	111.90	25	83.92	5.87	89.79
76710-T0A-003	MOTOR COMPWIPER	1	250.70	25	188.02	13.16	201.18
84441-T0A-A01ZC	POCKETTAILGATE LINING PULL	1	11.40	25	8.55	0.60	9.15
	SUM PARTS:				4,500.86	315.07	4,815.93
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	1610 SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60

47.42 cut
89.79 cut
89.79 cut
201.18 short
9.15 cut



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZC008 / CHINA TAIPING	Document No:	SVO18054945			
Chassis No:	MRHRM3850GP000113	Printed By:	SHNG			
License No:	SKV8536Y	Order Date:	18. September 2018			
Mileage:	28902	Order Time:	2:38:28 PM			
Engine No:	K24Z98502568	Service Advisor:	NG SIN HAI			
BOJSE	1610 SEALANT FOR TAILGATE	1	80.00	80.00	5.60	85.60
BML02I	1757 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	180.00	12.60	192.60
BMI02D	0671 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00	560.00	39.20	599.20
BKTG02R	1757 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00	560.00	39.20	599.20
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00	560.00	39.20	599.20
BODAMKIT	1757 WINDSCREEN DAM KIT.	1	100.00	100.00	7.00	107.00
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,800.00	2,800.00	196.00	2,996.00
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	2,700.00	2,700.00	189.00	2,889.00
BKBU01R	0671 REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00	380.00	26.60	406.60
BOMISC1	0671 REMOVE AND RENEW FRONT AND REAR DVR	1	560.00	560.00	39.20	599.20
BMI01D	1757 REMOVE & INSTALL ROOF LINING GARNISHES SEATS SPEAKER BOARD CARPET & ETC.(N)	1	560.00	560.00	39.20	599.20
BOMISC1	1757 RESET AND CALIBRATE ALL SMART ENTRY FOR ALL DOORS	1	380.00	380.00	26.60	406.60
			SUM LABOUR:	9,710.00	679.70	10,389.70
BO-V-KOOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00	300.00	21.00	321.00
			SUM EXT SERVICE:	300.00	21.00	321.00
TOTAL SGD				14,510.88	1,015.77	15,526.63
Total Payable (SGD)						15,526.63

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3638

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004098	Page	1
	3 ANSON ROAD #16-00	Date	: 27. Sep 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	:		
Registration No	: SKV8536Y	Engine No	: K24Z98502568		
Chassis No	: MRHRM3850GP000113	Date Time	: 27. Sep 2018 4:14:18 PM		
Model	: CRV 2.4L 2016 MODEL (EURO 4)	Surveyor Name	:		
Owner's Name	: JO-ANNE LAM MAY CHENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	supplementary						
74940-T0A-J01	BUZZER ASSYSMART	1	59.10	25	44.32	3.10	47.42 at
74410-T0A-J01	PROTECTORR.RR.WHEEL ARCH	1	111.90	25	83.92	5.87	89.79 cut
74450-T0A-J01	PROTECTORL.RR.WHEEL ARCH	1	111.90	25	83.92	5.87	89.79 cut
76710-T0A-003	MOTOR COMPWIPER	1	250.70	25	188.02	13.16	201.18 short
84441-T0A-A01ZC	POCKETTAILGATE LINING PULL	1	11.40	25	8.55	0.60	9.15 at
Sum Item					408.73	28.60	437.33

Survey By

Date & Time

Excess

Status

Signature

Total Amount 408.73 28.60 437.33

Total (Inclusive of GST) 437.33

Printed on 27/9/2018 4:16:29 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2018		18 Sep 2018 13:56 Edit Adj Rpt	S\$14,510.86 Edit Estimates	S\$14,510.86 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ID: -								
Main Claimant:	JO-ANNE LAM MAY CHENG								
Vehicle Reg. No.:	SKV8536Y	Date of Loss:	17/09/2018 00:00 - :59 [35 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04503C02	Policy/Cover Note No.:	DMCVSN1513851803						
Vehicle Reg. No. (Insured):	GBD388L	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 27/09/2018]								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV8536Y (SNM18D04503C02)
[GBD388L]
TP
JO-ANNE LAM MAY CHENG
Sep 17 2018 12:00AM
[-]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	19/10/18 14:31	Odometer Reading								Load JPG	☒	
2	19/10/18 14:31	Chassis Number								Load JPG	☒	
3	19/10/18 14:31	General View								Load JPG	☒	
4	19/10/18 14:31	General View								Load JPG	☒	
5	19/10/18 14:31	General View								Load JPG	☒	
6	19/10/18 14:31	General View								Load JPG	☒	
7	19/10/18 14:31	General View								Load JPG	☒	
8	19/10/18 14:31	General View								Load JPG	☒	
9	19/10/18 14:31	General View								Load JPG	☒	
10	19/10/18 14:31	General View								Load JPG	☒	
11	19/10/18 14:31	General View								Load JPG	☒	
12	19/10/18 14:31	General View								Load JPG	☒	
13	19/10/18 14:31	General View								Load JPG	☒	
14	19/10/18 14:31	General View								Load JPG	☒	
15	19/10/18 14:31	General View								Load JPG	☒	
16	19/10/18 14:31	General View								Load JPG	☒	
17	19/10/18 14:31	General View								Load JPG	☒	
18	19/10/18 14:31	General View								Load JPG	☒	
19	19/10/18 14:31	General View								Load JPG	☒	
20	19/10/18 14:31	General View								Load JPG	☒	
21	19/10/18 14:31	General View								Load JPG	☒	
22	19/10/18 14:31	General View								Load JPG	☒	
23	19/10/18 14:31	General View								Load JPG	☒	
24	19/10/18 14:31	General View								Load JPG	☒	
25	19/10/18 14:31	General View								Load JPG	☒	
26	19/10/18 14:31	General View								Load JPG	☒	
27	19/10/18 14:31	General View								Load JPG	☒	
28	19/10/18 14:31	General View								Load JPG	☒	
29	19/10/18 14:31	General View								Load JPG	☒	
30	19/10/18 14:31	General View								Load JPG	☒	
31	19/10/18 14:31	General View								Load JPG	☒	
32	19/10/18 14:31	General View								Load JPG	☒	
33	19/10/18 14:31	General View								Load JPG	☒	
34	19/10/18 14:31	General View								Load JPG	☒	
35	19/10/18 14:31	General View								Load JPG	☒	
36	19/10/18 14:31	General View								Load JPG	☒	
37	19/10/18 14:31	General View								Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/10/18 14:31	General View	 Load JPG	☒
39	19/10/18 14:31	General View	 Load JPG	☒
40	19/10/18 14:31	General View	 Load JPG	☒
41	19/10/18 14:31	General View	 Load JPG	☒
42	19/10/18 14:31	General View	 Load JPG	☒
43	19/10/18 14:31	General View	 Load JPG	☒
44	19/10/18 14:31	General View	 Load JPG	☒
45	19/10/18 14:31	General View	 Load JPG	☒
46	19/10/18 14:31	General View	 Load JPG	☒
47	19/10/18 14:31	General View	 Load JPG	☒
48	19/10/18 14:31	General View	 Load JPG	☒
49	19/10/18 14:31	General View	 Load JPG	☒
50	19/10/18 14:31	General View	 Load JPG	☒
51	19/10/18 14:31	General View	 Load JPG	☒
52	19/10/18 14:31	General View	 Load JPG	☒
53	19/10/18 14:31	General View	 Load JPG	☒
54	19/10/18 14:31	General View	 Load JPG	☒
55	19/10/18 14:31	General View	 Load JPG	☒
56	19/10/18 14:31	General View	 Load JPG	☒
57	19/10/18 14:31	General View	 Load JPG	☒
58	19/10/18 14:31	General View	 Load JPG	☒
59	19/10/18 14:31	General View	 Load JPG	☒
60	19/10/18 14:31	General View	 Load JPG	☒
61	19/10/18 14:31	General View	 Load JPG	☒
62	19/10/18 14:31	General View	 Load JPG	☒
63	19/10/18 14:31	General View	 Load JPG	☒
64	19/10/18 14:31	General View	 Load JPG	☒
65	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
66	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
67	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
68	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
69	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
70	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
71	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
72	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
73	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
74	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
75	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
76	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
77	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
78	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
79	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
80	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
81	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
82	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
83	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
84	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
85	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
86	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
87	19/10/18 14:31	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
89	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
90	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
91	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
92	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
93	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
94	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
95	19/10/18 14:31	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/09/18 13:56	PRS	 Load PDF	
2	18/09/18 13:56	TP GIA	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 10:22	SUPPLEMENTARY PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016970/R1QBQ2

Date: 23/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1513851803

Claimant Vehicle
No: SKV8536YInsured Vehicle
No: GBD388L

Date of Loss: 17/09/2018

Nature of Claim: TP

Claim
No: SNM18D04503C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV8536Y

Make & Model: HONDA CR-V, 2.4 (A)

Reg. Date: 05/10/2015 (Man. Year: 2015)

Colour: Grey

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: K24Z98502568

Chassis No: MRHRM3850GP000113

Odometer: 29716 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,618.14	4,830.86	3,787.28	43.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,270.00	9,680.00	5,590.00	36.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,888.14	14,510.86	9,377.28	39.25
+ GST 7.00/7.00% (S\$)	1,672.17	1,015.76	656.41	39.25
Nett Amount (S\$)	25,560.31	15,526.62	10,033.69	39.25

INSPECTION

Date of Assignment: 18/09/2018

Date Inspected: 18/09/2018 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2018)
Parts:	M1-SUV	HONDA CR-V 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV8536Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	4		*REAR SENSORS	Necessary	320.00 FS	*180.00 FS
3	1		*NUMBER PLATE WITH CASING-L	Not Necessary	45.00 FS	*- FS
4	1		*TAILLIGHT ASSYR.LOWER	Cracked	185.70 FS	*185.70 FS
5	1		*TAILLIGHT ASSYL.LOWER	Cracked	185.70 FS	*185.70 FS
6	1		*TAILLIGHT ASSYR,UPPER	Serviceable	116.62 FS	*- FS
7	1		*TAILLIGHT ASSYL,UPPER	Serviceable	116.62 FS	*- FS
8	1		*LIGHT ASSYHIGH MOUNT STOP	Serviceable	99.60 FS	*- FS
9	1		*TAILGATECOMP	Bent	586.42 FS	*586.42 FS
10	1		*WEATHERSTRIPTAILGATE	Necessary	75.52 FS	*75.52 FS
11	1		*LOCKTAILGATE	Bent	136.27 FS	*136.27 FS
12	1		*SWITCH ASSYTAILGATE OPENER	Not Necessary	44.32 FS	*- FS
13	1		*STAY ASSYR.TAILGATE OPENER	Not Necessary	27.97 FS	*- FS
14	1		*BRACKETR.TAILGATE OPEN STAY	Not Necessary	8.92 FS	*- FS
15	1		*STAY ASSYL.TAILGATE OPENER	Not Necessary	27.97 FS	*- FS
16	1		*BRACKETL.TAILGATE OPEN STAY	Not Necessary	8.92 FS	*- FS
17	1		*GARNISH ASSYRRR.LICENSE	Cracked	177.30 FS	*177.30 FS
18	1		*GARNISH ASSYTAILGATE NSE	Cracked	206.17 FS	*206.17 FS
19	1		*EMBLEMRR	Necessary	15.22 FS	*15.22 FS
20	1		*LINING ASSYTAILGATE LOWER	Deformed	127.57 FS	*127.57 FS
21	1		*GARNISH ASSYTAILGATE UPPER	Not Necessary	28.50 FS	*- FS
22	1		*GARNISH ASSYR,TAILGATE SIDE	Not Necessary	23.02 FS	*- FS
23	1		*GARNISH ASSYL.TAILGATE SIDE	Not Necessary	23.02 FS	*- FS
24	1		*SETRR.WINDSHIELD GLASS	Broken	540.45 FS	*491.02 FS
25	1		*DAMPERSTD 5X5 (3 PCS)	Necessary	18.67 FS	*18.67 FS
26	4		*RUBBER B WINDSCREEN DAMPER	Necessary	12.30 FS	*9.60 FS
27	1		*RUBBER C WINDSHIELD DAMPER (2 PCS)	Necessary	7.35 FS	*7.35 FS
28	1		*MOLDINGR.RR.WINDSHIELD CORNER (2 PCS)	Necessary	12.60 FS	*5.25 FS
29	1		*MOLDING .RR.WINDSHIELD CORNER	Necessary	12.60 FS	*11.55 FS
30	1		*STICKER I-VTEC	Necessary	9.30 FS	*9.30 FS
31	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
32	1		*FACETRR.BUMPER	Torn	457.05 FS	*361.50 FS
33	1		*REFLECTOR ASSYR.RR	Serviceable	40.50 FS	*- FS
34	1		*REFLECTOR ASSYL.RR	Serviceable	40.50 FS	*- FS
35	1		*FACERR.R.BUMPER LOWER	Deformed	48.37 FS	*48.37 FS
36	2		*CAPREAR BUMPER	Serviceable	14.70 FS	*- FS
37	1		*FACERR.L.BUMPER LOWER	Serviceable	48.37 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*GARNISHRR.BUMPER LOWER	Deformed	108.60 FS	*108.60 FS
39	1		*SPACERR.RR.BUMPER SIDE	Necessary	10.05 FS	*10.05 FS
40	1		*SPACERL.RR.BUMPER SIDE	Necessary	10.05 FS	*10.05 FS
41	15		*CLIPBUMPER	Necessary	22.50 FS	*22.50 FS
42	1		*PANEL SETL.RR.OUTSIDE	Serviceable	464.92 FS	*- FS
43	1		*GUTTER COMP.L.RR	Serviceable	83.70 FS	*- FS
44	1		*PANEL COMPRR	Bent	352.50 FS	*352.50 FS
45	1		*PANEL SETRR.FLOOR	Repair	424.50 FS	*- FS
46	1		*CROSS MEMBERRR.FLOOR UPPER	Serviceable	81.60 FS	*- FS
47	1		*LID ASSYCARGO FLOOR	Serviceable	195.60 FS	*- FS
48	1		*LINING COMRR.RR.SIDE	Serviceable	164.47 FS	*- FS
49	1		*LIDR .DMP MAINTENANCE	Serviceable	7.72 FS	*- FS
50	1		*LINING ASSYRR.PANEL	Necessary	61.95 FS	*61.95 FS
51	1		*LINING COMPL.RR.SIDE	Serviceable	164.47 FS	*- FS
52	1		*FRAME COMPL.RR	Serviceable	512.62 FS	*- FS
53	1		*PANEL COMPL.RR.INSIDE	Serviceable	607.05 FS	*- FS
54	1		*DVR BLACKVUE 2 CHANNEL	Cut	568.00 FS	*568.00 FS
55	1		*SOLAR FILM ON REAR WINDSCREEN	Necessary	300.00 FS	*300.00 FS
56	1		*BUZZER ASSYSMART	Cut	44.32 FS	*44.32 FS
57	1		*PROTECTORR.RR.WHEEL ARCH	Cut	83.92 FS	*83.92 FS
58	1		*PROTECTORL.RR.WHEEL ARCH	Cut	83.92 FS	*83.92 FS
59	1		*MOTOR COMPWIPER	Shorted	188.02 FS	*188.02 FS
60	1		*POCKETTAILGATE LINING PULL	Cut	8.55 FS	*8.55 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,618.14	4,830.86
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & RENEW REVERSE SENSORS	New	180.00	180.00
2	SEALANT FOR REAR END PANEL	New	80.00	80.00
3	SEALANT FOR REAR FLOOR PANEL	New	80.00	0.00
4	SEALANT FOR TAILGATE	New	80.00	80.00
5	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	180.00	180.00
6	RREMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	0.00
7	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	560.00	560.00
8	REMOVE & TRANSFER ITEMS TO NEW TAILGATE .ADJUST &	New	560.00	560.00
9	REMOVE & INSTALL RR .WINDSCREEN	New	560.00	560.00
10	WINDSCREEN DAM KIT	New	100.00	100.00
11	CUT OFF & RENEW RR PANEL	New	6,000.00	2,800.00
12	SPRAY PAINTIGN ON REPAIRED OR REPLACED AREAS	New	4,000.00	2,700.00
13	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	0.00
14	REMOVE,RE-FIX AND ALIGN REAR VIEW CAMERA	New	380.00	380.00
15	REMOVE AND RENEW FRONT AND REAR DVR	New	560.00	560.00
16	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	New	560.00	560.00
17	RESET AND CALIBRATE ALL SMART ENTRY FOR ALL DOORS	New	380.00	380.00
Gross Labour Cost (\$\$)			15,270.00	9,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >