Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC3/III18016977/KEA3Q2 Our File No:

Date: 27/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SHB7805T Insured Vehicle No: SHD3194M

Vehicle No:

Date of Loss: 14/09/2018 Nature of Claim: ΤP Claim No: MCT18090369

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHB7805T Reg No:

Make & Model: CHEVROLET EPICA, 2.0 (A) Engine No: Z20S1455794K Chassis No: Reg. Date: 28/08/2012 (Man. Year: 2011) KL1LA69RJBB096259

Colour: Red/White Odometer: 397401 km

Engine Capacity: 1991 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Giti 9 mm Rear Left Side: Giti 9 mm Front Right Side: Rear Right Side: Giti 9 mm Giti 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|--------------------|------------|------------|--------|
| Parts | 12,124.27 | 3,027.74 | 9,096.53 | 75.03 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 10,460.00 | 1,370.00 | 9,090.00 | 86.90 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 22,584.27 | 4,397.74 | 18,186.53 | 80.53 |
| Approved Total (Overridden) (S\$) | | 3,500.00 | | |
| (S\$) | 22,584.27 | 3,500.00 | 19,084.27 | 84.50 |
| + GST 7.00/7.00% (S\$) | 1,580.90 | 245.00 | 1,335.90 | 84.50 |
| Nett Amount (S\$) | 24,165.17 | 3,745.00 | 20,420.17 | 84.50 |
| + Loss of Use (5.0 x S\$4 | 10.00/day) (S\$) | 200.00 | | |
| + Car Rental (5.0 x S\$7 | 75.25/day) (S\$) | 376.25 | | |
| Net | tt Liability (S\$) | 4,321.25 | | |

INSPECTION

Date of Assignment: 17/09/2018

Date Inspected: 17/09/2018 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2020)

Parts: 143 CHEVROLET EPICA 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB7805T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|-------------|---|------------------|-------------|--------------|
| 1 | 1 | | *FRONT FENDER LH | Bent | 837.60 FL | *837.60 FL |
| 2 | 1 | | *FRONT FENDER LINER LH | Distorted | 47.00 FL | *47.00 FL |
| 3 | 1 | | *FRONT FENDER INNER WHEEL HOUSE PANEL LH | Repair | 1,437.00 FL | *-FL |
| 4 | 1 | | *FRONT SHOCK ABSORBER ASSY LH | Not Necessary | 216.17 FL | *-FL |
| 5 | 1 | | *FRONT SHOCK ABSORBER TOP MOUNTING LH | Not Necessary | 48.32 FL | *- FL |
| 6 | 1 | | *FRONT LOWER ARM LH | Not Necessary | 283.00 FL | *- FL |
| 7 | 1 | | *FRONT KNUCKLE ARM LH | Not Necessary | 230.00 FL | *-FL |
| 8 | 1 | | *FRONT DOOR LH | Bent | 1,133.00 FL | *1,133.00 FL |
| 9 | 1 | | *FRONT DOOR GLASS GUIDE RH CHROME MOULDING | Serviceable | 60.00 FL | *-FL |
| 10 | 1 | | *FRONT DOOR OUTER MOULDING | Serviceable | 220.00 FL | *-FL |
| 11 | 1 | | *FRONT DOOR OUTER HANDLE | Serviceable | 125.00 FL | *-FL |
| 12 | 1 | | *FRONT DOOR HANDLE SUPPORT | Serviceable | 3.00 FL | *-FL |
| 13 | 1 | | *FRONT DOOR OUTER HANDLE INNER SEAL | Serviceable | 89.15 FL | *- FL |
| 14 | 1 | | *FRONT DOOR OUTER KEY LOCK | Serviceable | 25.00 FL | *- FL |
| 15 | 1 | | *FRONT DOOR HINGE UPPER | Repair | 65.00 FL | *- FL |
| 16 | 1 | | *FRONT DOOR HINGE LOWER | Repair | 65.00 FL | *- FL |
| 17 | 1 | | *FRONT DOOR INNER LOCK | Repair | 586.00 FL | *-FL |
| 18 | 1 | | *FRONT DOOR INNER LOCK LATCH LH | Repair | 206.00 FL | *- FL |
| 19 | 1 | | *FRONT DOOR CHECK /ARRESTOR | Serviceable | 67.50 FL | *- FL |
| 20 | 1 | | *FRONT DOOR WEATHERSTRIP LH | Serviceable | 138.79 FL | *- FL |
| 21 | 1 | | *FRONT DOOR GLASS CHANNEL WEATHERSTRIP | Serviceable | 160.00 FL | *- FL |
| 22 | 1 | | *FRONT DOOR INNER TRIM BOARD | Serviceable | 455.69 FL | *- FL |
| 23 | 1 | | *FRONT DOOR WINDOW GLASS | Serviceable | 456.12 FL | *- FL |
| 24 | 1 | | *FRONT DOOR POWER WINDOW MOTOR (MASTER) LH | Serviceable | 284.97 FL | *-FL |
| 25 | 1 | | *FRONT DOOR POWER WINDOW MOTOR SWITCH | Serviceable | 145.00 FL | *- FL |
| 26 | 1 | | *FRONT DOOR WINDOW REGULATOR GEAR LH | Serviceable | 84.58 FL | *- FL |
| 27 | 1 | | *FRONT DOOR OUTER PILLAR PANEL LH | Repair | 715.00 FL | *- FL |
| 28 | 1 | | *FRONT DOOR PILLAR INNER PANEL LH | Repair | 850.00 FL | *- FL |
| 29 | 1 | | *FRONT DOOR CENTER PILLAR PANEL LH | Repair | 698.15 FL | *- FL |
| 30 | 1 | | *FRONT SIDE VIEW MIRROR ASSY LH | Dented / Cut | 1,191.00 FL | *1,191.00 FL |
| 31 | 1 | | *FRONT SIDE ROCKER PANEL GARNISH LH | Serviceable | 236.40 FL | *-FL |
| 32 | 1 | | *FRONT SIDE ROCKER PANEL OUTER LH | Repair | 600.00 FL | *- FL |
| 33 | 1 | | *FRONT SIDE ROCKER PANEL INNER LH | Repair | 519.30 FL | *- FL |
| 34 | 1 | | *SET FRONT FENDER LINER CLIP | Necessary | 30.00 FS | *30.00 FS |
| 35 | 1 | | *FRONT FENDER RR BRACKET LH | Repair | 7.10 FS | *-FS |
| 36 | 1 | | *REAR WHEEL RIM HUB CAP LH | Serviceable | 166.30 FS | *-FS |
| 37 | 1 | | *REAR TYRE LH | Serviceable | 180.00 FS | *-FS |
| | | | | | | |

Adjuster Report Page 4 of 5

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|-------------|---------------------------------------|-------------------|------------|-----------|
| 38 | 1 | | *REAR TYRE RIM LH | Dented | 126.00 FS | *50.00 FS |
| 39 | 1 | | *FRONT LEFT DOOR STICKER TRANS-CAB | Necessary | 80.00 FS | *60.00 FS |
| 40 | 1 | | *REAR DOOR STICKER 6555-3333 | Not Necessary | 80.00 FS | *-FS |
| 41 | 1 | | *SET REAR BUMPER PARKING SENSOR | Not Necessary | 300.00 FS | *-FS |
| 42 | 1 | | *SET REAR BUMPER FASTENER CLIP | Not Necessary | 44.00 FS | *-FS |
| 43 | 1 | | *SET REAR FENDER INNER TRIM CLIP LH | Not Necessary | 30.00 FS | *-FS |
| 44 | 1 | | *SET REAR BUMPER END DUST COVER CLIP | Not Necessary | 30.00 FS | *-FS |
| F=Fra | anchise | part. S=S | pcNett. L=ListItemDisc. | | | |
| | | | | Sub Total (S\$) | 13,352.14 | 3,348.60 |
| | | | - List Item Discount on L Items 1 | 0.00/10.00% (S\$) | 1,227.87 | 320.86 |
| | | | | Total Parts (S\$) | 12,124.27 | 3,027.74 |
| | | | Report was unsubmitted during this pr | int-out. | | |

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|-------------------|------------|--------|
| Lab | our Items | | | - |
| 1 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 20.00 |
| 2 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 4,500.00 | 500.00 |
| 3 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 4,000.00 | 600.00 |
| 4 | TOWING FEES | New | 120.00 | 50.00 |
| 5 | TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING | New | 380.00 | 0.00 |
| 6 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 60.00 |
| 7 | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING | New | 170.00 | 20.00 |
| 8 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 60.00 |
| 9 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 10 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 11 | TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 60.00 |
| 12 | TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| | Gross Labour | 10,460.00 | 1,370.00 | |
| | Report was unsubmitted durin | g this print-out. | | |

< END OF ESTIMATES >