

ASS. REC. BY:

REF: TEKenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

18/9File pass to Catherine

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Veh No: S1TB 78057Yr Regn: 08.12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: ChevroletEpica c.c. 1991Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 397401

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL1LA69RTBB 096259Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 14/9/18D.O.I. 17/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S R

The UIC / Chassis frame / Body Structure affected due to collision.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7805T**AAD1809-129***Not Authorized
1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7805T

KL1LA69RJB096259

CHEVROLET

EPICA 2.0

14.9.2018

III**PART****LIST**

1	1	Front Fender LH	\$	<i>B</i> 837.60	✓
2	1	Front Fender Liner LH	\$	<i>D</i> 47.00	✓
3	1	Front Fender Inner Wheel House Panel LH	\$	<i>N</i> 1,437.00	X
4	1	Front Shock Absorber Assy LH	\$	216.17	?
5	1	Front Shock Absorber Top Mounting LH	\$	48.32	?
6	1	Front Lower Arm LH	\$	283.00	?
7	1	Front Knuckle Arm LH	\$	230.00	?
8	1	Front Door LH	\$	<i>B</i> 1,133.00	✓
9	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>S</i> 60.00	} X
10	1	Front Door Outer Moulding	\$	<i>S</i> 220.00	
11	1	Front Door Outer Handle	\$	<i>S</i> 125.00	
12	1	Front Door Handle Support	\$	<i>S</i> 3.00	
13	1	Front Door outer handle inner seal	\$	<i>S</i> 89.15	
14	1	Front Door outer key lock	\$	<i>S</i> 25.00	
15	1	Front Door Hinge Upper	\$	<i>N</i> 65.00	
16	1	Front Door Hinge Lower	\$	<i>N</i> 65.00	
17	1	Front Door inner lock	\$	<i>N</i> 586.00	
18	1	Front Door Inner Lock Latch LH	\$	<i>N</i> 206.00	
19	1	Front Door Check / Arrestor	\$	<i>S</i> 67.50	
20	1	Front Door Weatherstrip LH	\$	<i>S</i> 138.79	
21	1	Front Door glass channel weatherstrip	\$	<i>S</i> 160.00	
22	1	Front Door inner trim board	\$	<i>S</i> 455.69	
23	1	Front Door window glass	\$	<i>S</i> 456.12	
24	1	Front Door Power Window Motor (Master) LH	\$	<i>S</i> 284.97	
25	1	Front Door power window motor switch	\$	<i>S</i> 145.00	
26	1	Front Door Window Regulator Gear LH	\$	<i>S</i> 84.58	
27	1	Front Door Outer Pillar Panel LH	\$	<i>N</i> 715.00	
28	1	Front Door Pillar Inner Panel LH	\$	<i>N</i> 850.00	
29	1	Front Door Center Pillar Panel LH	\$	<i>N</i> 698.15	

Trans-cab Auto Services Pte Ltd**AAD1809-129**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7805T

30	1	Front Side View Mirror Assy LH	\$	<i>1,191.00</i> 1,191.00 ✓
31	1	Front Side Rocker Panel Garnish LH	\$	<i>236.40</i> 236.40 X
32	1	Front Side Rocker Panel Outer LH	\$	<i>600.00</i> 600.00 X
33	1	Front Side Rocker Panel Inner LH	\$	<i>519.30</i> 519.30 X

TOTAL	\$	12,278.74
10%	\$	1,227.87
	\$	11,050.87

Special Nett

1 Set	Front Fender Liner clip	\$	<i>30.00</i> 30.00 ✓
1	Front Fender RR Bracket LH	\$	<i>7.10</i> 7.10 X
1	Rear Wheel Rim Hub Cap LH	\$	<i>166.30</i> 166.30 X
1	Rear Tyre LH	\$	<i>180.00</i> 180.00 X
1	Rear Tyre Rim LH	\$	<i>126.00</i> 126.00 <i>Garn</i>
1	Front left door sticker 'Trans-cab'	\$	<i>80.00</i> 80.00 <i>Garn</i>
1	Rear rear door sticker '6555-3333'	\$	<i>80.00</i> 80.00 X
1Set	Rear Bumper Parking Sensor	\$	<i>300.00</i> 300.00 X
1Set	Rear Bumper Fastener Clip	\$	<i>44.00</i> 44.00 X
1Set	Rear Fender Inner Trim Clip LH	\$	<i>30.00</i> 30.00 X
1Set	Rear Bumper End Dust Cover Clip	\$	<i>30.00</i> 30.00 X

TOTAL	\$	1,073.40
--------------	-----------	-----------------

TOTAL PARTS	\$	12,124.27
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	<i>201</i> 170.00
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>5001</i> 4,500.00
Putty and spray painting of the affected portion.	\$	<i>6001</i> 4,000.00
Towing Fees.	\$	<i>501</i> 120.00

Trans-cab Auto Services Pte Ltd**AAD1809-129**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7805T

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	<i>known</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X

TOTAL \$ 10,460.00**Over All Total \$ 22,584.27****Repair Days (Lump Sum)***15 days**3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: