

ASS. R.C. BY:

REF:

CS/MSH18016986/Urbn2

Special Instruction:

Survivor:

Marins.

## ASSIGNMENT (Office)

Mishman

From (Person):

Monica Chung

of

MSH

Date/Time:

18/09/2018 9:10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

PC 50546

Insured:

SKN 8231T

at Workshop m/s

Think One

Tel:

of

No. 18 Dehu Ave 2

Policy No:

1000748585

Claim No:

220798

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31081018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

18/09/2018

9:52am

Person Contacted:

Karen

Vehicle:

IN OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

PC 50546 - X

SKN 8231T - X

Revert thru menimen

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

*MSIC***ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *PC50546*at Workshop m/s *Think one*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

CA / PR Seen: *✓* Consistent? : Yes or NoEst. Repairs: *4* days Res.: Yes or NoLum Sum: *1.31* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

*LTA 3958*

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *PC50546*Yr Regn: *10/16*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Toyota hiace* c.c. *2982*Colour: *white* A/C: Insured / Std / NI / NASp. Reading: *111933* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *KDH2230029631*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: *195 R15*

R: \_\_\_\_\_

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or *Captiva*

Front

Rear

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *31/8/18* D.O.I. *18/9/18*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

*Rear*

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*\$4500.90**8/10/18 confirmed final fig \$4500.90 with Keren**Red: \$10514.85, 70%.*

RECEIVED 12 OCT 2018

Date/Time, File Pass to?



: Preli. Report

Days Of Repair: *4*Resurvey No. of Trip: *2*1) *typist*

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: *TP*Lump Sum / I.B.I. (\$) *4500.90**200**10**210*

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 12 Oct 2018

## Preliminary Advice

Insured Vehicle No : SKN8231T  
TP Vehicle No : PC5054G  
Make : TOYOTA HIACE  
Date of Inspection : 18/09/2018  
Inspection At : THINK ONE AUTOCARE PTE LTD (HQ)  
NO. 18 DEFU AVENUE 2  
SINGAPORE 539522

Accident Date : 31/08/2018  
Assignment Date : 18/09/2018  
Est. Duration of Repair : 4.00

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,015.75
Revised Amount	:S\$	4,500.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,500.90

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2018		18 Sep 2018 09:10 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

Insured:	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD, Co. Reg. No.: 197901535G, Email: kenkwek@tcls.com.sg			[Created by insurer]
Main Claimant:	THINK ONE LEASING PTE LTD, Co. Reg. No.: 201115609M			
Vehicle Reg. No.:	PC5054G	Date of Loss:	31/08/2018 08:00 - :59 [22 Months and 12 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 220798	Policy/Cover Note No.:	1000748585 (Comprehensive) Coverage: 21/07/2018 - 20/07/2019	
Vehicle Reg. No. (Insured):	SKN8231T	Policy No. (Claimant):		
Repairer:	Excess:		S\$300.00	
Handling Insurer:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2, 539522 Ubi - Tel: 68443300 MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/09/2018]			
Driver/Custodian (Insured):	CHUN KWI DO (), NRIC: G5315316Q, Tel: +6596734869			
Adj Asg. Remarks:	SJE AGREE LKK Auto Consultancy Marcus Chua. Liab 100%. Pls contact Karen Tan @ 9128 8488 / 6844 3300			

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

## ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete	Done?
No results.										

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/08/2018 10:36
Date Of Accident	31/08/2018 09:05
Exact Location Of Accident	SUNGEI ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC5054G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THINK ONE LEASING PTE LTD
Co Reg No	201115609M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 COMMUTER GL (A)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5070785764-03
Cover Note Number	

### Driver

Name of Driver	LAW TUCK WAI
NRIC No	S1736468E
Date Of Birth	25/09/1966
Occupation	OUTDOOR
Date Of Driving Pass	19/07/1989
Driving Experience	29 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96848373
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 21 QUEEN CLOSE # 05-135
Postcode	140021
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE 31.08.2018 AT ABOUT 0905HR I WAS DRIVING ALONG ROCHOR CANAL IN A 5 LANE ROAD. I WAS IN THE 3RD LANE FROM MY RIGHT. AS STOPPING AT THE TRAFFIC LIGHT AHEAD. A VEHICLE SKN8231T COLLIDE AT MY REAR. NO INJURIES INCURRED IN THIS ACCIDENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN8231T
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	CHUN KWI DO
NRIC/Passport Number	G5315316Q
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 31-08-2018 at about 0905HR I was driving along Rochor Canal in a 5 lane Road. I was in the 3rd lane from my right. As stopping at the traffic light ahead. A vehicle SKN833IT collide at my rear. No injuries incurred in this ~~accid~~ accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 3/8/18 1025 Hrs

Think One Autocare Pte Ltd  
18 Defu Lane Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5609M

### Vehicle Details

Vehicle No.: PC5054G

Vehicle to be Exported: No

Intended Deregistration Date: 18 Sep 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE COMMUTER 3.0 GL AUTO

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1KD2650193

Chassis No.: KDH2230029631

Maximum Power Output: -

Open Market Value: \$45,697.00

Original Registration Date: 19 Oct 2016

First Registration Date: 19 Oct 2016

Transfer Count: 0

Actual ARF Paid: \$2,285.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 18 Oct 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$4,897.00

COE Rebate Amount: \$3,958.00

**Total Rebate Amount: \$3,958.00**

The information contained herein is correct as at 18 Sep 2018

OK



P/P # 4500-901

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

Not Authorized  
Link

2/5/8  
Hdy.

18/9/18  
The above repair

PC5054G Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>02/12</i>	\$ 1,660.00
2	2	Rear bumper bracket <i>40.70 x 2 = 81.40</i>	\$ 172.00
3	1	Rear bumper inner beam <i>NT</i>	\$ 287.00
4	1	Rear tailgate assy <i>S. 1500</i>	\$ 2,662.00
5	1	Rear tailgate lock mechanism <i>701/5M</i>	\$ 266.00
6	1	Rear tailgate lock catch <i>11</i>	\$ 65.00
7	2	Rear tailgate hinges <i>11</i>	\$ 166.00
8	2	Rear tailgate damper <i>11</i>	\$ 375.00
9	1	Rear tailgate weatherstrip <i>11</i>	\$ 288.00
10	1	Rear tailgate inner board <i>11</i>	\$ 190.00
11	1	Rear tailgate centre logo <i>nee</i>	\$ 69.00
12	1	Rear tailgate 'hiace' emblem <i>nee</i>	\$ 65.00
13	1	Rear tailgate 'GL' emblem <i>nee</i>	\$ 68.00
14	1	Rear tailgate windscreen glass moulding <i>NS</i>	\$ 295.00
15	1	Rear tailgate lock actuator <i>11</i>	\$ 189.00
16	1	Rear tailgate outer garnish <i>11</i>	\$ 176.00
17	1	Rear tailgate lock cylinder <i>11</i>	\$ 191.00
18	1	Rear left taillamp <i>11</i>	\$ 885.00
19	1	Rear right taillamp <i>ene</i>	\$ 885.00
20	1	Rear left taillamp lower panel <i>11</i>	\$ 109.00
21	1	Rear right taillamp lower panel <i>11</i>	\$ 109.00
22	1	Rear end lower panel <i>11</i>	\$ 1,275.00
23	1	Rear spare tyre carrier <i>11</i>	\$ 376.00
24	1	Rear exhaust muffler assy <i>11</i>	\$ 2,400.00
25	2	Rear exhaust muffler rubber mounting <i>11</i>	\$ 38.00
			\$ 13,261.00
Less 25%			\$ 3,315.25
			\$ 9,945.75

3561.20  
25%

2670.90  
S.N 350  
1480  
4500.90

**Think One Autocare Pte Ltd**  
**No.18 Defu Avenue 2**  
**Singapore 539522**  
**Tel: 6844 3300 Fax: 6842 4988**

**PC5054G Toyota Hiace**

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Rear bumper clips <i>nee</i>	\$	50.00 <i>40</i>
2	12	Rear tailgate inner board clips <i>11</i>	\$	30.00 <i>X</i>
3	4	Rear tailgate outer garnish clips <i>11</i>	\$	20.00 <i>X</i>
4	1	Rear tailgate '70km/h' sticker <i>nee</i>	\$	30.00 <i>10</i>
5	1	Rear tailgate 'emergency door' sticker <i>nee</i>	\$	30.00 <i>✓</i>
6	1	Rear tailgate 'pull to open' sticker <i>nee</i>	\$	30.00 <i>✓</i>
7	1	Rear windscreen glass sealant <i>nee</i>	\$	80.00 <i>40</i>
8	1	Rear view camera <i>11</i>	\$	300.00 <i>X</i>
9	<i>2</i> <del>1</del>	Rear bumper reverse sensor <i>shut</i>	\$	250.00 <i>200</i>
10	1	Rear no plate <i>11</i>	\$	80.00 <i>X</i>
			\$	900.00
<b>Total Parts</b>			<b>\$ 10,845.75</b>	<i>350</i>

KK Auto Consultants hence notify the Repairer of the following:

- To be used before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

**PC5054G Toyota Hiace**

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,600.00	1-80
2	To putty and spray painting rear portion.	\$ 1,600.00	600
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00	X
6	To apply anti rust proofing to rear affected area.	\$ 120.00	50
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	120
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear view camera.	\$ 80.00	X
10	To remove and install rear exhaust muffler assy.	\$ 150.00	X
11	Towing service.	\$ 120.00	X
<b>Total labour :</b>		<b>\$ 4,170.00</b>	1480

**Total parts : \$ 10,845.75**

**Total labour : \$ 4,170.00**

**Total repair cost : \$ 15,015.75**

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016986/URBN2

Date: 15/10/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000748585
Claimant Vehicle No :	PC5054G	Insured Vehicle No :	SKN8231T
Date of Loss:	31/08/2018	Nature of Claim:	TP
		Claim No:	220798

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	PC5054G	Engine No:	1KD2650193
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2230029631
Reg. Date:	19/10/2016 (Man. Year: 2016)	Odometer:	111933 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,845.75	3,020.90	7,824.85	72.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	1,480.00	2,690.00	64.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,015.75</b>	<b>4,500.90</b>	<b>10,514.85</b>	<b>70.03</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,051.10</b>	<b>315.06</b>	<b>736.04</b>	<b>70.03</b>
<b>Nett Amount (S\$)</b>	<b>16,066.85</b>	<b>4,815.96</b>	<b>11,250.89</b>	<b>70.03</b>

## INSPECTION

Date of Assignment:	18/09/2018	
Date Inspected:	18/09/2018	Inspected At: Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2 Singapore 539522

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source:	(Last Synchronised: 15 Oct 2018)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5054G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented/Deformed	1,660.00 FL	*539.90 FL
2	2		*REAR BUMPER BRACKET	Bent	172.00 FL	*81.40 FL
3	1		*REAR BUMPER INNER BEAM	Not fitted	287.00 FL	*- FL
4	1		*REAR TAILGATE ASSY	Badly Dented	2,662.00 FL	*2,145.30 FL
5	1		*REAR TAILGATE LOCK MECHANISM	Twisted/Jammed	266.00 FL	*266.00 FL
6	1		*REAR TAILGATE LOCK CATCH	Not Necessary	65.00 FL	*- FL
7	2		*REAR TAILGATE HINGES	Not Necessary	166.00 FL	*- FL
8	2		*REAR TAILGATE DAMPER	Not Necessary	375.00 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	288.00 FL	*- FL
10	1		*REAR TAILGATE INNER BOARD	Not Necessary	190.00 FL	*- FL
11	1		*REAR TAILGATE CENTRE LOGO	Necessary	69.00 FL	*45.90 FL
12	1		*REAR TAILGATE HIACE EMBLEM	Necessary	65.00 FL	*46.60 FL
13	1		*REAR TAILGATE GL EMBLEM	Necessary	68.00 FL	*50.00 FL
14	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	295.00 FL	*- FL
15	1		*REAR TAILGATE LOCK ACTUATOR	Not Necessary	189.00 FL	*- FL
16	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	176.00 FL	*- FL
17	1		*REAR TAILGATE LOCK CYLINDER	Not Necessary	191.00 FL	*- FL
18	1		*REAR LEFT TAILLAMP	Not Necessary	885.00 FL	*- FL
19	1		*REAR RIGHT TAILLAMP	Cracked	885.00 FL	*386.10 FL
20	1		*REAR LEFT TAILLAMP LOWER PANEL	Repair	109.00 FL	*- FL
21	1		*REAR RIGHT TAILLAMP LOWER PANEL	Repair	109.00 FL	*- FL
22	1		*REAR END LOWER PANEL	Repair	1,275.00 FL	*- FL
23	1		*REAR SPARE TYRE CARRIER	Not Necessary	376.00 FL	*- FL
24	1		*REAR EXHAUST MUFFLER ASSY	Not Necessary	2,400.00 FL	*- FL
25	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	38.00 FL	*- FL
26	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
27	12		*REAR TAILGATE INNER BOARD CLIPS	Not Necessary	30.00 FS	*- FS
28	4		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
29	1		*REAR TAILGATE 70KM/H STICKER	Necessary	30.00 FS	*10.00 FS
30	1		*REAR TAILGATE EMERGENCY DOOR STICKER	Necessary	30.00 FS	*30.00 FS
31	1		*REAR TAILGATE PULL TO OPEN STICKER	Necessary	30.00 FS	*30.00 FS
32	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*REAR VIEW CAMERA	Not Necessary	300.00 FS	*- FS
34	1		*SET REAR BUMPER REVERSES ENSOR	Shorted	250.00 FS	*200.00 FS
35	1		*REAR NO PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) **14,161.00**      **3,911.20**  
 - List Item Discount on L Items 25.00/25.00% (\$\$)      3,315.25      890.30

**Total Parts (\$\$) 10,845.75      3,020.90**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,600.00	580.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,600.00	600.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	150.00	-
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	50.00
7	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
9	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	-
10	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	150.00	-
11	TOWING SERVICE	New	120.00	-
Gross Labour Cost (S\$)			4,170.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >