

O.S.K. Auto Spare Parts Trading (1994)

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-09
Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: oskautomotiveamk@gmail.com

*Kenrick
96910663*

*NOT Insured
Murry B & paint 1-B-1*

M/s AXA Insurance Pte Ltd DATE 17.09.2018
8 Shenton Way, #27-01 CAR NO SMA 5480 E
AXA Tower S068811 MAKE Honda Jazz

6 days

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : GX 5504 X

Qty	Pcs	JHMGK3850JX223191	UNIT PRICE	AMOUNT
1	DC	Rear bumper left hand side retainer		\$11.50
1	DC	Rear left side mudguard		\$29.90
1	DC	Rear left side mudguard inner cowling		\$53.70
8	DCS	Rear left side mudguard inner cowling clips	\$3.80	\$30.40
1	DC	Rear left side mudguard quarter glass		\$271.10
1	DC	Rear left side absorber		\$212.90
1	DC	Rear axle		\$929.30
1	DC	Rear left side hub and bearing		\$281.80
1	DC	Rear left side tyre rim		\$767.10
		To apply anti-rust coating onto repaired area.		\$120.00
		To provide labour, workmanship to realign rear end panel, left side rear door, cutting rear left side mudguard, dismantle and replace the above mentioned parts.		\$1,200.00
		Labour for respray rear end panel, rear left side door, rear left side mudguard and rear bumper in pearl white.		\$1,200.00
		To conduct water leakage test.		\$80.00
		To dismantle and replace rear left side quarter glass.		\$90.00
		To apply silicon onto rear left side quarter glass.		\$60.00

} wheel alignment

208

✓
✓
X
X
?
?
?
?
✓
300
600
660
200
800
300

Page 1 of 1 Total \$5,337.70

[Signature]

O.S.K. Auto Spare Parts Trading (1994)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: