

20072001

ASS. REC. BY

REF

CS/CT18017005/Urbn2

Special Instruction:

Surveyor

Melina

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

21/9/2018 10:00am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 4889K

Insured:

SKX 6936D

at Workshop m/s

Hup Motor

Tel:

of

Blk 5004 Tampines St 93 #01-120

Policy No:

DMPCSN 3003391800

Claim No:

SNM18D0455202.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/09/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 4889K - NA / <u>II</u> 18016168 / 64
	SKX 6936D - X

DA: 17/09/2018

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / NV / MV

To Inspect Vehicle No: GSM 4889Kat Workshop m/s hang nhe

of _____

Insured: SKX 69362

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 136 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GSM 4889KYr Regn: 6, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or inMake: Toyota hiace

c.c

2982Colour: silver

A/C:

Insured / Std / NI / NA

Sp.Reading: 7538

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JTFMT02P900242961Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 195 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 2 mmL/Bal. 2 mmL/Bal. 2 mmD.O.A. 17/9/18D.O.I. 18/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/ Time Action / Instruction

12/10/18 confirmed final G 1770.20 with David. (Red 1193.82, 40%)

RECEIVED 12 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

12/10 - typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 1770.20)220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Sep 2018		21 Sep 2018 10:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:			
Main Claimant:	HARMONY FURNISHING PTE LTD		
Vehicle Reg. No.:	GBH4889K	Date of Loss:	17/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04552C02	Policy/Cover Note No.:	DMPCSN3003391800
Vehicle Reg. No. (Insured):	SKX6936D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2018]		
Adj Asg. Remarks:	EST \$2964.02, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7314K
Vehicle Details	
Vehicle No.:	GBH4889K
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2805064
Chassis No.:	JTFHT02P900242961
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	14 Jun 2018
First Registration Date:	14 Jun 2018
Transfer Count:	1
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,901.00
COE Rebate Amount:	\$29,108.00
Total Rebate Amount:	\$29,108.00

The information contained herein is correct as at 19 Sep 2018

OK

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2923/09/18 Your Ref: _____ Date: 18th September 2018

HARMONY FURNISHING PTE. LTD.
15, SENANG CRESCENT,
SINGAPORE 416588

Estimate cost of repair to TOYOTA HIACE VAN TURBO - GBH 4889 K

1 pc rear bumper	DD/OK	\$	539.30	✓
6 pcs rear bumper top clips	@ \$	3.80	22.80	✓
6 pcs rear bumper top clips stopper	@ \$	4.20	25.20	✓
2 pcs rear bumper o/s & n/s side bracket	@ \$	40.70	81.40	✓
4 pcs rear bumper o/s & n/s side bracket clips	@ \$	3.80	15.20	✓
4 pcs rear bumper o/s & n/s low bracket	@ \$	29.40	117.60	✓
4 pcs rear bumper o/s & n/s low bracket clips	@ \$	3.80	15.20	✓
1 pc rear bumper beam			197.00	✓
1 set rear bumper reverse sensor			285.00	2005.20
1 pc rear end panel			328.00	✓
1 pc tail gate door 'TOYOTA' emblem sticker			45.90	✓
1 pc tail gate door 'HIACE' emblem sticker			46.60	✓
1 pc tail gate door '70km/h' sticker			19.50	105.20
			<u>\$ 1,738.70</u>	
	Less 25%		<u>\$ 434.68</u>	
			<u>\$ 1,304.02</u>	

To wiring check up 30.00 20

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, carrier & necessary parts, to enable repair rear end panel, tail gate door & necessary parts. 11 120.00 X

To respray Tuff-Kote on all affected accident parts. 11 60.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear end panel, tail gate door & necessary parts, to weld, renew & align above parts. 600.00 300

To putty & respray painting on all affected accident parts. 850.00 600

\$ 2,964.02

Dollars : Two Thousand Nine Hundred Sixty Four And Cents Two Only.

HUP MOTOR TRADING & SERVICE

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

2-853.60
252
640.20
S.N - 210
Idm - 920
1770.20

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017005/UVBN2

Date: 12/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3003391800
Claimant Vehicle No :	GBH4889K	Insured Vehicle No :	SKX6936D
Date of Loss:	17/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04552C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4889K	Engine No:	1KD2805064
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	JTFHT02P900242961
Reg. Date:	14/06/2018 (Man. Year: 2018)	Odometer:	7538 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repaire's	Adjuster's	Difference	Diff %
Parts	1,304.03	850.20	453.83	34.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	920.00	740.00	44.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	2,964.03	1,770.20	1,193.83	40.28

INSPECTION

Date of Assignment:	21/09/2018	
Date Inspected:	18/09/2018	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Oct 2018)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4889K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	539.30 FL	*539.30 FL
2	6		*REAR BUMPER TOP CLIPS	Necessary	22.80 FL	*22.80 FL
3	6		*REAR BUMPER TOP CLIPS STOPPER	Not Necessary	25.20 FL	*- FL
4	2		*REAR BUMPER O/S & N/S SIDE BRACKET	Bent	81.40 FL	*81.40 FL
5	4		*REAR BUMPER O/S & N/S SIDE BRACKET CLIPS	Not Necessary	15.20 FL	*- FL
6	4		*REAR BUMPER O/S & N/S LOW BRACKET	Bent	117.60 FL	*117.60 FL
7	4		*REAR BUMPER O/S & N/S LOW BRACKET CLIPS	Not Necessary	15.20 FL	*- FL
8	1		*REAR BUMPER BEAM	Repair	197.00 FL	*- FL
9	1		*REAR END PANEL	Repair	328.00 FL	*- FL
10	1		*TAIL GATE DOOR TOYOTA EMBLEM STICKER	Necessary	45.90 FL	*45.90 FL
11	1		*TAIL GATE DOOR HIACE EMBLEM STICKER	Necessary	46.60 FL	*46.60 FL
12	1		*TAIL GATE DOOR 70KM/H STICKER	Necessary	14.63 FS	*10.00 FS
13	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	213.75 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,662.58	1,063.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	358.55	213.40
Total Parts (\$\$)	1,304.03	850.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO WIRING CHECK UP	New	30.00	20.00
2	TO REMOVE & REFIX CARPET,FLOOR MAT,GARNISH,FLOOR BOARD COVER,SPARE TYRE,CARRIER & NECESSARY PARTS,TO ENABLE REPAIR REAR END PANEL,TAIL GATE DOOR & NECESSARY PARTS	New	120.00	-
3	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	60.00	-
4	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT REAR END PANEL,TAIL GATE DOOR & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	600.00	300.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	850.00	600.00
Gross Labour Cost (S\$)			1,660.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >