

REPAIR ESTIMATE*

VEHICLE NO : SHC 3498S

DATE 18/9/2018 10:56

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>one</i>			\$ 544.50
	Front Bumper Sponge <i>one</i>			\$ 99.20
	Front Bumper Reinforcement <i>one</i>			\$ 402.10
	Front Bumper Centre Grille <i>✓ at (lower)</i>			\$ 178.60
	Front Bumper Bracket Top (LH/RH) <i>one</i>		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>one</i>		\$ 24.60	\$ 49.20
	SUB TOTAL			\$ 1,318.40
	LESS 20%			\$ 263.68
	DISCOUNTED TOTAL			\$ 1,054.72
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
				200
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 1,654.72
<p><i>1 call 1 call</i></p> <p><i>18/9/18 14:20</i></p> <p><i>2 days</i></p> <p><i>4/5</i></p> <p><i>After Repair photo</i></p>				<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

PWO
JM