

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd

AIG Building

78 Shenton Way #08-16

Singapore (079120)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6419 3000 Fax : 6835 7416

DEAR SIR / MADAM :

*Not Authorized
1-B1
Presuming B4 point
6 days*

ACCIDENT REPAIR ON: SLN9802C

MODEL : HYUNDAI ELANTRA

POLICY NO : 18MPC00012125

CHASSIS NO : KMHD841CMHU460222

YEAR OF MANUFACTURE : 2017

DATE / TIME OF ACCIDENT: 14/09/2018 Time: 0630hrs at SLE Towards BKE.

THIRD PARTY VEHICLE NO: SJY9475D

Date: 18/09/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount	
S/N			S\$		S\$	
1	Bootlid	1	1,620.40	Bented	1,620.40	X
2	Bootlid hinge LH	1	94.30	Bented	94.30	X
3	Bootlid hinge RH	1	94.30	Bented	94.30	X
4	Bootlid emblem	1	28.00	Necessary	28.00	—
5	Bootlid lettering "ELANTRA"	1	48.80	Necessary	48.80	—
6	Bootlid weatherstrip	1	92.50	Torn	92.50	X
7	Bootlid lock assy	1	116.20	Bented	116.20	X
8	Bootlid lamp LH	1	284.90	Scratches	284.90	X
9	Bootlid lamp RH	1	284.90	Scratches	284.90	X
10	Rear bumper	1	459.40	Broken	459.40	—
11	Rear bumper side retainer LH	1	44.30	Necessary	44.30	X
12	Rear bumper side retainer RH	1	44.30	Necessary	44.30	X
13	Rear bumper lower garnish	1	250.10	Cut	250.10	—
14	Rear bumper sensor wiring harness	1	71.00	Malfunction	71.00	?
15	Rear bumper reflector LH	1	32.00	Scratches	32.00	X
16	Rear bumper reflector RH	1	32.00	Scratches	32.00	—
17	Rear bumper reinforcement	1	294.80	Dented	294.80	—
18	Rear smart key assist	1	40.50	Malfunction	40.50	?
19	Rear fender RH	1	1,768.30	Bented	1,768.30	X
20	Rear fender shield front section RH	1	60.40	Cut	60.40	X
21	Rear fender shield rear section RH	1	56.00	Cut	56.00	X
22	Rear tail lamp assy LH	1	362.60	Scratches	362.60	?
23	Rear tail lamp assy RH	1	362.60	Scratches	362.60	?
24	Rear end panel	1	379.00	Dented	379.00	—
25	Rear end panel top garnish	1	60.00	Kinked	60.00	—
26	Spare tyre panel	1	246.50	Dented	246.50	X
Sub-Total:					7,228.10	
Less: 20% discount -					1,445.62	
Total Parts after 20% discount:					5,782.48	

Special Nett Items

1	Anti-rust coating	3	80.00	240.00
---	-------------------	---	-------	--------

2	Rear bumper clips	12	3.00
3	Rear fender shield clips	24	2.00
4	Gum sealant	1	120.00
5	Rear bumper sensor set	1	250.00
6	Rear end panel top garnish clips	8	2.00

36.00	✓
48.00	X
120.00	X
250.00	?
16.00	✓
710.00	

Total Parts: 6,492.48

Labour Charges For Rear Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs
- 5 Provide skill labour to remove and replace bumper sensors
- 6 Provide skill labour to remove and refit rear end panel lining and garnish to facilitate repair

1,750.00	7001
1,500.00	8001
60.00	201
150.00	601
60.00	501
80.00	X

Total Labour:

Total Parts & Labour:
GST 7%
Grand Total:

3,600.00
10,092.48
706.47
10,798.95

Estimate Repair Duration

13 days
6 days

ACCIDENT VEHICLE OF : SLN9802C

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth
Company : LKK
Date : 19/9/18
Time : 11am
Contact No : 96910663
Email :

