

AJAX

Inspection Services Pte Ltd

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Corinne Hoo

Assign Date:	06/03/2017	Survey Date:	06/03/2017	TP Report Date:	02/03/2017
Accident Date:	01/03/2017	TP Policy No:	5087390677	Our Ref:	AVS2017-09701/BL
Place of Survey:	Wah Yu			Your Ref:	MT/0935991-002
	176 Sin Ming Drive Sin Ming Autocare #05-09			Claim Type:	Third Party
	Singapore 408898			Claimant:	Low Kim Harn

Description of Vehicle:

Veh. No:	SLJ1460D	Make/Model:	Saab 9-5 Vector 2.0T AT ABS D/AB 2WD 4DR HID		
Colour:	Grey	Engine No:	A20NFT0N003004	Sum Insured (S\$):	NA
Engine Capacity:	1,998cc	Chassis No:	Y53GP4AZ9B4002977	Mkt Value (S\$):	\$70,000.00
Odometer:	120221	Reg. Date:	14/01/2011	Excess (S\$):	NA

Condition of Vehicle:

General:	Good	Modification:	No	Steering:	Serviceable
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Good
Tyre Make:	Dunlop				
Front Tyre Size:	245/45R18	Front Left Side:	6mm	Front Right Side:	6mm
Rear Tyre Size:	245/45R18	Rear Left Side:	6mm	Rear Right Side:	6mm

Description of Damage:

The vehicle sustained damage on the rear portion.

The rear boot lid, rear bumper, rear end panel and rear tail lamps were among the items affected.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$11,900.00 with approximately 6 working days to complete. No finalisation was agreed with the repairer

All the stated damage are subject to consistency of the mentioned accident.



COMPLETED 06 APR 2017

Adjuster: Billy Loh
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:			SLJ1460D	Our Ref: AVS2017-09701/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Trunk lid	Bent	4,280.00	3,950.00
2	1	Trunk lid light bar	Cracked	2,225.60	1,450.00
3	1	Trunk lid light bar SAAB emblem	Necessary	111.30	80.00
4	1	Trunk lid 95 emblem	Necessary	137.00	60.00
5	1	Trunk lid turbo4 emblem	Necessary	137.00	85.00
6	9	Trunk lid interior trim clip	Necessary	72.00	45.00
7	1	Rear end panel	Bent	2,073.60	1,400.00
8	1	Rear LED combination lamp - O/S	Cracked	1,779.20	1,350.00
9	1	Rear bumper face	Bent	5,228.80	2,450.00
10	4	Rear bumper parking sender	Damaged	606.20	606.20
11	4	Rear bumper parking sender retainer	Necessary	82.40	82.40
12	1	Rear bumper tow cover	Not necessary	171.20	--
13	1	Rear bumper tail lamp	Not necessary	710.40	--
14	1	Rear bumper inner centre bracket	Cracked	479.40	479.40
15	1	Rear bumper energy absorber	Not necessary	616.30	--
16	1	Rear bumper impact bar	Bent	993.00	705.00
17	1	Rear bumper side bracket - O/s	Necessary	308.20	230.00
18	1	Rear bumper side bracket - N/S	Not necessary	--	--
Sub Total:				20,011.60	12,973.00
Discount (less 10%):				2,001.16	1,297.30
				18,010.44	11,675.70

Special Nett Items					
1	1	Trunk lid inner sealant	Necessary	60.00	40.00
2	1	Rear end panel joint sealant	Necessary	60.00	40.00
Sub Total:				120.00	80.00
Total Parts Price:				18,130.44	11,755.70

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:			SU1460D	Our Ref: AVS2017-09701/BL	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
Labour Cost					
1		To cut/ weld rear end panel to renew; panel beat right rear fender panel and repair spare wheel floor panel including replacement of the right rear accident damaged parts.		2,275.00	1,600.00
2		To transfer trunk lid locking mechanism and other components to new trunk lid Include checking components for function.		80.00	60.00
3		To remove/ install trunk compartment trim finishers, garnishes and interior upholstery to facilitate the replacement of the rear end panel and repairing of the right rear fender panel including the spare wheel floor panel.		225.00	80.00
4		To remove/ install fuel tank assembly and fittings to facilitate the repairing of the right rear fender panel include checking system for leaks.		120.00	80.00
5		To check rear lightings and electrical wiring systems include performing water leakage test.		50.00	30.00
6		To install rear bumper parking senders to new bumper face include testing for functions.		160.00	40.00
7		To putty and respray painting on trunk lid, spare wheel floor panel, rear end panel, right rear fender, left rear fender and rear bumper face.		1,800.00	1,200.00
8		Rust -proofing on the right rear accident affected portions.		80.00	50.00
Sub Total:				4,790.00	3,150.00
Grand Total:				22,920.44	14,905.70

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R