

090210

INS. CASE OWNER

Vale

CC 4 ASM
AXA1801 7053, U 463LKK
IDAC

Surveyor:

Marius

DOI:

ASSIGNMENT

21/1/18

Date / Time:

14/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YP 248P

Claim No.:

8800008 70226 8728

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$

D.O.A.:

21/8/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VA: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

GDF43714

INSRS:
WSP:
Tel:
Liability:
RMKS:think
oneINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

GDF43714-1

YP248P-1

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

\$

Loss of Rental (LOR):

\$

(days)

Loss of Use (LOU):

\$

(\$ x days)

Loss of Income (LOI):

\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost:

\$

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: Y/P

3) Survey fee: 8290

REF: ASM(AXA)

Surveyor Marcus

ASSIGNMENT

From: Date: 21092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 4371Y

at Workshop m/s:

Think One

of

No. 18 Delta Ave 2

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

10km

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

Spk.

IDAC Accident Rpt:

Consistent? : Yes or No

GVA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

5629M

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBF 4371Y Yr Regn: 10.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota hiace c.c. 2982

Colour: orange A/C: Insured / Std / NI / NA

Sp. Reading: 79064 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDH 2015023666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxtrek

Front:

6

mm

Rear:

6

mm

R/Bal:

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

31/8/18

D.O.I:

21/9/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 36313

45 - \$3600+ (Red: \$6430.75 / 64%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) 0 - RE 01

) Photo

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

not added
h/s
Hdy.
the pre. Hdy.
21/9/18

GBF4371Y Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy 20/sep 596.20	\$ 1,260.00
2	2	Rear bumper bracket 34	\$ 172.00
3	1	Rear bumper inner beam 11	\$ 287.00
4	1	Rear tailgate assy 5.45m	\$ 2,062.00
5	1	Rear tailgate lock mechanism 1m/3m	\$ 266.00
6	1	Rear tailgate lock catch 11	\$ 62.00
7	2	Rear tailgate hinges 11	\$ 162.00
8	2	Rear tailgate damper 11	\$ 375.00
9	1	Rear tailgate weatherstrip 11	\$ 288.00
10	1	Rear tailgate inner board 11	\$ 190.00
11	1	Rear tailgate centre logo 11	\$ 69.00
12	1	Rear tailgate windscreen glass moulding 11	\$ 295.00
13	1	Rear tailgate lock actuator 11	\$ 189.00
14	1	Rear tailgate outer garnish 11	\$ 176.00
15	1	Rear tailgate lock cylinder 11	\$ 191.00
16	1	Rear left taillamp 11 338.	\$ 785.00
17	1	Rear right taillamp 11	\$ 785.00
18	1	Rear left taillamp lower panel 11	\$ 109.00
19	1	Rear right taillamp lower panel 11	\$ 109.00
20	1	Rear end lower panel 11	\$ 1,275.00
21	1	Rear spare tyre carrier 11	\$ 376.00
22	1	Rear exhaust muffler assy 11	\$ 2,400.00
23	2	Rear exhaust muffler rubber mounting 11	\$ 38.00
Less 25% 11			\$ 11,921.00
			\$ 2,980.25
			\$ 8,940.75

1703.2
1751.60

Special Nett Items

1	10	Rear bumper clips 11	\$ 50.00
2	12	Rear tailgate inner board clips 11	\$ 30.00
3	4	Rear tailgate outer garnish clips 11	\$ 20.00
4	1	Rear tailgate '70km/h' sticker 11	\$ 30.00
5	1 set	Rear tailgate company sticker 11	\$ 250.00
6	1	Rear windscreen glass sealant 11	\$ 80.00
7	1	Rear view camera 11	\$ 300.00
8	1	Rear bumper reverse sensor 11	\$ 250.00
9	1	Rear no plate 11	\$ 80.00
			\$ 1,090.00

Total Parts

\$ 10,030.75

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBF4371Y Toyota Hiace

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,600.00	400
2	To putty and spray painting rear portion.	\$ 1,600.00	600
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear inner garnish and trim to facilitate the repair.	11 \$ 150.00	X
6	To apply anti rust proofing to rear affected area.	\$ 120.00	60
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	120
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear view camera.	11 \$ 80.00	X
10	To remove and install rear exhaust muffler assy.	11 \$ 150.00	X
11	Towing service.	11 \$ 120.00	X
Total labour :		\$ 4,170.00	

Total parts : \$ 10,030.75

Total labour : \$ 4,170.00

Total repair cost : \$ 14,200.75

LOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 5609M

Vehicle Details

Vehicle No.: GBF4371Y

Vehicle to be Exported: No

Intended Deregistration Date: 21 Sep 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE DX 3.0 MANUAL

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1KD2636657

Chassis No.: KDH2015023666

Maximum Power Output: -

Open Market Value: \$34,534.00

Original Registration Date: 27 Oct 2016

First Registration Date: 27 Oct 2016

Transfer Count: 1

Actual ARF Paid: \$1,727.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$44,849.00

COE Rebate Amount: \$36,313.00

Total Rebate Amount: \$36,313.00

The information contained herein is correct as at 21 Sep 2018

OK



Service Request Details

Claim

S8M00VO8

Reference

None 

Loss Date

August 31, 2018

Request Date

September 18, 2018

Due Date

September 25, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

18/09/2018 @ 430pm
Keren veh not in.
'Virtual'

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBF4371Y

Make

TPVD

Model

TBC

Service Address

...

Primary Contact/Insured

RHM ENGINEERING PTE LTD
BLOCK 170 GANGSA ROAD, #04-44, 670170, Singapore
63380083
CLIVE@VIRTUALINVEST.BIZ

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Additional Instructions

VIRTUAL'S CASE NON REPORTING

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

9/18/18 3:39 PM

FROM

OH Vale

SUBJECT

VIRTUAL CASE - NON REPORTING-VO

BODY

Hi Pls advise TP to do deem fit if they can't wai...





Service Request Details

Claim

S8M00VO8

Reference

CC4/ASM18017053/ub3 

Loss Date

August 31, 2018

Request Date

September 18, 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for: None - request canceled

Vehicle Information

Incident Vehicle Registration #

GBF4371Y

Make

TPVD

Model

TBC



INSRD PTE SETTLEMENT WITH TP -VO

Type

🔔 Question

Message

Reply

Service Request Details

Claim

S8M00VO8

Reference

None

Loss Date

August 31, 2018

Request Date

December 12, 2018

Due Date

December 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBF4371Y

Make

TPVD

Model

TBC

Service Address

Primary Contact/Insured

RHM ENGINEERING PTE LTD
BLOCK 170 GANGSA ROAD, #04-44, 670170, Singapore
63380083
CLIVE@VIRTUALINVEST.BIZ

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Additional Instructions
PLS SUBMIT YOUR BILL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[Post Message](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18017053/Ujb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 04-12-2018



ATTN:VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 2148P	Veh. Inspected	GBF 4371Y
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00VO8	Excess (\$)	0.00
Assign From		Assign Date	19/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KDH2015023666	Colour	ORANGE
Odometer	79064	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	MAXTREK	6 mm
L/H Front Tyre	195 R15	MAXTREK	6 mm
R/H Rear Tyre	195 R15	MAXTREK	6 mm
L/H Rear Tyre	195 R15	MAXTREK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/08/2018	Inspection Date	21/09/2018
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4371Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY (CONSISTENT)	DENTED / BENT	1,260.00	596.20
2	REAR BUMPER BRACKET (CONSISTENT)	BENT	172.00	172.00
1	REAR BUMPER INNER BEAM (CONSISTENT)	NOT NECESSARY	287.00	-
1	REAR TAILGATE ASSY (CONSISTENT)	BADLY DENTED	2,062.00	2,062.00
1	REAR TAILGATE LOCK MECHANISM (CONSISTENT)	TWISTED / JAMMED	266.00	266.00
1	REAR TAILGATE LOCK CATCH (CONSISTENT)	NOT NECESSARY	62.00	-
2	REAR TAILGATE HINGES (CONSISTENT)	NOT NECESSARY	162.00	-
2	REAR TAILGATE DAMPER (CONSISTENT)	NOT NECESSARY	375.00	-
1	REAR TAILGATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	288.00	-
1	REAR TAILGATE INNER BOARD (CONSISTENT)	NOT NECESSARY	190.00	-
1	REAR TAILGATE CENTRE LOCK LOGO (CONSISTENT)	NECESSARY	69.00	69.00
1	REAR TAILGATE WINDSCREEN GLASS MOULDING (CONSISTENT)	NO SUCH PARTS	295.00	-
1	REAR TAILGATE LOCK ACTUATOR (CONSISTENT)	NOT NECESSARY	189.00	-
1	REAR TAILGATE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	176.00	-
1	REAR TAILGATE LOCK CYLINDER (CONSISTENT)	NOT NECESSARY	191.00	-
1	REAR LEFT TAILLAMP (CONSISTENT)	CRACKED	785.00	338.00
1	REAR RIGHT TAILLAMP (CONSISTENT)	NOT NECESSARY	785.00	-
1	REAR LEFT TAILLAMP LOWER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	109.00	-
1	REAR RIGHT TAILLAMP LOWER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	109.00	-
1	REAR END LOWER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,275.00	-
1	REAR SPARE TYRE CARRIER (CONSISTENT)	NOT NECESSARY	376.00	-
1	REAR EXHAUST MUFFLER ASSY (CONSISTENT)	NOT NECESSARY	2,400.00	-
2	REAR EXHAUST MUFFLER RUBBER MOUNTING (CONSISTENT)	NOT NECESSARY	38.00	-
	LESS 20% DISCOUNT		-2,980.25	-
	LESS 50% DISCOUNT		-	-1,751.60
			8,940.75	1,751.60

Report Ref No. CC4/ASM18017053/Ujb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
10	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
12	REAR TAILGATE INNER BOARD CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
4	REAR TAILGATE OUTER GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR TAILGATE '70KM/H' STICKER (SN) (CONSISTENT)	NECESSARY	30.00	10.00
1	SET REAR TAILGATE COMPANY STICKER (SN) (CONSISTENT)	NECESSARY	250.00	200.00
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	REAR VIEW CAMERA (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	200.00
1	REAR NO PLATE (SN) (CONSISTENT)	CRACKED	80.00	20.00
			1,090.00	550.00
	LABOUR			
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR LEFT TAILLAMP LOWER PANEL,REAR RIGHT TAILLAMP LOWER PANEL AND REAR END LOWER PANEL.		1,600.00	400.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,600.00	600.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	20.00
	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM.		80.00	60.00
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	150.00	-
	TO APPLY ANTI RUST PROOFING TO AFFECTED AREAS.		120.00	60.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR.		140.00	120.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	50.00
	TO REMOVE AND INSTALL REAR VIEW CAMERA.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY .	NOT NECESSARY	150.00	-

Report Ref No. CC4/ASM18017053/Ujb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING SERVICE	NOT NECESSARY	120.00	-
			4,170.00	1,310.00
	GRAND TOTAL		14,200.75	3,611.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC4/ASM18017053/Ujb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SIMMOONOR

Reference

CCA/ASM18017053/Uto3u2

Loss Date

31 August 2018

Request Date

12 December 2018

Due Date

Vendor Name

LUK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

GBF4371Y

Make

TPVD

Model

TBC

Service Address

...

Primary Contact/Insured

RHM ENGINEERING PTE LTD

BLOCK 170 GANGSA ROAD, #04-44, 670170, Singapore

63380083

CLIVE@VIRTUALINVEST.BIZ

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions PLS SUBMIT YOUR BILL

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LockInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LUK AUTO CONSULTANTS PTE LTD (TP)	12 December 2018
LockInspection (1).pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	12 December 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKAdjustment11a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 December 2018
 LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 December 2018