

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

not Admit  
h/s #  
Hdy.  
the photo of the  
21/9/18

GBF4371Y Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy 20/sep	\$ 1,260.00
2	2	Rear bumper bracket 34	\$ 172.00
3	1	Rear bumper inner beam	\$ 287.00
4	1	Rear tailgate assy 5.45m	\$ 2,062.00
5	1	Rear tailgate lock mechanism 2m/ym	\$ 266.00
6	1	Rear tailgate lock catch 11	\$ 62.00
7	2	Rear tailgate hinges 11	\$ 162.00
8	2	Rear tailgate damper 11	\$ 375.00
9	1	Rear tailgate weatherstrip	\$ 288.00
10	1	Rear tailgate inner board	\$ 190.00
11	1	Rear tailgate centre logo 2m	\$ 69.00
12	1	Rear tailgate windscreen glass moulding 25	\$ 295.00
13	1	Rear tailgate lock actuator	\$ 189.00
14	1	Rear tailgate outer garnish	\$ 176.00
15	1	Rear tailgate lock cylinder 11	\$ 191.00
16	1	Rear left taillamp 2m	\$ 785.00
17	1	Rear right taillamp	\$ 785.00
18	1	Rear left taillamp lower panel 2	\$ 109.00
19	1	Rear right taillamp lower panel 2	\$ 109.00
20	1	Rear end lower panel	\$ 1,275.00
21	1	Rear spare tyre carrier 11	\$ 376.00
22	1	Rear exhaust muffler assy 11	\$ 2,400.00
23	2	Rear exhaust muffler rubber mounting 11	\$ 38.00
			\$ 11,921.00
Less 25%			\$ 2,980.25
			\$ 8,940.75
<u>Special Nett Items</u>			
1	10	Rear bumper clips 2m	\$ 50.00
2	12	Rear tailgate inner board clips 2m	\$ 30.00
3	4	Rear tailgate outer garnish clips 11	\$ 20.00
4	1	Rear tailgate '70km/h' sticker 2m	\$ 30.00
5	1set	Rear tailgate company sticker 2m	\$ 250.00
6	1	Rear windscreen glass sealant 2m	\$ 80.00
7	1	Rear view camera 11	\$ 300.00
8	1	Rear bumper reverse sensor 2m	\$ 250.00
9	1	Rear no plate 2m	\$ 80.00
			\$ 1,090.00

Total Parts

\$ 10,030.75

**Think One Autocare Pte Ltd**  
**No.18 Defu Avenue 2**  
**Singapore 539522**  
**Tel: 6844 3300 Fax: 6842 4988**

**GBF4371Y Toyota Hiace**

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,600.00	?
2	To putty and spray painting rear portion.	\$ 1,600.00	800
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear inner garnish and trim to facilitate the repair.	11 \$ 150.00	X
6	To apply anti rust proofing to rear affected area.	\$ 120.00	60
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	120
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear view camera.	11 \$ 80.00	X
10	To remove and install rear exhaust muffler assy.	11 \$ 150.00	X
11	Towing service.	11 \$ 120.00	X
<b>Total labour :</b>		<b>\$ 4,170.00</b>	

**Total parts : \$ 10,030.75**

**Total labour : \$ 4,170.00**

**Total repair cost : \$ 14,200.75**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: