

22/03/2002

REC. BY:

REF:

CS/SPF18017055/Gsb02

Special Instruction:

calculation slip
excl

Surveyor:

QA

ASSIGNMENT (Office)

From (Person):

Perry He

of

SPF

Date/Time:

19/09/2018 11:30am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 555m

Insured:

at Workshop m/s

Indeco

Tel:

of

39 Debu Lane 12

Policy No:

Claim No:

HOMSPFETQ17300218

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

QX 555m - CS3 / SPF18013068 / Vth02

DOI: 17/07/18

21/09/18

@ 16:29 p.m. revert to Perry He via email.

1,080.00

10/10/18

Material = ~~\$2,230~~ \$3,516.04 (exclude chede items ~~\$1,554.00~~)

Man hrs = 40 hrs (exclude chede items 2 hrs)

Sirajur

YML

REF: SPE

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 (OD) TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Indeco Engineers
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / (REV) / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: QX 555M Yr Regn: - /
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Police Car
 Make: Hyundai Avante C.C. -
 Colour: white A/C: Insured / Std / NI / NA
 Sp.Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMH0U41BMAU987290
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 185/65R15
 R: "
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. 20-09-18
 Survey held at w/s 11AM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
NS RT
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>20/9</u>	<u>Finalized 40 Hrs with Anson.</u>
<u>20/9</u>	
<u>20/10/18</u>	

RECEIVED 1 OCT 2018

Date/Time, File Pass to?
11/10/18
 1) Typist
 Date/Time, File Return to?

: Preli. Report
 : Final Report

Days Of Repair: 1
 Resurvey No. of Trip: 1

Survey Fee:	<u>200</u>
Transportation:	_____
Photos	_____
Others	_____
TOTAL	<u>200</u>

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Shirley Hiew (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 10 October 2018 5:35 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

Ok, pls send us, thanks.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 10 October 2018 12:05 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

Dear Perry,

Please advise whether can we submit our report of QX 555M accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Saturday, 22 September 2018 4:51 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

Received, thanks, will update if any.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 21 September 2018 4:29 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; sur@lkkauto.com; assignments@lkkauto.com
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

RE-SEND

Dear Perry,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Friday, 21 September 2018 4:20 PM
To: 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>
Cc: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; sur@lkkauto.com; assignments@lkkauto.com
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

Dear Perry,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 21 September 2018 4:29 PM
To: 'Perry HE (SPF)'
Cc: 'Wei Yea LIM (SPF)'; 'Kwee Huat TAN (SPF)'; 'Kim Pang CHAY (SPF)'; 'sur@lkkauto.com'; 'assignments@lkkauto.com'
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M
Attachments: QX 555M.xls; LKK SURVEYOR PHOTO.pdf

RE-SEND

Dear Perry,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 21 September 2018 4:20 PM
To: 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>
Cc: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; sur@lkkauto.com; assignments@lkkauto.com
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

Dear Perry,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Wednesday, 19 September, 2018 11:13 AM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 21 September 2018 4:20 PM
To: 'Perry HE (SPF)'
Cc: 'Wei Yea LIM (SPF)'; 'Kwee Huat TAN (SPF)'; 'Kim Pang CHAY (SPF)'; sur@lkkauto.com; assignments@lkkauto.com
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M
Attachments: QX 555M.xls; LKK SURVEYOR PHOTO.pdf

Dear Perry,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Wednesday, 19 September, 2018 11:13 AM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO.

Vehicle No: QX555M

Parts:

- 1 Scope Of Repairs
 - 1.1 BONNET
 - 1.2 BONNET HINGE RH
 - 1.3 BONNET HINGE LH
 - 1.4 BONNET LOCK
 - 1.5 SUPPORT PANEL
 - 1.6 HEADLAMP LH
 - 1.7 FRT BUMPER
 - 1.8 FRT BUMPER RETAINER RH
 - 1.9 FRT BUMPER RETAINER LH
 - 1.10 FRT BUMPER LOWER CENTER GRILLE
 - 1.11 FOGLAMP COVER RH
 - 1.12 FOGLAMP COVER LH

Catherine Chong (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 19 September, 2018 11:13 AM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - QX555M

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO.

Vehicle No: QX555M

Parts:

- 1 Scope Of Repairs
- 1.1 BONNET
- 1.2 BONNET HINGE RH
- 1.3 BONNET HINGE LH
- 1.4 BONNET LOCK
- 1.5 SUPPORT PANEL
- 1.6 HEADLAMP LH
- 1.7 FRT BUMPER
- 1.8 FRT BUMPER RETAINER RH
- 1.9 FRT BUMPER RETAINER LH
- 1.10 FRT BUMPER LOWER CENTER GRILLE
- 1.11 FOGLAMP COVER RH
- 1.12 FOGLAMP COVER LH
- 1.13 FRT BUMPER CLIPS
- 1.14 ENGINE UNDER COVER COMPLETE
- 1.15 ENGINE UNDER COVER CLIP
- 1.16 LHF FENDER
- 1.17 LHF FENDER INNER SHILED
- 1.18 LHF FENDER INNER SHILED CLIP
- 1.19 LHF SPORT RIM 15"
- 1.20 LHF TYRE 185/65/15 (SOR 5B)
- 1.21 LHF S/ABSORBER
- 1.22 LHF LOWER ARM
- 1.23 LHF KNUCKLE ARM
- 1.24 LHF WHEEL BEARING
- 1.25 LHF ANTI ROLL BAR LINK
- 1.26 LHF TIE ROD
- 1.27 LHF TIE ROD END
- 1.28 LHF LOWER ARM BALL JOINT
- 1.29 LHF S/ABSORBER TOP MOUNTING
- 1.30 LHF ABS SENSOR
- 1.31 LHF DRIVE SHAFT
- 1.32 ANTI ROLL BAR
- 1.33 ENGINE CROSS MEMBER
- 1.34 BATTERY (SOR 5A)
- 1.35 FRT NUMBER PLATE

Labour:

1.1	TO REPLACE AND RESPRAY BONNET	6	hr:
1.2	TO REPLACE SUPPORT PANEL	2	hr:
1.3	TO REPLACE AND RESPRAY FRT BUMPER	5	hr:
1.4	TO REPLACE AND RESPRAY LHF FENDER	4	hr:
1.5	TO REPAIR AND RESPRAY RHF FENDER	5	hr:
1.6	TO REPAIR AND RESPRAY LH WINDSCREEN PILLAR	2	hr:
1.7	TO REPAIR AND RESPRAY LHF DOOR	5	hr:
1.8	TO REPLACE ENGINE CROSS MEMBER	2	hr:
1.9	TO REPLACE LHF UNDER CARRIAGE	2	hr:
1.1	TO SEND VEHICLE FOR ALIGNMENT	1	hr:
1.11	TO REPAIR AND RESPRAY LHF WHEEL HOUSE	6	hr:
1.12	TO REMOVE AND REFIX CONDENSER,RADIATOR AND TOP UP AC GAS	2	hr:

Thank you.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Scope Of Work
Home Team Agency

SCOPE OF WORK

To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	G DIV
VEH NO :	QX555M	FRC	REPAIR TYPE:	ACCIDENT
VEH MAKE/MODEL	HYUNDAI AVANTE		Mileage:	0

Reference No.
MHA/SPF/2018/09-0019 1100012062

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	BONNET / BT	185.00	1	20%	222.00	222.00
1.2	BONNET HINGE RH / BT	30.00	1	20%	36.00	36.00
1.3	BONNET HINGE LH / BT	30.00	1	20%	36.00	36.00
1.4	BONNET LOCK / BT	35.00	1	20%	42.00	42.00
1.5	SUPPORT PANEL / BT	185.00	1	20%	222.00	222.00
1.6	HEADLAMP LH / BT	175.00	1	20%	210.00	210.00
1.7	FRT BUMPER / BT	190.00	1	20%	228.00	228.00
1.8	FRT BUMPER RETAINER RH / BT	20.00	1	20%	24.00	24.00
1.9	FRT BUMPER RETAINER LH / BT	20.00	1	20%	24.00	24.00
1.10	FRT BUMPER LOWER CENTER GRILLE / BT	35.00	1	20%	42.00	42.00
1.11	FOGLAMP COVER RH / BT	23.00	1	20%	27.60	27.60
1.12	FOGLAMP COVER LH / BT	23.00	1	20%	27.60	27.60
1.13	FRT BUMPER CLIPS / BT	2.00	10	20%	2.40	24.00
1.14	ENGINE UNDER COVER COMPLETE / BT	38.00	1	20%	45.60	45.60
1.15	ENGINE UNDER COVER CLIP / BT	2.00	10	20%	2.40	24.00
1.16	LHF FENDER / BT	80.00	1	20%	96.00	96.00
1.17	LHF FENDER INNER SHILED / BT	38.00	1	20%	45.60	45.60
1.18	LHF FENDER INNER SHILED CLIP / BT	2.00	6	20%	2.40	14.40
1.19	LHF SPORT RIM 15" / BT	240.00	1	20%	288.00	288.00
1.20	LHF TYRE 185/65/15 (SOR 5B) / BT	112.71	1	0%	112.71	112.71
1.21	LHF S/ABSORBER / BT	125.00	1	20%	150.00	150.00
1.22	LHF LOWER ARM / BT	115.00	1	20%	138.00	138.00
1.23	LHF KNUCKLE ARM / BT	165.00	1	20%	198.00	198.00
1.24	LHF WHEEL BEARING / BT	48.00	1	20%	57.60	57.60
1.25	LHF ANTI ROLL BAR LINK / BT	35.00	1	20%	42.00	42.00
1.26	LHF TIE ROD / BT	48.00	1	20%	57.60	57.60
1.27	LHF TIE ROD END / BT	35.00	1	20%	42.00	42.00
1.28	LHF LOWER ARM BALL JOINT / BT	35.00	1	20%	42.00	42.00
1.29	LHF S/ABSORBER TOP MOUNTING / BT	42.00	1	20%	50.40	50.40
1.30	LHF ABS SENSOR / BT	100.00	1	20%	120.00	120.00
1.31	LHF DRIVE SHAFT / BT	550.00	1	20%	660.00	660.00
1.32	ANTI ROLL BAR / BT	125.00	1	20%	150.00	150.00
1.33	ENGINE CROSS MEMBER / BT	800.00	1	20%	960.00	960.00
1.34	BATTERY (SOR 5A) / flat	112.93	1	0%	112.93	112.93
1.35	FRT NUMBER PLATE / BT	20.00	1	20%	24.00	24.00
2	Additional Services					
Remarks:	SUBJECT TO PARTS AVAILABILITY				Parts Total:	\$ 4,596.04

3516.04

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	TO REPLACE AND RESPRAY BONNET	61.80	6	370.80
1.2	TO REPLACE SUPPORT PANEL	61.80	2	123.60
1.3	TO REPLACE AND RESPRAY FRT BUMPER	61.80	5	309.00
1.4	TO REPLACE AND RESPRAY LHF FENDER	61.80	4	247.20
1.5	TO REPAIR AND RESPRAY RHF FENDER	61.80	5	309.00
1.6	TO REPAIR AND RESPRAY LH WINDSCREEN PILLAR	61.80	2	123.60
1.7	TO REPAIR AND RESPRAY LHF DOOR	61.80	5	309.00
1.8	TO REPLACE ENGINE CROSS MEMBER	61.80	2	123.60
1.9	TO REPLACE LHF UNDER CARRIAGE	61.80	2	123.60
1.10	TO SEND VEHICLE FOR ALIGNMENT	61.80	1	61.80
1.11	TO REPAIR AND RESPRAY LHF WHEEL HOUSE	61.80	6	370.80
1.12	TO REMOVE AND REFIX CONDENSER,RADIATOR AND TOP UP AC GAS	61.80	2	123.60
2	Additional Services			42 40
Labour Total:				\$ 2,595.60
GRAND TOTAL:				\$ 7,191.64
Contractor shall complete the entire repair within <u>15</u> working days upon quotation approved date.				
Contractor QC		Vetted By:		Approved By:
Name:	Gan Hup Tiong	Name:		Name:
Date:	18/9/18	Date:		Date:
Sign:		Sign:		Sign:
Verification of Completed Repairs				
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager
Name:		Name:		Name:
Date:		Date:		Date:
Sign:		Sign:		Sign:
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made				

5788.04

Guo Qi up. - 82880282

20/9/18.

Not Authorised.

Before paint photos.
After paint photos.


24/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Registration No. QX 555M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BONNET	1	BENT	\$ 222.00	\$ 222.00	
1.2	BONNET HINGE RH	1	BENT	\$ 36.00	\$ 36.00	
1.3	BONNET HINGE LH	1	BENT	\$ 36.00	\$ 36.00	
1.4	BONNET LOCK	1	BENT	\$ 42.00	\$ 42.00	
1.5	SUPPORT PANEL	1	BROKEN	\$ 222.00	\$ 222.00	
1.6	HEADLAMP LH	1	CRACKED	\$ 210.00	\$ 210.00	
1.7	FRT BUMPER	1	DEFORMED	\$ 228.00	\$ 228.00	
1.8	FRT BUMPER RETAINER RH	1	DEFORMED	\$ 24.00	\$ 24.00	
1.9	FRT BUMPER RETAINER LH	1	DEFORMED	\$ 24.00	\$ 24.00	
1.10	FRT BUMPER LOWER CENTER GRILLE	1	DEFORMED	\$ 42.00	\$ 42.00	
1.11	FOGLAMP COVER RH	1	DEFORMED	\$ 27.60	\$ 27.60	
1.12	FOGLAMP COVER LH	1	DEFORMED	\$ 27.60	\$ 27.60	
1.13	FRT BUMPER CLIPS	10	NECESSARY	\$ 2.40	\$ 24.00	
1.14	ENGINE UNDER COVER COMPLETE	1	TORN	\$ 45.60	\$ 45.60	
1.15	ENGINE UNDER COVER CLIP	10	NECESSARY	\$ 2.40	\$ 24.00	
1.16	LHF FENDER	1	DISTORTED	\$ 96.00	\$ 96.00	
1.17	LHF FENDER INNER SHILED	1	TORN	\$ 45.60	\$ 45.60	
1.18	LHF FENDER INNER SHILED CLIP	6	NECESSARY	\$ 2.40	\$ 14.40	
1.19	LHF SPORT RIM 15"	1	CUT	\$ 288.00	\$ 288.00	
1.20	LHF TYRE 185/65/15 (SOR 5B)	1	SCRATCHED	\$ 112.71	\$ 112.71	
1.21	LHF S/ABSORBER	1	BENT	\$ 150.00	\$ 150.00	
1.22	LHF LOWER ARM	1	BENT	\$ 138.00	\$ 138.00	

1.23	LHF KNUCKLE ARM	1	BENT	\$ 198.00	\$ 198.00
1.24	LHF WHEEL BEARING	1	BENT	\$ 57.60	\$ 57.60
1.25	LHF ANTI ROLL BAR LINK	1	BENT	\$ 42.00	\$ 42.00
1.26	LHF TIE ROD	1	BENT	\$ 57.60	\$ 57.60
1.27	LHF TIE ROD END	1	BENT	\$ 42.00	\$ 42.00
1.28	LHF LOWER ARM BALL JOINT	1	BENT	\$ 42.00	\$ 42.00
1.29	LHF S/ABSORBER TOP MOUNTING	1	BENT	\$ 50.40	\$ 50.40
1.30	LHF ABS SENSOR	1	UNCONFIRM	\$ 120.00	\$ 120.00
1.31	LHF DRIVE SHAFT	1	BROKEN	\$ 660.00	\$ 660.00
1.32	ANTI ROLL BAR	1	BENT	\$ 150.00	\$ 150.00
1.33	ENGINE CROSS MEMBER	1	UNCONFIRM	\$ 960.00	\$ 960.00
1.34	BATTERY (SOR 5A)	1	FLAT	\$ 112.93	\$ 112.93
1.35	FRT NUMBER PLATE	1	BENT	\$ 24.00	\$ 24.00
	LABOUR DESCRIPTION				
1	SCOPE OF REPAIRS				
1.1	TO REPLACE AND RESPRAY BONNET				6
1.2	TO REPLACE SUPPORT PANEL				2
1.3	TO REPLACE AND RESPRAY FRT BUMPER				5
1.4	TO REPLACE AND RESPRAY LHF BUMPER				4
1.5	TO REPAIR AND RESPRAY RHF BUMPER				5
1.6	TO REPAIR AND RESPRAY LH WINDSCREEN PILLAR				2
1.7	TO REPAIR AND RESPRAY LHF DOOR				5
1.8	TO REPLACE ENGINE CROSS MEMBER		UNCONFIRM		2
1.9	TO REPLACE LHF UNDER CARRIAGE				2
1.10	TO SEND VEHICLE FOR ALIGNMENT				1
1.11	TO REPAIR AND RESPRAY LHF WHEEL HOUSE				6
1.12	TO REMOVE AND REFIX CONDENSER, RADIATOR AND TOP UP AC GAS				2
			TOTAL PARTS COST	\$4,596.04	

COSTING

TOTAL MAN-HOUR

42



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18017055/Gsbe2	
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 01-11-2018	
ATTN : PERRY HE		Code : SPF3	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	QX 555M
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ17300218	Excess (\$)	0.00
Assign From	PERRY HE	Assign Date	19/09/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KMHDU41BMAU987290	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	FALKEN	5 mm
L/H Front Tyre	185/65 R15	FALKEN	5 mm
R/H Rear Tyre	185/65 R15	FALKEN	5 mm
L/H Rear Tyre	185/65 R15	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date		Inspection Date	20/09/2018
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		
5a. Remarks			



Registration No. QX 555M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BONNET	1	BENT	\$ 222.00	\$ 222.00	
1.2	BONNET HINGE RH	1	BENT	\$ 36.00	\$ 36.00	
1.3	BONNET HINGE LH	1	BENT	\$ 36.00	\$ 36.00	
1.4	BONNET LOCK	1	BENT	\$ 42.00	\$ 42.00	
1.5	SUPPORT PANEL	1	BROKEN	\$ 222.00	\$ 222.00	
1.6	HEADLAMP LH	1	CRACKED	\$ 210.00	\$ 210.00	
1.7	FRT BUMPER	1	DEFORMED	\$ 228.00	\$ 228.00	
1.8	FRT BUMPER RETAINER RH	1	DEFORMED	\$ 24.00	\$ 24.00	
1.9	FRT BUMPER RETAINER LH	1	DEFORMED	\$ 24.00	\$ 24.00	
1.10	FRT BUMPER LOWER CENTER GRILLE	1	DEFORMED	\$ 42.00	\$ 42.00	
1.11	FOGLAMP COVER RH	1	DEFORMED	\$ 27.60	\$ 27.60	
1.12	FOGLAMP COVER LH	1	DEFORMED	\$ 27.60	\$ 27.60	
1.13	FRT BUMPER CLIPS	10	NECESSARY	\$ 2.40	\$ 24.00	
1.14	ENGINE UNDER COVER COMPLETE	1	TORN	\$ 45.60	\$ 45.60	
1.15	ENGINE UNDER COVER CLIP	10	NECESSARY	\$ 2.40	\$ 24.00	
1.16	LHF FENDER	1	DISTORTED	\$ 96.00	\$ 96.00	
1.17	LHF FENDER INNER SHILED	1	TORN	\$ 45.60	\$ 45.60	
1.18	LHF FENDER INNER SHILED CLIP	6	NECESSARY	\$ 2.40	\$ 14.40	
1.19	LHF SPORT RIM 15"	1	CUT	\$ 288.00	\$ 288.00	
1.20	LHF TYRE 185/65/15 (SOR 5B)	1	SCRATCHED	\$ 112.71	\$ 112.71	
1.21	LHF S/ABSORBER	1	BENT	\$ 150.00	\$ 150.00	
1.22	LHF LOWER ARM	1	BENT	\$ 138.00	\$ 138.00	
1.23	LHF KNUCKLE ARM	1	BENT	\$ 198.00	\$ 198.00	
1.24	LHF WHEEL BEARING	1	BENT	\$ 57.60	\$ 57.60	
1.25	LHF ANTI ROLL BAR LINK	1	BENT	\$ 42.00	\$ 42.00	
1.26	LHF TIE ROD	1	BENT	\$ 57.60	\$ 57.60	
1.27	LHF TIE ROD END	1	BENT	\$ 42.00	\$ 42.00	
1.28	LHF LOWER ARM BALL JOINT	1	BENT	\$ 42.00	\$ 42.00	

1.29	LHF S/ABSORBER TOP MOUNTING	1	BENT	\$ 50.40	\$ 50.40	
1.30	LHF ABS SENSOR	1	UNCONFIRM	\$ 120.00	\$ 120.00	
1.31	LHF DRIVE SHAFT	1	BROKEN	\$ 660.00	\$ 660.00	
1.32	ANTI ROLL BAR	1	BENT	\$ 150.00	\$ 150.00	
1.33	ENGINE CROSS MEMBER	1	UNCONFIRM	\$ 960.00	\$ 960.00	
1.34	BATTERY (SOR 5A)	1	FLAT	\$ 112.93	\$ 112.93	
1.35	FRT NUMBER PLATE	1	BENT	\$ 24.00	\$ 24.00	
	LABOUR DESCRIPTION					
1	SCOPE OF REPAIRS					
1.1	TO REPLACE AND RESPRAY BONNET					6
1.2	TO REPLACE SUPPORT PANEL					2
1.3	TO REPLACE AND RESPRAY FRT BUMPER					5
1.4	TO REPLACE AND RESPRAY LHF BUMPER					4
1.5	TO REPAIR AND RESPRAY RHF BUMPER					5
1.6	TO REPAIR AND RESPRAY LH WINDSCREEN PILLAR					2
1.7	TO REPAIR AND RESPRAY LHF DOOR					5
1.8	TO REPLACE ENGINE CROSS MEMBER		UNCONFIRM			2
1.9	TO REPLACE LHF UNDER CARRIAGE					2
1.10	TO SEND VEHICLE FOR ALIGNMENT					1
1.11	TO REPAIR AND RESPRAY LHF WHEEL HOUSE					6
1.12	TO REMOVE AND REFIX CONDENSER, RADIATOR AND TOP UP AC GAS					2
COSTING		TOTAL PARTS COST			\$4,596.04	
		TOTAL MAN-HOUR				42

Registration No. QX 555M

Vehicle Inspected By

XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.