INS. CASE OWNER: CC 3	1 12051 180 17054	CNASYL DAG
Surveyor: D	ASSIGNMENT IS 19 11	Date / Y'me : 19/09/18
Pre-assign / CCU / FTE GB 3 YET 3 YE	Claim No. Policy No. Make / Model	Registered in Merimen: Arm 1500 4499002 N.NV3500
is driver the owner? (YES / 10) Namire of Ac If NO, Driver Name / Age : Hang Fei	09 20 8 Place of Accide	RT: YES NO ; TP GIA REPORT: YES / NO
SHE 9602 7 INSES	DISRS: WSP:	INSRS:
Tel: Liability: RMKS: Tel: Liability: RMKS:	Tel: Liability: RMKS:	WSP: Tel: Liability: RMKS:
MG (HAGEZ CALLULATIVE	914/6/23 , O+ 11/8/18	STAGE DATE/PIC
IODO FEMANT OIR CHECK LO SEMENT CONTRACTO SALA MITT SOLI ESPORT. SHE MITT SHE MITT SOLI ESPORT. SHE MITT SOLI	ED UPPARTE. OID EATORTHIC CONTROL. HULT) OW ONLY TO EWHED NIDEO FOOKCE. THE TIC SOHT BASIS) THE TIC SOHT BASIS.	Non-Reporting itr (Ind): Non-Reporting itr (Final): Notification itr (if non-pickup): Call OI: \O(\o)\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
+ TO CLOSE -	SECTION. HOPPIED BOILL.	Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA : Medical Bill: PIR:
RECEIVED	11-10-18	Mandate/Reject Instruction: LUD Payment Breakdown Form:
FINALIZATION Date/Time: C Repair Cost: US S\$ 2,800.00 (2 days) R		Post-Repair Photos: Others: Confirm by: Email Call
FINAL SETTLEMENT Date/Time: Confirm wit Final Liability: % (Agreed / Assessed) B Repair Cost S\$ — Loss of Rental (LOR): S\$ — (days)		Email Call If NO or B 28, Ass Lia:
Loss of Use (LOU): S\$ — (\$ x days) Loss of Income (LOI): S\$ — (\$ x days) LOR only LOR + LOU LOR + LOI GIA/LTA Search S\$ —	[Tick only one]	Chile
		Claim status: Normal/Reject/Private Settle Report Format: Survey fee:
Payee 1: S\$ — Name 1: Payee 2: (Strike if N.A.) S\$ — Name 2: Payee 3: (Strike if N.A.) S\$ — Manne 3:		3

Kenneth	ACCION
From:	ASSIGNMENT
Estimated Cost:	Veh No: SHB 9602 Z Yr Regn: 04, 1
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Paxl / Prime Mover /
OD UTP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	(1 - 4.
at Workshop m/s Tans Ca	4 moralet chica cc 18
of	San Arc: Insured / Std / NI / N.
Insured:	Sp.Reading 5055/8 T/Radio: Insured / Std / NI / N
Policy No.	Eng/No:
Claims No.	Gen. Cond: 860d) Fair / Park /
Sum Insured:	Correction
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inerder / Jammed / Leaked / Burnt or
	Modi: MIT I S/Rim / STD A/Rim or
Date of the Control o	Tyre Size: F: 19511-2
(Policy Condition)	Tyre Size: F: 195/65R15
Remark: The veh had commenced its	
repair at the time of inspection.	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal, or Market Value:	417)
IDAC Accident Rport: Consistent? : Yes or No	Front Rear
GIA / PR Seen: Consistent?: Yes or No	mm R/8a!. 9
Est. Repairs: OZ days Res.: Yes or No	DBal, 9 mm L/Bal Q
Lum Sum: 20% 3 Val.: Yes or No	D.O.A. 15/9/18 DOI 18/9/10
	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN	OUT NIS FT
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
18/9 Fit poss to Corneral	anocied due to consion.
61 Ry 8 28000	
CRAD: \$ 13,804.97 BS	
1,004,11,00	1.)
tto/Time, File Pass to?	
: Prell. Report	Days Of Repair:
: Final Report	Resuprou No. of T.
and a definition	
Add F	ee: Site Insp (\$
Add F	50. Site insp (5)_5+RS_Si
	letest to
port Format :	: Interview (\$), Fixebs
	Interview (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9602Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer:

AAD1809-155

Not Nothanker

SHB 9602Z

KL1LA69RJBB122741

CHEVROLET

EPICA 2.0

15.9.2018

CHINA TAIPING

		PART	LIST
1	1	Front Bumper	\$ Bu 1,202.00 -
2	1	Front Bumper Lower Absorber	\$ Ph 180.00 X
3	1	Front Bumper Reinforcement	\$ A 356.00 X
4	1	Front Bumper Retainer RH	\$ 102.00 X
5	1	Front Bumper Retainer LH	\$ DIY 102.00
6	1	Front Bumper Lower Grille	\$ Ph 78.00 ×
7	1	Front Bumper Lower Stiffener	\$ M 134.37 X
8	1	Front Bumper Bracket LH	\$ 7 10.00 X
9	1	Front Bumper Bracket RH	\$ N 10.00 X
10	1	Bumper Fog Lamp Cover RH	\$ 54 32.40 x
11	1	Bumper Fog Lamp Cover LH	\$ Sh 32.40 X
12	1	Headlamp LH	\$ CA1 816.00 -
13	1	Headlamp LH inner panel	\$ N 611.16 X
14	1	Front Fender LH	\$ Bu 837.60 -
15	1	Front Fender Liner LH	\$ Sa 47.00
16	1	Front Fender Inner Wheel House Panel LH	\$ 1,437.00
17	1	Front Shock Absorber Assy LH	\$ Sm 216.17
18	1	Front Shock Absorber Top Mounting LH	\$ Sh 48.32
19	1	Front Lower Arm LH	\$ £ 283.00
20	1	Front Knuckle Arm LH	\$ 1 230.00 X
21	1	Front Hub Unit	\$ PL 376.00
22	1	Front Disc Brake LH	\$ رم 157.55
23	1	Front Strut Bar Bracket LH	\$ N 235.01
24	1	Front Stabilizer Bar	\$ ₽ ₁ 234.00
25	1	Front Stabilizer Bar Link LH	\$ Ju 51.79
26	1	Front Stabilizer Bar Bracket LH	\$ N 105.75
27	1	Front Stabilizer Bar Bush LH	\$ SL 66.00
28	1	Front Beam A - Impact LH	\$ A 214.00

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SH

		VO. 201019020G				
HB 9	602Z		OTAL	•	8,205.52	
			10%		820.55	
			10%	\$	7,384.97	
		Specical Nett				
1	1 Set	Front Fender Liner clip LH		\$	~~ 30.00 ·	X
2	1 Set	Louver Cowl Top clip		\$	~~ 30.00 ·	X
3	1	Front right tyre rim		\$	Sm 380.00	
4	1	Front right tyre		\$	JL 330.00	X
			TOTAL	\$	770.00	
		TOTAL	PARTS	\$	8,154.97	
		LABOUR				
		To Check Electrical Lighting Concerned.		\$	170.00	20/
		Panel beating, knocking and straightening the				
		necessary portion, remove and renewal of parts,	adjust		80	0
		and realign the same		\$	3,500.00	
		Putty and spray painting of the affected portion.		\$	3,200.00	400
		To Remove And Refit Front And Rear W/Screen G	ilass			
		To Facilitate Bodywork Repair.		\$	N ~ 440.00	X
		Labour charge to mount and dismount vehicle or	i jig			
		bench, to facilitate repair.		\$	Na 380.00	X
		To remove and refit interior fittings, trimings, gar	nish,			
		fittings and other, to enable repair.		\$	~~ 380.00 .	X
		To dismantle and refit front end suspension.				
		undercarrage parts, final checking and testing.		\$	₹ 380.00	X
		To display damaged part(s) during resurvey Parts prices are subject to confirmation Third parts.	OTAL	\$	8,450.00	
		* No illegal modification(s) is an a "Without Prejudice" basis Over Al			16,604.97	
		Supplementary it allowed	r Days	(A)	7 Days	
		The Holl Haurance Company	- 1.00 E		2day,	
		Acknowledged by Repairer Signature:			Theres	
		Date:				

Vic (LKKAuto)

From:

Vic (LKKAuto)

Sent:

Thursday, 11 October, 2018 12:02 PM

To:

Ng Wai Yin

Cc:

claims@transcab.com.sg; 'Jasmine Tan'; Admin A; Vic (LKKAuto)

Subject:

Your Ref: AAD1809-155_ACCIDENT INVOLVING VEHICLES GBH 3481J AND SHB

9602Z ON 15/09/2018 LKK REF CC3/CTI18017059/Kha3

Attachments:

WhatsApp Video 2018-09-18 at 12:50:11.mp4

Your Ref: AAD1809-155

Without Prejudice

Our Ref: CC3/CTI18017059/Kha3

Dear Wai Yin,

ACCIDENT INVOLVING VEHICLES GBH 3481J AND SHB 9602Z ON 15/09/2018

We refer to the subject matter.

Please be informed that our principal had further reviewed the matter and based on the available evidence provided, our principal is in the view that our Insured is not liable of this accident. Please refer to the attached video footage for your reference.

As such, we have our principal's instruction to deny your client's claim in view that your client should have gave way to our Insured when turning.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

5 T D

Save the Earth Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Vic (LKKAuto)

From:

Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent:

Thursday, 11 October, 2018 10:35 AM

To

Vic (LKKAuto); Admin A

Cc:

Chong Boon Sen; Alfred Toh; Chee So Chow; KKLau; Hsiao Tong (LKKAuto)

Subject:

RE: Direct Settlement - Accident Involving GBH3481J (OI: SNM18D04499C02/1) and

SHB9602Z (TP: LKK REF - CC3/CT118017059/Kha3) on 15/09/2018

Attachments:

MLHM18120179-01-GBH3481J.pdf

LKK REF - CC3/CTI18017059/Kha3

CTI REF - SNM18D04499C02/1 (GBH3481J)

Dear Vic

We refer to your email of even date pertaining to the above matter.

Please proceed to reject the third party property claim in the first instance.

Meanwhile, please assist to check with mutual client on the status of their claim against SHB9602Z (100% SUCCESSFUL or 50% SUCCESSFUL)

Best Regards

Alfred Toh Senior Executive Claims Department China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: +65 6389 6183

FAX: +65 6224 7478/6224 7175

Email: claimsdept@sq.cntaiping.com alfred.toh@sg.cntaiping.com www.sq.cntaiping.com



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]

Sent: Wednesday, October 10, 2018 5:13 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: Direct Settlement - Accident Involving GBH3481J (OI: SNM18D04499C02/1) and SHB9602Z (TP: LKK REF - CC3/CTI18017059/Kha3) on 15/09/2018

CTI REF - SNM18D04499C02 LKK REF - CC3/CTI18017059/Kha3

Dear Boon Sen,

We refer to the above matter,

We had spoken to the Insured Driver Mr Huang where he disputed on the liability and insisted that the TP driver was at fault.

As such, we had requested for a copy of his video footage to support his version of the accident. Please find attached copy of the video footage for your reference.

Based on the footage, it was observed that the traffic light is green for both Insured and TP when both vehicles made a turn towards the same direction. We are of the view that TP vehicle must give way to our Insured vehicle when making a turn.



In view of the above, we intend to reject the TP claim.

For your approval and/or further instruction please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: <u>vicalpeh@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LIKE Save the Earth Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

СНІ	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI180170	059/Kha3q2
	NSON ROAD #16-0 RINGLEAF TOWER	00 RSINGAPORE 079909	Date : 15-10-2018 Code : CTI	
١.		Policy Particula	ars :- THIRD PARTY CLAI	M
	Insured Veh.	GBH 3481J	Veh. Inspected	SHB 9602Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNM18D04499/C01/1	Excess (\$)	0.00
	Assign From		Assign Date	18/09/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	CHEVROLET EPICA (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	KL1LA69RJBB122741	Colour	WHITE /RED
	Odometer	505518	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	GITI	9 mm
	L/H Front Tyre	195/65 R15	GITI	9 mm
	R/H Rear Tyre	195/65 R15	GITI	9 mm
	L/H Rear Tyre	195/65 R15	GITI	9 mm
1.		Descri	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	N/S FRONT PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	15/09/2018	Inspection Date	18/09/2018
	Survey held at	TRANS-CAB AUTO SERVIC	ES PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.			Remarks	
	A)THE INSPECTION B)IN ACCORDANCE	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BASI WE HAVE NOT AUTHORIS	S. ED REPAIRS.
5b.	1000	Estima	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Days	s



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9602Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
-1	FRONT BUMPER	BUCKLED	1,202.00	1,202.00
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	712.77
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	356.00	74
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	18
1	FRONT BUMPER RETAINER LH	DISTORTED	102.00	102.00
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	9
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	34
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	10.00	19
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	10.00	34
-1	BUMPER FOG LAMP COVER RH	SERVICEABLE	32.40	93
1	BUMPER FOG LAMP COVER LH	SERVICEABLE	32.40	
া	HEADLAMP LH	CRACKED	816.00	816.00
1	HEADLAMP RH	TO REPAIR SEE LABOUR	611.16	13
1	FRONT FENDER LH	BUCKLED	837.60	837,60
-1	FRONT FENDER LINER LH	SERVICEABLE	47.00	3
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	1,437.00	
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	216.17	9
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	SERVICEABLE	48.32	
1	FRONT LOWER ARM LH	SERVICEABLE	283.00	
1	FRONT KNUCKLE ARM LH	SERVICEABLE	230.00	
1	FRONT HUB UNIT	SERVICEABLE	376.00	
1	FRONT DISC BRAKE LH	SERVICEABLE	157.55	
1	FRONT STRUT BAR BRACKET LH	TO REPAIR SEE LABOUR	235.01	5
1	FRONT STABILIZER BAR	SERVICEABLE	234.00	
1	FRONT STABILIZER BAR LINK LH	SERVICEABLE	51.79	
1	FRONT STABILIZER BAR BRACKET LH	TO REPAIR SEE LABOUR	105.75	

Report Ref No. CC3/CTI18017059/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
- 1	FRONT STABILIZER BAR BUSH LH	SERVICEABLE	66.00	
1	FRONT BEAM A- IMPACT LH	SERVICEABLE	214.00	2.5
	LESS 10%DISCOUNT		-820.55	-295.76
			7,384.97	2,661.84
	SPECIAL NETT ITEMS			
1	SET FRONT FENDER LINER CLIP LH (SN)	NOT NECESSARY	30.00	
- 11	SET LOUVER COWL TOP CLIP (SN)	NOT NECESSARY	30.00	13
	FRONT RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	
-11	FRONT RIGHT TYRE (SN)	SERVICEABLE	330.00	10
			770.00	
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BUMPER LOWER STIFFENER, FRONT BUMPER BRACKET LH, FRONT BUMPER BRACKET RH, HEADLAMP LH INNER PANEL, FRONT FENDER INNER WHEEL HOUSE PANEL LH, FRONT STRUT BAR BRACKET LH AND FRONT STABILIZER BAR BRACKET LH.	3,500. OF VE OF	3,500.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		3,200.00	400.00
	TO REMOVE AND REFIT FRONT AND REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	440.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH , TO FACILITATE REPAIR.	NOT NECESSARY	380.00	9
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER , TO ENABLE REPAIR.	NOT NECESSARY	380.00	8
	TO DISMANTLE AND REFIT FRONT AND SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	
			8,450.00	820.00
	GRAND TOTAL		16,604.97	3,481.84

Report Ref No. CC3/CTI18017059/Kha3q2



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS	2,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC3/CTI18017059/Kha3q2

KONG SENG CHEONG

Licensed Appraiser