

Trans-cab Auto Services Pte Ltd

AAD1809-155

Not Authorized
11 Sep @ 2800h

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9602Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9602Z

KL1LA69RJB122741

CHEVROLET

EPICA 2.0

15.9.2018

CHINA TAIPING

		PART		LIST
1	1	Front Bumper	\$	<i>Bu</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00 X
3	1	Front Bumper Reinforcement	\$	<i>N</i> 356.00 X
4	1	Front Bumper Retainer RH	\$	<i>Sn</i> 102.00 X
5	1	Front Bumper Retainer LH	\$	<i>Div</i> 102.00 ✓
6	1	Front Bumper Lower Grille	\$	<i>Sn</i> 78.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>N</i> 134.37 X
8	1	Front Bumper Bracket LH	\$	<i>N</i> 10.00 X
9	1	Front Bumper Bracket RH	\$	<i>N</i> 10.00 X
10	1	Bumper Fog Lamp Cover RH	\$	<i>Sn</i> 32.40 X
11	1	Bumper Fog Lamp Cover LH	\$	<i>Sn</i> 32.40 X
12	1	Headlamp LH	\$	<i>CM</i> 816.00 ✓
13	1	Headlamp LH inner panel	\$	<i>N</i> 611.16 X
14	1	Front Fender LH	\$	<i>Bu</i> 837.60 ✓
15	1	Front Fender Liner LH	\$	<i>Sn</i> 47.00
16	1	Front Fender Inner Wheel House Panel LH	\$	<i>N</i> 1,437.00
17	1	Front Shock Absorber Assy LH	\$	<i>Sn</i> 216.17
18	1	Front Shock Absorber Top Mounting LH	\$	<i>Sn</i> 48.32
19	1	Front Lower Arm LH	\$	<i>Sn</i> 283.00
20	1	Front Knuckle Arm LH	\$	<i>Sn</i> 230.00
21	1	Front Hub Unit	\$	<i>Sn</i> 376.00
22	1	Front Disc Brake LH	\$	<i>Sn</i> 157.55
23	1	Front Strut Bar Bracket LH	\$	<i>N</i> 235.01
24	1	Front Stabilizer Bar	\$	<i>Sn</i> 234.00
25	1	Front Stabilizer Bar Link LH	\$	<i>Sn</i> 51.79
26	1	Front Stabilizer Bar Bracket LH	\$	<i>N</i> 105.75
27	1	Front Stabilizer Bar Bush LH	\$	<i>Sn</i> 66.00
28	1	Front Beam A - Impact LH	\$	<i>Sn</i> 214.00

Trans-cab Auto Services Pte Ltd

AAD1809-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9602Z

TOTAL	\$	8,205.52
10%	\$	820.55
	\$	7,384.97

Special Nett

1	1 Set	Front Fender Liner clip LH	\$	nn	30.00	X
2	1 Set	Louver Cowl Top clip	\$	nn	30.00	X
3	1	Front right tyre rim	\$	sn	380.00	X
4	1	Front right tyre	\$	sn	330.00	X
TOTAL			\$		770.00	

TOTAL PARTS	\$	8,154.97
--------------------	-----------	-----------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	20/
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	800/
Putty and spray painting of the affected portion.	\$	3,200.00	400/
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	440.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn	380.00 X

TOTAL	\$	8,450.00
Over All Total	\$	16,604.97

Repair Days 7 Days
20 days

Trans-cab Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: