



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 1733L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	635.00	-
10	REAR BUMPER CLIP @\$5.50	NOT NECESSARY	55.00	-
1	REAR BUMPER SIDE RETAINER RH INNER	NOT NECESSARY	135.00	-
1	REAR BUMPER SIDE RETAINER RH OUTER	NOT NECESSARY	135.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	60.00	-
	LESS 25% DISCOUNT		-255.00	-
			765.00	-
	<u>LABOUR</u>			
	PANEL BEAT, CUT, WELD, RE-ALIGN & REPLACE DAMAGED PARTS OF AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		500.00	250.00
	PUTTY, BLEND AND SPRAY PAINT AFFECTED AREA.		500.00	250.00
	CHECK WIRING AND ENSURE PROPER FUNCTION.		80.00	30.00
	REMOVE & REINSTALL 2 PIECES BUMPER SENSORS.		120.00	30.00
			1,200.00	560.00
GRAND TOTAL			1,965.00	560.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				560.00

Report Ref No. CS/FC118017064/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.