

CS, REC, BY:

REF:

CS/FCI/18017073/714d3

n2

Special Instruction:

Invoyor
CWS

ASSIGNMENT (Office)

From (Person):

T. W. Fitch
Sifhara

of

FCI

Date/Time:

19/9/18 2.27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 6170Z

Insured:

SHC03624

at Workshop m/s

CYS Automobile

Tel:

62192098

of

38 woodlands Ind. Park East # 07-17 admiralty

Policy No:

Claim No:

D18006873MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/09/2018

20/09/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

2.30pm 19/09/18

Person Contacted:

esther

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
19/9/18	esther ask to arrange tomorrow for survey as she wants further to survey
	GBA 6170Z-X
	SHC03624-CS/4PC 08 020740/Dth
	D.O.A: 27/11/2018
26/9	Revert via email preli advise

REF:

FCI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$40k-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBAG170Z Yr Regn: 2007, Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Daihatsu Hijet

cc 659

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

264578

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

5320V0086027

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

15x/K12

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/9/18 @ 1230

Survey held at

cys, Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S, Frt o/s u/c

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Lump Sum \$9100, 10 days. (Red: 4987, 3810)

RECEIVED 27 NOV 2019

Date/Time, File Pass to?



Preli. Report



Final Report

1) 27/11 Typist

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

TP

8100/-

Survey Fee:

Transportation

S + R + SI

Photo

Cost

TOTAL

3x15: 45

170 + 45

50

50

95

410



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017073/T1td3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 362U	Veh. Inspected	GBA 6170Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006873MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	19/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/09/2018	Inspection Date	20/09/2018	
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006873MFSH

Date: 26/9/2018

Our Ref: CS/FCI18017073/T1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBA 6170Z

Please be informed that we had conducted the inspection of the abovementioned vehicle 20/09/2018 at the premises of M/s CYS Automotive and have the following to report: -

Workshop Estimate Amount	: S\$ <u>13,087.00</u>
Revised Estimate Amount	: S\$ <u>7,991.00</u>
"Check" Items Amount	: S\$ <u>2,394.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the n/s portion. The undercarriage affected due to collision



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-09-2018	Our Ref No. D18006873MFSH
Accident Date	13-09-2018	Claim Type. Third Party
Insured Vehicle	SHC0362U	Third Party Vehicle. GBA6170Z
Survey Location	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK	
Contact Person.	ESTHER LIM	
Contact No.	62192098/ 0	Fax No. 62192096
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYS AUTOMOBILE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244284)



PRI Documents



Close



PRI Header Details

Claim No	D18006873MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CYS AUTO
Workshop Name	CYS AUTOMOBILE SERVICES PTE LTD (Contact Person : ESTHER LIM)	Survey Location & Contact Details	38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADP Mobile: 0 , Phone: 62192098 , Fax: 62192096 EmailId: CYSAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0362U	TP Vehicle No	GBA6170Z
PRI Recieved Date	18-09-2018 08:19:19 PM	Surveyor Appointed Date	19-09-2018 02:25:57 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-09-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Denise Tay (LKKAUTO)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Tuesday, 27 November 2018 1:26 PM
To: Denise Tay (LKKAUTO)
Subject: RE: PRI REQUEST : FC REF: SHC0362U. (D18006873MFSH) & TP REF: GBA6170Z. (SJP5891J) ACCIDENT ON 13-09-2018 - FINALISATION CONFIRMED

Dear Ms Denise Tay,

WITHOUT PREJUDICE

Confirmed with thanks

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Denise

Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]

Sent: Tuesday, November 27, 2018 1:22 PM

To: CYSAUTO <cysauto@singnet.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: PRI REQUEST : FC REF: SHC0362U. (D18006873MFSH) & TP REF: GBA6170Z. (SJP5891J) ACCIDENT ON 13-09-2018 - FINALISATION

Dear Sir,

Offer lump sum at \$8100, 10days.

Please check and revert.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO <cysauto@singnet.com.sg>

Sent: Wednesday, 24 October 2018 10:28 AM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FW: PRI REQUEST : FC REF: SHC0362U. (D18006873MFSH) & TP REF: GBA6170Z. (SJP5891J) ACCIDENT ON 13-09-2018 - FINALISATION

Dear Mr Taufikh,

WITHOUT PREJUDICE

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 26 September 2018 11:15 AM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006873MFSH/1
Attachments: PRELI ADVISED GBA 6170Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBA 6170Z**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 19 September 2018 2:36 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006873MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer arrange survey on 20/09/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 19 September 2018 2:26 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006873MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7657K
Vehicle Details	
Vehicle No.:	GBA6170Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Sep 2018
Vehicle Make:	DAIHATSU
Vehicle Model:	HIJET 660 M
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	EF0112889
Chassis No.:	S320V0086027
Maximum Power Output:	-
Open Market Value:	\$9,896.00
Original Registration Date:	13 Sep 2007
First Registration Date:	13 Sep 2007
Transfer Count:	3
Actual ARF Paid:	\$495.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,070.00
COE Rebate Amount:	\$30,195.00
Total Rebate Amount:	\$30,195.00

The information contained herein is correct as at 18 Sep 2018.

OK



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR REDDOT DÉCOR PTE LTD
BLK 684B EDGEDALE PLAINS
#09-639 (S) 822684

POLICY NO :
YOUR REF :
OUR REF :
VEHICLE NO :
MAKE/MODEL :
DATE OF ACCIDENT :
THIRD PARTY CLAIMS :
SHC362U (1ST CAP)
TP 5939
GBA6170Z
Daihatsu Hijet 660M
13.9.18

SURVEY BY

DATE : 18.9.18

1	PC	BONNET		S\$	650.00	Rx
1	PC	BONNET HINGE L/H			110.00	Rx
1	PC	HEADLAMP L/H			420.00	cur
1	PC	FRONT BUMPER			580.00	de
2	PCS	FRONT BUMPER SIDE RETAINERS	110.00		220.00	ne
1	PC	FRONT WHEEL HOUSING L/H			550.00	Rx
1	PC	FRONT FENDER L/H			420.00	bt
1	PC	FRONT FENDER INNER SHIELD L/H			125.00	de
1	PC	MUD FLAP L/H			80.00	cur
1	PC	FRONT DOOR PILLAR L/H			460.00	bt
1	PC	FRONT DOOR L/H			950.00	bt
2	PCS	FRONT DOOR HINGES (TOP&BOTTOM)	105.00		210.00	bt
1	PC	FRONT DOOR WEATHERSTRIP L/H			135.00	ne
1	PC	ROCKER PANEL L/H			280.00	bt
1	PC	SLIDING DOOR L/H			1,050.00	bt
1	PC	GLOVE BOX L/H			180.00	? X nn
2	PCS	FRONT SHOCK ABSORBERS	150.00		300.00	? ✓ bt
2	PCS	FRONT LOWER ARM	215.00		430.00	? ✓ bt
2	PCS	FRONT KNUCKLE ARM	280.00		560.00	? ✓ bt
2	PCS	FRONT KNUCKLE ARM BEARING	120.00		240.00	? ✓ bt
1	PC	FRONT CROSS MEMBER			750.00	X X nn
1	PC	STEERING RACK AND PINION			950.00	? ✓ bt
2	PCS	FRONT WHEEL HUB CAP	90.00		180.00	nn
1	PC	FRONT WINDSCREEN MOULDING			80.00	cur
				S\$	9,910.00	
				LESS	10%	991.00
				S\$	8,919.00	
1	SET	FRONT FENDER INNER SHIELD CLIPS		S\$	48.00	"S/NETT"
1	PC	FRONT DOOR STICKER			20.00	"
2	PCS	RIM	100.00		200.00	"
2	PCS	TYRE	120.00		240.00	192 "
2	PCS	SEALANT	40.00		80.00	"
				S\$	588.00	



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

TO TRANSFER DOOR	S\$ 80.00 ⁵⁰
TOWING CHARGES	50.00 ✓
TO TRANSFER SLIDING DOOR	80.00 ⁵⁰
TO REMOVE AND REFIX SLIDING DOOR GLASS	100.00 ^{80.}
TO REMOVE AND REFIX FRONT WINDSCREEN GLASS	140.00 ^{120 ✓}
TO DO COMPUTER ALIGNMENT	150.00 ^{80.}
TO DISMANTLE AND REFIX FRONT UNDERCARRIAGE	250.00 ¹⁵⁰
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL	100.00 ^{60.}
TO CHECK WIRING FUNCTION	30.00 ✓
LABOUR CHARGES	950 1,100.00 ^{800.}
TO PUTTY AND SPRAY PAINTING CHARGES	1,500.00 ¹²⁰⁰

S\$ 13,087.00

SIN DOLLARS: THIRTEEN THOUSAND AND EIGHTY-SEVEN DOLLARS ONLY.

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tanpin 97495749
'wp'

20/9/18 @ 1245

Resurvey after repair.
sure link auto con.

10 days.

26/9/18



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR REDDOT DÉCOR PTE LTD
BLK 684B EDGEDALE PLAINS
#09-639 (S) 822684

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SHC362U (1ST CAP)
OUR REF : TP 5939
VEHICLE NO : GBA6170Z
MAKE/MODEL : Daihatsu Hijet 660M
DATE OF ACCIDENT : 13.9.18

SURVEY BY

DATE : 18.9.18

1 PC BONNET			S\$ 650.00 <i>Rp</i>
1 PC BONNET HINGE L/H			110.00 <i>Rp</i>
1 PC HEADLAMP L/H			420.00 <i>ana</i>
1 PC FRONT BUMPER			580.00 <i>de</i>
2 PCS FRONT BUMPER SIDE RETAINERS	110.00		220.00 <i>ne</i>
1 PC FRONT WHEEL HOUSING L/H			550.00 <i>Rp</i>
1 PC FRONT FENDER L/H		7670.00	420.00 <i>bt</i>
1 PC FRONT FENDER INNER SHIELD L/H			125.00 <i>de</i>
1 PC MUD FLAP L/H			80.00 <i>ml</i>
1 PC FRONT DOOR PILLAR L/H		6903.00	460.00 <i>bt</i>
1 PC FRONT DOOR L/H			950.00 <i>bt</i>
2 PCS FRONT DOOR HINGES (TOP&BOTTOM)	105.00		210.00 <i>bt</i>
1 PC FRONT DOOR WEATHERSTRIP L/H			135.00 <i>ne</i>
1 PC ROCKER PANEL L/H			280.00 <i>bt</i>
1 PC SLIDING DOOR L/H			1,050.00 <i>bt</i>
1 PC GLOVE BOX L/H			180.00 ?
2 PCS FRONT SHOCK ABSORBERS	150.00		300.00 ?
2 PCS FRONT LOWER ARM	215.00		430.00 ?
2 PCS FRONT KNUCKLE ARM	280.00		560.00 ?
2 PCS FRONT KNUCKLE ARM BEARING	120.00		240.00 ?
1 PC FRONT CROSS MEMBER			750.00 ?
1 PC STEERING RACK AND PINION			950.00 ?
2 PCS FRONT WHEEL HUB CAP	90.00		180.00 <i>mg</i>
1 PC FRONT WINDSCREEN MOULDING			80.00 <i>ml</i>
			S\$ 9,910.00
	LESS 10%		991.00
			S\$ 8,919.00
1 SET FRONT FENDER INNER SHIELD CLIPS			S\$ <i>ne</i> 48.00 "S/NETT"
1 PC FRONT DOOR STICKER			<i>ne</i> 20.00 "
2 PCS RIM	100.00		<i>bt</i> 200.00 "
2 PCS TYRE	120.00		80% <i>pushed</i> 240.00 1920
2 PCS SEALANT	40.00		<i>ne</i> 40 80.00 "
			S\$ 588.00



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

TO TRANSFER DOOR		S\$ 80.00 ⁵⁰
TOWING CHARGES		50.00 ✓
TO TRANSFER SLIDING DOOR		80.00 ⁵⁰
TO REMOVE AND REFIX SLIDING DOOR GLASS		100.00 ⁸⁰
TO REMOVE AND REFIX FRONT WINDSCREEN GLASS		140.00 ¹²⁰
TO DO COMPUTER ALIGNMENT		150.00 ⁸⁰
TO DISMANTLE AND REFIX FRONT UNDERCARRIAGE	2810.00	250.00 ¹⁵⁰
TO APPLY RUST PROOING ON REPLACED/REPAIRED PANEL		100.00 ⁶⁰
TO CHECK WIRING FUNCTION		30.00 ✓
LABOUR CHARGES		⁹⁵⁰ 1,100.00 ⁸⁰⁰
TO PUTTY AND SPRAY PAINTING CHARGES		1,500.00 ¹²⁰⁰

^{2810.00}
\$10223.00 S\$ 13,087.00

SIN DOLLARS: THIRTEEN THOUSAND AND EIGHTY-SEVEN DOLLARS ONLY.

YOUR FAITHFULLY,



 CYS AUTOMOBILE SERVICES PTE LTD

LS = \$8150

Tanfer 9749549
 'wp'

20/7/18 @ 1245

Resurvey after repair
 surell auto.com.

10 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017073/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 362U	Veh. Inspected	GBA 6170Z	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18006873MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	19/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	DAIHATSU HIJET	c.c	659	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	S320V0086027	Colour	RED	
Odometer	264578	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	155 R12	FALKEN	6 mm	
L/H Front Tyre	155 R12	FALKEN	6 mm	
R/H Rear Tyre	155 R12	FALKEN	6 mm	
L/H Rear Tyre	155 R12	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY,FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/09/2018	Inspection Date	20/09/2018	
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 6170Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	TO REPAIR SEE LABOUR	650.00	-
1	BONNET HINGE L/H	TO REPAIR SEE LABOUR	110.00	-
1	HEADLAMP L/H	CRACKED	420.00	420.00
1	FRONT BUMPER	DEFORMED	580.00	580.00
2	FRONT BUMPER SIDE RETAINERS @\$110.00	NECESSARY	220.00	220.00
1	FRONT WHEEL HOUSING L/H	TO REPAIR SEE LABOUR	550.00	-
1	FRONT FENDER L/H	BENT	420.00	420.00
1	FRONT FENDER INNER SHIELD L/H	DEFORMED	125.00	125.00
1	MUD FLAP L/H	CUT	80.00	80.00
1	FRONT DOOR PILLAR L/H	BENT	460.00	460.00
1	FRONT DOOR L/H	BENT	950.00	950.00
2	FRONT DOOR HINGES (TOP & BOTTOM) @\$105.00	BENT	210.00	210.00
1	FRONT DOOR WEATHERSTRIP L/H	NECESSARY	135.00	135.00
1	ROCKER PANEL L/H	BENT	280.00	280.00
1	SLIDING DOOR L/H	BENT	1,050.00	1,050.00
1	GLOVE BOX L/H	NOT NECESSARY	180.00	-
2	FRONT SHOCK ABSORBERS @\$150.00	BENT	300.00	300.00
2	FRONT LOWER ARM @\$215.00	BENT	430.00	430.00
2	FRONT KNUCKLE ARM @\$280.00	BENT	560.00	560.00
2	FRONT KNUCKLE ARM BEARING @\$120.00	BENT	240.00	240.00
1	FRONT CROSS MEMBER	NOT NECESSARY	750.00	-
1	STEERING RACK AND PINION	BENT	950.00	950.00
2	FRONT WHEEL HUB CAP @\$90.00	MISSING	180.00	180.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-991.00	-767.00
			8,919.00	6,903.00
SPECIAL NETT ITEMS				
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	48.00	48.00

Report Ref No. CS/FCI18017073/T1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR STICKER (SN)	NECESSARY	20.00	20.00
2	RIM @\$100.00 (SN)	BENT	200.00	200.00
2	TYRE @\$120.00 (80%)(SN)	PUNCTURE	240.00	192.00
2	SEALANT @\$40.00 (SN)	NECESSARY	80.00	40.00
			588.00	500.00
	LABOUR			
	TO TRANSFER DOOR.		80.00	50.00
	TOWING CHARGES.		50.00	50.00
	TO TRANSFER SLIDING DOOR.		80.00	50.00
	TO REMOVE AND REFIX SLIDING DOOR GLASS.		100.00	80.00
	TO REMOVE AND REFIX FRONT WINDSCREEN GLASS.		140.00	120.00
	TO DO COMPUTER ALIGNMENT.		150.00	80.00
	TO DISMANTLE AND REFIX FRONT UNDERCARRIAGE.		250.00	150.00
	TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL.		100.00	60.00
	TO CHECK WIRING FUNCTION.		30.00	30.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF BONNET,BONNET HINGE L/H AND FRONT WHEEL HOUSING L/H.		1,100.00	950.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		1,500.00	1,200.00
			3,580.00	2,820.00
	GRAND TOTAL		13,087.00	10,223.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,100.00

Report Ref No. CS/FCI18017073/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.