

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18017075/KPA3Q2

Date: 17/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00002380

Claimant
Vehicle No : GX4708G **Insured Vehicle No :** SJC2913T

Date of Loss: 17/09/2018 Nature of Claim: TP Claim No: 1201800011743

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX4708G		
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Engine No:	5L5436694
Reg. Date:	28/05/2004 (Man. Year: 2004)	Chassis No:	LH1621011148
Colour:	Metallic Dark Blue	Odometer:	347415 km
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R15X8	Rear Tyre Size:	185 R15X8
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,189.75	2,613.50	576.25	18.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,270.00	590.00	31.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,049.75	3,883.50	1,166.25	23.10
Approved Total (Overridden) (\$\$)		3,100.00		
(\$\$)	5,049.75	3,100.00	1,949.75	38.61
+ GST 7.00/7.00% (\$\$)	353.48	217.00	136.48	38.61
Nett Amount (\$\$)	5,403.23	3,317.00	2,086.23	38.61
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 18/09/2018

Date Inspected: 19/09/2018 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)
160 Sin Ming Drive #02-20, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Aug 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX4708G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,305.00 FL	*1,305.00 FL
2	1		*TAILGATE LOCK	Jammed	235.00 FL	*235.00 FL
3	1		*TAILGATE LOCK CATCH	Distorted	55.00 FL	*55.00 FL
4	1		*TAILGATE WEATHERSTRIP	*Check	295.00 FL	*- FL
5	1		*TAILGATE GLASS RUBBER (50%)	Necessary	258.75 FS	*172.50 FS
6	1		*TAILGATE LOGO	Necessary	60.00 FL	*60.00 FL
7	1		*REAR BUMPER	Buckled	568.00 FL	*568.00 FL
8	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Distorted	40.00 FL	*40.00 FL
9	8		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
10	1		*REAR BUMPER CENTRE BEAM	Bent	260.00 FL	*260.00 FL
11	1		*REAR END PANEL -OUTER	Bent	385.00 FL	*385.00 FL
12	1		*REAR END PANEL TOP MOULDING	*Check	75.00 FL	*- FL
13	2		*REAR BUMPER LOWER BRACKET	*Check	230.00 FL	*- FL
14	1		*TAILGATE 70KM/HSTICKER	Necessary	25.00 FS	*15.00 FS
15	1		*TAILGATE 6 PAX STICKER	Necessary	25.00 FS	*15.00 FS
16	1		*REVERSE SENSOR ASSY	Cracked	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,076.75	3,350.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	887.00	737.00
Total Parts (\$\$)	3,189.75	2,613.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS	New	800.00	600.00
2	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	60.00	50.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	60.00
4	TO TRANSFER TAILGATES FITTINGS	New	80.00	60.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	800.00	500.00
Gross Labour Cost (\$)			1,860.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >