

INSURANCE

INS. CASE OWNER:

CC 7/1111801

7076, TIS 9/1/18

LKK:

IDAC:

Surveyor:

Tamirah

DOE:

ASSIGNMENT

11/1/18

Date / Time:

11/1/18

Registered in Merimen:

11/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

XD 2589T

Name of Insured:

INTER TERMINAL SERVICES

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

15/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN YIN BENH MEUVIN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

ME2018490

Policy No.:

MYA72621

Make / Model:

MITSUBISHI

Place of Accident:

near PF ORTHO DORO & PATERSUN RD

OI GIA REPORT:

YES / NO

TP GIA REPORT:

YES / NO

Insured Liability:

%

Final? Yes / No

SFV 81610



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SFV 81610-X

XD 2589T-X

STAGE

DATE / PIC

Non-Reporting in (1st):

Non-Reporting in (2nd):

Non-Reporting in (Final):

Notification in (if non-pickup):

Call OI:

After call in to OI:

Documentation Check List: Handler Typist

Notification in (if non-pickup):

After call in to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

OID changing lane. SFV send to

Liability not approved. AVF not able to view.

TP was inform via phone call that claimant

convert ad. Notify lit of WP submission via

email.

Pending file re-open in merimen. (File return

Don Admin).

Merimen open (File pass admin)

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

-100- (Agreed / Assessed) BOLA S/N No. : -15-

If NO or B 28. Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5

(5

x

days)

Loss of Income (LOI):

\$5

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search:

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT 4/8/18

REF:

II

1

3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLump Sum: 1-21 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFV81610Yr Regn: 2017 MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 740LiC.C. 2998Colour: White

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 7E22069764249Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 275/40R19R: 275/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Haruharu

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 19/9/15 @ 1200Survey held at PM C

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear U/S, 4/C
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No key

P/R = \$21,474.05
 ? HCM = \$4102.50

(Red = \$2213.80 / 26%)

Date/Time, File Pass to?

☐

: Preli. Report

If _____

☐

: Final Report

Date/Time, File Return to?

21 _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weat/and (\$

Report Format: _____

Lump Sum / I.B.E. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18017076/ub3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 19-09-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 3589T	Veh. Inspected	SFV 8161D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/09/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SFV8161D

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Farrer Road
East Coast Centre
Singapore 478180
Tel. 63190888 (AfterSales)
Fax. 63449771

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64756601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48453
Date Estimated : 17/09/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Wan Chye
4A Rochalie Drive

Singapore 248261

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV8161D	G764249	25/05/2017	740Li	0

DESCRIPTION

To replace rear bumper & attachments, rear right fender, right trunk floor panel including to knock out dented area caused by the accident

To respray rear bumper, rear right fender, tail panel, right roof frame, right running board panel and boot compartment

To carry out body cavity preservation.
(For cut panel).

To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests.

To supply and install rear windscreen solar film.

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

To replace tyre and wheel rim including balancing. (1x).

To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

No trunk - 5525 10,200.00
Repair Trunk - 7650
Replace Trunk - 2500
4284 - 4,766.00

451 531.00

photo: 451 531.00

✓ 451 531.00

451 531.00

80 94.00

451 531.00

150 177.00

? 150.00

Total Labour 1: 18,042.00

DESCRIPTION

ALLOY RIM 9.5X19 DOUBLE SPK
HUB CAP WITH CHROME EDGE
TRUNK FLOOR

QTY	PRIC	VALUE
1	1,401.50	inf 1,401.50
1	35.75	? 35.75
1	290.45	? 290.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 478180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/536 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48453
Date Estimated : 17/09/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV8161D	G764249	25/05/2017	740Li	0

DESCRIPTION	QTY	PRIC	VALUE
# RR RH FENDER	1	2,721.50	bt ✓ 2,721.50
# Mount for SC	1	38.50	? 38.50
REAR BUMPER CENTRE GUIDE	1	51.50	? 51.50
# REAR RH MOUNT LATERAL	1	160.55	nk ✓ 160.55
REAR RH MOULDING ROCKER PANEL	1	51.50	? 51.50
BUMPER GUARD REAR	1	102.95	? 102.95
RH RUBBER STRIP	1	85.05	? 85.05
REAR BUMPER COVER	1	107.05	nm ✓ 107.05
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,586.85	de ✓ 1,586.85
PLASTIC NUT	5	0.85	nk ✓ 4.25
REAR WINDOW GREEN (ESG)	1	1,271.35	? 1,271.35
EXPANDING RIVET D=8MM	10	1.05	nk ✓ 10.50
# RR RH WHEEL HOUSING COVER	1	180.00	? 180.00
REAR DIFFUSER	1	139.75	? 139.75
EXPANDING NUT	10	0.55	? 5.50
REAR RH REAR REFLECTOR	1	36.25	nm x 36.25
# REAR RH LIGHT IN TRUNK LID	1	473.65	? 473.65
# RH WATER CHANNEL	1	37.95	? 37.95
REAR RH LIGHT IN THE SIDE PANEL	1	735.95	nm ✓ 735.95
DECOUPING RING PDC TORQUE CONVERTER	2	5.05	nk ✓ 10.10
ULTRASONIC SENSOR MINERALWEISS(WA96	2	368.80	? 737.60
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	nk ✓ 18.45
BLIND RIVET AVIBVLB	40	0.55	nk ✓ 22.00
SCREW (SF PLUS M5X15)	10	0.55	nk ✓ 5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	nk ✓ 281.55
PUNCH RIVET N5	10	0.55	nk ✓ 5.50
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	nk ✓ 118.35
(DG) CLEANER R1 (100ML)	1	26.15	nk ✓ 26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	nk ✓ 263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	nk ✓ 27.85
(S/L) SEAM SEAL 300ML	3	33.80	nk ✓ 101.40

Total Parts : 11,145.85

Claim: OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time: 19/9/18 @ 1245 Excess \$:

Surveyor's Name: Tan Jiahn Sign: [Signature]

Surveyor's Tel: 97495749 Authorised: Yes / No

Authorised Date: _____ Time: _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail: tan.jiahn@lkk.com

No. of Working Days Recommend: 10-14 days

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts price & labour confirmation

• Third party liability on a "Without Prejudice" basis

• No illegal modification(s) allowed

• Supplemental repair(s) must be resurveyed and

is subject to final approval from Insurance Company

Total GST @ 7%

Acknowledged by Repairer

Signature: Grand Total

Date:

18,042.00

11,145.85

0.00

0.00

2,043.15

31,231.00

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Friday, 28 June 2019 5:10 PM
To: Lalitha Krishnan - III
Subject: YOUR REF: MC20182790 (OUR REF: CC3/III18017076/T1gb3) *** ACCIDENT INVOLVING XD 3589T (OI) & SFV 8161D (TP) ON 15/09/2018 ***

Dear Lalitha,

We refer to the above matter

We check with TP repairer that claimant covert to OD.

In view of above, we will submit the WP report to your good office.

Kindly send back our report via Merimen.

Thank you.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2018 Edit Reg		19 Sep 2018 00:00 Edit Adj Rpt	S\$21,474.05 Edit Estimates	S\$21,474.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	INTER TERMINAL SERVICES, Co. Reg. No.: -								
Main Claimant:	MR TAN WAN CHYE, ID: S0611580B								
Vehicle Reg. No.:	SFV8161D	Date of Loss:	15/09/2018 18:00 - :59 [15 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MC20182790	Policy/Cover Note No.:	M497362						
Vehicle Reg. No. (Insured):	XD3589T	Policy No. (Claimant):	VPA/P1941404						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 28/09/2018]								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
• III_SG (01/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SFV8161D - Claim Handler: Lalitha Krishn...									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFV8161D (MC20182790)
[XD3589T]
TP
MR TAN WAN CHYE
Sep 15 2018 6:00PM
[INTER TERMINAL SERVICES]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 10:01	Video - Accident TP	Load AVI	
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/09/18 16:25	TP ESTIMATE	Load PDF	
2	19/09/18 16:25	TP GIA REPORT	Load PDF	
3	24/09/18 17:34	TP ESTIMATE- MARKED	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/09/18 08:45	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18017076/T1GB3Q2

Date: 30/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M497362

Claimant Vehicle No: SFV8161D

Insured Vehicle No: XD3589T

Date of Loss: 15/09/2018

Nature of Claim: TP

Claim No: MC20182790

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFV8161D

Make & Model: BMW 740LI, 3.0 (A)

Engine No: 10269924B58B30A

Reg. Date: 25/05/2017 (Man. Year: 2017)

Chassis No: WBA7E22020G764249

Colour: White

Odometer: 0 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/40 R19

Rear Tyre Size: 275/40 R19

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,295.85	7,501.05	3,794.80	33.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,892.00	13,973.00	3,919.00	21.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,187.85	21,474.05	7,713.80	26.43
+ GST 7.00/7.00% (S\$)	2,043.15	1,503.18	539.97	26.43
Nett Amount (S\$)	31,231.00	22,977.23	8,253.77	26.43

INSPECTION

Date of Assignment: 19/09/2018

Date Inspected: 19/09/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
Parts:	143	BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFV8161D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	*Check	150.00 FS	*- FS
2	1		*ALLOY RIM 9.5X19 DOUBLE SPK	Cut	1,401.50 FS	*1,401.50 FS
3	1		*HUB CAP WITH CHROME EDGE	*Check	35.75 FS	*- FS
4	1		*TRUNK FLOOR	*Check	290.45 FS	*- FS
5	1		*RR RH FENDER	Bent	2,721.50 FS	*2,721.50 FS
6	1		*MOUNT FOR SC	*Check	38.50 FS	*- FS
7	1		*REAR BUMPER CENTRE GUIDE	*Check	51.50 FS	*- FS
8	1		*REAR RH MOUNT LATERAL	Necessary	160.55 FS	*160.55 FS
9	1		*REAR RH MOULDING ROCKER PANEL	*Check	51.50 FS	*- FS
10	1		*BUMPER GUARD REAR	*Check	102.95 FS	*- FS
11	1		*RH RUBBER STRIP	*Check	85.05 FS	*- FS
12	1		*REAR BUMPER COVER	Not Necessary	107.05 FS	*- FS
13	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,586.85 FS	*1,586.85 FS
14	5		*PLASTIC NUT	Necessary	4.25 FS	*4.25 FS
15	1		*REAR WINDOW GREEN (ESG)	*Check	1,271.35 FS	*- FS
16	10		*EXPANDING RIVET D=8MM	Necessary	10.50 FS	*10.50 FS
17	1		*RR RH WHEEL HOUSING COVER	*Check	180.00 FS	*- FS
18	1		*REAR DIFFUSER	*Check	139.75 FS	*- FS
19	10		*EXPANDING NUT	*Check	5.50 FS	*- FS
20	1		*REAR RH REAR REFLECTOR	Not Necessary	36.25 FS	*- FS
21	1		*REAR RH LIGHT IN TRUNK LID	*Check	473.65 FS	*- FS
22	1		*RH WATER CHANNEL	*Check	37.95 FS	*- FS
23	1		*REAR RH LIGHT IN THE SIDE PANEL	Cracked	735.95 FS	*735.95 FS
24	2		*DECOUPLING RING PDC TORQUE CONVERTER	Necessary	10.10 FS	*10.10 FS
25	2		*ULTRASONIC SENSOR MINERALWEISS (WA96)	*Check	737.60 FS	*- FS
26	1		*CAVITY PROTECTION WAX REMOVER 500ML	Necessary	18.45 FS	*18.45 FS
27	1		*BLIND RIVET AVIBVLB (40 PCS)	Necessary	22.00 FS	*22.00 FS
28	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
29	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
30	10		*PUNCH RIVET N5	Necessary	5.50 FS	*5.50 FS
31	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
32	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
33	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
34	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
35	3		*(S/L) SEAM SEAL 300ML	Necessary	101.40 FS	*101.40 FS
Total Parts (\$\$)					11,295.85	7,501.05

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS ,REAR RIGHT FENDER ,RIGHT TRUNK FLOOR PANEL INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	10,200.00	7,650.00
2	TO RESPRAY REAR BUMPER ,REAR RIGHT FENDER ,TAIL PANEL ,RIGHT ROOF FRAME ,RIGHT RUNNING BOARD PANEL AND BOOT COMPARTMENT	New	4,766.00	4,289.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
4	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS	New	531.00	451.00
5	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	451.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
7	TO REPLACE TYRE AND WHEEL RIM INLUDING BALANCING	New	94.00	80.00
8	TO REMOVE AND INSTALL WIRE HARNESS ,CONTROL UNITS AND BATTERY AT THE REAR SECTION TO FACILITATE PANEL REPLACEMENT (*Check)	New	531.00	0.00
9	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			17,892.00	13,973.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >