

**LAI HUAT (MENG KEE)
MOTOR PTE LTD
SIN MING INDUSTRIAL
ESTATE SECTOR A
BLK 21 #01-58
SINGAPORE 575679**

Claim Reference:
Assessment Number: LHMJ0597
Version: LAI HUAT/10
Date Calculated: 29/03/2019 09:57

Full Report - V1
Registration: SJZ 6296T
Printed: 29/03/2019 17:58

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	15/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3086821702	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 250 CGI
Model Sheet Number:	3AE 01
Registration:	SJZ 6296T
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

TRIM ELEGANCE

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection: 22/09/2018
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:
 Assessment Number: LHMJ0597
 Version: LAI HUAT/10
 Date Calculated: 29/03/2019 09:57

Full Report - V1
 Registration: SJZ 6296T
 Printed: 29/03/2019 17:58



Addresses

Cost Summary

Total Labour	\$2,742.60
Total Paint/Material	\$245.26
Total Parts	\$8,097.00
Total of Additional Costs	\$1,116.00
Excess:	- \$0.00
Grand Total Exc GST:	\$12,200.86
7 % GST:	\$854.06
Grand Total Inc GST:	\$13,054.92

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
 Price/Dent = \$42.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
40-6500 01	ALIGNMENT CPL BEFORE REPAIR	7.0	29.40
88-4705 02	R + R L/F PARTITION REAR SECTION	3.0	12.60
60-1587 01	R + R LEFT REAR OUTER DOOR HANDLE	2.0	8.40
88-9705 02	R + R LEFT ROOF MOULDING	2.0	8.40
60-2175 01	R + R ATTACHED PARTS OF THE REAR PANNELLING FOR RENEWAL OF THE L/R WING INCLUDES: R + R ATTACHED PARTS IN THE REPAIR SECTION	58.0	243.60
60-2120 01	R + R ATTACHED PARTS OF THE INTERIOR FOR RENEWAL OF THE SPARE WHEEL WELL INCLUDES: R + R CENTRE BOOT TRIM AND IF NECESSARY REAR AXLE PRESSURE ACCUMULATOR	5.0	21.00
63-1882 01	RENEW L/REAR WING CPL	111.0	466.20
64-1201 01	RENEW SPARE WHEEL WELL	14.0	58.80
88-3501 02	RENEW MERCEDES STAR	2.0	8.40
88-3512 02	R + R REAR TYPE BADGE	4.0	16.80
82-4912 02	R + R LEFT INNER TAILLAMP	3.0	12.60
88-8805 02	DIS + ASS REAR BUMPER (REMOVED)	2.0	8.40
88-8882 ZAX	ADD TO DIS/ASS REAR BUMPER CPL (LUXURY VERSION VEHICLE)	2.0	8.40
91-2157 01	R + R DRIVER AIRBAG	3.0	12.60
68-3051 02)	R + R L/BOOT TRIM	4.0	16.80
40-1590 01	R + R FRONT WHEELS	3.0	12.60
33-3510 03)	R + R L/F STEERING KNUCKLE	20.0	84.00

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: LHMJ0597

Registration: SJZ 6296T

Version: LAI HUAT/10

Printed: 29/03/2019 17:58

Date Calculated: 29/03/2019 09:57

33-3630 03)	R + R FRONT STEERING KNUCKLE ASS WORK	3.0	12.60
32-1955 03)	R + R L/F STRUT	5.0	21.00
32-1908 02)	DISS/ASS L/F SUSPENSION STRUT REMOVED	3.0	12.60
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	12.60
46-7001 01)	R + R BOTH TIE RODS	8.0	33.60
40-2410 01	R + R LEFT FRONT TYRE	3.0	12.60
40-2410 01	R + R LEFT REAR TYRE	3.0	12.60
40-2055 01	L/FRONT WHEEL BALANCE	2.0	8.40
40-2055 01	L/R ROAD WHEEL BALANCE	2.0	8.40
NO NUMBER	LOWER REAR AXLE	14.0	58.80
32-1065 02)	R + R LEFT REAR SHOCK ABSORBER	3.0	12.60
35-7826 02)	R + R LEFT SPRING LINK OF REAR AXLE	8.0	33.60
35-7856 02)	R + R LEFT REAR TIE ROD	2.0	8.40
35-7861 02)	R + R L/R CAMBER STRUT	4.0	16.80
49-6900 ZAX	R + R EXHAUST HEAT SHIELD	4.0	16.80
82-1130 01	ADJUST FRONT LAMP UNITS AND FRONT FOG LAMPS	3.0	12.60
40-6500 01	ALIGN VEHICLE INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER, CHECK FRONT AND REAR VEHICLE LEVEL	7.0	29.40
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	8.40
40-4403 01	ADJUST REAR WHEEL TOE (VEHICLE ALIGNMENT)	2.0	8.40
40-6716 01	ADDITIONAL TO OPTICAL ALIGNMENT ADJUST L/FRONT AXLE HALF CAMBER/CASTER	6.0	25.20
7359	REMOVE&REFIT STEERING COLUMN CPL	20.0*	84.00
7400	REMOVE&REFIT STEERING WHEEL	5.0*	21.00
7407	REMOVE&REFIT STRG COLUMN COVER	5.0*	21.00
7417	REMOVE&REFIT COMBI SWITCH MODULE	5.0*	21.00
9852	SHORT TEST ERROR MEMORY	20.0*	84.00
9973	KN TEST DRIVE	10.0*	42.00
2711	REPAIR LOWER REAR PANELLING	40.0*	168.00
4043	REPAIR L/R FLOOR PANEL	20.0*	84.00
4101	REPAIR L/R INNER PILLAR	50.0*	210.00

LABOUR COST

Total Work Units	509.0	
Panel / Mechanical Labour	48.5HRS	\$2,037.00
Visual Alignment Labour	2.4HRS	\$100.80
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	50.9HRS	\$2,137.80
Paint Labour	14.4HRS	\$604.80
Total Labour	65.3HRS	\$2,742.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
3481	L/R WING NEW PART PAINTING WITH FRONT SURFACE BELOW DOOR	25.0	
2207	L/SILL PANELLING NEW PART PAINT K1R	7.0	

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHMJ0597

Version: LAI HUAT/10

Date Calculated: 29/03/2019 09:57

Full Report - V1

Registration: SJZ 6296T

Printed: 29/03/2019 17:58

2583	REAR BUMPER COVER NEW PART PAINT K1R	11.0	
283	FRONT BUMPER COVER REPAIR PAINT PLASTIC	14.0	
2101	L/SILL PANEL REPAIR PAINTING <50%	11.0	
2353	L/ROOF COVER PANEL REPAIR PAINTING <50%	9.0	
2711	LOWER REAR PANELLINGREPAIR PAINTING <50%	12.0	
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	16.0	
1781	L/R DOOR SURFACE PAINT	7.0	
4043	L/R FLOOR PANEL SURFACE PAINT	4.0	
4101	L/R INNER PILLAR SURFACE PAINT	5.0	
LABOUR COST - PAINT			
	TIME(PAINT)	121.0	
	Preparation Main Work Metal	17.0	
	Preparation Comp. Work Plastic	6.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	144.0	
	Total Paintwork Labour	14.4HRS	\$604.80
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$28.84
	New Part Painting - Plastic K1R		\$69.11
	Surface-/Blend Paint		\$23.76
	Repair Painting		\$56.75
	Repair Painting Plastic		\$36.00
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$245.26
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$245.26

PARTS

				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3939	1	ADHESIVE SEALANT	168 670 0093		0%	0.00F
3023	1	BADGE "CGI"	209 817 0515		0%	39.00*
7065	1	L/F BALL JOINT	212 330 0135		0%	73.00*
7071	1	L/F LWR CONTROL ARM	212 330 3900		0%	254.00*
7103	1	L/F S-ABSORB BOOT	212 323 0392		0%	26.00*
7087	1	L/F SHOCK ABSORBER	212 323 5300		0%	415.00*
7095	1	L/F SP/STRUT SUPPORT	204 981 0025		0%	32.00*
7251	1	L/F SPEED SENSOR	212 540 0117		0%	185.00*
7081	1	L/F STEERING KNUCKLE	212 332 0700		0%	635.00*
7091	1	L/F STRUT BEARING	212 323 0020		0%	105.00*
7201	1	L/F WHEEL	212 401		0%	470.00*
			0002649765			
7131	1	L/F WHEEL HUB	212 330 0025		0%	360.00*
841	1	L/F W-HOUSE CVR REAR	212 690 3030		0%	88.00*
4981	1	L/INNER BOOT TRIM	212 690 4300 9F08		0%	160.00*
3527	1	L/LOWER INSULATION	212 682 1141		0%	10.00*
7311	1	L/OUTER TIE ROD BALL	212 330 2303		0%	150.00*
9385	1	L/R AXLE STEERING	204 350 3506		0%	95.00*
2593	1	L/R BUMPER GUIDE	212 880 1330		0%	20.00*
2619	1	L/R BUMPER SUPPORT	212 880 0103		0%	35.00*
9371	1	L/R CAMBER STRUT	205 350 6103		0%	120.00*

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:
Assessment Number: LHMJ0597
Version: LAI HUAT/10
Date Calculated: 29/03/2019 09:57

Full Report - V1
Registration: SJZ 6296T
Printed: 29/03/2019 17:58

3283	1	L/R INNER LAMP	212 906 0158	0%	230.00*
2615	1	L/R MOULDING	212 885 2121	0%	72.00*
3281	1	L/R OUTER LAMP	212 906 6601	0%	355.00*
8827	1	L/R PROTECT SHIELD	212 680 0122	0%	43.00*
9201	1	L/R SHOCK ABSORBER	212 320 0630	0%	285.00*
9375	1	L/R TIE ROD	205 350 6503	0%	105.00*
9565	1	L/R TYRE	205/60 R 16 .. H	0%	0.00F
9389	1	L/R UPP C-ARM COVER	204 352 1588	0%	15.00*
3685	1	L/R VENT INSERT	212 830 0242	0%	15.00*
9551	1	L/R WHEEL	212 401	0%	470.00*
			0002649765		
3677	1	L/R WHL-HOUSE COVER	212 690 0930	0%	85.00*
3481	1	L/R WING	212 630 0321	0%	1,140.00*
2207	1	L/SILL PANELLING	212 698 0154 9999	0%	355.00*
7309	1	L/TIE ROD	212 330 2103	0%	93.00*
7101	1	L/UPPER BUFFER	212 321 0106	0%	35.00*
3525	1	L/UPPER INSULATION	212 682 5300	0%	55.00*
7312	1	R/OUTER TIE ROD BALL	212 330 2203	0%	88.00*ds
2616	1	R/R MOULDING	212 885 2221	0%	72.00*
7310	1	R/TIE ROD	212 330 2103	0%	94.00*ds
3011	1	REAR BADGE	124 817 6115	0%	38.00*
2583	1	REAR BUMPER COVER	212 880 4340 9999	0%	820.00*
2617	1	REAR BUMPER MOULDING	212 885 2021	0%	90.00*
3160	1	REAR SCREEN BOND KIT	000 670 0100	0%	0.00F
3161	3	REAR SCREEN SUPPORTS	164 742 0097	0%	0.00F
3935	1	SPARE WHEEL WELL	212 610 0075	0%	145.00*
3010	1	STAR EMBLEM	212 817 0016	0%	25.00*
f: OEM Parts			Saving		\$231.06
g: Original			Sub Total		\$7,997.00
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$8,097.00
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
REAR W/S SEAL	SPECIALIST	0%	\$40.00
WATER LEAK TEST	SPECIALIST		\$30.00
L/R TYRE	SPECIALIST	0%	\$198.00
L/F TYRE	SPECIALIST		\$198.00
REAR W/S MOULDING	SPECIALIST	0%	\$150.00
REPAIR STEER_G LOCK	SPECIALIST		\$250.00
PROGRAM STEER_G LOCK	SPECIALIST	0%	\$250.00
Total Extras			\$1,116.00

Final Calculation

Total Parts	\$8,097.00
Labour	
Total Panel/Mechanical	\$2,037.00
Total Paintwork	\$604.80

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: LHMJ0597

Registration: SJZ 6296T

Version: LAI HUAT/10

Printed: 29/03/2019 17:58

Date Calculated: 29/03/2019 09:57

Total Visual Alignment work	\$100.80	
Total Labour		\$2,742.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,116.00	
Total of Additional Costs		\$1,116.00
Total Paint/Material Costs		\$245.26
Grand Total Excludes GST		\$12,200.86
GST @ 7 %		\$854.06
Grand Total Includes GST		\$13,054.92

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018 Sendback Est	25 Sep 2018 14:02 S\$12,965.08	25 Sep 2018 14:55 Edit Adj Rpt	S\$12,170.86 Edit Estimates	S\$12,170.86 View Rpt		Pending for Survey Report Cancel Case
Supp #1	12 Oct 2018 10:22	12 Oct 2018 10:31 S\$1,221.00	12 Oct 2018 10:31			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	18 Oct 2018 11:56	18 Oct 2018 11:56 S\$88.00	18 Oct 2018 11:56			(Combined)	Combined with Main Uncombine Suppl.
Supp #3	11 Apr 2019 17:38	11 Apr 2019 17:39 S\$182.00	11 Apr 2019 17:39			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	NG SIK SUAN , ID: S1484542I								
Vehicle Reg. No.:	SJZ6296T	Date of Loss:	15/09/2018 06:00 - :59 [93 Months From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D04490C01	Policy/Cover Note No.:	DMPCSN3086821702 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, S75722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/10/2018]								
Driver/Custodian:	VALERIE NG ZHI-YAN (31 / Female) , NRIC: S8701665Z, Tel: +6594567242 Email: ngvalerie87@gmail.com								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (27/09/2018): Alert - Adj Mandate Approved (S\$12923.08) - SJZ6296T - Claim Handler: Irene Tay ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJZ6296T (SNM18D04490C01)
OD
Sep 15 2018 6:00AM
[NG SIK SUAN]
Lai Huat (Meng Kee) Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	25/09/18 14:02	Repairer Estimates	 Load HTM	<input type="checkbox"/>
2	12/10/18 10:31	Repairer Estimates Suppl. #1	 Load HTM	<input type="checkbox"/>
3	18/10/18 11:56	Repairer Estimates Suppl. #2	 Load HTM	<input type="checkbox"/>
4	11/04/19 17:39	Repairer Estimates Suppl. #3	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 13:00	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
2	17/10/18 15:48	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>

Photos/Images

3 per page ▼

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	25/09/18 14:20	Rear View Left	 Load JPG <input checked="" type="checkbox"/>	
2	25/09/18 14:20	Rear View Right	 Load JPG <input checked="" type="checkbox"/>	
3	25/09/18 14:20	Rear View	 Load JPG <input checked="" type="checkbox"/>	
4	25/09/18 14:20	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
2	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
3	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
4	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
5	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
6	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
7	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
8	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
9	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
10	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
11	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
12	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
13	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
14	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
15	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
16	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
17	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
18	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
19	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
20	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
21	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
22	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
23	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	
24	26/09/18 12:16	General View	 Load JPG <input checked="" type="checkbox"/>	

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No.	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
25	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/09/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/05/19 09:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
73	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	07/05/19 09:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	07/05/19 09:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
121	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
122	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
123	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
124	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
125	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
126	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
127	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
128	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
129	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
130	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
131	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
132	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
133	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
134	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
135	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
136	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
137	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
138	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
139	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
140	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
141	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
142	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
143	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
144	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
145	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
146	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
147	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
148	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
149	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
150	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
151	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
152	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
153	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
154	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
155	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
156	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
157	07/05/19 09:26	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	25/09/18 14:02	E-filed GIA report		<input type="checkbox"/>
2	25/09/18 14:02	Driver's NRIC + Driving License		<input type="checkbox"/>
3	25/09/18 14:02	Certificate of Insurance		<input type="checkbox"/>
4	25/09/18 14:02	Enquire PARF / COE Rebate for Registered Vehicle		<input type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/02/19 18:42	VICOM INSPECTION REPORT		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 12:15	AUDATEX		<input type="checkbox"/>
2	26/09/18 12:15	ESTIMATE		<input type="checkbox"/>
3	08/05/19 16:57	SUPPLEMENTARY		<input type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser ▼
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	17/09/18 15:38	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	17/09/18 15:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	17/09/18 15:22	Sketch Plan	 Load TIF	
2	17/09/18 15:37	Motor Accident Advice Form	 Load TIF	
3	17/09/18 15:37	Insurance Certificate	 Load TIF	
4	17/09/18 15:37	Driver NRIC	 Load TIF	
5	17/09/18 15:37	Driver Driving Licence	 Load TIF	
6	17/09/18 15:37	Owner Driving Licence	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18017081/T1QBS2
Date: 08/05/2019

REFERENCE

Insured/Claimant: NG SIK SUAN Policy No: DMPCSN3086821702
Date of Loss: 15/09/2018 Nature of Claim: OD Claim No: SNM18D04490C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ6296T**
Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A) Engine No: 27186030157361
Reg. Date: 15/12/2010 (Man. Year: 2010) Chassis No: WDD2120472A347221
Colour: Brown Odometer: 0 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$58,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R17 Rear Tyre Size: 245/45 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,223.00	8,097.00	2,126.00	20.80
Miscellaneous Items	650.00	586.00	64.00	9.85
Labour	3,583.08	3,487.86	95.22	2.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,456.08	12,170.86	2,285.22	15.81
+ GST 7.00/7.00% (S\$)	1,011.93	851.96	159.97	15.81
Nett Amount (S\$)	15,468.01	13,022.82	2,445.19	15.81

INSPECTION

Date of Assignment: 25/09/2018 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Lai Huat (Meng Kee) Motor Pte Ltd
Date Inspected: 20/09/2018 Inspected At: 160 SIN MING DRIVE #04-01/02
SIN MING AUTOCITY
SINGAPORE 575722
Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
Parts: 143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ6296T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE "CGI"	Necessary	39.00 F	*39.00 F
2	1	NA	*L/F LWR CONTROL ARM	Bent	254.00 F	*254.00 F
3	1	NA	*L/F SHOCK ABSORBER	Bent	415.00 F	*415.00 F
4	1	NA	*L/F STEERING KNUCKLE	Bent	635.00 F	*635.00 F
5	1	NA	*L/F STRUT BEARING	Bent	105.00 F	*105.00 F
6	1	NA	*L/F TENSION ROD	Not Necessary	316.00 F	*- F
7	1	NA	*L/F WHEEL	Cut	470.00 F	*470.00 F
8	1	NA	*L/F WHEEL HUB	Bent	360.00 F	*360.00 F
9	1	NA	*L/INNER BOOT TRIM	Deformed	160.00 F	*160.00 F
10	1	NA	*L/LOWER INSULATION	Deformed	10.00 F	*10.00 F
11	1	NA	*L/OUTER TIE ROD BALL	Bent	150.00 F	*150.00 F
12	1	NA	*L/R AXLE STEERING	Bent	95.00 F	*95.00 F
13	1	NA	*L/R BUMPER GUIDE	Necessary	20.00 F	*20.00 F
14	1	NA	*L/R BUMPER SUPPORT	Necessary	35.00 F	*35.00 F
15	1	NA	*L/R CAMBER STRUT	Bent	120.00 F	*120.00 F
16	1	NA	*L/R CONTROL ARM	Not Necessary	870.00 F	*- F
17	1	NA	*L/R INNER LAMP	Cut	230.00 F	*230.00 F
18	1	NA	*L/R MOULDING	Necessary	72.00 F	*72.00 F
19	1	NA	*L/R OUTER LAMP	Cracked	355.00 F	*355.00 F
20	1	NA	*L/R PROTECT SHIELD	Deformed	43.00 F	*43.00 F
21	1	NA	*L/R SHOCK ABSORBER	Bent	285.00 F	*285.00 F
22	1	NA	*L/R THRUST ARM	Not Necessary	55.00 F	*- F
23	1	NA	*L/R TIE ROD	Bent	110.00 F	*105.00 F
24	1	NA	*L/R TOWING STRUT	Not Necessary	95.00 F	*- F
25	1	NA	*L/R UPP C-ARM COVER	Deformed	15.00 F	*15.00 F
26	1	NA	*L/R VENT INSERT	Deformed	15.00 F	*15.00 F
27	1	NA	*L/R WHEEL	Cut	470.00 F	*470.00 F
28	1	NA	*L/R WHEEL HUB	Not Necessary	110.00 F	*- F
29	1	NA	*L/R WHL-HOUSE COVER	Deformed	85.00 F	*85.00 F
30	1	NA	*L/R WING	Buckled	1,140.00 F	*1,140.00 F
31	1	NA	*L/SILL PANELLING	Cut	355.00 F	*355.00 F
32	1	NA	*L/TIE ROD	Bent	93.00 F	*93.00 F
33	1	NA	*L/UPPER INSULATION	Deformed	55.00 F	*55.00 F
34	1	NA	*LOWER REAR PANELLING	Not Necessary	635.00 F	*- F
35	1	NA	*R/R MOULDING	Necessary	72.00 F	*72.00 F
36	1	NA	*REAR BADGE	Necessary	38.00 F	*38.00 F
37	1	NA	*REAR BUMPER COVER	Distorted	820.00 F	*820.00 F
38	1	NA	*REAR BUMPER MOULDING	Cut	90.00 F	*90.00 F
39	1	NA	*REAR SCREEN BOND KIT	Not Necessary	40.00 F	*- F
40	1	NA	*SPARE WHEEL WELL	Cracked	145.00 F	*145.00 F
41	1	NA	*STAR EMBLEM	Necessary	25.00 F	*25.00 F
42	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
Supplementary #1							
43	1		*FRONT WHEEL SPEED SENSOR LH	Distorted	185.00 F	*185.00 F	
44	1		*L/F BALL JOINT	Bent	73.00 F	*73.00 F	
45	1		*FRONT ABSORBER BEARING LH	Bent	32.00 F	*32.00 F	
46	1		*FRONT ABSORBER STOPPER LH	Bent	35.00 F	*35.00 F	
47	1		*FRONT ABSORBER STOPPER BOOT LH	Distorted	26.00 F	*26.00 F	
Supplementary #2							
48	1		*L/F W-HOUSE CVR REAR	Deformed	88.00 F	*88.00 F	
Supplementary #3							
49	1		*RIGHT OUTER TIE ROD BALL	Distorted	88.00 F	*88.00 F	
50	1		*RIGHT TIE ROD	Distorted	94.00 F	*94.00 F	
					Total Parts (\$\$)	10,223.00	8,097.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	L/R TYRE (PUNCTURED) (80%)	210.00	168.00
2	1	REAR W/S SEAL	40.00	40.00
3	1	WATER LEAK TEST	30.00	30.00
Supplementary #1				
4	1	L/F TYRE (CUT) (90%)	220.00	198.00
5	1	REAR WINDSCREEN MOULDING (NECESSARY)	150.00	150.00
Sub Total (S\$)			650.00	586.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	651.00	604.80
2	Total Paint Materials	New	256.48	245.26
3	Total Panel/Mechanical Labour	New	2,175.60	2,037.00
4	TOTAL VISUAL ALIGNMENT WORK.	New	-	100.80
Supplementary #1				
Labour Items				
5	REPAIR STEERING LOCK	New	250.00	250.00
6	REPROGRAMME STEERING LOCK	New	250.00	250.00
Gross Labour Cost (S\$)			3,583.08	3,487.86

Report was unsubmitted during this print-out.

< END OF ESTIMATES >