

Part 4 - Spare Parts / Material Usage

Reservation No : _

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x) Repair (R) Replace (/)
52119-47930	BUMPER FRT	1	482	25%	361.5	/	R
52127-47903	COVER, FR BUMPER HOLE RH	1	18.5	25%	13.88	/	R
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1	311.1	25%	233.33	/	* ✓ CWA
53111-47040	GRILLE RADIATOR	1	310.6	25%	232.95	/	X NN
75310-47010	EMBLEM FRONT	1	86.5	25%	64.88	/	new /
	NUMBER PLATE	1	15	0%	15	/	CWA ✓
	NUMBER PLATE FRAME	1	12	0%	12	/	CWA /
52114-47140	BRACKET, FR BUMPER	1	110.4	25%	82.8	/	X ✓ new
52021-47023	BUMPER REINFORCEMENT FRT	1	498.4	25%	373.8	/	? ✓ BT
52611-47080	BUMPER ENERGY ABSORBER FRT	1	78.8	25%	59.1	/	? ✓ CWA
57014-47030	ARM SUB-ASSY, FR BUMPER LH	1	250.4	25%	187.8	/	? ✓ BT
57013-47030	ARM SUB-ASSY, FR BUMPER RH	1	250.4	25%	187.8	/	? X PVC
TOTAL MATERIALS					LUMPSUM REPAIR 20%	\$	1,459.87

3729.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: