

27/03/2002

ASS. REC. BY:

REF:

CS/FCI18017/21/Atd3ⁿ⁷

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

CWS

From (Person):

Eileen Lee

of

FCI

Date/Time:

20/9/18 @ 12.21pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 9250A

Insured:

SHC 3198H

at Workshop m/s

Modern Automotive

Tel:

6748 4422

of

Blk 3023A, Ubi Rd 1 #01-58/61

Policy No:

Claim No:

D18006909MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

12:39pm @ 20/9/18

Person Contacted:

Grace

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 9250A-X
	SHC 3198H-CC3/ CFI 16014985/H/wb3q2 DOA: 9/8/16
21/9/18 @ 1:39pm	Informed Eileen Lee, we are pending estimate from repairer.
	lump sum 1250 (red: 1765.31; 39%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKT9250A Yr Regn: 2015 / Jue

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai C.C. 1997

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 68201 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SJNFBAJ11U1268508

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/45R19

R: 225/45R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 20/09/18

Survey held at Modern

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap

RECEIVED 07 NOV 2018

Date/Time, File Pass to?

1) 5/11 Typast

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) TP 2750/-

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others:

TOTAL

140

50

50

35

275



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017121/Atd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 20-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3198H	Veh. Inspected	SKT 9250A
Policy No.		Coverage (\$)	0.00
Claim No.	D18006909MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	20/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/09/2018	Inspection Date	20/09/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	18-09-2018	Our Ref No. D18006909MFSH
Accident Date	15-09-2018	Claim Type. Third Party
Insured Vehicle	SHC3198H	Third Party Vehicle. SKT9250A
Survey Location	BLK 3023A UBI ROAD 1 #01-58/61	
Contact Person.	GRACE CHIN	
Contact No.	67484422/ 0	Fax No. 67476720
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MODERN AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MS First Capital Insurance Ltd
 36 Robinson Road
 #16-01 City House
 Singapore 068877
 Tel : 6507 - 3848
 Fax : 6507 - 3849

Denise

QUOTATION
 DATE : 20.09.2018
 VEH NO : SKT9250A
 MODEL : Nissan Qashqai
 D O A : 15.09.2018
 YR REF : SHC3198H

Attn : Motor Claim Dept (Pls arrange survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKT9250A (NISSAN QASHQAI)

Item	Description	Qty	Amt
<u>LIST ITEMS</u>			
1	Rear Bumper <i>behind</i>	1	755.50 ✓
2	Rear Bumper Clips <i>new</i>	1	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	72.40 ✓
4	Rear Bumper Tow Cover <i>behind</i>	1	16.80 ✓
5	Rear Bumper Reflector - LH & RH <i>new</i>	2	110.00 x
6	Rear Bumper Reinforcement <i>derided</i>	1	674.00 ✓
7	Rear Bumper Sponge <i>cracked</i>	2216	126.40 ✓
8	Rear End Panel <i>derided</i>	1994.40	540.90 ✓
9	Rear End Panel Top Garnish <i>new</i>	1	142.00 +
10	Rear Exhaust Pipe <i>3 new</i>	1	762.40 x
11	Rear Exhaust Mounting	1	20.80 x
12	Rear Exhaust Heat Shield <i>new</i>	1	142.10 x

10	\$	3,393.30
Less 30%	\$	(1,017.99)
	\$	2,375.31

S/NET ITEMS

1	Reverse Sensor <i>damaged</i>	1	230.00 <i>200</i>
2	Rear End Panel Sealant <i>new</i>	260	60.00 ✓
			\$ 340.00

Total Parts **\$ 2,715.31**

LABOUR CHARGE

1	To knocking & pull out rear portion & renew damage parts	\$	900.00 <i>600</i>
2	To putty & spray up paint works	\$	600.00 <i>600</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SKT9250A (NISSAN QASHQAI)

3	To check wiring	\$	50.00 30
4	To remove reverse sensor	\$	100.00 60
5	To remove exhaust pipe	\$	150.00 X
		\$	<u>1,800.00</u>
GRAND TOTAL		\$	<u>4,515.31</u>

GST Will be reflected in the final bills

5193.97

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 3444.40

L/S: 2750

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18017121/Atd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3198H	Veh. Inspected	SKT 9250A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006909MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	20/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFBAJ11U1268508	Colour	WHITE	
Odometer	68201	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	YOKOHAMA	6 mm	
L/H Front Tyre	225/45 R19	YOKOHAMA	6 mm	
R/H Rear Tyre	225/45 R19	YOKOHAMA	6 mm	
L/H Rear Tyre	225/45 R19	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/09/2018	Inspection Date	20/09/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 9250A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	755.50	755.50
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER-LH & RH	NECESSARY	72.40	72.40
1	REAR BUMPER TOW COVER	DEFORMED	16.80	16.80
2	REAR BUMPER REFLECTOR-LH & RH	NOT NECESSARY	110.00	-
1	REAR BUMPER REINFORCEMENT	DENTED	674.00	674.00
1	REAR BUMPER SPONGE	CRACKED	126.40	126.40
1	REAR END PANEL	DENTED	540.90	540.90
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	142.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	762.40	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	20.80	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	142.10	-
	LESS 10% DISCOUNT		-339.33	-221.60
			3,053.97	1,994.40
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
			340.00	260.00
LABOUR				
	TO KNOCKING & PULL OUT REAR PORTION & RENEW DAMAGE PARTS.		900.00	600.00
	TO PUTTY & SPRAY UP PAINT WORKS.		600.00	500.00
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	60.00
	TO REMOVE EXHAUST PIPE.	NOT NECESSARY	150.00	-
			1,800.00	1,190.00
GRAND TOTAL			5,193.97	3,444.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00



Report Ref No. CS/FCI18017121/Atd3n2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.