

22/03/2002

ASS. REC. BY:

REF:

CS3/ASM18017152/Gcheb

Special Instruction:

Surveyor

Smart claim

From (Person):

Gao Qiang

Vale Oh

of

ASM

Date/Time:

20/09/2018 2:48 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 8596D

Insured:

SLR 8293G

at Workshop m/s

Asia motorsport

Tel:

6745 3811

of

568 Geylang Rd

Policy No:

Claim No:

88MOOW7P

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/09/2018

CA / REV / REP. / REV 24 HRS 'Wp'

21.09.2018

H.O.D. Endorsement:

Date/Time:

20/09/2018 4:26 pm

Person Contacted:

Mr. Loo

Vehicle (IN) OUT

Date/Time

Action/Instruction ( X ) Estimate

FBH 8596D - X

SLR 8293G - X

Dismantle: 27/9/2018

After repair: 9/10/2018

Surgeon

PRS  
Karl

REF: ASM (AXA)

# ASSIGNMENT

From: Date: 21/09/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBH 8596D

at Workshop m/s Asia Motorsport

of 568 Gaylang Rd

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBH 8596D Yr Regn: - /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: C.C. -

Colour: yellow A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/80-14

R: 150/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SHINKO

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. D.O.I. 21-09-18

Survey held at W/S 11:30AM

Des. of Damages: Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000

RECEIVED 11 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ )

☐ : Interview (\$ )

☐ : Tech. Invs (\$ )

☐ : Weekend (\$ )

Report Format : PRS

Lump Sum / I.B.I: (\$ )

100

100




## Service Request Details

Claim

S8M00W7P

Reference

None 

Loss Date

September 18, 2018

Request Date

September 20, 2018

Due Date

September 27, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

---

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

---

Incident Vehicle Registration #

FBH8596D

Make

TPVD BIKE

Model

UNKNOWN

Service Address

---

, , ,

Primary Contact/Insured

---

DWARAKNATH ASOORI VANAMALI  
9 TANJONG RHU ROAD, #06-03, 436894, Singapore

gdwarak@gmail.com

Claim Handler

---

OH Vale  
6568804897  
vale.oh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CS3/ASM18017152/Gcb		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 20-09-2018		
		Code : ASM		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SLR 8293G	Veh. Inspected	FBH 8596D	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00W7P	Excess (\$)	0.00	
Assign From	SMART CLAIM (VALE OH)	Assign Date	20/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	18/09/2018	Inspection Date	21/09/2018	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18017152/Gcbe2		
8 SHENTON WAY #24-01 AXA TOWER		Date: 29-10-2018		
SINGAPORE 068811		Code: ASM		
ATTN : VALE OH				
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SLR 8293G	Veh. Inspected	FBH 8596D	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00W7P	Excess (\$)	0.00	
Assign From	VALE OH	Assign Date	20/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	YELLOW	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/80-14	SHINKO	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150/70-13	SHINKO	4 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
<b>5. General Information</b>				
Accident Date	18/09/2018	Inspect Date / Time	21/09/2018 ( 11:30 AM )	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/ASM18017152/Gcbe2

**Inspected By**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.