



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2006803
INV Date 02/10/2020
Reference CC4/LPC18017154/T1ea3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. XE 471M
Insured Veh. SGV 7399E
Claim No. 18/18/18/VP05/020901
Policy No. Z18VP05018878
Accident Date 10/09/2018
Inspection Date 26/09/2018

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD	Ref : CC4/LPC18017154/T1ea3q2
300 BEACH ROAD	Date : 02-10-2020
#17-04/07 THE CONCOURSESINGAPORE 199555	Code : LPC2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 7399E	Veh. Inspected	XE 471M
Policy No.	Z18VP05018878	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020901	Excess (\$)	0.00
Assign From		Assign Date	19/09/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FUSO	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	FP51SDA10145	Colour	ORANGE
Odometer	267252	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	AMBERSTONE	8 mm
L/H Front Tyre	295/80 R22.5	AMBERSTONE	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	AMBERSTONE	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	AMBERSTONE	8/8 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	10/09/2018	Inspection Date	26/09/2018
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days
--	---



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 471M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	CROSSMEMBER NO 3	BENT	1,042.90	1,042.90
1	TANK,AIR	NOT NECESSARY	1,193.04	-
1	BRKT,LICENSE PLATE LAMP	CRACKED	71.62	71.62
1	BRKT,LICENSE PLATE LAMP	CRACKED	71.62	71.62
2	LAMP,LICENSE PLATE @\$66.98	BENT	133.96	133.96
2	SPRING,REAR @\$6437.99	NOT NECESSARY	12,875.98	-
2	SHACKLE LINK ASSY @\$371.16	NOT NECESSARY	742.32	-
4	PIN,SHACKLE @\$62.49	NOT NECESSARY	249.96	-
4	NIPPLE,GREASE (10) @\$4.82	NOT NECESSARY	19.28	-
2	HOSE,AIR @\$198.56	NOT NECESSARY	397.12	-
2	HOSE,RR AXLE BRAKE TUBE @\$255.48	NOT NECESSARY	510.96	-
2	BRACKET,AIR TANK,NO 2 @\$95.40	NOT NECESSARY	190.80	-
	LESS 10% DISCOUNT		-1,749.96	-132.01
			15,749.60	1,188.09
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	BENT	20.00	20.00
2	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	240.00	-
1	SUNDRIES (SN)	NECESSARY	80.00	50.00
			340.00	70.00
<u>LABOUR</u>				
	TO REMOVE AND REFIX DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC.		1,800.00	1,200.00
	TO REMOVE AND REFIX BRAKE AIR TANK,TO CHECK FUNCTION.	NOT NECESSARY	600.00	-
	TO REMOVE AND REFIX BOTH SUSPENSION & LEAF SPRING ASSY.	NOT NECESSARY	2,400.00	-
	TO CHECK AND RECTIFY WIRING FAULTS,TO CONDUCT DIAGNOSTIC CHECK.		180.00	150.00
	TO PUTTY,CLEAN & SPRAY PAINT.		400.00	200.00
			5,380.00	1,550.00



GRAND TOTAL		21,469.60	2,808.09
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00

Report Ref No. CC4/LPC18017154/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 471M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 471M

RE-INSPECTION

