



ESTIMATE

Date : 12/09/2018
To : LONPAC INSURANCE BHD.
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : LILEWEI
Office / Mobile : +65 6864 0637
Email / Fax No. : LiLewei@goldbell.com.sg

Reg No : XE471M
Model : FP51SDR3VDEA C/C
Chassis No : FP51SDA10145
Engine No : OM457295278
Quotation No. : 70826
Ref. No. : GBE/SVC/SALES-4688/180912
D.O.A. : 10/09/2018
Policy No. : D-17088925MFVS/6
Claim Type : TP CLAIM - LONPAC
Workshop : 29 TANJONG PENJURU

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MK656490	CROSSMEMBER NO.3 <i>bt</i>	1	1,042.90	-10	938.61	938.61
2	MK372162	TANK,AIR ?	1	1,193.04	-10	1,073.74	1,073.74
3	MC085637	BRKT,LICENSE PLATE LAMP <i>ca</i>	1	71.62	-10	64.46	64.46
4	MC085638	BRKT,LICENSE PLATE LAMP <i>ca</i>	1	71.62	-10	64.46	64.46
5	MX915944	LAMP,LICENSE PLATE <i>bt</i>	2	66.98	-10	60.28	120.56
6	MK631324	SPRING,REAR <i>x</i>	2	6,437.99	-10	5,794.19	11,588.38
7	MC013467	SHACKLE LINK ASSY <i>x</i>	2	371.16	-10	334.04	668.09
8	MK300383	PIN,SHACKLE <i>x</i>	4	62.49	-10	56.24	224.96
9	MF524022	NIPPLE,GREASE (10) <i>x</i>	4	4.82	-10	4.34	17.35
10	MH031237	HOSE,AIR ?	2	198.56	-10	178.70	357.41
11	MH030789	HOSE,RR AXLE BRAKE TUBE ?	2	255.48	-10	229.93	459.86
12	MK326200	BRACKET,AIR TANK,NO.2 ?	2	95.40	-10	85.86	171.72

PARTS TOTAL : 15,749.60

SPECIAL NETT ITEMS

1	REAR NUMBER PLATE	1	20.00
2	REAR NUMBER PLATE HOLDER	2	240.00

PARTS TOTAL: 260.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	600 1200	1800.00
2	TO REMOVE AND REFIX BRAKE AIR TANK, TO CHECK FUNCTION.	?	600.00
3	TO REMOVE AND REFIX BOTH SUSPENSION & LEAF SPRING ASSY	X	2400.00
4	TO CHECK AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK	150	180.00
5	TO PUTTY, CLEAN & SPRAY PAINT	200	400.00
6	SUNDRIES	50	80.00

LABOUR TOTAL : 4,860.00

SUB-TOTAL : 20,869.60



Certificate No: AJA18101243

Certificate No: AJA011804



ESTIMATE

Date :	12/09/2018	Reg No :	XE471M
To :	LONPAC INSURANCE BHD.	Model :	FP51SDR3VDEA C/C
Attn. :		Chassis No :	FP51SDA10145
Office / Mobile :		Engine No :	OM457295278
Email Address :		Quotation No. :	70826
		Ref. No. :	GBE/SVC/SALES-4688/180912
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	10/09/2018
Attn. :	LILEWEI	Policy No. :	D-17088925MFVS/6
Office / Mobile :	+65 6864 0637	Claim Type :	TP CLAIM - LONPAC
Email / Fax No. :	LiLewei@goldbell.com.sg	Workshop :	29 TANJONG PENJURU

GST @ 7% for \$ 20,869.60 1,460.87
GRAND TOTAL (\$\$) : 22,330.47

PREPARED BY : LILEWEI

DATE / TIME : 26/9/18 @ 1400
SURVEYOR : Tanpin
MOBILE NO : 97495746
OFFICE FAX NO : _____
EMAIL ADDRESS : sur@lkkauto.com

EXCESS AMOUNT : _____
REPAIR TYPE : PART-BY-PART / LUMPSUM
AUTHORISATION : AUTHORISED / NOT AUTHORISED WP
RE-SURVEY : BEFORE PAINT / AFTER PAINT
NO. OF DAYS : 3 days
REMARKS : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____