

Repair Estimates

## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

			1014/
arts (a) Cost / List Price Items	\$	4,694.90	Bern
Plus/Less 20%	\$	887.44	Menny Ble pain
Total of Cost / List	\$	3,807.46	
(b) Nett Price Items			
Less			LKK Auto Consultants hence notify the Repairer of the following:
Total of Nett Item		<u> </u>	To display damaged
(c) Special Nett Items			Third party suproving
otal Parts Cost	\$	3,807.46	No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  No illegal modification(s) is allowed  Supplementary item(s) must be resurveyed and
abour	\$	2,810.00	Acknowledged by Repairer Signature:
	\$	6,617.46	Date:
otal The above total will be subjected	to 7% G.S.T.		
	to 7% G.S.T.		Kennesh
he above total will be subjected	to 7% G.S.T.		Kennesh
The above total will be subjected  Name of Surveyor	to 7% G.S.T.		Kennesh IKIC IRII8 at
Name of Surveyor Company	to 7% G.S.T.		
Name of Surveyor Company Survey conducted on		24 is not authorized until further	er notice.
Name of Surveyor Company Survey conducted on Remarks By Surveyor	e is authorized /	24	er notice.
Name of Surveyor Company Survey conducted on  Remarks By Surveyor  (a) The repair of this vehicle	e is authorized /	24 is not authorized until further	er notice.
Name of Surveyor Company Survey conducted on  Remarks By Surveyor  (a) The repair of this vehicle (b) Recommended Days of	e is authorized /	is not authorized until further 4-5	er notice.

SMC 916 M



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

**Spare Parts** 

Vehicle No. Make & Model:

Chassis No

**SMC 916 M** 

HONDA SHUTTLE GP71211706

Submit By

Carmen Lim 2018

Year Manufacture : Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	New	1	\$55.00		
2	Rear windscreen sealant	Na	1	\$50.00	S.N	GOSN
3	Reverse sensor	nu	1	\$200.00	S.N	
4	Reverse Camera	Sz	1	\$580.00	S.N	X
5	Rear bumper	B	1	\$1,150.60		_
6	Rear bumper clip	M	10	\$40.00		
7	Rear bumper side retainer LH	Sn	1	\$26.50		×
8	Rear bumper side retainer RH	Sn	1	\$26.50		X
9	Rear bumper sponge	Sm	1	\$89.50		×
10	Rear bumper reflector LH	In	1	\$58.00		X
11	Rear bumper reflector cover LH		1	\$58.00		X
12	Tail door	R	1	\$1,193.00		
13	Tail door lock	N	1	\$157.70		X
14	Tail door emblem	Ma	1	\$38.00		
15	Wording "HYBRID"	M	1	\$66.20		
16	Wording "SHUTTLE"	14	1	\$55.00		
17	Tail door chrome	Su	1	\$383.10		×
18	Taildoor inner trim	JL	1	\$385.00		*
19	Taildoor inner trim clip	nn	8	\$28.00		X
20	Tail end panel		1	\$560.80		7
21	Tail end panel garnish	Sh	1	\$155.50		×
22	Boot weatherstrip	In	1	\$168.50		Χ
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N



## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Labour

Vehicle No.	:	SMC 916 M	Submit By :	Carmen Lim	
Make & Model	: -	HONDA SHUTTLE	Year of Manufacture:	2018	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL,		
	SPARE TYRE WELL PANEL)	\$1,200.00	5001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL,		
	SPARE TYRE WELL PANEL)	\$1,000.00	4001
3	To check wiring	\$50.00	201
4	To tuff coat	\$50.00	301
5	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	?
6	To remove & refit rear windscreen.	\$120.00	
7	To transfer boot mechanism to new boot	\$120.00	601
8	To remove & refit reverse sensor	\$120.00	501

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.