



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

21/09/2018

20h Kim.
TP ALG.

Accident date: 20/09/2018

Estimated repair cost for vehicle no: SJH6571T MITSUBISHI LANCER EX 1.5 A '08

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front L/H Head Lamp <i>crushed</i>		\$792.00 ✓
2	1	Front Bumper <i>Deformed</i>		\$858.00 ✓
3	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
4	1	Front Bumper Top Rubber		\$68.00 +
5	1	Front Bumper Top Beam		\$94.00 +
6	1	Front Bumper Reinforcement		\$390.00 +
7	1	Front L/H Bumper Side Retainer <i>new</i>		\$40.00 ✓
8	1	Front L/H Bumper Fog Lamp		\$386.00 +
9	1	Front L/H Bumper Fog Lamp Cover		\$46.00 +
10	1	Front L/H Fender <i>Buckled</i>		\$486.00 ✓
11	1	Front L/H Fender Cowling		\$107.00 +
12	10	Front L/H Fender Cowling Clip	\$6.50	\$65.00 +
13	1	Front L/H Rim <i>bt</i>		\$650.00 400/sv
14	1	Front L/H Tyre <i>new</i>		\$350.00 +
15	1	Front L/H Lower Arm		\$292.00 +
16	1	Front L/H Knuckle Arm		\$358.00 +
17	1	Front L/H Knuckle Arm Bearing		\$259.00 +
18	1	Front L/H Shock Absorber		\$387.00 +
19	1	Front L/H Drive Shaft		\$1,386.00 +
20	1	Front Steering Rack		\$1,833.00 +

Subtotal :- **\$8,912.00**

2206
198540
S.N: 400

Labour charges

To remove & refit front L/H undercarriage	\$380.00	X
To remove & refit L/H drive shaft & steering rack	\$450.00	X
To check wheel alignment	\$150.00	80
To check wiring	\$100.00	30
Towing fee	\$100.00	X
Tuff kote	\$150.00	X
Panel beating	\$1,400.00	400
Spray painting	\$1,400.00	400
	Subtotal :-	\$4,130.00
	Total:-	\$13,042.00

total : 329540
H/s: 2.6K - ✓
O/A Imp. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: