

15/02/18

INS. CASE OWNER:

CC 1801

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
27/1/18	SHC 70498 - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm with:	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(\$ 50 x 6 days)	
Loss of Use (LOU):	SS	(\$ x days)	
Loss of Income (LOI):	SS	(\$ x days)	
LOR only	☐	LOU only	☐
LOR + LOU	☐	LOR + LO	☐
[Tick only one]			
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/Independent)	
Legal Cost	SS		
Total:	SS	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18017242/R1wb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 21-09-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGS 1927L	Veh. Inspected	SHC 7299Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/09/2018	Inspection Date	24/09/2018	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0514

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

21/09/2018 12:46

JOB-NO: 50110968

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHG7299Z

TRANS: AUTO

CHASSIS: KMHLB41UMGU093590

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU671690

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

LABOUR

1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	440 650
2 R&R RADIATOR & CONDENSER & TURBO	1.00	180.00	0.00	180.00		Y	80.80
3 CHECK WIRING & HEAD LAMP AIM	1.00	180.00	0.00	180.00		Y	30
4 ALIGNMENT BONNET & FENDER & SUPPORT PANEL	1.00	180.00	0.00	180.00		Y	X 12
5 RUST PROOFING	1.00	120.00	0.00	120.00		Y	40
6 SUNDRIES	1.00	120.00	0.00	120.00		Y	X 12
7 RESPRAY FRONT BONNET & FENDER RHS & BUMPER	1.00	750.00	0.00	750.00		Y	530
8 TOP UP AIR-COND GAS 134A	1.00	120.00	0.00	120.00		Y	80
TOTAL:		2,650.00	0.00	2,650.00			

MATERIALS

1 FRONT BUMPER	1.00	599.68	119.94	479.74	L	Y	PRIDE
2 FRONT BUMPER RETAINER RHS	1.00	42.32	8.46	33.86	L	Y	can
3 FRONT BUMPER RETAINER LHS	1.00	42.32	8.46	33.86	L	Y	X SUC
4 FRONT SUPPORT PANEL	1.00	962.87	192.57	770.30	L	Y	X CR
5 FRONT HEAD LAMP PANEL RHS	1.00	198.67	39.73	158.94	L	Y	X SUC
6 FOG LAMP COVER RHS	1.00	178.55	35.71	142.84	L	Y	X SUC
7 FRONT FENDER RHS	1.00	659.50	131.90	527.60	L	Y	HA
8 FRONT FENDER INNER SHIELD RHS	1.00	185.12	37.02	148.10	L	Y	X SUC
9 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	CR
10 BONNET	1.00	1,812.68	362.54	1,450.14	L	Y	repair
11 BONNET HINGE RHS	1.00	41.85	8.37	33.48	L	Y	X SUC
12 RADIATOR COOLANT	1.00	89.55	17.91	71.64	L	Y	X SUC
TOTAL:		6,821.21	1,324.23	5,296.98			

TOTAL PARTS & LABOUR : 9,271.21 1,324.23 7,946.98

EXCESS/LOADING: \$0.00

No. Of Day:

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

SURVEYED BY:

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour = \$1430

S/N: \$0

Parts = \$4162.02 - 20% AAG

= \$3329.61

L+STP = \$4759.61

Final Amount = \$4759.61

Part by part 6 days

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

21/09/2018 12:46

JOB-NO: 50110968

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7299Z

TRANS: AUTO

CHASSIS: KMHLB41UMGU093590

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU671690

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	1000 650
2 R&R RADIATOR & CONDENSER & TURBO	1.00	180.00	0.00	180.00		Y	180 80?
3 CHECK WIRING & HEAD LAMP AIM	1.00	180.00	0.00	180.00		Y	30
4 ALIGNMENT BONNET & FENDER & SUPPORT PANEL	1.00	180.00	0.00	180.00		Y	X
5 RUST PROOFING	1.00	120.00	0.00	120.00		Y	40
6 SUNDRIES	1.00	120.00	0.00	120.00		Y	X
7 RESPRAY FRONT BONNET & FENDER RHS & BUMPER	1.00	750.00	0.00	750.00		Y	550
8 TOP UP AIR-COND GAS 134A	1.00	120.00	0.00	120.00		Y	80?
TOTAL:		2,650.00	0.00	2,650.00			

MATERIALS

1 FRONT BUMPER	1.00	599.68	119.94	479.74	L	Y	PRTE
2 FRONT BUMPER RETAINER RHS	1.00	42.32	8.46	33.86	L	Y	on new
3 FRONT BUMPER RETAINER LHS	1.00	42.32	8.46	33.86	L	Y	X
4 FRONT SUPPORT PANEL	1.00	962.87	192.57	770.30	L	Y	? CR
5 FRONT HEAD LAMP PANEL RHS	1.00	198.67	39.73	158.94	L	Y	X
6 FOG LAMP COVER RHS	1.00	178.55	35.71	142.84	L	Y	X
7 FRONT FENDER RHS	1.00	659.50	131.90	527.60	L	Y	fit
8 FRONT FENDER INNER SHIELD RHS	1.00	185.12	37.02	148.10	L	Y	X
9 HEAD LAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	CR
10 BONNET	1.00	1,812.68	362.54	1,450.14	L	Y	repair
11 BONNET HINGE RHS	1.00	41.85	8.37	33.48	L	Y	X
12 RADIATOR COOLANT	1.00	89.55	17.91	71.64	L	Y	1.5L
TOTAL:		6,621.21	324.23	5,296.98			

TOTAL PARTS & LABOUR : 9,271.21 1,324.23 7,946.98

EXCESS/LOADING: \$ 0.00

No. Of Day: 6 days

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 21 / 09 / 18

SURVEYED BY: RASUL

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO: 90060068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Service Request Details

Claim

S8M00WBL

Reference

None 

Loss Date

September 20, 2018

Request Date

September 21, 2018

Due Date

September 28, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

21092018 @ 9:50am

Alex veh in

31 Corporation Rd

Rasul

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHC7299Z

Make

TPVD HYUNDAI

Model

I40-1:7 D CRDI (A)

Service Address

...

Primary Contact/Insured

MARGARET SHONE PENELOPE

66 GARLICK AVENUE, 279674, Singapore

MOTOR.OPERATIONS@GNM.COM.SG

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:Seeking Mandate Approval S8M00WBL

Type

🔔 Question

Message

repair cost \$ 4,579.60 (w/gst) Loss of rental \$ 644.88 (6 days x \$ 107.48) Loss of income \$ 300.00 (6 days x \$ 50) LTA search fees \$ 2.00 Proposed Total \$ 5,526.48

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGS 1927L (Insd veh)	Model:	HYUNDAI I40 1.7
	SHC 7299Z (TP veh)		
Date of Accident:	20/09/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	8,503.27
Final Repair Cost	:	\$	5,092.78
Loss of Token Sum	:	\$	300.00
Rental (if any)	:	\$	644.88
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum (GLOBAL SUM)	:	\$ 5,500.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	DING AUTOMOTIVE PTE LTD	:	\$ 5,500.00

NUR SHAQILAH BTE ABDOL
WAHAB

03/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18017242/R1wb3s2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: KIAN CHUAN			Date : 03-01-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGS 1927L	Veh. Inspected	SHC 7299Z	
Policy No.	GA340185/1	Coverage (\$)	0.00	
Claim No.	S8M00WBL	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	21/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40 1.7	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093590	Colour	YELLOW	
Odometer	241406	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	TRIANGLE	6 mm	
L/H Front Tyre	205/60R16	TRIANGLE	6 mm	
R/H Rear Tyre	205/60R16	TRIANGLE	6 mm	
L/H Rear Tyre	205/60R16	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2018	Inspection Date	21/09/2018	
Survey held at	CORPORATION ROAD			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7299Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	599.68	599.68
1	FRONT BUMPER RETAINER RHS (CONSISTENT)	NECESSARY	42.32	42.32
1	FRONT BUMPER RETAINER LHS (CONSISTENT)	SERVICEABLE	42.32	-
1	FRONT SUPPORT PANEL (CONSISTENT)	CRACKED	962.87	962.87
1	FRONT HEAD LAMP PANEL RHS (CONSISTENT)	SERVICEABLE	198.67	-
1	FOG LAMP COVER RHS (CONSISTENT)	SERVICEABLE	178.55	-
1	FRONT FENDER RHS (CONSISTENT)	BENT	659.50	659.50
1	FRONT FENDER INNER SHIELD RHS (CONSISTENT)	SERVICEABLE	185.12	-
1	HEAD LAMP RHS (CONSISTENT)	CRACKED	1,808.10	1,808.10
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,812.68	-
1	BONNET HINGE RHS (CONSISTENT)	SERVICEABLE	41.85	-
1	RADIATOR COOLANT (CONSISTENT)	NECESSARY	89.55	89.55
	LESS 20% DISCOUNT		-1,324.23	-832.41
			5,296.98	3,329.61
SPECIAL NETT ITEMS				
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
			120.00	-
LABOUR				
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF BONNET.		1,000.00	650.00
	R&R RADIATOR & CONDENSER & TURBO.		180.00	80.00
	CHECK WIRING & HEAD LAMP AIM.		180.00	30.00
	ALIGNMENT BONNET & FENDER & SUPPORT PANEL.	NOT NECESSARY	180.00	-
	RUST PROOFING.		120.00	40.00
	RESPRAY FRONT BONNET & FENDER RHS & BUMPER.		750.00	550.00
	TOP UP AIR-COND GAS 134A.		120.00	80.00
			2,530.00	1,430.00
GRAND TOTAL			7,946.98	4,759.61
RECOMMENDED COST OF REPAIRS				4,759.61

Report Ref No. CC4/ASM18017242/R1wb3s2



Report Ref No. CC4/ASM18017242/R1wb3s2

A handwritten signature in black ink, appearing to read 'MRB'.

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to read 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.