

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 9657M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR V6 (SN) (CONSISTENT)	DEFORMED	1,252.60	1,127.34
1	PROTECTING PLATE REA (SN) (CONSISTENT)	CUT	820.30	738.27
1	SKID PLATE RIM LH S6 (SN) (CONSISTENT)	NOT NECESSARY	253.30	-
1	BUMPER BRACKET LHR V (SN) (CONSISTENT)	NOT NECESSARY	45.50	-
1	BUMPER BRACKET RHR V (SN) (CONSISTENT)	NECESSARY	45.50	40.95
1	BUMPER BRACKET REAR (SN) (CONSISTENT)	NECESSARY	77.10	69.39
1	BUMPER BRACKET REAR (SN) (CONSISTENT)	NECESSARY	88.70	79.83
1	BUMPER BRACKET CTR R (SN) (CONSISTENT)	NOT NECESSARY	88.70	-
1	TOW COVER REAR V60 1 (SN) (CONSISTENT)	DEFORMED	73.90	66.51
1	BUMPER RAIL (BEAM) R (SN) (CONSISTENT)	NOT NECESSARY	1,277.20	-
1	REAR BOOT V60 11- (SN) (CONSISTENT)	BENT	2,300.80	2,070.72
1	WINDSCREEN REAR V60 (SN) (CONSISTENT)	NECESSARY	1,288.90	1,160.01
2	*D* WINDSCREEN SEALA (SN) (CONSISTENT)	NECESSARY	244.20	219.78
1	*D* PRIMER GLASS & P (SN) (CONSISTENT)	NECESSARY	37.40	33.66
1	V001161436 / D GLASS (SN) (CONSISTENT)	NECESSARY	55.40	49.86
1	EMBLEM 'VOLVO' REAR (SN) (CONSISTENT)	NECESSARY	92.00	82.80
1	EMBLEM 'V60' (SN) (CONSISTENT)	NECESSARY	92.00	82.80
1	EMBLEM 'T5' XC60 S80 (SN) (CONSISTENT)	NECESSARY	88.00	79.20
1	MUDGUARD WIDENER (SN) (CONSISTENT)	NOT NECESSARY	143.80	-
1	TAILLAMP RH V60 (SN) (CONSISTENT)	CRACKED	400.30	360.27
10	BLIND RIVET 4.0*21 P (SN) (CONSISTENT)	NECESSARY	30.00	27.00
10	BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	54.00	48.60
1	BUMPER INSTALLING MT (SN) (CONSISTENT)	NECESSARY	83.40	75.06
4	ADHESIVE TUBE CHEMIC (SN) (CONSISTENT)	NECESSARY	303.20	272.88
1	FLOOR SUPPORT RH V 60 (SN) (CONSISTENT) (ADDITIONAL)	BENT	274.77	274.77
1	AIR VENT REAR XC60 0 (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	78.30	78.30
1	TAILGATE FRAME V60/C (SN) (CONSISTENT) (ADDITIONAL)	BENT	1,406.88	1,406.88
1	FENDER REAR RH V60 1 (SN) (CONSISTENT) (ADDITIONAL)	BENT	1,829.43	1,829.43

Report Ref No. CC4/ASM18017244/T1ps3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

	Tugo No.				
Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
1	GLASS (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	605.79	605.79	
1	SIDE PLATE (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	197.10	197.10	
1	MUDGUARD WIDENER RHR (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	277.29	277.29	
10	WIDENER CLIP WHITE F (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	37.80	37.80	
10	WIDENER CLIP RED S60 (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	50.40	50.40	
1	PARKING SENSOR 90' F (SN) (CONSISTENT) (ADDITIONAL)	NOT WORKING	174.60	174.60	
			14,168.56	11,617.29	
	LABOUR				
	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET, REAR SENSOR, REAR LOWER SPOILER, REAR BEAM, REAR END PANEL, ETC.		5,600.00	2,400.00	
	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, REAR END PANEL, REAR RH FENDER, ETC.		4,900.00	2,100.00	
	TO TRANSFER REAR BOOT LID PART.		500.00	500.00	
	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS.		2,400.00	800.00	
	TO REPLACE REAR WINDSCREEN.		800.00	800.00	
	TO INSTALL REAR WINDSCREEN FIL.		280.00	280.00	
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.	NOT NECESSARY	60.00	-	
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		450.00	450.00	
	TO REPLACE REAR RH FENDER, REAR END PANEL, REAR RH QUARTER GLASS. (ADDITIONAL)		6,400.00	6,400.00	
	TO REMOVE & INSTALL INTERIOR. (ADDITIONAL)		2,400.00	2,400.00	
	TO REMOVE & INSTALL PETROL TAN. (ADDITIONAL)		1,600.00	1,600.00	
	TO PUTTY SPRAY PAINT ON RH ROCKER PANEL, REAR END PANEL, ETC. (ADDITIONAL)		1,400.00	1,400.00	
	TO INSTALL RERA RH QUARTER GLASS FILM. (ADDITIONAL)		280.00	280.00	
			27,070.00	19,410.00	
	GRAND TOTAL		41,238.56	31,027.29	

Report Ref No. CC4/ASM18017244/T1ps3s2



Page No.:3 of 3

RECOMMENDED COST OF REPAIRS 31,027.29

Report Ref No. CC4/ASM18017244/T1ps3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.