

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Enquire Vehicle & Owner Information (Vehicle No. SJT7315Y As At 20 Jul 2018 / 07:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: DP.10569.18.BW

Current Owner Details

Owner ID Type: Foreign Identification Number
Owner ID: G2295685Q
Owner Name: CHEAH WOO YANG
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 80
Registered Street Name: ANSON ROAD
Registered Unit No.: -
Registered Building Name: -
Registered Postal Code: 079907

Current Vehicle Details

Vehicle No.: SJT7315Y
Make Description/Model: KIA / CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Enquire Transaction History

Transaction History Details

Log Date/Time: 23 Jul 2018 / 11:26:02

Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	SJT7315Y		
Transaction Type:	18.19 Enquire Veh Owner Info (Others) by Law Firm	Channel:	External Agency
User ID:	EDPOSABO - SITI AWIYAH BTE SENIAN	Business Transaction Reference No.:	20180723112602247753

As at Date of Search: 20 Jul 2018

As at Time: 07:45:00

Vehicle No.: SJT7315Y

Search Reason: Insurance claim in relation to traffic accident

Date of Filing: -

Suit No.: -

Law Firm Case No.: DP.10569.18.BW

Information displayed is correct as at the log date and time.

Enquire Related Logs

OK


GST REG NO. 201504834E

TO : IMD SHAFULAH B SELAMAT
AS PER REPORT
SINGAPORE

Our Reference:	FREED/SLQ7063R
Date:	15-Aug-2018
Vehicle Num:	SLQ 7063 R
Make/Model:	HONDA FREED HYBRID 1.5G AUTO
Chassis No.:	GB71029955
Engine No.:	LEB5555893
Accident Date:	20-Jul-2018

[illegible]

BW WORKSHOP SERVICES PTE LTD



INVOICE

TO : MD SHAIFULAH B SELAMAT
C/O: BW WORKSHOP SERVICES PTE LTD
30 UBI ROAD 4
SINGAPORE 408615

Invoice No.: 718/BW745
Date: 15-Aug-2018

PARTICULARS

Vehicle Registration No.: SLQ 7063 R
Date of Loss: 20-Jul-2018
Date of Assessment: 24-Jul-2018

SERVICES

FEES

1. Assessment with report Photographs -
Including films, developing, storage and Transport. \$500.00

TOTAL \$500.00

SINGAPORE DOLLARS FIVE HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: MD SHAFULAH B SELAMAT
C/O: BW WORKSHOP SERVICES PTE LTD
30 UBI ROAD 4
SINGAPORE 408615

Our Reference: 718/BW745
Date: 15-Aug-2018

ASSESSMENT OF VEHICLE NO. SLQ 7063 R

DATE OF LOSS: 20-Jul-2018

We have carried out a physical assessment at BW WORKSHOP SERVICES PTE LTD,
30 Ubi Road 4 Singapore 408615, according to your instruction

24-Jul-2018 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SLQ 7063 R
Make & Model: HONDA FREED HYBRID 1.5G AUTO
Year of Registration: 2017
Engine Capacity: 1496
Chassis No.: GB71029955
Engine No.: LEB5555893
Colour: BLUE
Mileage (km): 31805

2. VEHICLE CONDITION

Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: DUNLOP 185/65 R15 - 80%
LH Make/Size/Thread: DUNLOP 185/65 R15 - 80%


Rear
RH Make/Size/Thread: DUNLOP 185/65 R15 - 80%
LH Make/Size/Thread: DUNLOP 185/65 R15 - 80%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$12,360.60
Adjusted Amount:	\$9,964.12
Loss Sum:	\$7,500.00
Estimated Repair Days:	8 days



Pursuant to your instruction, we have NOT AUTHORISED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

(

ASSESSMENT REPORT FOR VEHICLE NO. SLQ 7063 R

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR TAILGATE	Bent <i>50/300</i>	1,193.20	1,193.20 ✓
1	REAR TAILGATE LOCK	Bent <i>20</i>	157.20	157.20 ✓
1	REAR TAILGATE POCKET	Cracked <i>NN (No Dye)</i>	26.90	26.90 X
1	REAR TAILGATE EMBLEM FREED	Necessary <i>nn</i>	69.50	69.50 ✓
1	REAR TAILGATE EMBLEM HYBRID	Necessary <i>nn</i>	75.50	75.50 ✓
1	REAR TAILGATE CAMERA	Faulty <i>NN (No Dye)</i>	1,020.70	1,020.70 X
3	REAR WINDSCREEN RUBBER	Cut <i>nn</i>	91.50	91.50 ✓
1	REAR WINDSCREEN RUBBER LOWER	Cut <i>nn</i>	69.30	69.30 ✓
1	REAR WINDSCREEN RUBBER SEAL <i>S.N</i>	Necessary <i>nn</i>	60.00	60.00 30
1	REAR WINDSCREEN SPONG TAPE <i>S.N</i>	Necessary <i>nn</i>	120.00	120.00 30
1	REAR TAILGATE REFLECTOR L/R	Cracked <i>NN (No Dye)</i>	827.00	827.00 X
2	REAR TAILGATE REFLECTOR SEAL L/R	Necessary <i>NN</i>	37.00	37.00 X
1	REAR TAILGATE OUTER GARNISH	Cracked <i>NN (No Dye)</i>	282.30	282.30 X
2	REAR TAILGATE NUMBER PLATE LAMP L/R	Cracked <i>NN (No Dye)</i>	66.40	66.40 X
1	REAR TAILGATE INNER TRIM GARNISH	Cracked <i>NN (No Dye)</i>	225.00	225.00 X
2	REAR TAILGATE DAMPER L/R	Repair <i>NN</i>	366.20	- X
2	REAR TAILGATE HINGES L/R	Bent <i>NN (No Dye)</i>	122.60	122.60 X
1	REAR TAILGATE MECHANISM LOCK STRIKER	Bent <i>NN (No Dye)</i>	28.80	28.80 X
1	REAR TAILGATE WEATHER STRIP	Cut <i>nn</i>	148.20	148.20 ✓
1	REAR TAILGATE WIPER ARM	Repair <i>NN</i>	80.00	- X
1	REAR TAILGATE WIPER ARM COVER	Repair <i>NN</i>	10.00	- X
1	REAR TAILGATE WIPER BLADE	Reuse <i>NN</i>	48.60	- X
1	REAR TAILGATE WIPER MOTOR	Faulty <i>NN (No Dye)</i>	264.90	264.90 X
2	REAR TAILLAMP L/R	Repair <i>NN</i>	948.20	- X
2	REAR TAILLAMP RUBBER SEAL L/R	Necessary <i>NN</i>	48.80	48.80 X
1	REAR BUMPER	Cracked <i>50/100</i>	1,150.20	1,150.20 ✓
2	REAR BUMPER SIDE LOWER RETAINER L/R	Bent <i>nn</i>	53.80	53.80 ✓
2	REAR BUMPER SIDE TOP RETAINER L/R	Bent <i>nn</i>	62.40	62.40 ✓
1	REAR BUMPER REFLECTOR L/R	Necessary <i>NN (No Dye)</i>	282.20	282.20 X
1	REAR END PANEL INNER TOP GARNISH	Cut <i>NN (No Dye)</i>	92.30	92.30 X
1	REAR END PANEL	Bent <i>nn</i>	623.20	623.20 X
1	REAR EXHAUST SILENCER BOX	Repair <i>nn</i>	880.10	- X
			9,532.00	7,198.90
Less 20% discount			1,906.40	1,439.78
Parts Total:			7,625.60	5,759.12

3070.8
20%
2456.64

ASSESSMENT REPORT FOR VEHICLE NO. SLQ 7063 R

SPECIAL NETT ITEMS

1	REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	Necessary	NN	45.00	45.00	X
1	REAR TAILGATE OUTER GARNISH CLIPS - SET	Necessary	NN	30.00	30.00	X
1	REAR TAILGATE WINDSCREEN SEALANT	Necessary	NN	100.00	100.00	40
1	REAR TAILGATE NUMBER PLATE	Cracked	NN (can't see eye)	25.00	25.00	X
1	REAR TAILGATE NUMBER PLATE HOLDER	Cracked	NN	50.00	50.00	X
1	REAR BUMPER CLIPS -SET	Necessary	NN	45.00	45.00	-
1	REAR BUMPER PARKING SENSOR	Cracked	NN	350.00	350.00	200
Special Nett Total :				645.00	645.00	

OUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. *	1,600.00	1,500.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet. *	1,400.00	1,200.00
3	To remove, reinstall tailgate windscreen.	180.00	150.00
4	To reset system after repair works.	150.00	120.00
5	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. *	300.00	250.00
6	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. *	110.00	90.00
	To apply anti-rust chemical on repaired and replaced panel.	350.00	250.00
Labour Total :		4,090.00	3,560.00

TOTAL (PARTS & LABOUR) \$ 12,360.60 9,964.12

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$7,500.00

(SINGAPORE DOLLARS SEVEN THOUSAND FIVE HUNDRED ONLY)



Amas Ong
Automobile Assessor

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018		23 Jul 2018 15:33 Edit Adj Rpt	S\$4,161.64 Edit Estimates	S\$4,161.64 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEAH WOO YANG, ID: S8861958G, Tel: +6584114688, Email: jerry_yang77@hotmail.com		
Main Claimant:	MD SHAFULAH B SELAMAT, ID: S7434128D		
Vehicle Reg. No.:	SLQ7063R	Date of Loss:	20/07/2018 07:00 - :59 [12 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 565088	Policy/Cover Note No.:	A80456385QMX (Comprehensive) Coverage: 28/04/2018 - 27/04/2019
Vehicle Reg. No. (Insured):	SJT7315Y	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Bw Workshop Services Pte Ltd (HQ) 30 UBI ROAD 4, 408615 Ubi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/09/2018]		
Driver/Custodian (Insured):	CHEAH WOO YANG (29 / Male), NRIC: S8861958G, Tel: +6584114688		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY: 100% CONTACT: AH QUAN 6745 8800		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (24/09/2018): Report Send Back Alerts - SLQ7063R (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLQ7063R (565088)**
[SJT7315Y]

TP

MD SHAFULAH B SELAMAT
Jul 20 2018 7:00AM
[CHEAH WOO YANG]
Bw Workshop Services Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/07/18 14:31	Accident Statement From: SC - Reg. No: SJT7315Y, Claimant: CHEAH WOO YANG	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 13:08	Odometer Reading	 Load JPG ☒	☒
2	24/07/18 13:08	Chassis Number	 Load JPG ☒	☒
3	24/07/18 13:08	General View	 Load JPG ☒	☒
4	24/07/18 13:08	General View	 Load JPG ☒	☒
5	24/07/18 13:08	General View	 Load JPG ☒	☒
6	24/07/18 13:08	General View	 Load JPG ☒	☒
7	24/07/18 13:08	General View	 Load JPG ☒	☒
8	24/07/18 13:08	General View	 Load JPG ☒	☒
9	24/07/18 13:08	General View	 Load JPG ☒	☒
10	24/07/18 13:08	General View	 Load JPG ☒	☒
11	24/07/18 13:08	General View	 Load JPG ☒	☒
12	24/07/18 13:08	General View	 Load JPG ☒	☒
13	24/07/18 13:08	General View	 Load JPG ☒	☒
14	24/07/18 13:08	General View	 Load JPG ☒	☒
15	24/07/18 13:08	General View	 Load JPG ☒	☒
16	24/07/18 13:08	General View	 Load JPG ☒	☒
17	24/07/18 13:08	General View	 Load JPG ☒	☒
18	24/07/18 13:08	General View	 Load JPG ☒	☒
19	24/07/18 13:08	General View	 Load JPG ☒	☒
20	24/07/18 13:08	General View	 Load JPG ☒	☒
21	24/07/18 13:08	General View	 Load JPG ☒	☒
22	24/07/18 13:08	General View	 Load JPG ☒	☒
23	24/07/18 13:08	General View	 Load JPG ☒	☒
24	24/07/18 13:08	General View	 Load JPG ☒	☒
25	24/07/18 13:08	General View	 Load JPG ☒	☒
26	24/07/18 13:08	General View	 Load JPG ☒	☒
27	24/07/18 13:08	General View	 Load JPG ☒	☒
28	24/07/18 13:08	General View	 Load JPG ☒	☒
29	24/07/18 13:08	General View	 Load JPG ☒	☒
30	24/07/18 13:08	General View	 Load JPG ☒	☒
31	24/07/18 13:08	General View	 Load JPG ☒	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	24/07/18 13:08	General View	 Load JPG	☒
33	24/07/18 13:08	General View	 Load JPG	☒
34	24/07/18 13:08	General View	 Load JPG	☒
35	24/07/18 13:08	General View	 Load JPG	☒
36	24/07/18 13:08	General View	 Load JPG	☒
37	24/07/18 13:08	General View	 Load JPG	☒
38	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
39	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
40	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
41	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
42	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
43	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
44	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
45	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
46	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
47	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
48	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
49	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
50	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
51	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
52	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
53	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
54	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
55	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
56	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
57	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
58	26/07/18 09:07	Reinspection Photo	 Load JPG	☒
59	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
60	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
61	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
62	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
63	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
64	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
65	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
66	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
67	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
68	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
69	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
70	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
71	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
72	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
73	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
74	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
75	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
76	28/07/18 10:19	Reinspection Photo	 Load JPG	☒
77	04/08/18 10:55	Photo After Spray	 Load JPG	☒
78	04/08/18 10:55	Photo After Spray	 Load JPG	☒
79	04/08/18 10:55	Photo After Spray	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	04/08/18 10:55	Photo After Spray	Load JPG	☒
81	04/08/18 10:55	Photo After Spray	Load JPG	☒
82	04/08/18 10:55	Photo After Spray	Load JPG	☒
83	04/08/18 10:55	Photo After Spray	Load JPG	☒
84	04/08/18 10:55	Photo After Spray	Load JPG	☒
85	04/08/18 10:55	Photo After Spray	Load JPG	☒
86	04/08/18 10:55	Photo After Spray	Load JPG	☒
87	04/08/18 10:55	Photo After Spray	Load JPG	☒
88	04/08/18 10:55	Photo After Spray	Load JPG	☒
89	04/08/18 10:55	Photo After Spray	Load JPG	☒
90	04/08/18 10:55	Photo After Spray	Load JPG	☒
91	04/08/18 10:55	Photo After Spray	Load JPG	☒
92	04/08/18 10:55	Photo After Spray	Load JPG	☒
93	04/08/18 10:55	Photo After Spray	Load JPG	☒
94	04/08/18 10:55	Photo After Spray	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/07/18 14:31	SLQ7063R TP E-FILE REPORT From: SC - Reg. No: SJT7315Y, Claimant: CHEAH WOO YANG	Load PDF	
2	23/07/18 14:32	PRI & SURVEY DISAGREE ON SJE - DANIEL POON & CO.	Load PDF	
3	03/09/18 16:46	Acknowledgement Email to TP lawyer	Load HTM	
4	24/09/18 11:14	LOD & SUPPORTING DOCUMENTS	Load PDF	
5	24/09/18 11:14	SURVEY REPORT	Load PDF	
6	24/09/18 11:14	SURVEY PHOTOS PART 1	Load PDF	
7	24/09/18 11:14	SURVEY REPORT PART 2	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 17:00	PRS INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18013393/USD3S2-1
Date: 01/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A80456385QMX
Claimant Vehicle No : SLQ7063R **Insured Vehicle No :** SJT7315Y
 Date of Loss: 20/07/2018 Nature of Claim: TP Claim No: 565088

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ7063R**
 Make & Model: HONDA FREED, 1.5 G (A) Engine No: LEB5555893
 Reg. Date: 20/07/2017 (Man. Year: 2017) Chassis No: GB71029955
 Colour: Blue Odometer: 31805 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
 Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
 Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,270.60	2,801.64	5,468.96	66.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	1,360.00	2,730.00	66.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,360.60	4,161.64	8,198.96	66.33
+ GST 7.00/7.00% (S\$)	865.24	291.31	573.93	66.33
Nett Amount (S\$)	13,225.84	4,452.95	8,772.89	66.33

INSPECTION

Date of Assignment: 23/07/2018
 Date Inspected: 24/07/2018 Inspected At: Bw Workshop Services Pte Ltd (HQ)
 30 UBI ROAD 4
 Singapore 408615
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2018)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ7063R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,193.20 FL	*1,193.20 FL
2	1		*REAR TAILGATE LOCK	Dented	157.20 FL	*157.20 FL
3	1		*REAR TAILGATE POCKET (NOT NECESSARY)	No Damage	26.90 FL	*- FL
4	1		*REAR TAILGATE EMBLEM FREED	Necessary	69.50 FL	*69.50 FL
5	1		*REAR TAILGATE EMBLEM HYBRID	Necessary	75.50 FL	*75.50 FL
6	1		*REAR TAILGATE CAMERA (NOT NECESSARY)	No Damage	1,020.70 FL	*- FL
7	3		*REAR WINDSCREEN RUBBER	Necessary	91.50 FL	*91.50 FL
8	1		*REAR WINDSCREEN RUBBER LOWER	Necessary	69.30 FL	*69.30 FL
9	2		*REAR TAILGATE REFLECTOR L/R (NOT NECESSARY)	No Damage	827.00 FL	*- FL
10	2		*REAR TAILGATE REFLECTOR SEAL L/R	Not Necessary	37.00 FL	*- FL
11	1		*REAR TAILGATE OUTER GARNISH (NOT NECESSARY)	No Damage	282.30 FL	*- FL
12	2		*REAR TAILGATE NUMBER PLATE LAMP L/R (NOT NECESSARY)	No Damage	66.40 FL	*- FL
13	1		*REAR TAILGATE INNER TRIM GARNISH (NOT NECESSARY)	No Damage	225.00 FL	*- FL
14	2		*REAR TAILGATE DAMPER L/R	Not Necessary	366.20 FL	*- FL
15	2		*REAR TAILGATE HINGES L/R (NOT NECESSARY)	No Damage	122.60 FL	*- FL
16	1		*REAR TAILGATE MECHANISM LOCK STRIKER (NOT NECESSARY)	No Damage	28.80 FL	*- FL
17	1		*REAR TAILGATE WEATHER STRIP	Necessary	148.20 FL	*148.20 FL
18	1		*REAR TAILGATE WIPER ARM	Not Necessary	80.00 FL	*- FL
19	1		*REAR TAILGATE WIPER ARM COVER	Not Necessary	10.00 FL	*- FL
20	1		*REAR TAILGATE WIPER BLADE	Not Necessary	48.60 FL	*- FL
21	1		*REAR TAILGATE WIPER MOTOR (NOT NECESSARY)	No Damage	264.90 FL	*- FL
22	2		*REAR TAILLAMP L/R	Not Necessary	948.20 FL	*- FL
23	2		*REAR TAILLAMP RUBBER SEAL L/R	Not Necessary	48.80 FL	*- FL
24	1		*REAR BUMPER	Dented / Deformed	1,150.20 FL	*1,150.20 FL
25	2		*REAR BUMPER SIDE LOWER RETAINER L/R	Necessary	53.80 FL	*53.80 FL
26	2		*REAR BUMPER SIDE TOP RETAINER L/R	Necessary	62.40 FL	*62.40 FL
27	1		*REAR BUMPER REFLECTOR L/R (NOT NECESSARY)	No Damage	282.20 FL	*- FL
28	1		*REAR END PANEL INNER TOP GARNISH (NOT NECESSARY)	No Damage	92.30 FL	*- FL
29	1		*REAR END PANEL	Repair	623.20 FL	*- FL
30	1		*REAR EXHAUST SILENCER BOX	Not Necessary	880.10 FL	*- FL
31	1		*REAR WINDSCREEN RUBBER SEAL	Necessary	48.00 FS	*30.00 FS
32	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	96.00 FS	*30.00 FS
33	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Not Necessary	45.00 FS	*- FS
34	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
35	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR TAILGATE NUMBER PLATE (NOT NECESSARY)	Can't See Damage	25.00 FS	*- FS
37	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
39	1		*REAR BUMPER PARKING SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	10,141.00	3,415.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,870.40	614.16
Total Parts (\$\$)	8,270.60	2,801.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR	New	110.00	30.00
2	TO REMOVE,REINSTALL TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET	New	300.00	80.00
3	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	180.00	120.00
4	TO RESET SYSTEM AFTER REPAIR WORKS	New	150.00	-
5	TO RESPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	600.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	500.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	350.00	30.00
Gross Labour Cost (S\$)			4,090.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >