



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GY8464C180914

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 24-09-18

Address Motor Claims Department

Vehicle No: GY8464C

78 Shenton Way #07-16

Model/Make: Toyota Hiace

AIG Building

Singapore 079120

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>905.00/Ref</i>	\$ 1,472.50	
2	Tailgate "Toyota Logo" Motif <i>Ref</i>	\$ 70.50	
3	Tailgate "70 KM/H" Sticker <i>Ref</i>	\$ 15.00	SN 105-N
4	Tailgate "8 PAX" Sticker <i>Ref</i>	\$ 15.00	SN 105-N
5	Tailgate Inner Lock <i>11</i>	\$ 359.00	X
6	Tailgate Weatherstrip <i>2W1</i>	\$ 387.90	
7	Tailgate Windscreen Moulding <i>NS</i>	\$ 219.00	X
8	Tailgate Windscreen Sealant <i>Ref</i>	\$ 50.00	SN 405-N
9	Tailgate Number Plate & Base <i>11</i>	\$ 48.00	SN X
10	Bumper <i>Ref</i>	\$ 496.50	
11	Bumper Clips 1 set <i>Ref</i>	\$ 65.00	X
12	Bumper Side Holder 02 pcs (@S\$69.10) <i>11</i>	\$ 138.20	X
13	Bumper Lower Bracket 04 pcs (@S\$103.00) <i>Ref</i>	\$ 412.00	
14	Tail Lamps 02 pcs (@ S\$365.10) <i>11</i>	\$ 730.20	X
15	End Panel Outer <i>2</i>	\$ 566.10	X
16	End Panel Inner <i>2</i>	\$ 936.20	X
17	End Panel Top Plate <i>11</i>	\$ 166.50	X
18	End Panel Sealant <i>11</i>	\$ 50.00	SN X
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water	\$ 120.00	- 100
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	- 60
	Remove and replace rear exhaust pipe system to facilitate repairs <i>11</i>	\$ 80.00	- X
	Remove and refix rear Bumper distance sensor <i>11</i>	\$ 90.00	- X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	- 400
	To putty & spray painting & including touch up paint on accident affect	\$ 800.00	- 450
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	- 30

Total Parts & Labour of estimate for damaged vehicle

\$ 8,377.60

Total amount in Lump Sum Basis for repaired vehicle



SDLS:

M/s Liu's Brother Auto Engrg Wks

not Authorized
Wk
2600/2
24/9/18
Whepht. Adherson
H. Chen

P-2904.4
257

2178.30
S.N-60
1chm-1060

3298.30
2638

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: