3/4/2019 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG18017399/AQBS2

AIG Building, 78 Shenton Way #08-16
Singapore 079120

Date: 04/03/2019

REFERENCE

Insured/Claimant: EU KEE HOE, GREGORY Policy No: 2100507392-01

Date of Loss: 20/09/2018 Nature of Claim: OD Claim No: 5412095788SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EP2232R

Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ325699

Reg. Date: 19/04/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V3H1060083

Colour: Grey Odometer: 34871 km

Engine Capacity: 999 cc

Market Value/New Car Price: \$\$95,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm
Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		12,145.00	6,088.32	6,056.68	49.87
Miscellaneous Items		0.00	0.00	0.00	
Labour		18,032.00	11,182.00	6,850.00	37.99
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	30,177.00	17,270.32	12,906.68	42.77
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	29,577.00	16,670.32	12,906.68	43.64
	+ GST 7.00/7.00% (S\$)	2,070.39	1,166.92	903.47	43.64
	Nett Amount (S\$)	31,647.39	17,837.24	13,810.15	43.64

INSPECTION

Date of Assignment: 25/09/2018

Date Inspected: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

1 2 3	1				
	1	*REAR BUMPER	Repair	1,697.00 FS	*- FS
2	4	*REAR BUMPER STICKY PAD (NPA)	Not Necessary	0.00 FS	*- FS
3	1	*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
4	1	*REAR WHEEL HOUSING LINER - LH	Not Necessary	32.00 FS	*- FS
5	1	*REAR BUMPER SPOILER	Not Necessary	206.00 FS	*- FS
6	1	*REAR BUMPER GUIDE SECTION - LH	Not Necessary	57.00 FS	*- FS
7	2	*REAR LIGHT REFLECTOR - LH/RH	Not Necessary	70.00 FS	*- FS
8	4	*REAR BUMPER SEAL RING	Not Necessary	14.00 FS	*- FS
9	1	*SIDE PANEL - LH	Distorted	2,006.00 FS	*1,604.80 FS
10	1	*REAR WINDOW	Necessary	704.00 FS	*563.20 FS
11	1	*REAR SIDE WINDOW - LH	Necessary	502.00 FS	*401.20 FS
12	1	*REAR SIDE WINDOW TRIM STRIPS - LH	Not Necessary	388.00 FS	*- FS
13	2	*PRIMER	Necessary	37.00 FS	*14.56 FS
14	1	*REAR WHEEL HOUSING LINER - LH	Not Necessary	532.00 FS	*- FS
15	1	*REAR REINFORCEMENT FOR C PILLAR - LH	Not Necessary	172.00 FS	*- FS
16	1	*REAR DOOR - LH	Dented	2,190.00 FS	*1,752.00 FS
17	1	*REAR OUTER DOOR SEAL - LH	Necessary	139.00 FS	*111.20 FS
18	1	*BONDING AGENT	Necessary	43.00 FS	*34.16 FS
19	1	*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
20	1	*APPLICATOR	Not Necessary	7.00 FS	*- FS
21	1	*REAR DOOR INNER SEAL - LH	Not Necessary	165.00 FS	*- FS
22	1	*REAR DOOR CATCH - LH	Not Necessary	82.00 FS	*- FS
23	1	*REAR DOOR CATCH COVER - LH	Not Necessary	14.00 FS	*- FS
24	1	*REAR DOOR EXTERIOR HANDLE - LH	Repair	207.00 FS	*- FS
25	1	*REAR DOOR HANDLE HOUSING - LH	Repair	26.00 FS	*- FS
26	1	*REAR DOOR SLIDE VALVE - LH	Not Necessary	11.00 FS	*- FS
27	1	*REAR DOOR MOUNTING BAR - LH	Not Necessary	143.00 FS	*- FS
28	1	*REAR WINDOW REGULATOR - LH	Not Necessary	220.00 FS	*- FS
29	1	*REAR RIM - LH	Cut	659.00 FS	*527.20 FS
30	4	*REAR TYRE RUBBER VALVE - LH	Not Necessary	12.00 FS	*- FS
31	1	*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
32	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
33	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
34	1	*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
35	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
36	1	*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
37	1	*SUNDRIES	Not Necessary	500.00 FS	*- FS
	nchise part. S		=		
	•	•	Total Parts (S\$)	12,145.00	6,088.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

New New New New	280.00 600.00 280.00 1,400.00 1,400.00	280.00 1,400.00 1,400.00
New New New	600.00 280.00 1,400.00	600.00 280.00 1,400.00
New New	280.00 1,400.00 1,400.00	600.00 280.00 1,400.00 1,400.00 3,500.00
New	1,400.00	1,400.00
New	1,400.00	1,400.00
	·	·
New	8,400.00	3,500.00
New	4,800.00	2,850.00
New	280.00	280.00
New	192.00	192.00
New	400.00	400.00
Cost (S\$)	18,032.00	11,182.00
	New New	New 280.00 New 192.00 New 400.00

< END OF ESTIMATES >